वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 14/10/2026

Shift: C

Incharge(s): Nagendra Midde

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO 25	TRIPPING ON OVER CURRENT/8 TIMES	RESET DONE/MOTOR REPLACEMENT IS GOING ON	00:05:00	02:30:00	SOUND OBSERVED FROM DRIVE END BEARING
2	OHP	BRC ON CO 8A	HYDROLIC PUMP NOT RUNNING/COOLING FAN MPCB TRIPPED	MPCB MADE ON THEN OK	00:30:00	00:45:00	
3	OHP	CR 3A	LUBRICATION PUMP NOT WORKING/EMERGENCY STOP PB NOT RELEASED	PB RELEASED	22:30:00	22:45:00	PB TO BE REPLACED
4	OHP	BRC ON CO 28	LT NOT TAKING PLACE/PCRD MCCB TRIPPED AND TENSION ACTED	MCCB MADE ON AND TENSION RELEASED	23:40:00	00:00:00	
5	OHP	BRC ON CO 31	BC NOT RUNNING/CJD ACTED DUE JAMMING	INFORM TO OPERATION	02:30:00	02:50:00	
6	OHP	TBS ON CO 20	LT NOT TAKING PLACE/M 4 TRIPPED AND MPCB BURNT	M4 TERMINATION DISCONNECTED THEN GIVEN CLEARENCE	05:20:00	05:35:00	MPCB TO BE CHANGED AND MOTOR TOBE CHE.
7	OHP	BRC ON CO 31	BC NOT RUNNING/OLR ACTED	RESET DONE	04:10:00 05:30:00	04:25:00 05:45:00	
8	CHP	SCR 8 ON CC106	LT NOT TAKING PLACE/MAIN CONTROL MCB TRIPPED ON EART FAULT	EARTH FAULT IN TBX -9 CONTROL WIRE REMOVED AND MCB MADE ON	00:00:00	00:15:00	

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 14/10/2026

Shift: C

Incharge(s): Nagendra Midde

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
9	CHP	SCR 5 ON CC32	LT NOT TAKING PLACE/PCRD TENSION ACTED	TENSION RELEASED	22:35:00	22:45:00	
10	CHP	SCR 1 ON CC31	SLEW NOT TAKING PLACE/30 DEGREE LIMT ACTED	LIMIT RELEASED THEN OK	23:00:00	23:10:00	
11	CHP	CC 38	CS ACTED/PROBE GROUNDED DUE TO RAIN	BYPASSED	04:50:00	05:00:00	
12	CHP	SCR 6 ON CC	BC NOT RUNNING/CS ACTED DUE TO RAIN	BYPASSED	05:10:00	05:20:00	
13	CHP	CC 107	BSS ACTED/RF SWITCH NOT RESETED	BYPASSED	05:20:00	05:30:00	
14	CHP	SCR 9 ON CC104	BC NOT RUNNING/COMMUNICATION BIT MISSING TO CCR/MODEM PROBLEM	COMMUNICATION BIT BYPASSED THEN GIVEN CLEARENCE	01:45:00	01:55:00	MODEM TO BE CHANGED
15	CHP	CC 14	TRIPPED ON OLR	RESET DONE	04:20:00	04:30:00	
16	CHP	CC 8	NOT RUNNING/MCCB TRIPPED	RATING ADJUSTMENT DONE AND MADE ON	22:30:00	22:45:00	
17	CHP	CC 28 TO 31	POSITION SIGNAL NOT GETTING	BYPASSED AT I/O RACK	22:30:00	22:40:00	