



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 10/09/2026

Shift: A

Incharge(s): Amit Roy,K SANKARA RAO

| Sl No | Area | Equipment     | Problem                                                                                                             | Action                                                                                                          | From     | To       | Remarks |
|-------|------|---------------|---------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|----------|----------|---------|
| 1     | OHP  | WOBR ON CO-29 | REPORTED LT NOT TAKING PLACE FOUND PCRD O/T NOT HEALTHY LIMIT SWITCH INSIDE ONE WIRE OPENED                         | WIRE RE-CONNECTED THAN OK                                                                                       | 06:25:00 | 06:45:00 |         |
| 2     | OHP  | BRC ON CO-28  | B/C OLR ACTED DUE TO MATERIAL OVER LOAD                                                                             | RESET DONE AND INFORMED TO OPERATION                                                                            | 07:15:00 | 07:25:00 |         |
| 3     | OHP  | TBS ON CO-21  | REPORTED LT NOT TAKING PLACE PCRD O/T ACTED DUE TO PCRD DRUM NOT ROTATING FOUND PCRD PANEL TIMER CONTACT WIRE LOOSE | PROPERLY TIGHT THAN OK                                                                                          | 07:30:00 | 07:50:00 |         |
| 4     | OHP  | TBS ON CO-22  | PCRD CABLE OVER LAPPING DUE TO GUIDE PROBLEM                                                                        | PCRD CABLE PROPER LAYING WAS DONE WITH MECHANICAL                                                               | 09:30:00 | 10:15:00 |         |
| 5     | OHP  | CO-34         | OLR ACTED                                                                                                           | RESET DONE                                                                                                      | 09:25:00 | 09:30:00 |         |
| 6     | OHP  | HVMCC-4       | ALL CONVEYORS NOT HEALTHY                                                                                           | IC-1 TRIPPED ON UNDER VOLTAGE AND ALSO IC-1 TRIPPED IN LBDS-8 ON OVER CURRENT.BOTH IC'S MADE ON AND TESTED OKAY | 08:48:00 | 09:10:00 |         |
| 7     | WT   | OP-6          | REPORTED NOT MOVE FOUND E/STOP ACTED (DEAD-END )                                                                    | RELEASED THAN OK                                                                                                | 07:35:00 | 07:45:00 |         |
| 8     | WT   | OT-5          | OUT-HALL SIDE INITIAL SENSOR FREQUENTLY ACTED                                                                       | INITIAL SENSOR BYPASSED                                                                                         | 10:45:00 | 11:00:00 |         |