



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 20/09/2026

Shift: B

Incharge(s): Saurabh Kumar Yadav

| Sl No | Area | Equipment          | Problem                                                                             | Action                                                                         | From     | To       | Remarks                                                       |
|-------|------|--------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------|----------|----------|---------------------------------------------------------------|
| 1     | OHP  | TBS on CO 22       | pending from A shift,brake problem,brake coil towards crmp side got burn            | brake resistance,diode all ok,crmp side brake power removed only kept chp side | 14:30:00 | 15:10:00 |                                                               |
| 2     | OHP  | wobr on co 26      | no power complaint,control mcb tripped in PLC and LT drive panel MCB malfunctioning | PLC mcb made on,LT drive panel mcb replaced with 10 A(2A mcb not available)    | 19:20:00 | 19:45:00 | MCB to be replaced * latest i/o chart to be kept in PLC panel |
| 3     | OHP  | CO 25              | OLR acted                                                                           | reset                                                                          | 16:00:00 | 16:15:00 |                                                               |
| 4     | OHP  | WOBR on co 25      | LT not working,M3 motor mpcb tripped                                                | made it on                                                                     | 18:50:00 | 19:10:00 |                                                               |
| 5     | OHP  | CR1A,3A and co 11A | not running,HMCC4 i/c 1 no power from1-2 LBDS 8                                     | in 1-2LBDS8 FDR1 for hvmcc4 made on from crp panel                             | 15:45:00 | 16:05:00 |                                                               |
| 6     | CHP  | CC 22 on CC 29     | bit missing,sensor wire loose connection                                            | tightened                                                                      | 14:30:00 | 14:45:00 |                                                               |
| 7     | CHP  | CC 40 SCR7         | luff up not working,filter clog 2                                                   | informed to operation and mechanical                                           | 17:05:00 | 17:18:00 |                                                               |
| 8     | WT   | SCO1A              | ZSS acted,probe loose connection                                                    | tightened it                                                                   | 15:30:00 | 15:45:00 |                                                               |