



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 07/05/2026

Incharge(s): Amit Roy

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-16	Reported tripped	OLR acted.Reset done	12:40:00	12:55:00	
2	OHP	BRC on CO-28	Reported no operations taking place	ACB made off and made on properly and tested okay	10:00:00	10:20:00	
3	OHP	BRC on CO-34	B/W-2 not rotating	Control problem rectified along with general shift and tested okay	10:15:00	11:45:00	
4	CHP	Cc-37 SCR-3	Slewing and B/W not working	Checked and found command fuse blown in I/O rack.Replaced and tested okay	06:00:00	07:00:00	
5	CHP	Cc-31 SCR-1	Slewing not working	30degree limit acted	06:45:00	07:00:00	Informed to operation
6	CHP	Cc-33 SCR-2	LT not taking place	PCRD cable slackness found.Released and tested okay	06:30:00	06:50:00	
7	CHP	CC-51	MPD tripped	Reset done(5 times)	09:40:00	13:00:00	
8	CHP	CC-12	Reported not running in healthy condition	Checked and found route emergency acted in HMI.Released and tested okay	10:00:00	10:30:00	Informed to operation