



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 20/09/2026

Shift: B

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TBS on CO 22	pending from A shift,brake problem,brake coil towards crmp side got burn	brake resistance,diode all ok,crmp side brake power removed only kept chp side	14:30:00	15:10:00	
2	OHP	wobr on co 26	no power complaint,control mcb tripped in PLC and LT drive panel MCB malfunctioning	PLC mcb made on,LT drive panel mcb replaced with 10 A(2A mcb not available)	19:20:00	19:45:00	MCB to be replaced * latest i/o chart to be kept in PLC panel
3	OHP	CO 25	OLR acted	reset	16:00:00	16:15:00	
4	OHP	WOBR on co 25	LT not working,M3 motor mpcb tripped	made it on	18:50:00	19:10:00	
5	OHP	CR1A,3A and co 11A	not running,HMCC4 i/c 1 no power from1-2 LBDS 8	in 1-2LBDS8 FDR1 for hvmcc4 made on from crp panel	15:45:00	16:05:00	
6	CHP	CC 22 on CC 29	bit missing,sensor wire loose connection	tightened	14:30:00	14:45:00	
7	CHP	CC 40 SCR7	luff up not working,filter clog 2	informed to operation and mechanical	17:05:00	17:18:00	
8	WT	SCO1A	ZSS acted,probe loose connection	tightened it	15:30:00	15:45:00	