



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 06/08/2026

Shift: C

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	WOBR-2 on CO-29	LT not taking place	Drive tripped due to Crmp side track jamming.Reset done	22:30:00	22:45:00	Informed to operation to clear jamming
2	OHP	TBS on CO-20	CJD acting continously	CJD malfunctioning	22:45:00	22:50:00	Bypassed as per operation request
3	OHP	WOBR on CO-26	Reported B/C not running	CJD acted and not resetting	23:10:00	23:20:00	Bypassed as per operation request.To be checked
4	OHP	CO-26	Reported tripped	OLR acted.Reset done	01:20:00 02:55:00 04:30:00 04:50:00 05:45:00	01:30:00 03:05:00 04:40:00 05:00:00 05:50:00	
5	OHP	CO-10A	Reported tripped	OLR acted.Reset done	22:00:00	22:08:00	
6	OHP	CO-26	Reported zss acting	Checked and found emergency acted by mechanical while running	02:15:00	02:30:00	NO electrical complaint.
7	OHP	CO-34	Reported tripped	OLR acted.Reset done	03:15:00	03:20:00	



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 06/08/2026

Incharge(s): Amit Roy

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
8	OHP	BRC-2 on CO-31	Reported B/W-1 not running	MCCB tripped.Made on and again tripped while on load.Checked and found plate got stuck.Removed and tested okay	03:15:00	04:00:00	
9	OHP	CO-29	Reported tripped	OLR acted.Reset done	04:55:00	05:05:00	
10	CHP	CC-112 SCR-8	B/C not running	CJD malfunctioning.Bypassed and given clearance	23:40:00	23:55:00	To be checked and to be rectified
11	CHP	CC-112	D/E CJD acted	Cleaning done and tested okay	02:20:00	02:35:00	
12	CHP	Cc-52	MPD tripped	Reset done	00:00:00	00:10:00	
13	CHP	CC-130	ZSS acted	Due to over material on belt	02:50:00	03:00:00	
14	WT	OP-2	Reported not moving	Power tripped at column no.66. checked and made on	22:40:00	22:50:00	
15	WT	CP-1	Reported no power	Breaker tripped in LC-10A.Checked and found bus bar flashover.C-type isolator kept off at column no.41 and breaker made on and tested okay	00:20:00	01:17:00	
16	IOSA	OC-6A	BRS acting frequently	BRS checked and problem not found.BRS bypassed and given clearance	01:45:00	02:30:00	TO be checked