



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 03/07/2026

Incharge(s): Amit Roy

Shift: B

| Sl No | Area | Equipment              | Problem                             | Action                                                                                                      | From     | To       | Remarks                            |
|-------|------|------------------------|-------------------------------------|-------------------------------------------------------------------------------------------------------------|----------|----------|------------------------------------|
| 1     | OHP  | Reported power failure | LBDS-4 11KV I/C-2 no power from TPP | ALL LC's in CHP,OHP,Tipler and IOSA LT side I/C-1 and buscoupler made on and power restored                 | 21:00:00 | 22:00:00 |                                    |
| 2     | OHP  | WOBR on CO-29          | Luffing not taking place            | OLR acted.Reset done                                                                                        | 18:00:00 | 18:10:00 |                                    |
| 3     | CHP  | CC-106 SCR-9           | Luffing not working                 | Checked and found pump main solenoid not picking up.Fuse blown at I/O.Fuse replaced and tested okay         | 19:00:00 | 20:00:00 |                                    |
| 4     | CHP  | CC-31                  | B/C not running                     | 30 degree limit acted.Released and tested okay                                                              | 19:20:00 | 19:35:00 |                                    |
| 5     | CHP  | CC-51                  | MPD tripped                         | Reset done(3 times)                                                                                         | 17:20:00 | 20:05:00 |                                    |
| 6     | CHP  | CC-52                  | MPD tripped                         | Reset done(4 times)                                                                                         | 17:15:00 | 19:00:00 |                                    |
| 7     | CHP  | CC-54                  | Reported tripped                    | OLR acted.Reset done(2 times)                                                                               | 17:20:00 | 17:30:00 |                                    |
| 8     | WT   | OT-5                   | Reported not rotating               | Limit switches 5 and 8 got stuck up.Bypassed at CJB.                                                        | 16:00:00 | 17:00:00 |                                    |
| 9     | WT   | OT-5                   | Reported not healthy                | Power restored in LC and CPU interchanged from redundancy module and communication restored and tested okay | 22:00:00 | 22:30:00 | Communication restored at 12.00 PM |