वी.एस.पी
VSP

# RASHTRIYA ISPAT NIGAM LIMITED

## VISAKHAPATNAM STEEL PLANT

### RAW MATERIAL HANDLING PLANT

### ELECTRICAL SHIFT REPORT

Date: 22/10/2026

Shift: A

Incharge(s): M Kailash

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|---|---|---|---|---|---|---|---|
| 1 | OHP | BRC ON CO-8A | Bucket wheel not running due to Air blast cooler not healthy | PLC side loose connection found. Tightness done | 07:35:00 | 07:55:00 | |
| 2 | OHP | CO-34 | BRS not getting reset. | Found wrong complaint | 09:25:00 | 09:40:00 | |
| 3 | OHP | BRC ON CO-8A | Bucket wheels not running but pump is in ON condition. Operator has not operated Bucket Wheel start button | Informed to operation | 09:00:00 | 09:20:00 | |
| 4 | OHP | CO-6 | BRS not getting reset. Found loose contact in module | Tightened and made OK | 10:55:00 | 11:15:00 | |
| 5 | OHP | TT-1 | Not moving. Found MPCB tripped | Reset done | 12:30:00 | 12:40:00 | |
| 6 | CHP | CC-54 | Overload acted | Reset done | 10:35:00 | 10:40:00 | |
| 7 | CHP | STK-2 ON CC-35 | LT not working. Found M-2 tripped. | Reset done | 10:15:00 | 10:30:00 | |
| 8 | CHP | CC-125 | BRS acting frequently. Found canopy damaged completely and obstructing BRS. | Kept in bypass and informed agency to rectify canopy | 11:30:00 | 11:50:00 | Bypass to be removed |
| 9 | CHP | CC-9 | MCCB flash over occurred when conveyor started. Voltas breaker feeding to CM-6 also tripped. Found contactor one pole is internally short. | MCCB panel racked out. Voltas breaker is not closing. Spare voltas breaker racked in and given clearance. | 07:10:00 | 08:15:00 | Rectification is under progress |
| 10 | CHP | CC-28 | Overload acted | Reset done | 08:30:00<br>11:15:00 | 08:40:00<br>11:25:00 | |