RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 31/10/2026

Shift: C

Incharge(s): M Kailash

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	WOBR ON CO-29	LT not working. Drive tripped on OVA fault. Reset done. With command, sound observed from DBU. DBU disconnected and given command. Drive is tripping on OVA fault and not getting reset.	Changed the mode to DOL and given command. Then spark observed at transformer neutral. MCCB tripped and M-4 OLR acted. M-4 motor disconnected in both Drive and DOL mode. Then checked OK in drive mode	22:30:00	23:30:00	M-4 motor to be checked
2	OHP	TBS ON CO-5A	LT not moving. PCRD tension acted	Released and made OK	23:25:00	23:35:00	
3	OHP	CO-25	Overload acted	Reset done	02:00:00 02:25:00 22:35:00	02:15:00 02:35:00 23:45:00	
4	OHP	CO-26	Overload acted	Reset done	00:00:00	00:10:00	
5	OHP	WOBR ON CO-29	LT not moving. M-2 MPCB tripped	Reset done and made OK	00:50:00 05:50:00	01:00:00 06:10:00	
6	OHP	CR-1A	Remote mode not showing. Found Emergency not released properly	Released	05:10:00	05:20:00	
7	CHP	CC-40	ZSS acted. Found zss cage rod and pins damaged	Replaced and made OK	05:30:00	05:40:00	
8	CHP	CC-56	Healthy stop complaint. But found belt sway feedback missing.	Bypassed and then found running	00:00:00	00:25:00	
9	CHP	CC-27	ZSS complaint received. checked module and probe. found OK. checked in Local mode and found contactor not holding. checked and found selector switch side wire opened. Reconnected.	But with PLC command, immediately command is dropping. Then off delay of 2sec provided in program. then tested OK	23:30:00	01:00:00	to be checked further

वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 31/10/2026

Shift: C

Incharge(s): M Kailash

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
10	CHP	CC-26	Command is dropping immediately after contactor picks up.	Off delay provided for contactor on feedback	00:30:00	01:20:00	to be checked further
11	CHP	CC-26A	chute sensor acted. found material attached to probe.	cleaned and made OK	00:00:00	00:15:00	
12	CHP	CC-103	chute sensor acted. Found material touched	sensor cleaned and made OK	04:00:00	04:10:00	