



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 17/08/2026

Incharge(s): Amit Roy

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	WOBR on CO-26	LT not taking place	PCRD tension acted.Cable winded in drum and again tied with rope	14:30:00	14:45:00	Mechanical gearbox problem
2	OHP	CO-25	Reported tripped	OLR acted.Reset done	15:00:00	15:15:00	
3	OHP	BRC on CO-30	LT not working	PCRD tension acted.Released and tested okay	18:45:00	18:55:00	
4	OHP	CO-6A	BRS malfunctioning	Electronic BRS sensor cable found damaged.Electronic BRS bypassed.Mechanical JOD in line	19:50:00	20:10:00	Electronic BRS to be kept in line
5	CHP	CC-52	MPD tripped	Reset done(2 times)	15:55:00 21:30:00	16:00:00 21:35:00	
6	CHP	SCR-1 on CC-31	Signal missing	LT done and tested okay	20:10:00	20:20:00	