



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 22/09/2026

Shift: A

Incharge(s): P Venkat Kiran,P Venkat Kiran

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	RCO-1a	reported zss acted	target type probe damaged, bypassed and replaced later.	09:00:00	09:20:00	restored in circuit.
2	OHP	co-48	olr acted	reset done	06:40:00	06:55:00	
3	OHP	co-10a	olr acted	reset done	08:45:00	08:50:00	
4	OHP	brc-5 on co-32	reported all drives are not running	acb tripped, made on	09:20:00	09:40:00	
5	OHP	brc-2 on co-28	bw-1 not starting	olr acted, reset done	13:00:00	13:15:00	
6	OHP	co-76r	olr acted	reset done	12:20:00	12:35:00	
7	OHP	co-6a	a) reported machine not working. b) brs not resetting	a) checked all drives found ok. b) material jamming near sensors, cleaned and restored BRS	13:20:00	13:40:00	No electrical Delay
8	CHP	SCR 5 on CC 32	B/C not running	Stacking 30 degree angle acted / Bypassed	10:00:00	10:15:00	
9	CHP	SCR 2 on CC 33	Slew not working	Luff pump interlock/Luff pump made off	11:00:00	11:20:00	
10	CHP	CC 201	OLR acted	Reset	10:30:00	10:40:00	
11	CHP	CC 28/31 position	Not coming	Bypassed	10:30:00	10:40:00	