



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 09/05/2026

Shift: A

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TT-3 on CO-16	Reported Lt not taking place	Checked and found cable loop stuck at shaft and damaged.Cable taken out and rejoin done and tested okay	07:45:00	09:45:00	
2	OHP	CO-2A	Reported tripped	Checked and found master trip relay tripped.Motor checked and found one lug got cut.Relugging done and tested okay	08:15:00	12:30:00	
3	OHP	WOBR on CO-26	Slewing not taking place	Drive tripped.Reset done	12:10:00	12:30:00	
4	OHP	WOBR on CO-25	B/C not running	Yard interlock signal missing.Probe problem replaced and tested okay	12:00:00	14:00:00	
5	OHP	CO-26	Reported tripped	OLR acted.reset done	13:50:00	14:00:00	
6	OHP	CO-1A	PC acted	Checked and tested okay	13:20:00	13:50:00	
7	OHP	TBS on CO-21	LT not healthy	PCRD tension acted.Released and tested okay	12:40:00	13:10:00	
8	CHP	CC-36 R-1	B/C not running	signal missing.Lt done and tested okay	08:10:00	08:20:00	
9	CHP	CC-31 SCR-1	B/C not running	ZSS stuck.Made free and tested okay	10:30:00	10:50:00	
10	CHP	CC-201	Reported tripped	OLR acted.Reset done	10:50:00	11:00:00	
11	CHP	CC-203	Reported tripped	OLR acted.Reset done	11:00:00	11:10:00	
12	WT	OT-3	Reported tripped	D-2 tripped.Reset done	07:15:00	07:30:00	