



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 24/09/2026

Shift: A

Incharge(s): K SANKARA RAO

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO 34a	ZSS acting due to belt slipping	Informed to oprn	06:30:00	06:45:00	
2	OHP	TBS-2 ON CO-20	R/LUFF NOT TAKING PLACE FOUND OLR ACTED AND BRAKE PANEL 110v terminals burnt in TB	OLR reset AND terminations rejoined, brake regulation is also done.	07:05:00	07:30:00	
3	OHP	CO-26	OLR ACTED (2TIMES)	RESET DONE	07:20:00 09:05:00	07:30:00 09:15:00	
4	OHP	tbs3 on co-5a	LT not stopping	Brakes were loose and found not magnetising, fuse blown in brake panel, bypassed fuse and tested, brake regulation is done	07:30:00	07:45:00	
5	OHP	brc-1 on co-30	a) ct mccb tripped b) tripped again found, VFD outgoing cable near Terminals, insulation got daamged and was shorting,	a) reset done b) proper insulation provided.	07:55:00	08:05:00	
6	OHP	tbs-4 on co-22	LT not taking place	M1,m2 olr acted due to track jamming, reset done	13:05:00	13:15:00	
7	OHP	brc-5 on co-32	skew acted,	track jam observed, It speed changed and skew adjustment is done along with mechanical.	12:30:00	12:45:00	
8	CHP	SCR 3 on CC37	B/C stopping frequently	ZSS cage struck/Bypassed	09:05:00	09:25:00	
9	CHP	SCR 1 on CC 31	LT not working	M5 tripped	10:15:00	10:30:00	Observed track jamming
10	CHP	CC 37	Reported BS and BRS acted	Found cable got cut/jointed the cable	11:10:00	11:45:00	