वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 15/10/2026

Shift: A

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CC 104 SCR9	communication and smps problem,	smps and modem replaced	06:30:00	07:15:00	
2	OHP	BRC on co 8A	hydraulic cooling fan tripped,checked and found B phase touch motor TB	insulation provided	08:40:00	09:00:00	
3	OHP	co 25	olr acted	reset	09:15:00	09:25:00	4 times
4	OHP	TBs on co 20	LT not working,checked and found CRMP side loose connection and voltage dropping after connected	only one coil CHP side brake is in ckt	10:20:00	10:40:00	
5	OHP	TBS on CO 20	LT not working,brake not opening	informed mechanical ,mechanical adjusted the brake	07:50:00	08:05:00	
6	CHP	CC 106 scr 8	/c not working,c/s acteddue to jamming	informed to operation	09:45:00	09:55:00	