



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 29/09/2026

Shift: C

Incharge(s): Saurabh Kumar Yadav

| Sl No | Area | Equipment     | Problem                                       | Action                                                                 | From     | To       | Remarks                                            |
|-------|------|---------------|-----------------------------------------------|------------------------------------------------------------------------|----------|----------|----------------------------------------------------|
| 1     | OHP  | WOBR on CO 25 | luff up not working, limit switch stucked     | control check and found D# not picked up, limit switch lever made free | 23:15:00 | 23:30:00 |                                                    |
| 2     | OHP  | CO 25         | OLR acted                                     | reset                                                                  | 05:20:00 | 05:28:00 |                                                    |
| 3     | OHP  | VF 10A        | tripped in ol, reset,                         | megger done found 100 m ohm value for all phase to Earth               | 05:00:00 | 06:00:00 | after megger again tripping immediately ...pending |
| 4     | OHP  | CO 51         | OLR acted                                     | reset                                                                  | 03:50:00 | 04:00:00 | 2 times                                            |
| 5     | OHP  | RSCO 6A(C)    | olr acted                                     | reset                                                                  | 03:15:00 | 03:25:00 |                                                    |
| 6     | CHP  | CC 131        | motor tripped inn ol                          | reset                                                                  | 02:20:00 | 02:30:00 | 3 times                                            |
| 7     | CHP  | CC 58         | zss acted, zss malfunctioning                 | bypassed                                                               | 02:20:00 | 02:30:00 | module replacement going on now                    |
| 8     | CHP  | CC 115        | stopped in ZSS, olr on belt                   | reset                                                                  | 02:10:00 | 02:30:00 |                                                    |
| 9     | CHP  | CC 31 scr1    | b/c stopped in ZSS, fuse blown                | fuse replaced                                                          | 23:40:00 | 23:55:00 |                                                    |
| 10    | CHP  | CC 39 R1      | BC not working, c/s acted due to coal jamming | informed to operation                                                  | 00:40:00 | 00:50:00 |                                                    |
| 11    | CHP  | CC 32 scr 5   | b/c not running 30 degree limit acted         | released                                                               | 05:00:00 | 05:07:00 |                                                    |