

Recommended Action Get the output of show xdr multicast immediately after this error. Copy the message exactly as it appears, and report it to your technical support representative.

`%XDR-3-XDRMCASTGRPINVALID : Invalid XDR multicast group for slot(s) [chars]: [chars]`

Explanation Internal error. May result in unpredictable behaviour.

Recommended Action Copy the message exactly as it appears, and report it to your technical support representative.

`%XDR-3-XDRMCASTJOIN : Attempt to join [chars] to [chars] failed because client [chars] returned an error`

Explanation Internal error. May result in unpredictable behaviour.

Recommended Action Get the output of show xdr multicast, show xdr client all and show monitor event-trace xdr all. Copy the message exactly as it appears, and report it to your technical support representative.

`%XDR-3-XDRMCASTJOINREQ : Client [chars] returned an invalid response to a join request for groups [chars] and [chars]`

Explanation Internal error. May result in unpredictable behaviour.

Recommended Action Get the output of show xdr multicast, show xdr client all and show monitor event-trace xdr all. Copy the message exactly as it appears, and report it to your technical support representative.

`%XDR-3-XDRMCAST_PEER_BINDING : XDR peer [chars] bind to group [chars] (was bound to [chars]): [chars]`

Explanation Internal error. May result in unpredictable behaviour.

Recommended Action Get the output of show xdr multicast, and show monitor event-trace xdr all. Copy the message exactly as it appears, and report it to your technical support representative.

`%XDR-3-XDRNOMEM : XDR failed to allocate memory during [chars] creation.`

Explanation Allocation of memory by the XDR subsystem failed. This may result in an unpredictable behavior of XDR

Recommended Action Make sure that there is enough memory for the operations being performed by your machine. Copy the message exactly as it appears, and report it to your technical support representative.

`%XDR-3-XDR00S : Received an out of sequence IPC message. Expected [dec] but got [dec] from slot [chars].`

Explanation An out of sequence IPC message was received

Recommended Action We weren't meant to get the IPC message we did. From this point onwards IPC can't be relied on. Copy the message exactly as it appears, and report it to your technical support representative.

`%XDR-4-FAILATTEMPTOPENIPCPORT : Attempt to open the IPC ports failed. [chars]`

Explanation XDR failed an attempt to open the IPC port to communicate to the specified peer

Recommended Action No action is required.

```
%XDR-6-CLIENTISSUBADRCVTFM : Failed to rcv_transform message -from slot [chars], XDR client [chars], context [dec]
```

Explanation Cannot perform ISSU receive transform. This is likely due to a failure in negotiation earlier, or when one side of an ISSU-enabled XDR connection is out of sync with the other.

Recommended Action Get the output of show xdr multicast, show xdr client all and show issu message types [XDR client ISSU ID]. Copy the message exactly as it appears, and report it to your technical support representative.

```
%XDR-6-CLIENTISSUBADTXTFM : Failed to xmit_transform message -to slot [chars], XDR client [chars], context [dec]
```

Explanation Cannot perform ISSU transmit transform. This is likely due to a failure in negotiation earlier, or when one side of an ISSU-enabled XDR connection is out of sync with the other.

Recommended Action Get the output of show xdr multicast, show xdr client all and show issu message types [XDR client ISSU ID]. Copy the message exactly as it appears, and report it to your technical support representative.

```
%XDR-6-CLIENTISSUUNREG : Failed to unregister session -XDR client [chars], slot [chars], reason [chars]
```

Explanation Unable to unregister this session. This will likely cause problems when reregistering and should be reported.

Recommended Action Get the output of show xdr multicast, show xdr client all and show issu message types [XDR client ISSU ID]. Copy the message exactly as it appears, and report it to your technical support representative.

```
%XDR-6-CLIENTNOTREGONRP : Client [chars] has registered on slot [chars] before RP.
```

Explanation XDR client has registered on non-RP card before RP card. If this has occurred while toggling the client's registration status rapidly then it may be a transient problem and will resolve itself. If not, then the client's status may be unpredictable, and ISSU negotiation (if platform is ISSU-aware) may not take place correctly.

Recommended Action Verify whether the client's registration status is the same on both the RP and the card on which the problem is reported by comparing the output of 'show xdr client all' to see if the client is present or absent in BOTH. If so, and no other error messages have been seen, then this is a transient issue and no further action is required. Otherwise, copy the message exactly as it appears, and report it to your technical support representative.

```
%XDR-6-ISSUBADRCVTFM : Failed to rcv_transform message -slot [chars], reason: [chars]
```

Explanation Unable to perform ISSU transform on incoming XDR header. Message will be ignored

Recommended Action Get the output of show xdr multicast, show xdr client all and show issu message types [XDR client ISSU ID]. Copy the message exactly as it appears, and report it to your technical support representative.

```
%XDR-6-ISSUBADTXTFM : Failed to xmit_transform message -slot [chars], reason [chars]
```

Explanation Unable to perform ISSU transform on outgoing XDR header. Message will be ignored

Recommended Action Get the output of show xdr multicast, show xdr client all and show issu message types [XDR client ISSU ID]. Copy the message exactly as it appears, and report it to your technical support representative.

```
%XDR-6-ISSUCLIENTABSENT : XDR client [chars] absent on slot [chars]. Client functionality may be affected.
```

Explanation The remote slot doesn't support this ISSU client. The software will handle this by reducing client functionality locally to continue in SSO mode, or by forcing the remote peer into RPR mode as appropriate. This is expected behaviour in ISSU-capable systems.

Recommended Action No action required. This message just indicates that certain functionality may be reduced due to running different images together.

```
%XDR-6-XDRDISABLEREQUEST : Peer in slot [chars] requested to be disabled due to: [chars]. Disabling linecard
```

Explanation Due to some error condition the linecard has requested to be disabled

Recommended Action Execute clear xdr linecard from the RP followed by clear xdr channel on the linecard in question to clear the error condition. If the problem persists get the output of show monitor event-trace xdr all from the RP and the linecard in question and report it to your technical support representative.

```
%XDR-6-XDRINVALIDHDR : XDR for client ([chars]) dropped (slots:[chars] from slot:[chars] context:[int] length:[int]) due to: [chars]
```

Explanation The XDR message was dropped for the reason given.

Recommended Action If the failure was due to an invalid context for the CEF push client and occurred during an ISSU upgrade then it may be safely ignored. Otherwise: LOG_STD_ACTION

```
%XDR-6-XDRINVALIDHDRISSU : XDR ISSU negotiation message for client ([chars]) dropped (slots:[chars] from slot:[chars] context:[int] length:[int]) due to: [chars]
```

Explanation The XDR ISSU negotiation message was dropped for the reason given.

Recommended Action If the message occurred during an ISSU upgrade then it may be safely ignored. Otherwise: LOG_STD_ACTION

```
%XDR-6-XDRIPCPEER : XDR IPC error occurred for peer in slot [chars] due to [chars] [chars].
```

Explanation A general IPC related error occurred which may prevent transfer of data to other peers using the IPC mechanism

Recommended Action Get the output of show xdr multicast and show xdr linecard immediately after this error. Copy the message exactly as it appears, and report it to your technical support representative.

Z

`%XDR-6-XDRLCDISABLEREQUEST : Client [chars] requested to be disabled. [chars]`

Explanation Due to some error condition the linecard has requested to be disabled

Recommended Action Execute clear xdr linecard from the RP followed by clear xdr channel on the linecard in question to clear the error condition. If the problem persists get the output of show monitor event-trace xdr all from the RP and the linecard in question and report it to your technical support representative.

`%XDR-6-XDRMCASTINIT : XDR mcast subsystem initilisation error: [chars]`

Explanation XDR non functional.

Recommended Action A failure occurred which prohibits the XDR client from registering with the core. Copy the message exactly as it appears, and report it to your technical support representative.

`%XDR-6-XDRREGISTRATION : XDR failed to register [chars] client due to [chars]`

Explanation Failure to register the said XDR client.

Recommended Action A failure occurred which prohibits the XDR client from registering with the core. Copy the message exactly as it appears, and report it to your technical support representative.

Z

ZONE

`%ZONE-4-API : Zone [chars] [chars][chars] [chars] failed to notify the data plane`

Explanation The notification of a zone operation has failed to update the data plane and as such the application of the zone information within the object will not be applied to the data plane. It is also possible that the common classification may fail to locate and bind to the zone rendering the configuration inconsistent in terms of application.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Issue the show memory command to gather data that may help identify the nature of the error. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start> , or contact your Cisco technical support representative and provide the representative with the gathered information.

`%ZONE-4-LICENSE : License smart enable and zone-license enable should be enabled first`

Explanation The notification indicates that zone smart license should be enabled

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Issue the show running command to gather data that may help identify the nature of the error. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start> , or contact your Cisco technical support representative and provide

the representative with the gathered information.

```
%ZONE-6-CONFIG : Zone security [chars] is removed due to VRF config change on inter-  
face [chars]
```

Explanation The notification of a zone is removed from an interface due to a vrf is removed from the interface

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Issue the show running command to gather data that may help identify the nature of the error. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start> , or contact your Cisco technical support representative and provide the representative with the gathered information.

Obtaining Documentation and Submitting a Service Request

For information on obtaining documentation, using the Cisco Bug Search Tool (BST), submitting a service request, and gathering additional information, see **What's New** in Cisco Product Documentation.

To receive new and revised Cisco technical content directly to your desktop, you can subscribe to the **What's New** in Cisco Product Documentation RSS feed. The RSS feeds are a free service.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Copyright ©2018, Cisco Systems, Inc.

All rights reserved. Printed in USA.