



System Error Messages Guide for Access and Edge Routers

Revised: November 28, 2018

Overview of System Messages

Use this document together with the tools and utilities that are available on Cisco.com on this page:

<http://www.cisco.com/c/en/us/support/index.html>

- Cisco Technical Assistance Center (TAC): <https://mycase.cloudapps.cisco.com/case>
- Bug Search Tool link: <https://bst.cloudapps.cisco.com/bugsearch/>

Note: When contacting TAC, please have available the nonzipped, plain-text (.txt) output of the show logging and show tech-support commands, as well as any pertinent troubleshooting logs.

System messages can be grouped into these categories:

- System Event Messages—Describe the system and error messages that are generated for events related to the Cisco platform, and its hardware and software components.
- DOCSIS Event Messages—Describe the error messages for events as required by the DOCSIS specifications.
- Video/QAM Event Messages—Describe the error messages for events as required by the Video specifications.

System error messages begin with a percent sign (%) and are structured as follows:

%FACILITY-SUBFACILITY-SEVERITY-MNEMONIC: Message-text

System error messages contain the following components:

- FACILITY is a code indicating the platform or other component that is generating the message.
- SEVERITY is a number that reflects the significance of the error message. All error messages have a Cisco severity number that ranges from 0 to 7. DOCSIS-related events also contain a DOCSIS severity level that ranges from 129 to 136. The lower the number, the more serious the situation. This table describes the possible severity levels and their meanings.

Cisco Level	DOCSIS	Class	Description
0	129	Emergency	The system has become unusable and requires immediate attention. This problem might also be affecting other parts of the network.
1	130	Alert	Some type of system or connection failure has occurred and requires immediate attention.
2	131	Critical	An error occurred that requires immediate attention to avoid system or connection failure.
3	132	Error	An error condition occurred that requires attention to resolve. Failure to address this problem will result in some type of system or connection failure in the near

Cisco Level	DOCSIS	Class	Description
			future.
4	133	Warning	A condition occurred that indicates attention is needed in near future to avoid potential problems. Failure to address this problem could result in some type of system or connection failure later on.
5	134	Notice	A situation occurred that is normal but is significant enough that system administrators might want to notice.
6	135	Informational	An information message that might or might not be significant to the system administrators.
7	136	Debug	Messages that appear only while debugging is turned on.

- MNEMONIC is a string that uniquely identifies the error message. Error messages are usually organized and referred to by their mnemonic value.
- The Message-text is a string that provides details about the particular error. This string can include specifics about cable interface, IP or MAC addresses, and other information. In this document, the specific information is presented by variable fields that are indicated by square brackets ([]). A decimal number, for example, is represented as [dec].

System Messages Description

A

AAA

%AAA-2-AAAMULTILINKERROR : [chars]([hex]): Acct db for Id [hex] absent

Explanation AAA internal error

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

%AAA-2-FORKFAIL : Cannot fork process [chars]

Explanation Attempted to fork a process and failed. The reason could be either hardware or software.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%AAA-3-ACCT_IOMEM_LOW : AAA ACCT process suspended : low I/O memory
```

Explanation AAA ACCT process has been suspended due to insufficient IO memory.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%AAA-3-ACCT_LOW_IO_MEM_TRASH : AAA unable to handle accounting requests due to in-  
sufficient I/O memory and could be trashing the queued accounting records
```

Explanation Dropping the accounting request as there is no enough I/O memory. Hence all queued accounting requests shall be trashed

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%AAA-3-ACCT_LOW_MEM_UID_FAIL : AAA unable to create UID for incoming calls due to  
insufficient processor memory
```

Explanation Stop creating the AAA UID, due to LOW processor memory

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%AAA-3-ACCT_LOW_PROC_MEM_TRASH : AAA unable to handle accounting requests due to in-  
sufficient processor memory and could be trashing the queued accounting records
```

Explanation Dropping the accounting request as there is no enough processor memory. Hence all queued accounting requests shall be trashed

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%AAA-3-ACCT_UNKNOWN_REASON_TRASH : AAA unable to handle accounting requests, reason  
unknown and could be trashing the queued accounting records
```

Explanation Dropping the accounting request, reason unknown. Hence all queued accounting requests shall be trashed

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

%AAA-3-ATTRFORMATERR : Attribute with unknown format [dec]

Explanation An attribute was found with an invalid format.

Recommended Action Attribute with unknown format in definition. Enable AAA debug and try to replicate the steps to get the message. If the message appears again, Check bug toolkit on Cisco website for the issue. If you didn't find one, Enter <CmdBold>Show tech-support<NoCmdBold> command, Collect all the information and error message and report it to your technical support representative.

%AAA-3-AUTH_LOW_IOMEM : RADIUS process is unable to handle the requests due to insufficient I/O memory

Explanation RADIUS process unable to handle request due to insufficient IO memory. Hence returning failure.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

%AAA-3-AUTHORMLISTUNDEF : Authorization method list '[chars]' is not defined. Please define it.

Explanation A given method list was listed in a command without defining it first. The method list should be defined before use.

Recommended Action Define the method list before using it.

%AAA-3-BADCURSOR : invalid cursor index [dec] max [dec] service [chars] protocol [chars]

Explanation A AAA client has provided an invalid attribute cursor to AAA.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

%AAA-3-BADLIST : invalid list AAA ID [int]

Explanation A AAA client has provided an invalid attribute list to AAA.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

%AAA-3-BADMAGIC : Data structure failed magic number sanity check

Explanation A corrupted data structure has been found which was stored internally.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

%AAA-3-BADMETHOD : Cannot process [chars] method [int]

Explanation A method list function encountered a method list that was unknown, or could not be handled.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

%AAA-3-BADMETHODERROR : Cannot process [chars] method [chars]

Explanation A method list function encountered a method type that was unknown, or could not be handled.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

%AAA-3-BADSERVERTYPEERROR : Cannot process [chars] server type [chars]

Explanation A method list function encountered a server type that was unknown, or could not be handled. This may be due to a server misconfiguration.

Recommended Action Research the cause of the misconfiguration and attempt to correct it, otherwise take the following action. LOG_STD_ACTION

%AAA-3-BUFFER_OVERFLOW : Radius I/O buffer has overflowed

Explanation An unusually large number of RADIUS attributes has caused AAA to overflow its RADIUS I/O buffer.

Recommended Action This is an internal software error. Check bug toolkit on Cisco website for the issue. If you didn't find one, Enter <CmdBold>Show tech-support<NoCmdBold> command, Collect all the information and error message

and report it to your technical support representative.

`%AAA-3-DROPACCTFAIL : Accounting record dropped, send to server failed: [chars]`

Explanation An attempt to send an accounting record to a server failed. This happens when device exhaust all its retries and retransmission. The cause for this be the servers may not be operational or the NAS is not configured properly.

Recommended Action Check the server , whether they are operational or not. Next check whether the device is configured properly. Refer to the server configuration section of the cisco IOS documentation. Finally, check that the NAS can communicate with the server. If the problem persist, Enter `<CmdBold>show running- config<NoCmdBold>` command, contact your cisco technical support representative and provide all the information gathered to the representative.

`%AAA-3-HA_INIT_FAILURE : High availability initialization failure: [chars]`

Explanation The AAA subsystem was unable to perform necessary high-availability related initialization. In the event of switchover to a standby device, sessions depending on high availability capabilities in the AAA subsystem will be forced to renegotiate.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

`%AAA-3-HA_INTERNAL_ERROR : High availability internal error for unique id [hex]: [chars]`

Explanation The AAA subsystem was suffered an internal error. In the event of switchover to a standby device, sessions depending on high availability capabilities in the AAA subsystem may be forced to renegotiate.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

`%AAA-3-INVALIDATTRLIST : aaa attribute list CLI is not valid when configuring in sub-mode.`

Explanation An internal error has occurred

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

`%AAA-3-INVALIDPARM : invalid parameter was used when accessing AAA function`

A

Explanation A AAA client tried to use a AAA function with an invalid parameter.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%AAA-3-IPILLEGALMSG : Invalid use of ip_pid([int])
```

Explanation This error means a process sent an illegal message.

Recommended Action If this message recurs. Check bug toolkit on Cisco website for the issue. If you didn't find one, Enter <CmdBold>Show tech-support<NoCmdBold> command, Collect all the information and error message and report it to your technical support representative.

```
%AAA-3-ISDNINTF : [chars] [chars]: Can not apply configuration to ISDN channel:  
[chars]
```

Explanation Configuration can not be applied to individual ISDN channels.

Recommended Action You need virtual-profiles and virtual-access interfaces to apply configuration to ISDN. Refer to the section on Configuring virtual profile by AAA Configuration in the Cisco IOS Dial Technologies Configuration Guide.

```
%AAA-3-LOW_MEM : [chars] process is unable to handle the incoming packet due to low  
memory
```

Explanation Please check the processor memory or IO memory. Most likely one of them has less available memory or worst case, both may have insufficient memory.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%AAA-3-MLIST_INTERNAL_ERROR : method list '[chars]': [chars]
```

Explanation This is an internal software error.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%AAA-3-MLIST_TOO_MANY_METHODS : method list '[chars]'
```

Explanation This is an internal software error. An AAA client attempted to add too many methods to a method list.

Recommended Action This is an internal software error. Check bug tool-kit on Cisco web-site for the issue. If you didn't find one, Collect the error message and report it to your technical support representative.

`%AAA-3-NOTABLE : AAA ID [int]`

Explanation Resource failure.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

`%AAA-3-NULLCURSOR : Null cursor`

Explanation A AAA client has provided a nonexistent attribute cursor to AAA.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

`%AAA-3-NULLVRF : Null vrf entry`

Explanation A NULL VRF entry found while comparing the AAA VRF attributes.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

`%AAA-3-PARSEERR : Error([dec]) parser is unable to parse [chars] per-user command`

Explanation All attempts to parse this per_user unconfigure command failed. The unconfigure command is called when an error occurs while configuring per-user commands, to revert back. The unconfiguration may fail due to parser or AAA error.

Recommended Action The given unconfigure command was not executed. Switch on the debug peruser command and repeat the steps that caused the error. If you get the error, Report it to your technical support representative.

`%AAA-3-PASSWDRESTRICTERR : AAA password restriction failed.-[chars]`

Explanation The password/secret/key entered is not meeting the password restrictions configured

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and

provide the representative with the gathered information.

```
%AAA-3-SERVER_INTERNAL_ERROR : Server '[chars]': [chars]
```

Explanation This is an internal software error in the AAA server group subsystem.

Recommended Action This is an internal software error. Check bug toolkit on Cisco website for the issue. If you didn't find one, Enter **<CmdBold>Show tech-support<NoCmdBold>** command, Collect all the information and error message and report it to your technical support representative.

```
%AAA-3-SG_DEADTIME_FORKFAIL : Failed to fork process for [chars].
```

Explanation Quite likely, we ran out of memory. Other explanations are possible.

Recommended Action If this message recurs. Check bug toolkit on Cisco website for the issue. If you didn't find one, Enter **<CmdBold>Show tech-support<NoCmdBold>** command, collect all the information and error message and report it to your technical support representative.

```
%AAA-3-SG_INTERNAL_ERROR : server group '[chars]': [chars]
```

Explanation This is an internal software error in the AAA server group subsystem.

Recommended Action This is an internal software error. Check bug toolkit on Cisco website for the issue. If you didn't find one, Enter **<CmdBold>Show tech-support<NoCmdBold>** command, collect all the information and error message, report it to your technical support representative.

```
%AAA-3-SG_TESTPROC_FORKFAIL : Failed to fork process for [chars].
```

Explanation Quite likely, we ran out of memory. Other explanations are possible.

Recommended Action If this message recurs. Check bug toolkit on Cisco website for the issue. If you didn't find one, Enter **<CmdBold>Show tech-support<NoCmdBold>** command, Collect all the information and error message and report it to your technical support representative.

```
%AAA-3-SORTFAIL : [chars] :Peruser Could not sort the [chars] attributes
```

Explanation Sorting of the attributes received from AAA server failed.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%AAA-5-LOCAL_USER_BLOCKED : User [chars] blocked for login till [chars]
```

Explanation User blocked since the number of authentication failures in the watch time exceeded the configured threshold.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%AAA-5-USER_LOCKED : User [chars] locked out on authentication failure
```

Explanation User locked out since the number of authentication failures exceeded the configured threshold.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%AAA-5-USER_RESET : User [chars] failed attempts reset by [chars]
```

Explanation User's number of failed authentication attempts so far has been reset to zero

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%AAA-5-USER_UNLOCKED : User [chars] unlocked by [chars]
```

Explanation User unlocked by the system administrator. User is enabled to login to the system.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%AAA-6-ACCTSESSIDWRAP : Accounting-Session-ID [dec] exceeded max value allowed
```

Explanation Accounting-Session-ID value exceeded max value allowed. Now it is wrapping.

Recommended Action This is informational only, not an error.

```
%AAA-6-BADHDL : invalid hdl AAA ID [int], hdl [hex], [chars]
```

Explanation A AAA client has provided an invalid attribute list handle to AAA.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and

A

provide the representative with the gathered information.

```
%AAA-6-INVALIDROUTE : Syntax error in route statement: [chars]
```

Explanation Currently downloading route contains syntax error.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%AAA-6-SKIP_MOH_ATTRIBUTE : Warning: Hardware idb is NULL. No Modem. MoH attribute  
can not be applied and it is Skipped for authorization.
```

Explanation To handle Modem-on-Hold attribute, we need connectivity with modems supporting V.92 modem standards. If there is no modem, there wouldn't be any tty, without which we cannot use MOH attributes.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%AAA-6-USER_BLOCKED : Enable view requires to be authenticated by non-none methods,  
Please use the appropriate method with the login authentication
```

Explanation None method authentication is not allowed in CLI

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%AAA-6-USER_FAIL_VIEW_AAA : User [chars] failed to enter view '[chars]'.
```

Explanation You have provided wrong User ID or Password for the requested view

Recommended Action This message is for information only. No action is required.

AAAA

```
%AAAA-3-AAAFORKFAIL : Failed to start AAA process. AAA requests may not be pro-  
cessed.
```

Explanation Failed to create the AAA process.

Recommended Action Free up some memory.

%AAAA-3-ACCTATTR : last accounting attribute:

Explanation The data buffer overflowed while building the accounting packet. The accounting attribute that was being written to the buffer while the buffer overflow occurred was logged.

Recommended Action LOG_STD_ACTION Collect the logs with these debugs by using commands #debug aaa api, #debug aaa attr, #debug aaa accounting

%AAAA-3-ACCTDUMP : dump of accounting data:

Explanation The data buffer overflowed while building the accounting packet as the total length of the attributes exceeded the buffer size. Last 128 bytes of buffer data is dumped.

Recommended Action LOG_STD_ACTION Collect the logs with these debugs by using commands #debug aaa api, #debug aaa attr, #debug aaa accounting

%AAAA-3-ACCTFORKFAIL : Failed to start accounting process. Accounting records may not be sent.

Explanation Failed to create the accounting process.

Recommended Action Free up some memory.

%AAAA-3-BADARG : %%AAA: bad argument (%0#4x)

Explanation We tried to NVGEN a non-existent AAA command.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

%AAAA-3-BADAUTHENSTR : Bad authentication data: [chars]

Explanation The data buffer overflowed while building the authentication packet as the total length of the attributes exceeded the buffer size.

Recommended Action LOG_STD_ACTION Collect the logs with these debugs by using the commands #debug aaa api, #debug aaa attr, #debug aaa authentication

%AAAA-3-BADCOMM : Trying config command but should not be.

Explanation An internal error has occurred

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and

provide the representative with the gathered information.

```
%AAAA-3-BADLIST : %%AAA: bad [chars] list [chars]
```

Explanation One of the AAA methods does not seem to have a list associated with it.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%AAAA-3-BADREG : Illegal registry call.
```

Explanation An internal software error has occurred

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%AAAA-3-BADSTATE : %%AAA: Bad state for [chars] list name ([dec])
```

Explanation A AAA method list is neither default nor named. This is bad.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%AAAA-3-BADSTR : Bad accounting data: [chars]
```

Explanation During AAA accounting operations, the internal database of accounting information for a user was found to be corrupt. In all cases, this indicates an internal software error, and that accounting information for a particular user session has been lost.

Recommended Action Copy the error message exactly as it appears, and report it to your technical support representative.

```
%AAAA-3-DLRFORKFAIL : Failed to fork process for [chars].
```

Explanation Quite likely, we ran out of memory. Other explanations are possible.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

%AAAA-3-DROPACCTFULLQ : Accounting record dropped due to a full aaa accounting queue: [chars]-[chars] [chars] [chars]

Explanation An accounting record was dropped because there are too many accounting packets enqueued.

Recommended Action Disable periodic accounting if it is on. The accounting queue may have grown to be large, which is usually due to a non-responsive AAA server. Use 'show radius statistics' or 'show tacacs' to see if the number of timeouts is increasing or if the response delay is unusually high.

%AAAA-3-DROPACCTLOWMEM : Accounting record dropped due to low memory: [chars]-[chars] [chars] [chars]

Explanation An accounting record dropped due to low memory.

Recommended Action Disable periodic accounting if it is on. Try to reduce the load on the router.

%AAAA-3-DROPACCTQUEUEEXCEEDED : accounting record dropped, output record queue full: [chars]-[chars] [chars] [chars]

Explanation An accounting record was dropped. The record could not be enqueued because the number of records in the output queue has exceeded the system limit.

Recommended Action Disable periodic accounting if it is on. **<CmdBold>**[no] aaa accounting update newinfo periodic **<interval>****<NoCmdBold>**

%AAAA-3-DROPACCTSNDFAIL : Accounting record dropped, send to server failed: [chars]-[chars] [chars] [chars]

Explanation An attempt to send an accounting record to a server failed.

Recommended Action Check that the server (TACACS+ or RADIUS) is operational. Next, check the NAS is configured properly. Finally, check that the NAS can communicate with the server

%AAAA-3-ILLEGALNAME : Illegal [chars] [chars] name [chars] rejected

Explanation A method-list name should not be the same as a method name. Please choose a different name for the method list.

Recommended Action Pick a different method-list name, that is not also a method-name.

%AAAA-3-ILLSGNAME : Illegal server-group name [chars] (type [chars]).

Explanation The given server-group name is a name that could conflict with internally chosen lists.

Recommended Action Please pick a different server-group name.

%AAAA-3-INTERNAL_ERROR : [chars]

Explanation This is an internal software error.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%AAAA-3-INVALIDATTRLIST : aaa attribute list CLI is not valid when configuring in
sub-mode.
```

Explanation An internal error has occurred

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%AAAA-3-INVALIDLIST : %%AAA: invalid [chars] list [dec].
```

Explanation One of the AAA methods lists has inconsistent settings

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%AAAA-3-INVSTATE : [chars] AUTHOR/[chars]: Internal state is invalid: astruct
0x[int]struct [hex]
```

Explanation One of the two mentioned data-structures is not set, but is needed here. This is an internal software error.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%AAAA-3-LISTCREATE : The list [dec] for [chars] is NULL. This should never be.
```

Explanation One of the method-lists, created at startup, wasn't created. This may cause a reload

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%AAAA-3-MKTIMERFAIL : Failed to create periodic accounting timer for user [chars].
This user may not generate periodic accounting records.
```

Explanation Failed to malloc a timer struct for periodic accounting.

Recommended Action Free up some memory and have user re-authenticate.

```
%AAAA-3-MKTIMERINVALID : Invalid request to create periodic accounting timer for user [chars]. Timer already exists.
```

Explanation Invalid client usage of timer struct for periodic accounting.

Recommended Action Copy the error message exactly as it appears, and report it to your technical support representative.

```
%AAAA-3-NOADMINPROC : [chars]
```

Explanation Administrative process has been enabled but somehow could not run

Recommended Action None

```
%AAAA-3-NOFREELISTS : %%AAA: No free [chars] lists for [chars]
```

Explanation You have reached the maximum number of possible authentication lists for this method.

Recommended Action If this message recurs, copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%AAAA-3-NOLIST : [chars]: no method list-name.
```

Explanation An internal software error.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%AAAA-3-NOREG : [chars] method [dec] has no registry!
```

Explanation An internal error has occurred

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%AAAA-3-NOSERV : No name for servergroup in method [chars]
```

Explanation An internal error has occurred

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%AAAA-3-NOSG : No server-group passed through parser.
```

Explanation An internal error has occurred

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%AAAA-3-NULPORT : Could not establish port information
```

Explanation This message indicates an internal software error. AAA could not determine a valid port string based on the information provided to it via a client.

Recommended Action Copy the error message exactly as it appears, and report it to your technical support representative.

```
%AAAA-3-NULUSR : accounting for null user
```

Explanation This message indicates an internal software error. During shutdown of a line or interface, the system tried to send accounting information via AAA, but could not find the user to which the accounting information belonged. The most likely reason for this error is trying to do accounting twice for the same event. This error message can occur without any loss of accounting information.

Recommended Action Copy the error message exactly as it appears, and report it to your technical support representative.

```
%AAAA-3-OVERWRITE : Overwrote internal buffer space [chars]
```

Explanation An internal software error.

Recommended Action Report to tac@cisco.com.

```
%AAAA-3-PERIODICFORKFAIL : Failed to start periodic accounting process. Periodic accounting records may not be sent.
```

Explanation Failed to create the periodic accounting process.

Recommended Action Free up some memory.

```
%AAAA-3-PERNOTIMER : AAA/ACCT/TIMER: Periodic update but no timer.
```

Explanation We are trying to free a timer, and the method is PERIODIC, but no timer seems to exist.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%AAAA-3-RELOGIN : sanity check in re-login [chars] to [chars]
```

Explanation A software or hardware error occurred.

Recommended Action Copy the error message exactly as it appears, and report it to your technical support representative.

```
%AAAA-3-SGDUPFREE : Duplicate free of server group [hex]
```

Explanation This is an internal software error.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%AAAA-3-STRCREATE : str_create overwrote its internal buffer.
```

Explanation An internal buffer, used to assemble a string, was exceeded, thus possibly corrupting other memory.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%AAAA-3-SUBTYPE : Bad Subtype [dec] for [chars] ([dec])
```

Explanation An internal software error.

Recommended Action Report to tac@cisco.com.

```
%AAAA-3-TIMERNOOPER : AAA/ACCT/TIMER: No periodic update but timer set.
```

Explanation We are trying to free a timer, but the update method is not PERIODIC, and so no timer should exist.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and

A

provide the representative with the gathered information.

```
%AAAA-4-BADMETHNAME : Bad [chars] method-list name [chars] (this is only a warning)
```

Explanation A method-list name should not be the same as a method name. Please choose a different name for the method list.

Recommended Action Pick a different method-list name, that is not also a method-name.

```
%AAAA-4-BADSGNAME : Bad server-group name [chars] (type [chars]).
```

Explanation The given server-group name either doesn't exist or the given type does not match the defined server-group.

Recommended Action Verify that the group exists and has the same type.

```
%AAAA-4-BADSGTYPE : Server-group [chars] is not of type [chars].
```

Explanation The given server-group name does not match the specified type

Recommended Action Verify that the group exists and has the same type.

```
%AAAA-4-CLI_DEPRECATED : [chars]
```

Explanation CLI deprecated. New CLI to be used

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%AAAA-4-DNISGPUNDEF : Warning: DNIS group [chars] is not defined.
```

Explanation The DNIS group was used without defining it first. It should be defined before use.

Recommended Action Define the DNIS group before using it.

```
%AAAA-4-NOCACHEPROC : The aaa cache process is not created. Please configure aaa  
cache profile first
```

Explanation Cache was listed in a method-list without defining it first. Cache profile should be defined before use.

Recommended Action Define the cache profile before using it.

```
%AAAA-4-NOSERVER : Warning: Server [chars] is not defined.
```

Explanation The given server is not on the master-list, and should be defined, or unexpected things might happen.

Recommended Action Please define the server on the appropriate master-list as soon as possible.

```
%AAAA-4-SERVNOGRP : Warning: Server [IP_address]:[dec],[dec] is not part of server group [chars].
```

Explanation The server does not belong to the specified server group

Recommended Action Please check that the specified server belongs to the server group

```
%AAAA-4-SERVNORADIUS : The server-group [chars] is not a radius server group. Please define [chars] as a radius server group.
```

Explanation The protocol used by the server-group doesn't support the configured aaa action.

Recommended Action Use a radius server-group.

```
%AAAA-4-SERVNOTACPLUS : The server-group [chars] is not a tacacs+ server group. Please define [chars] as a tacacs+ server group.
```

Explanation The protocol used by the server-group doesn't support the configured aaa action.

Recommended Action Use a tacacs+ server-group.

```
%AAAA-4-SERVUNDEF : The server-group [chars] is not defined. Please define it.
```

Explanation A given server-group was listed in a method-list without defining it first. Server-groups should be defined before use.

Recommended Action Define the server-group before using it.

```
%AAAA-4-UNSUPWAITSTART : %%AAA: Unsupported option wait-start mapped to start-stop.
```

Explanation wait-start accounting is not supported. It is being mapped to start-stop

Recommended Action wait-start accounting is not supported. It is being mapped to start-stop

```
%AAAA-6-ACCTLOCAL : Username: [chars] Privilege level: [dec] Command: [chars]
```

Explanation AAA local accounting log message

Recommended Action This information is to store buffered logs locally and send to SYSLOG server

```
%AAAA-6-ACCTSTART : [chars]
```

Explanation A AAA accounting start message.

Recommended Action This information is for information only.

A

%AAAA-6-ACCTSTOP : [chars]

Explanation A AAA accounting stop message.

Recommended Action This information is for information only.

%AAAA-6-ACCTWATCH : [chars]

Explanation A AAA accounting watchdog/update message.

Recommended Action This information is for information only.

%AAAA-6-ADMINMSG : [chars] [chars]: [chars]

Explanation This administrative message was passed to the NAS from the AAA server

Recommended Action No action need be taken, but the message may contain usefull information regarding some event on the server

%AAAA-6-SERVERMSG : [chars] [chars]: [chars]

Explanation This message was passed to the NAS from the AAA server

Recommended Action No action need be taken, but the message may contain usefull information regarding some event on the server

AC

%AC-3-ACMGR_INVALID_HDL : Received invalid [chars] handle

Explanation Attachment Circuit Manager receives invalid handle.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

%AC-3-ACMGR_INVALID_MSG : Received [chars]

Explanation Attachment Circuit Manager receives invalid message.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

%AC-3-ACMGR_MISSED_CIRCUIT : Circuit info missing in [chars] message.

Explanation AC Manager received message with missing circuit info

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%AC-3-ACMGR_XDM_CREATE : Failed to create XDM -rc [int]
```

Explanation Attachment Circuit Manager was unable to create a Dispatch Manager instance for event handling.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%AC-3-AC_SANITY : [chars]
```

Explanation A unexpected sanity check failed during Attachment Circuit processing.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%AC-3-AC_WS_REGISTER : L2VPN WS registration failed for [chars]
```

Explanation An error was encountered when attempting to register the specified Attachment Circuit type with the Layer 2 Virtual Private Network Wire Service facility.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%AC-3-L2SS_BAD_HANDLE : Corrupted L2SS handle [[hex]].
```

Explanation An internal L2SS Manager occurred.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%AC-3-L2SS_NULL_CONTEXT : Encountered a NULL context in [chars]
```

A

Explanation Encountered a NULL context in L2SS Manager.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%AC-3-L2SS_UNEXPECTED : Received unexpected [chars] message
```

Explanation L2SS received unexpected message.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%AC-3-L2SS_WRONG_KEYS : Wrong set of keys in [chars] message
```

Explanation SIP sends a wrong set of keys to L2SS Manager.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

ACCESS_IE

```
%ACCESS_IE-3-INVALID_HANDLE : Caller passed in invalid handle -traceback to follow.
```

Explanation An invalid handle was encountered in the Access IE library.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

ACCESS_SESSION

```
%ACCESS_SESSION-3-TRACE_INIT_FAIL : Initialization failed with code: [dec]
```

Explanation Failed to initialize access-session trace.

Recommended Action No action is required.

A

`%ACCESS_SESSION-3-TRACE_REG_FAIL : Component [chars] registration failed. Error code: [dec]`

Explanation Component failed to register with access-session trace

Recommended Action No action is required.

ACCESS_SESSION_TRACE

`%ACCESS_SESSION_TRACE-3-TRACE_INIT_FAIL :`

Explanation Failed to initialize access-session trace.

Recommended Action Review smd logs taking note of the timestamp information to select specific information to review. Copy the message and other related information exactly as it appears on the console or in the system log.

`%ACCESS_SESSION_TRACE-3-TRACE_REG_FAIL :`

Explanation Component failed to register with access-session trace

Recommended Action Review smd logs taking note of the timestamp information to select specific information to review. Copy the message and other related information exactly as it appears on the console or in the system log.

ACE

`%ACE-2-CRYPTOENGERR : Crypto engine error: [chars] ([dec])`

Explanation A crypto engine operation did not complete. This error condition can indicate that the crypto engine cannot bind or unbind an interface to a crypto engine. It can also indicate that the crypto engine cannot query an interface ID.

Recommended Action Remove the cryptomap set from the interface by issuing **<CmdBold>no crypto map** command. Then reattach the cryptomap set to the interface using **<CmdBold>crypto map** command. Although removing and reattaching the crypto map might fix the cryptographic engine operation failure, report the failure to your technical support representative along with the sequence of commands that lead to the failure.

`%ACE-2-INTTABOPERR : Internal [chars] table error: [chars]`

Explanation Internal table operation fails. This means the state of the module is mostly like inconsistent.

Recommended Action Contact your technical support representative

`%ACE-3-BOOTMSGERR : [chars]: boot error: [chars]`

Explanation The ACE completed booting, but with an error status code. ACE will not operate and it will not register with the crypto subsystem.

Recommended Action Copy the error message exactly as it appears, and report it to your technical support representative.

A

%ACE-3-CEAL_REGISTRATION : ACE [chars] failed to register.

Explanation The ACE failed to register with CEAL

Recommended Action Reset the hw module

%ACE-3-CRASHDUMPERR : [chars]: crashdump retrieval error: [chars] [chars]

Explanation An error occurred during crashdump file retrieval from ACE.

Recommended Action Copy the error message exactly as it appears, and report it to your technical support representative.

%ACE-3-CRASHDUMPSTART : [chars]: crashdump retrieval initiated to file [chars]

Explanation The ACE crashed and was rebooted. Upon reboot, a crashdump file was detected and uploaded to the sup-bootflash filesystem.

Recommended Action Report the crash and transfer the crashdump file to your technical support representative.

%ACE-3-HAPITRUNC : [chars]: Received truncated HAPI message (tlen=[dec], actual=[dec])

Explanation The received ACE control packet was smaller than the size field indicated

Recommended Action Copy the error message exactly as it appears, and report it to your technical support representative.

%ACE-3-INITFAIL : [chars]: initialization failed ([chars])

Explanation ACE initialization sequence failed.

Recommended Action Copy the error message exactly as it appears, and report it to your technical support representative.

%ACE-3-INVTTID : [chars]: [chars] of invalid [chars] trans id [dec]

Explanation An invalid transaction ID of for the indicated transaction type was encountered

Recommended Action Copy the error message exactly as it appears, and report it to your technical support representative.

%ACE-3-NOENGINESLOT : Interface [chars] has no crypto engine slot

Explanation An IKE SA was requested for a given interface, but no crypto engine slot was assigned to that interface

Recommended Action Configure the interface in question with the `crypto engine [sub]slot' command

%ACE-3-NOMORETID : [chars]: out of [chars] transactions

Explanation Transaction pool for the indicated transaction type was exhausted.

Recommended Action Copy the error message exactly as it appears, and report it to your technical support representative.

```
%ACE-3-OUTOFID_RL : Too many [chars] IDs in the system. Cannot allocate a new one
```

Explanation All the IDs of the specified type are in use

Recommended Action Reduce the traffic load, number of IPSec tunnels and/or frequency of re-key. If this message was seen under light loading conditions, then copy the error message exactly as it appears, and report it to your technical support representative.

```
%ACE-3-OUTOFRES : Too many [chars] in the system. Cannot allocate a new one
```

Explanation All VPN-accelerator resources of a particular are in used and thus this allocation request fails.

Recommended Action Remove the cryptomap set from the interface. Reduce the number of that resource in the system. For ACL, reduce the number of ACL permit ACE in the system. For cryptomap, reduce the number of cryptomaps in the system. For SPD and SPD map, reduce the number of interface with cryptomap set attached.

```
%ACE-3-TRANSERR : [chars]: [chars] trans [hex]; opcode [hex]; param [hex]; error [hex]; retry cnt [dec]
```

Explanation An error occurred in the indicated control transaction.

Recommended Action Copy the error message exactly as it appears, and report it to your technical support representative.

```
%ACE-3-TRANSERR_RL : [chars]: [chars] trans [hex]; opcode [hex]; param [hex]; error [hex]; retry cnt [dec]
```

Explanation An error occurred in the indicated control transaction.

Recommended Action Copy the error message exactly as it appears, and report it to your technical support representative.

```
%ACE-3-TRANSNAK : [chars]: [chars] NAK trans [hex]; opcode [hex]; param [hex]
```

Explanation An negative acknowledge occurred in the indicated control transaction.

Recommended Action Copy the error message exactly as it appears, and report it to your technical support representative.

```
%ACE-3-TRANSTO : [chars]: [chars] trans [hex]; opcode [hex]; param [hex]; too many retries
```

Explanation An error occurred in the indicated control transaction.

A

Recommended Action Copy the error message exactly as it appears, and report it to your technical support representative.

`%ACE-4-BV_IDMGR_DESTROY : ACE failed to destroy [chars] ID manager. Leaking memory.`

Explanation The ACE failed to destroy memory space for ID management.

Recommended Action Copy the error message exactly as it appears, and report it to your technical support representative.

`%ACE-6-BOOTMSGINFO : [chars]: boot info: [chars]`

Explanation The ACE completed booting, but with a non-zero informational status code. This does not indicate an error and ACE will run normally.

Recommended Action No action is necessary.

`%ACE-6-CRASHDUMPEND : [chars]: crashdump retrieval complete`

Explanation The ACE crashed and was rebooted. Upon reboot, a crashdump file was detected and uploaded to the sup-bootflash filesystem.

Recommended Action Report the crash and transfer the crashdump file to your technical support representative.

`%ACE-6-INFO : [chars]: [chars]`

Explanation This is informational message from ACE

Recommended Action This is informational message from ACE. This occurs in normal operation.

`%ACE-6-SWITCHOVER : VPN-SM switchover: [dec]/[dec] has been [chars] [dec]/[dec]`

Explanation A blade to blade switchover has occurred. System performance is not affected.

Recommended Action System performance is not affected. No customer action is necessary.

`%ACE-6-UNEXP_INBOUND_IPSEC : [chars]: received unexpected IPsec packet: src IP: [IP_address]; dst IP: [IP_address]; (count=[dec])`

Explanation An IPsec packet was unexpectedly forwarded to the RP

Recommended Action If this message was seen in the context of the router booting, enabling the hardware crypto accelerator, then this message is normal and can be safely ignored. Otherwise, please copy the error message exactly as it appears, and report it to your technical support representative.

`%ACE-6-UNEXP_OUTBOUND_IPSEC : [chars]: received unexpected IPsec packet: src IP: [IP_address]; dst IP: [IP_address]; firsthop/lasthop = [chars]/[chars] (count=[dec])`

Explanation An IPsec packet was unexpectedly forwarded to the RP

A

Recommended Action If this message was seen in the context of the router booting, enabling the hardware crypto accelerator, or with an invalid peer IP address then this message is normal and can be safely ignored. Otherwise, please copy the error message exactly as it appears, and report it to your technical support representative.

ACL

```
%ACL-3-UNEXPECTED_PKT_TYPE : type [dec], int [dec] [chars]put
```

Explanation ACL logging has encountered unexpected pkt type.

Recommended Action LOG_STD_ACTION

```
%ACL-3-UNEXPECTED_STATE : type [dec], int [chars] [chars]put, w0: [hex], w1: [hex]
```

Explanation An error has occurred in the setup of ACL hardware.

Recommended Action LOG_STD_ACTION

ADJ

```
%ADJ-3-ADJGENALLOCATEFAIL : Failed to allocate memory [chars]
```

Explanation An internal software error occurred. This is probably because not enough memory was available.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%ADJ-3-ADJGENDEALLOCATEFAIL : Failed to deallocate memory [chars]
```

Explanation An internal software error occurred.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%ADJ-3-ADJMGRALLOCATEFAIL : Failed to allocate an adjacency summary event block
```

Explanation An internal software error occurred. This is probably because not enough memory was available.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and

provide the representative with the gathered information.

`%ADJ-3-ADJMRDISPATCHFAIL : Failed to enqueue an adjacency summary event block`

Explanation An internal software error occurred.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

`%ADJ-3-ADJMRREFRESHFAIL : Failed to dispatch a refresh adjacency summary event`

Explanation An internal software error occurred.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

`%ADJ-3-ADJSTACK2 : Adj stack2 error [chars]: [chars]`

Explanation An internal software error occurred.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

`%ADJ-3-ALLOCATEFAIL : Failed to allocate an adjacency`

Explanation An internal software error occurred. This is probably because not enough memory was available.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

`%ADJ-3-ALLOCATEONDOWN : Allocating adj when adj subsystem down`

Explanation An internal software error occurred.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and

provide the representative with the gathered information.

```
%ADJ-3-BADADDRLEN : Zero address length detected distributing adj [chars]
```

Explanation An internal software error occurred. An attempt to reference an adjacency with an unsupported address type has been made.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%ADJ-3-BADADDRTYPE : Using an unsupported address type [dec] when trying to  
add/delete/modify/find an adjacency
```

Explanation An internal software error occurred. An attempt to reference an adjacency with an unsupported address type has been made.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%ADJ-3-BADLINKTYPE : Using an unsupported linktype [chars] when trying to  
add/delete/modify/find an adjacency
```

Explanation An internal software error occurred. An attempt to reference an adjacency with an unsupported address type has been made.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%ADJ-3-BADMACALIGN2 : Adjacency mac string for [chars] not byte aligned, offset  
[hex], length [hex]
```

Explanation An internal software error occurred.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%ADJ-3-BADMACALIGN : adjacency mac string end [hex] not [chars] aligned
```

Explanation An internal software error occurred.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%ADJ-3-BADMAGIC : adjacency [chars] is followed by bad magic
```

Explanation An internal software error occurred.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%ADJ-3-BOARDENCAP : Generation of encapsulation string for [chars] failed
```

Explanation An internal software error occurred.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%ADJ-3-BROKERINITFAIL : Failed to initialise adjacency RP broker facility
```

Explanation An internal software error occurred.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%ADJ-3-BUNDLES : Adj bundles: [chars]
```

Explanation An internal software error occurred.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%ADJ-3-DBGFILTERALLOCATEFAIL : Failed to allocate an adjacency debug filter block
```

Explanation An internal software error occurred. This is probably because not enough memory was available.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

`%ADJ-3-ILALLOCATEFAIL : Failed to allocate an adjacency interest list subblock`

Explanation An internal software error occurred. This is probably because not enough memory was available.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

`%ADJ-3-ILDEALLOCATEFAIL : Failed to deallocate an adjacency interest list subblock`

Explanation An internal software error occurred. This is probably because not enough memory was available.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

`%ADJ-3-ILINITFAIL : Failed to initialise adjacency interest list facility`

Explanation An internal software error occurred.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

`%ADJ-3-ILLEGALARGS : Illegal arguments -[chars]`

Explanation An internal software error occurred.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

`%ADJ-3-ISSU_REG : ISSU client [chars] ([dec]), entity [dec], failed ISSU registration: [chars]`

Explanation ISSU negotiation failed for this XDR client.

Recommended Action This error indicates a coding problem. It is an error that will occur every time this image is run, and requires a code change to fix it.

```
%ADJ-3-LCXDRCLIENT : Adjacency distribution client: [chars]
```

Explanation An internal software error occurred.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%ADJ-3-MACOVERFLOW : Adjacency mac address for [chars] overflowed by [dec] bytes
```

Explanation An internal software error occurred.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%ADJ-3-MACSTRING_PD_ERROR : Platform request for header type [chars] from adjacency  
[chars] [chars][chars]
```

Explanation An internal software error occurred.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%ADJ-3-NOFIBIDB : CEF Interface not found -[chars]
```

Explanation An internal software error occurred.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%ADJ-3-RPXDRCLIENT : Adjacency distribution client: [chars]
```

Explanation An internal software error occurred.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical

Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

`%ADJ-3-SBINITFAIL : Failed to initialise adjacency subblock facility`

Explanation An internal software error occurred.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

`%ADJ-3-STATETRANSITION : Unexpected state transition from [chars] to [chars]`

Explanation An internal software error occurred.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

`%ADJ-5-ADJISSUINCOMPATIBLE : All or part of sdjacency message for [chars] not sent to incompatible CEF instance for [chars]`

Explanation The adjacency is not distributed in whole to the remote CEF instance. This may impact traffic forwarding on remote CEF instance

Recommended Action No action is required.

`%ADJ-5-PARENT : Midchain parent maintenance for [chars] -[chars]`

Explanation A midchain adjacency failed to stack onto output chain because a loop was detected. Traffic through the adjacency will be dropped until the adj is restacked. This condition is typically transient and is rectified by the control plane driving stacking. E.g. if an ip tunnel destination resolves through the tunnel transiently this message would appear. The situation would be rectified either by learning the tunnel destination through an interface other than the tunnel itself or by bringing the tunnel down. Monitor 'show adjacency internal' to determine if the problem has been resolved.

Recommended Action No action is required.

`%ADJ-5-RESOLVE_REQ_FAIL : Adj resolve request failed for [chars] on [chars]`

Explanation The source (e.g. ARP or ND) could not resolve the address.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and

A

provide the representative with the gathered information.

ALARM

%ALARM-3-CLEAR : [chars] [chars] [chars] [chars] [chars]

Explanation None

Recommended Action None

%ALARM-3-NOMEM : OUT of Memory: [chars]

Explanation None

Recommended Action None

%ALARM-6-ENTITY_INFO : [chars] [chars] [chars] [chars] [chars]

Explanation Entity alarm assertion or deassertion information.

Recommended Action No action is required.

ALG_COM

%ALG_COM-3-ALG_COND_DEBUG_REG_FAILED : [chars]

Explanation None

Recommended Action None

%ALG_COM-3-ALG_REGISTER_FAILED : [dec]

Explanation ALG registration failed.

Recommended Action LOG_STD_ACTION

%ALG_COM-3-CHUNK_CREATE_FAIL : [chars]

Explanation A request to create a chunk failed

Recommended Action LOG_STD_ACTION

%ALG_COM-3-CHUNK_EXTEND_FAIL : [chars]

Explanation A request to create a chunk failed

Recommended Action LOG_STD_ACTION

A

%ALG_COM-3-IPC_INIT_FAILED : [dec]

Explanation IPC handler initialization failed.

Recommended Action LOG_STD_ACTION

ALG_PROXY

%ALG_PROXY-3-PROXY_IPC_FAIL : rc= [dec], MSGDEF_LIMIT_MEDIUM

Explanation The ALG proxy has experienced a failure when trying to send an IPC

Recommended Action LOG_STD_ACTION

%ALG_PROXY-3-PROXY_MEM_EXTEND_FAILED : ALG IPC subtype: [dec]

Explanation Extending memory failed.

Recommended Action LOG_STD_ACTION

%ALG_PROXY-3-PROXY_MEM_REQ_FAILED : ALG IPC subtype: [dec]

Explanation Requesting more memory failed.

Recommended Action LOG_STD_ACTION

%ALG_PROXY-4-PROXY_IPC_INVALID_MSG : [dec]

Explanation Invalid IPC message subtype.

Recommended Action LOG_STD_ACTION

%ALG_PROXY-4-PROXY_IPC_INVALID_MSG_LEN : [dec]:[dec] len [dec] flags [hex] source [dec]

Explanation Invalid IPC message length.

Recommended Action LOG_STD_ACTION

ALIGN

%ALIGN-3-CORRECT : Alignment correction made at [chars] [chars]ing [hex]

Explanation A software component within the router needs memory optimization.

Recommended Action Copy the error message exactly as it appears, and report it to your technical support representative.

A

`%ALIGN-3-CORRECT_SO : Alignment correction made at [chars] [chars]ing [chars]`

Explanation A software component within the router needs memory optimization.

Recommended Action Copy the error message exactly as it appears, and report it to your technical support representative.

`%ALIGN-3-FULL : Alignment log is full -no new entries will be recorded`

Explanation The router identified more software components in need of memory optimization than it can record.

Recommended Action Copy the error message exactly as it appears, and report it to your technical support representative.

`%ALIGN-3-READEXCEPTION : Warning : read access failed at [chars], still continuing`

Explanation In Is1010 read access failures do not make the box reload. They can be caused by either a bad register value in the asp ver 3.3 or earlier or a real problem in the hardware

Recommended Action If the ASP version is 3.3 or more, report it to your technical support representative.

`%ALIGN-3-RO_WRITE : Spurious memory access made at [chars] writing to [hex]`

Explanation An attempted but illegal access to a low memory address within a software component in the router has been temporarily blocked.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Issue the `<CmdBold>show alignment` command to gather data that may help identify the nature of the error. If you cannot determine the nature of the error from the error message text or from the `<CmdBold>show alignment` output, call your Cisco technical support representative and provide the representative with the gathered information.

`%ALIGN-3-SPURIOUS : Spurious memory access made at [chars] reading [hex]`

Explanation An attempted but illegal access to a low memory address within a software component in the router has been temporarily blocked.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Issue the `<CmdBold>show alignment` command to gather data that may help identify the nature of the error. If you cannot determine the nature of the error from the error message text or from the `<CmdBold>show alignment` output, call your Cisco technical support representative and provide the representative with the gathered information.

`%ALIGN-3-TRACE : -Traceback= [chars]`

Explanation A trace that shows where the previous ALIGN error occurred.

Recommended Action Copy the error message exactly as it appears, and report it to your technical support representative.

`%ALIGN-3-TRACEX : [chars]`

A

Explanation A trace that shows where the previous ALIGN error occurred.

Recommended Action Copy the error message exactly as it appears, and report it to your technical support representative.

ALPS

%ALPS-3-ALPSFAIL : ALPS: Assertion failed: [chars]

Explanation An internal software error has occurred.

Recommended Action LOG_STD_ACTION

%ALPS-3-ASCU_FSM_ERR : ASCU [hex] on interface [chars] has an internal FSM error.

Explanation Internal error.

Recommended Action Turn debug flags on, capture traces & contact Cisco technical support

%ALPS-3-ASCU_IF_STUCK : Polling for ASCU [hex] on interface [chars] is stalled.

Explanation The polling mechanism for an ALPS interface has become stuck.

Recommended Action LOG_STD_NO_ACTION

%ALPS-5-ASCU_DISABLED_ASCU_STUCK : ASCU [hex] on interface [chars] has been disabled since 4 consecutive messages were received from same SID.

Explanation An ALPS ASCU has been automatically disabled.

Recommended Action LOG_STD_NO_ACTION

%ALPS-5-ASCU_DOWN : ASCU [hex] on interface [chars] is down.

Explanation An ALPS ASCU has transitioned from up to down.

Recommended Action LOG_STD_NO_ACTION

%ALPS-5-ASCU_UP : ASCU [hex] on interface [chars] is up.

Explanation An ALPS ASCU has transitioned from down to up.

Recommended Action LOG_STD_NO_ACTION

%ALPS-5-CIRCUIT_CLOSED : Circuit [chars] changed state to closed, rsn = [chars].

Explanation An ALPS circuit has transitioned from open to closed

A

Recommended Action LOG_STD_NO_ACTION

%ALPS-5-CIRCUIT_OPEN : Circuit [chars] changed state to open.

Explanation An ALPS circuit has transitioned from closed to open.

Recommended Action LOG_STD_NO_ACTION

%ALPS-5-PEER_CLOSED : Peer ([IP_address], [chars]) changed state to closed.

Explanation An ALPS peer connection is now closed.

Recommended Action LOG_STD_NO_ACTION

%ALPS-5-PEER_CLOSED_DYNAMIC_INACTIVITY : Peer ([IP_address], [chars]) closed due to inactivity.

Explanation An ALPS peer connection is now closed due to inactivity.

Recommended Action LOG_STD_NO_ACTION

%ALPS-5-PEER_CONN_ID_CHANGE : Peer ([IP_address], [chars]) ID modified to ([IP_address], [chars]).

Explanation An ALPS peer connection identifier has changed.

Recommended Action LOG_STD_NO_ACTION

%ALPS-5-PEER_OPEN : Peer ([IP_address], [chars]) changed state to open.

Explanation An ALPS peer connection is now open.

Recommended Action LOG_STD_NO_ACTION

%ALPS-6-CIRCUIT_ASCU_REJECT : Circuit [chars] received a Circuit Open Confirm with a list of rejected ascus

Explanation An ALPS circuit sent a Circuit Open Request message and received a Circuit Open Confirm with a list of rejected ascus.

Recommended Action LOG_STD_NO_ACTION

%ALPS-6-CIRCUIT_BUSY_START : Circuit [chars] has entered a congested state.

Explanation An ALPS circuit is experiencing congestion.

Recommended Action LOG_STD_NO_ACTION

%ALPS-6-CIRCUIT_OPEN_FAILED : Circuit [chars] received a Circuit Open Failed message, rsn = [chars].

Explanation An ALPS circuit sent a Circuit Open Request message and received a Circuit Open Failed message as a reply.

Recommended Action LOG_STD_NO_ACTION

%ALPS-6-CIRCUIT_UPDATE_FAILED : Circuit [chars] received a Circuit Open Failed message, rsn = [chars].

Explanation An ALPS circuit sent a Circuit Update message and received a Circuit Open Failed message as a reply.

Recommended Action LOG_STD_NO_ACTION

%ALPS-6-CIRCUIT_X25_VC_STUCK : Host unresponsive on X.25 VC for circuit [chars]

Explanation The X.25 or EMTX host is not advancing the transmit window for extended periods of time. This may be indicative of a temporary problem with the host application. An X.25 Reset is sent to reset the transmit and receive windows to allow communication to proceed.

Recommended Action None

%ALPS-6-PEER_BUSY_END : Peer ([IP_address], [chars]) has exited a congested state.

Explanation An ALPS peer connection is no longer experiencing congestion.

Recommended Action LOG_STD_NO_ACTION

%ALPS-6-PEER_BUSY_START : Peer ([IP_address], [chars]) has entered a congested state.

Explanation An ALPS peer connection is experiencing congestion.

Recommended Action LOG_STD_NO_ACTION

%ALPS-6-PEER_OPEN_FAIL : Peer ([IP_address], [chars]) open failed, rsn = [chars]

Explanation An ALPS peer connection attempted to open, but failed to open.

Recommended Action LOG_STD_NO_ACTION

%ALPS-7-CIRCUIT_BUSY_END : Circuit [chars] has exited a congested state.

Explanation An ALPS circuit is no longer experiencing congestion.

Recommended Action LOG_STD_NO_ACTION

A

`%ALPS-7-CIRCUIT_DROPS_CKT_DISABLED : Threshold exceeded for circuit disabled drops for circuit [chars]`

Explanation The number of ALPS circuit drops due to circuit disabled exceeds the ALPS circuit threshold value.

Recommended Action LOG_STD_NO_ACTION

`%ALPS-7-CIRCUIT_DROPS_INVALID_ASCU : Threshold exceeded for invalid ASCU drops for circuit [chars]`

Explanation The number of ALPS circuit drops due to invalid ASCU identifier exceeds the ALPS circuit threshold value.

Recommended Action LOG_STD_NO_ACTION

`%ALPS-7-CIRCUIT_DROPS_LIFETIME_EXPIRED : Threshold exceeded for lifetime timer expiration drops for circuit [chars]`

Explanation The number of ALPS circuit drops due to lifetime timer expiration exceeds the ALPS circuit threshold value.

Recommended Action LOG_STD_NO_ACTION

`%ALPS-7-CIRCUIT_DROPS_QUEUE_OVERFLOW : Threshold exceeded for queue overflow drops for circuit [chars]`

Explanation The number of ALPS circuit drops due to queue overflow exceeds the ALPS circuit threshold value.

Recommended Action LOG_STD_NO_ACTION

`%ALPS-7-CIRCUIT_DROPS_VC_RESET : Threshold exceeded for X.25 VC Reset drops for circuit [chars]`

Explanation The number of ALPS circuit drops due to X.25 VC Reset exceeds the ALPS circuit threshold value.

Recommended Action LOG_STD_NO_ACTION

`%ALPS-7-PEER_DROPS_MAX_SIZE_EXCEEDED : Threshold exceeded for maximum size exceeded drops for peer ([IP_address], [chars]).`

Explanation The number of ALPS peer drops due to maximum size exceeded exceeds the ALPS peer threshold value.

Recommended Action LOG_STD_NO_ACTION

`%ALPS-7-PEER_DROPS_PEER_UNREACHABLE : Threshold exceeded for peer unreachable peer drops for peer ([IP_address], [chars]).`

Explanation The number of ALPS peer drops due to a peer unreachable condition exceeds the ALPS peer threshold value.

Recommended Action LOG_STD_NO_ACTION

A

`%ALPS-7-PEER_DROPS_QUEUE_OVERFLOW : Threshold exceeded for TCP Queue overflow peer drops for peer ([IP_address], [chars]).`

Explanation The number of ALPS peer drops due to queue overflow exceeds the ALPS peer threshold value.

Recommended Action LOG_STD_NO_ACTION

`%ALPS-7-PEER_DROPS_VERSION_MISMATCH : Threshold exceeded for version mismatch peer drops for peer ([IP_address], [chars]).`

Explanation The number of ALPS peer drops due to version mismatch exceeds the ALPS peer threshold value.

Recommended Action LOG_STD_NO_ACTION

AMT

`%AMT-2-ADD_GATEWAY : Error adding new Gateway`

Explanation Can't get memory for a new Gateway %s, port %d

Recommended Action No action is required.

`%AMT-2-GATEWAY_INIT : Error initializing AMT Gateway`

Explanation Insufficient memory is available to initialize Gateway

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start> , or contact your Cisco technical support representative and provide the representative with the gathered information.

`%AMT-2-MSGTYPE_ERR : [chars] AMT message with invalid type [dec]`

Explanation AMT type is not 1-7

Recommended Action No action is required.

`%AMT-2-PROCESS_ERR : Error initializing AMT process`

Explanation Can't start the AMT process

Recommended Action No action is required.

`%AMT-2-RELAY_INIT : Error initializing AMT Relay`

Explanation Insufficient memory is available to initialize Relay

A

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start> , or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%AMT-2-RPT_WAVLINIT : Error initializing IGMP Unsolicited Report handler
```

Explanation Insufficient memory is available to initialize the IGMP Unsolicited Report handler.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start> , or contact your Cisco technical support representative and provide the representative with the gathered information.

AN

```
%AN-3-ACP_CHANNEL_TO_NBR_FAILED : Failed to create ACP channel to neighbor [chars]  
on phy interface [chars]
```

Explanation Autonomic Network Control Plane Channel has not been created to the neighbor

Recommended Action No action is required.

```
%AN-3-ACP_IPSEC_TO_NBR_FAILED : Failed to create IPSEC tunnel [chars] to neighbor  
[chars]
```

Explanation Autonomic Network Control plane - Failed to create IPSEC tunnel to neighbor

Recommended Action No action is required.

```
%AN-3-ACP_VRF_GLOBAL_CREATE_FAIL : Failed to create AN VRF globally, vrf name  
[chars], vrf id [dec]
```

Explanation Autonomic network VRF has not been created globally

Recommended Action No action is required.

```
%AN-3-ACP_VRF_INTERFACE_CREATE_FAIL : Failed to create AN VRF on interface [chars],  
vrf name [chars], vrf id [dec]
```

Explanation Autonomic network VRF has not been created on the interface

Recommended Action No action is required.

A

`%AN-3-ANRA_WHITELIST_FILE_ERROR : ANRA dev id [chars] domain id [chars] -error in reading from whitelist file [chars], will continue without any whitelist devices`

Explanation The autonomic registration authority encountered file error when reading from whitelist file, check the file name and its contents

Recommended Action No action is required.

`%AN-3-DOMAIN_KEY_GEN_FAIL : The bootstrapping device [chars] failed to generate key pair for enrollment at ANRA`

Explanation The key pair generation failed at the device for triggering BS request message to ANRA. Can be due to failure in RSA key pair generation in the crypto library

Recommended Action No action is required.

`%AN-3-IDP_INTENT_FILE_ERROR : Error in reading from intent file -[chars]`

Explanation The Intent Distribution Protocol Module, encountered file error when reading from intent file, check the file name and its contents

Recommended Action No action is required.

`%AN-3-MSG_INVALID_HEADER : Invalid message header type [dec] received`

Explanation The message packet header got corrupted and invalid header obtained

Recommended Action No action is required.

`%AN-3-NBR_DOMAIN_CERT_INVALID : Invalid domain certificate of neighbor device udi [chars] on interface [chars]`

Explanation The domain certificate of the neighbor device is in invalid

Recommended Action No action is required.

`%AN-3-TLV_PARSE_ALIGN_ERROR : TLV parsed Len [dec], Next TLV could be misaligned`

Explanation Parsed TLV message is not a multiple of 4 and the next TLV message can be misaligned

Recommended Action No action is required.

`%AN-3-TLV_PARSE_LEN_INCORRECT : TLV parsed len [dec] > original message length [dec]`

Explanation Parsed TLV message length is greater than original message length

Recommended Action No action is required.

A

`%AN-4-ANRA_SIGN_VERIFY_FAIL : Signature verification of ANRA by new device has [chars]`

Explanation The new device joining the network verified the signature of ANRA as a part of mutual authentication and the verification failed

Recommended Action No action is required.

`%AN-4-DEVICE_NOT_ALLOWED_BY_ANRA : Device udi [chars] is not allowed by ANRA in its domain [chars]`

Explanation The autonomic network registration authority will not allow this device to join

Recommended Action No action is required.

`%AN-4-MASA_AUDIT_LOG_FAIL : Device udi [chars] is not in the audit log of MASA`

Explanation The manufacturer authorised signing authority audit log doesnt contain this device in its database

Recommended Action No action is required.

`%AN-4-MASA_AUTH_FAIL : Device udi [chars] is not authorized by MASA`

Explanation The MASA - manufacturer authorised signing authority has not authorised this device in its network

Recommended Action No action is required.

`%AN-4-MASA_AUTH_TOKEN_PARSE_ERROR : Error while parsing authentication token from MASA server for device udi-[chars]`

Explanation Encountered error while parsing the authentication token response string from MASA server

Recommended Action No action is required.

`%AN-5-ANRA_DOWN : Disabled ANRA @ device udi [chars]`

Explanation The autonomic network registration authority functionality is disabled

Recommended Action No action is required.

`%AN-5-ANRA_UP : Configured ANRA, device id [chars], AN domain id [chars]`

Explanation The autonomic network registration authority has been configured and is locally up

Recommended Action No action is required.

`%AN-5-DEVICE_BOOTSTRAPPED_BY_ANRA : Device udi [chars] has been boot strapped by AN-RA, in AN domain [chars]`

Explanation The autonomic network registration authority has bootstrapped this device

A

Recommended Action No action is required.

`%AN-5-IDP_INTENT_VER_OLD_DISCARD : Discarding older intent version-[dec]`

Explanation The device obtained an old intent file by Intent Distribution Protocol and is discarding it

Recommended Action No action is required.

`%AN-5-IDP_INTENT_VER_UPDATED : Updated to a new intent version [dec]`

Explanation The device obtained a new intent file by Intent Distribution Protocol

Recommended Action No action is required.

`%AN-5-NBR_ADDED : nbr udi [chars] is added as a neighbor on interface [chars]`

Explanation A hello message was obtained and the device is added in the neighbor table

Recommended Action No action is required.

`%AN-5-NBR_IN_DOMAIN : nbr udi [chars] on interface [chars] is inside the AN domain [chars] -got device id [chars]`

Explanation The device has been admitted into the autonomic domain

Recommended Action No action is required.

`%AN-5-NBR_LOST : connectivity to nbr udi [chars] on interface [chars] is lost`

Explanation Lost connectivity to the neighboring device & it is no longer part of AN domain

Recommended Action No action is required.

`%AN-5-NBR_OUT_DOMAIN : nbr udi [chars] on interface [chars] is outside the AN domain`

Explanation The device is removed from the AN domain, it can happen if the domain certificate is NULL or if the domain certificate is invalid

Recommended Action No action is required.

`%AN-5-SERVICE_LEARNT : AN service learnt, Service Type [dec] Service IP Addr [chars]`

Explanation The device obtained a new AN service by Service Discovery Protocol

Recommended Action No action is required.

`%AN-6-ACP_CHANNEL_TO_NBR_CREATED : Established ACP channel [chars] to neighbor [chars] on phy interface [chars]`

A

Explanation Autonomic Network Control plane Channel has been created to the neighbor

Recommended Action No action is required.

```
%AN-6-ACP_CHANNEL_TO_NBR_REMOVED : Removed ACP channel (phy int [chars]) to neighbor [chars]
```

Explanation Autonomic Network Control Plane Channel to neighbor is removed

Recommended Action No action is required.

```
%AN-6-ACP_IPSEC_TO_NBR_CREATED : Established IPSEC tunnel [chars] to neighbor [chars]
```

Explanation Autonomic Network Control plane - IPSEC tunnel established to neighbor

Recommended Action No action is required.

```
%AN-6-ACP_IPSEC_TO_NBR_REMOVED : Removed IPSEC tunnel [chars] to neighbor [chars], Tunnel state [dec]
```

Explanation Autonomic Network Control plane - IPSEC tunnel to neighbor is removed

Recommended Action No action is required.

```
%AN-6-ACP_ROUTING_GLOBAL_DISABLE : Removed OSPFv3 routing globally, pid [dec]
```

Explanation OSPF routing has been disabled globally

Recommended Action No action is required.

```
%AN-6-ACP_ROUTING_GLOBAL_ENABLED : Enabled global OSPFv3 pid [dec], rid [IP_address], area [dec]
```

Explanation OSPF routing has been enabled globally

Recommended Action No action is required.

```
%AN-6-ACP_ROUTING_INTERFACE_ENABLED : OSPF routing enabled on interface: [chars], (pid [dec], rid [IP_address], area [dec])
```

Explanation OSPF routing has been enabled on all physical interface

Recommended Action No action is required.

```
%AN-6-ACP_VRF_GLOBAL_CREATE_SUCCESS : AN VRF created globally vrf name [chars], vrf id [dec]
```

Explanation Autonomic network VRF has been created globally

A

Recommended Action No action is required.

`%AN-6-ACP_VRF_GLOBAL_REMOVE : AN VRF removed globally vrf name [chars], vrf id [dec]`

Explanation Autonomic network VRF has been removed globally

Recommended Action No action is required.

`%AN-6-ACP_VRF_INTERFACE_CREATE_SUCCESS : AN VRF created on interface [chars], vrf name [chars], vrf id [dec]`

Explanation Autonomic network VRF has been created on the interface

Recommended Action No action is required.

`%AN-6-ANRA_WHITELIST_CONFIG : ANRA dev id [chars] domain id [chars] has whitelist-will allow only these devices in AN network`

Explanation The autonomic registration authority has been configured with white list and will allow only these devices to enter its network

Recommended Action No action is required.

`%AN-6-ANRA_WHITELIST_NOT_CONFIG : ANRA dev id [chars] domain id [chars] has no whitelist-will allow all devices`

Explanation The autonomic registration authority has not been configured with white list and will allow all devices to enter its network

Recommended Action No action is required.

`%AN-6-DEVICE_ALLOWED_BY_ANRA : Device udi [chars] is allowed by ANRA in its domain [chars]`

Explanation The autonomic network registration authority has authorised this device to enter its network

Recommended Action No action is required.

`%AN-6-MASA_NOT_CONFIG : ANRA udi [chars] has no reachability to MASA -not configured, Cant verify device udi [chars]`

Explanation The manufacturer authorised signing authority has not been configured, cannot do the verification of device

Recommended Action No action is required.

`%AN-6-NBR_DOMAIN_CERT_VALID : Validated domain certificate of neighbor device udi [chars] on interface [chars]`

Explanation The domain certificate of the neighbor device is validated successfully

A

Recommended Action No action is required.

%AN-6-SUDI_AVAILABLE : secure UDI -[chars]

Explanation Secure unique device identification number is available on the device

Recommended Action No action is required.

%AN-6-UDI_AVAILABLE : UDI -[chars]

Explanation Unique device identification number is available on the device

Recommended Action No action is required.

APM

%APM-3-INIT : [chars]

Explanation Easy Perf Mon Initialization failed

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

%APM-3-LIST : [chars] [chars]

Explanation List operation error occurred.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

%APM-3-MEM : Memory [chars] failed -[chars]

Explanation Memory operation failed

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

APPFW

%APPFW-3-HTTP_APPFW_CONF_ERROR : Application Firewall configuration error --[chars]

Explanation An error has occurred during Application Firewall configuration.

Recommended Action This message indicates an error during firewall configuration and may be a potential security problem.

```
%APPFW-3-HTTP_MAX_REQ_EXCEED : Maximum of [dec] unanswered HTTP requests exceeded  
from [IP_address]:[dec] to [IP_address]:[dec]
```

Explanation The HTTP message has been detected to violate the transfer encoding application firewall inspection rule.

Recommended Action This message is for informational purposed only, but may indicate a security problem.

```
%APPFW-4-HTTP_CONT_LENGTH : content-length
```

Explanation The HTTP message has been detected to violate the content-length application firewall inspection rule.

Recommended Action This message is for informational purposed only, but may indicate a security problem.

```
%APPFW-4-HTTP_CONT_TYPE_MATCH : Sig:[dec] Content type not found -[chars] [chars]  
from [IP_address]:[dec] to [IP_address]:[dec]
```

Explanation The HTTP message has been detected to violate the content-type-verification application firewall inspection rule.

Recommended Action This message is for informational purposed only, but may indicate a security problem.

```
%APPFW-4-HTTP_CONT_TYPE_SIZE : Sig:[dec] Content size [int] out of range -[chars]  
[chars] from [IP_address]:[dec] to [IP_address]:[dec]
```

Explanation The HTTP message has been detected to violate the content-type-verification application firewall inspection rule.

Recommended Action This message is for informational purposed only, but may indicate a security problem.

```
%APPFW-4-HTTP_CONT_TYPE_VERIFY : Sig:[dec] Content type does not match the specified  
type -[chars] [chars] from [IP_address]:[dec] to [IP_address]:[dec]
```

Explanation The HTTP message has been detected to violate the content-type-verification application firewall inspection rule.

Recommended Action This message is for informational purposed only, but may indicate a security problem.

```
%APPFW-4-HTTP_DEOBFUSCATE : Sig:[dec] Deobfuscation signature detected -[chars]  
[chars] from [IP_address]:[dec] to [IP_address]:[dec]
```

Explanation The HTTP message has been detected to violate the deobfuscate application firewall inspection rule.

Recommended Action This message is for informational purposed only, but may indicate a security problem.

A

%APPPFW-4-HTTP_MATCH_REQ_RESP : Sig:[dec] Content type: [chars] does not match the Accept-Type from [IP_address]:[dec] to [IP_address]:[dec]

Explanation The HTTP message has been detected to violate the content-type-verification application firewall inspection rule.

Recommended Action This message is for informational purposed only, but may indicate a security problem.

%APPPFW-4-HTTP_MAX_HDR_LEN : Sig:[dec] HTTP Header length exceeded. Received [int] byte of header -[chars] [chars] from [IP_address]:[dec] to [IP_address]:[dec]

Explanation The HTTP message has been detected to violate the max-hdr-len application firewall inspection rule.

Recommended Action This message is for informational purposed only, but may indicate a security problem.

%APPPFW-4-HTTP_MAX_URI_LEN : Sig:[dec] HTTP URI length exceeded. Received [int] byte of URL -[chars] [chars] from [IP_address]:[dec] to [IP_address]:[dec]

Explanation The HTTP message has been detected to violate the max-uri-len application firewall inspection rule.

Recommended Action This message is for informational purposed only, but may indicate a security problem.

%APPPFW-4-HTTP_PORT_MISUSE_IM : Sig:[dec] HTTP Instant Messenger detected -[chars] [chars] from [IP_address]:[dec] to [IP_address]:[dec]

Explanation The HTTP message has been detected to violate the port misuse application firewall inspection rule.

Recommended Action This message is for informational purposed only, but may indicate a security problem.

%APPPFW-4-HTTP_PORT_MISUSE_P2P : Sig:[dec] HTTP Peer-to-Peer detected -[chars] [chars] from [IP_address]:[dec] to [IP_address]:[dec]

Explanation The HTTP message has been detected to violate the port misuse application firewall inspection rule.

Recommended Action This message is for informational purposed only, but may indicate a security problem.

%APPPFW-4-HTTP_PORT_MISUSE_TUNNEL : Sig:[dec] HTTP Tunnel detected -[chars] [chars] from [IP_address]:[dec] to [IP_address]:[dec]

Explanation The HTTP message has been detected to violate the port misuse application firewall inspection rule.

Recommended Action This message is for informational purposed only, but may indicate a security problem.

%APPPFW-4-HTTP_REQ_METHOD_EXT : Sig:[dec] HTTP Extension method illegal -[chars] '[chars]' from [IP_address]:[dec] to [IP_address]:[dec]

Explanation The HTTP message has been detected to violate the request-method application firewall inspection rule.

Recommended Action This message is for informational purposed only, but may indicate a security problem.

```
%APPFW-4-HTTP_REQ_METHOD_RFC : Sig:[dec] HTTP RFC method illegal -[chars] '[chars]'
from [IP_address]:[dec] to [IP_address]:[dec]
```

Explanation The HTTP message has been detected to violate the request-method application firewall inspection rule.

Recommended Action This message is for informational purposed only, but may indicate a security problem.

```
%APPFW-4-HTTP_STRICT_PROTOCOL : Sig:[dec] HTTP protocol violation detected -[chars]
[chars] from [IP_address]:[dec] to [IP_address]:[dec]
```

Explanation The HTTP message has been detected to violate the strict-http application firewall inspection rule.

Recommended Action This message is for informational purposed only, but may indicate a security problem.

```
%APPFW-4-HTTP_TRANSFER_ENCODE : Sig:[dec] HTTP Transfer encoding violation detected
-[chars] [chars] from [IP_address]:[dec] to [IP_address]:[dec]
```

Explanation The HTTP message has been detected to violate the transfer encoding application firewall inspection rule.

Recommended Action This message is for informational purposed only, but may indicate a security problem.

```
%APPFW-6-HTTP_SESSION_AUDIT_TRAIL : HTTP session initiator [IP_address]:[dec] sends
[dec] bytes -responder [IP_address]:[dec] sends [dec] bytes
```

Explanation The HTTP message has been detected to violate the transfer encoding application firewall inspection rule.

Recommended Action This message is for informational purposed only, but may indicate a security problem.

```
%APPFW-6-IM_AOL_CLIENT_VERSION : im-aol [IP_address]:[dec] attempting to establish
connection with aol server [IP_address]:[dec] using an unsupported version of the
client
```

Explanation The AOL client version is not supported

Recommended Action This message is for informational purposed only.

```
%APPFW-6-IM_AOL_SESSION : im-aol [chars] service session initiator
[IP_address]:[dec] [chars] [dec] bytes [chars] responder [IP_address]:[dec]
```

Explanation The AIM well known service message has been detected.

Recommended Action This message is for informational purposed only.

```
%APPFW-6-IM_MSN_CLIENT_VERSION : im-msn [IP_address]:[dec] attempting to establish
connection with msn server [IP_address]:[dec] using an unsupported version of the
client
```

Explanation The MSN client version is not supported

A

Recommended Action This message is for informational purposed only.

```
%APPPFW-6-IM_MSN_SESSION : im-msn [chars] service session initiator
[IP_address]:[dec] [chars] [dec] bytes [chars] responder [IP_address]:[dec]
```

Explanation The MSNMSG well known service message has been detected.

Recommended Action This message is for informational purposed only.

```
%APPPFW-6-IM_YAHOO_CLIENT_VERSION : im-yahoo [IP_address]:[dec] attempting to establish
connection with yahoo server [IP_address]:[dec] using an unsupported version of
the client
```

Explanation The YAHOO client version is not supported

Recommended Action This message is for informational purposed only.

```
%APPPFW-6-IM_YAHOO_P2P_CHAT : im-yahoo text-chat service session: [IP_address]:[dec]
establishing a direct chat with [dec].[dec].[dec].[dec]
```

Explanation A specific service yyyy has been detected to establish a direct connection with another peer in a Yahoo! Instant Messenger application and the application firewall inspection policy has been configured to send an alarm for this event. Typical services are O text-chat, voice-chat, file-transfer etc.

Recommended Action This message is for informational purposed only.

```
%APPPFW-6-IM_YAHOO_SESSION : im-yahoo [chars] service session initiator
[IP_address]:[dec] [chars] [dec] bytes [chars] responder [IP_address]:[dec]
```

Explanation The YMSG well known service message has been detected.

Recommended Action This message is for informational purposed only.

APPNAV_CLIENT

```
%APPNAV_CLIENT-3-CFT_INIT_FAILED : AppNav failed initialize flow table -[int].
```

Explanation Flow table is a critical component of AppNav. The failure is likely due to lack of memory (DRAM) on the ESP. The previous configuration needs to be removed and re-applied.

Recommended Action Reduce other system activity to ease memory demands. If conditions warrant, upgrade to a larger memory configuration.

APPNAV_CONTROLLER

```
%APPNAV_CONTROLLER-3-CM_REGISTER_FAILED : AppNav registration with Central Manager
failed for the following reason: [chars]
```

Explanation Received a registration failure message from the AppNav Central Manager. AppNav has not registered with the Central Manager

A

Recommended Action Issue the debug waas management errors command, and the debug waas management events , Contact your Cisco technical support representative , and provide the representative with the gathered information.

%APPNAV_CONTROLLER-4-ACG_IP_CHANGED : APPNAV-CONTROLLER: Alarm #10000, Severity: Major Appnav controller group IP address changed! All relevant service contexts will be disabled

Explanation Appnav controller group IP address changed! All relevant service contexts will be disabled

Recommended Action Change AppNav Controller's IP

%APPNAV_CONTROLLER-4-SC_SC_UNREACHABLE : APPNAV-CONTROLLER: Alarm #29006, Severity: Major

Explanation Connectivity with AC's under ACG is lost

Recommended Action Make sure AC's configured under ACG are up and reachable

%APPNAV_CONTROLLER-4-SC_SN_EXCLUDED : APPNAV-CONTROLLER: Alarm #29008, Severity: Major

Explanation Stable SN views across AC's are different. Those SN's that are not reachable by other AC's are excluded

Recommended Action Make sure excluded SN's are reachable from all AC's

%APPNAV_CONTROLLER-4-SC_SN_UNREACHABLE : APPNAV-CONTROLLER: Alarm #29007, Severity: Major

Explanation Service context has entered Operational state and there is at least one configured node that is not part of the SN view.

Recommended Action Check status of configured SNs.

%APPNAV_CONTROLLER-4-SERVICE_CTX_DISABLE : SERVICE-CONTROLLER: Alarm 10001, Severity: Major Disabling service context [chars]

Explanation Disabling service context

Recommended Action None

%APPNAV_CONTROLLER-4-SNG_AO_UNAVAILABLE : APPNAV-CONTROLLER: Alarm #30000, Severity: Major

Explanation No node in service node group is available for optimization and traffic is getting optimized by a secondary SNG.

Recommended Action Check status of configured SNs.

A

%APPNAV_CONTROLLER-4-SNG_UNAVAILABLE : APPNAV-CONTROLLER: Alarm #30001, Severity: Major

Explanation No SN in appnav node group is available for optimization.

Recommended Action Check status of configured nodes.

%APPNAV_CONTROLLER-5-SC_CONVERGENCE_FAILED : APPNAV-CONTROLLER: Alarm #29001, Severity: Critical

Explanation CMM is not coming out of convergence state

Recommended Action Check connectivity between SN's and AC's

%APPNAV_CONTROLLER-5-SC_DEGRADED_CLUSTER : APPNAV-CONTROLLER: Alarm #29002, Severity: Critical

Explanation Mismatch of stable AC views between AC's

Recommended Action Check connectivity between AC's

%APPNAV_CONTROLLER-5-SC_MIXED_FARM : APPNAV-CONTROLLER: Alarm #29003, Severity: Minor

Explanation When an appnav controller detects upon that there are other appnav-controllers/SNs in the cluster with different ICIMP/DMP minor version number.

Recommended Action Check versions of SNs in network.

%APPNAV_CONTROLLER-6-CM_REGISTER_SUCCESS : AppNav registered with Central Manager successfully

Explanation Received a registration success message from the Central Manager

Recommended Action None. All is well

ARAP

%ARAP-0-DEFAULT : TTY [dec]

Explanation An internal software error occurred.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start> , or contact your Cisco technical support representative and provide the representative with the gathered information.

%ARAP-0-NOTNULLRESEND : TTY [dec]

Explanation An internal software error occurred.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start> , or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%ARAP-0-NULLRESEND : TTY [dec]
```

Explanation An internal software error occurred.

Recommended Action Report this error to you technical support representative.

```
%ARAP-0-VSError : TTY [dec]: VS queued error
```

Explanation An internal software error occurred.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start> , or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%ARAP-0-WAITBADMSG : TTY [dec]: arg msg bad [hex]
```

Explanation The router received an invalid packet during ARAP MNP4 connection setup phase.

Recommended Action Check for excessive line noise. Check the ARAP client software configuration for possible problems.

```
%ARAP-2-NOLOG : TTY [dec]: Could not malloc log
```

Explanation Memory not available for internal MNP4 logging.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start> , or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%ARAP-3-ABORTED : TTY [dec]: arap callback aborted
```

Explanation An unexpected message was received during the Microcom Networking Protocol version 4 (MNP4) link setup.

A

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%ARAP-3-BADCONFIG : TTY [dec]: unhandled configuration command
```

Explanation A configuration command was not recognized.

Recommended Action Check the configuration file on the server for any invalid configuration commands.

```
%ARAP-3-BADPAK : TTY [dec]: Bad packet type in arap_send_msg
```

Explanation Internal data structures are corrupted.

Recommended Action Check for abnormally high CPU usage.

```
%ARAP-3-REMOTEERROR : TTY [dec]: arap input error
```

Explanation ARAP connection was terminated without a known cause.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%ARAP-3-TIMEOUT : TTY [dec]: arap expected message timeout
```

Explanation The software timed out during the MNP4 link setup.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%ARAP-4-CONFAILED : TTY [dec]: ARAP connection failed: [chars]
```

Explanation The ARA protocol client was denied access, probably due to a configuration problem on the server. The error message should indicate the problem. This message does not indicate access denials due to bad passwords.

Recommended Action Investigate the problem reported in the error message.

```
%ARAP-4-NOEXTTACACS : TTY [dec]: arap TACACS is configured but extended TACACS is not.
```

Explanation Terminal Access Controller Access Control System (TACACS) authentication failed because extended TACACS is not configured.

Recommended Action Configure extended TACACS.

`%ARAP-5-INITCONFUSED : TTY [dec]: ARAP unexpected initialization packet [chars]`

Explanation The startup negotiation between a client and the ARA protocol server fell out of order. If this message is received sporadically, it indicates line noise.

Recommended Action If this message recurs, reinstall the ARA client software.

`%ARAP-5-PAKINVALID : TTY [dec]: ARAP invalid packet received`

Explanation A corrupted packet reached the ARA protocol code.

Recommended Action Check for excessive CPU usage or excessive line noise.

`%ARAP-6-ADDRFREE : TTY [dec]: ARAP ended for user [chars]; address %A; [dec] seconds connected`

Explanation This message appears only when ARA protocol logging is configured. The message notes that an ARA protocol user has logged out.

Recommended Action No action is required.

`%ARAP-6-ADDRUSED : TTY [dec]: ARAP started for user [chars]; address [dec].[dec]`

Explanation This message appears only when ARA protocol logging is configured. The message notes that an ARA protocol user has logged in.

Recommended Action No action is required.

`%ARAP-6-BADEXIT : TTY [dec]: exited user [chars]: [chars]`

Explanation A user was disconnected from ARA protocol at an unexpected time. The disconnection may be due to modems dropping, server error, client problems, or any number of other difficulties.

Recommended Action To determine the cause of the disconnection, correlate the receipt of this message with the user problem reports.

`%ARAP-6-LRPHASERROR : TTY [dec]: Received LT in CONNECTION PHASE`

Explanation The router received an invalid packet during ARA connection setup phase.

Recommended Action Check for excessive line noise. Check the ARAP client software configuration for possible problems.

`%ARAP-6-MAXRESENDS : TTY [dec]`

Explanation The router resent MNP4 packets maximum number of times without receiving an acknowledgement.

A

Recommended Action To determine the cause of the disconnection, correlate the receipt of this message with the user problem reports.

```
%ARAP-6-MNP4RCVDISC : TTY [dec]: MNP4 input disconnect
```

Explanation This indicates that the router received disconnect request from the remote Macintosh client.

Recommended Action No action is required.

```
%ARAP-6-MNP4T401 : TTY [dec]: T401 [dec] baud rate [dec]
```

Explanation This message indicates that the router received MNP4 connection request. MNP4 acknowledgement timer value is also indicated.

Recommended Action No action is required.

```
%ARAP-6-RCVGIANT : TTY [dec]: Rcv giant. dropping frame
```

Explanation The router received an oversized MNP4 frame.

Recommended Action Check for excessive line noise. Check the ARAP client software configuration for possible problems.

```
%ARAP-6-RCVNOPAK : TTY [dec]: Receive getbuffer failure. dropping frame
```

Explanation No buffer exists for an incoming packet.

Recommended Action Examine buffer usage statistics. Possibly more memory is required.

```
%ARAP-6-RESEND SLOW : TTY [dec]
```

Explanation The router repeated resending of MNP4 packets as the Macintosh client failed to acknowledge previously resent packets.

Recommended Action If this error message persists for several ARAP connections report it to your technical support representative.

```
%ARAP-6-TIMERERROR : TTY [dec]: MNP4 timeout error
```

Explanation The router is dropping the connection after doing maximum resends.

Recommended Action To determine the cause of the disconnection, correlate the receipt of this message with the user problem reports.

```
%ARAP-6-XTICKLE : TTY [dec]: exited user [chars]: Other side stopped answering ARAP  
tickles (mnp4 pak resent [dec] mnp4 pak sent [dec] last [dec] now [dec])
```

Explanation The router disconnected as the remote Macintosh client stopped sending ARAP tickle or data packets.

Recommended Action To determine the cause of the disconnection, correlate the receipt of this message with the user problem reports.

ARCHIVE_CONFIG

`%ARCHIVE_CONFIG-4-ARCHIVE_DELETE_FAILED` : Delete of a previously saved archive of the router configuration could not be completed.

Explanation The router could not delete a file that was previously written. The file that was being deleted file contains an archive of the router configuration. This could occur for example if the file was manually deleted.

Recommended Action None

`%ARCHIVE_CONFIG-4-ARCHIVE_SKIPPED` : Archive of router configuration was skipped due to a previous initiation.

Explanation Only one archive can be created at a time. Two or more simultaneous archives in progress is not allowed. This could occur for example if two users attempt to create an archive simultaneously.

Recommended Action Retry the archive creation later, when the previous archive has finished being written.

`%ARCHIVE_CONFIG-6-ARCHIVE_CREATE_FAILED_STANDBY` : Could not create an archive of the router configuration on the standby RP.

Explanation The router could not create an archive file on the standby RP. The file that was being created contains an archive of the router configuration. This could occur for example if the active RP cannot communicate with the standby RP.

Recommended Action None

`%ARCHIVE_CONFIG-6-ARCHIVE_DELETE_FAILED_STANDBY` : Delete of a previously saved archive of the router configuration could not be completed on the standby RP.

Explanation The router could not delete a file that was previously written on the standby RP. The file that was being deleted file contains an archive of the router configuration. This could occur for example if the file was manually deleted. Alternatively, the file could not be deleted when the active RP cannot communicate with the standby RP.

Recommended Action None

ARCHIVE_ISSU

`%ARCHIVE_ISSU-2-GET_BUFFER` : Archive ISSU client failed to get buffer for message.
Error: [dec] ([chars])

Explanation The Archive ISSU client failed to get buffer space for building a negotiation message. A negotiation message cannot be sent to the standby device. If a problem occurs with the ISSU session negotiation, the standby device cannot be brought up properly.

Recommended Action LOG_STD_SH_CMD_ACTION(show logging and show checkpoint client)

```
%ARCHIVE_ISSU-2-INIT : Archive ISSU client initialization failed to [chars]. Error:
[dec] ([chars])
```

Explanation The Archive ISSU client could not be initialized. This initialization failure must be addressed before in-service software upgrade or downgrade can be performed successfully. If you do not address this failure, there will be downtime during software upgrade or downgrade.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%ARCHIVE_ISSU-2-SEND_NEGO_FAILED : Archive ISSU client failed to send negotiation
message. Error: [dec] ([chars])
```

Explanation The Archive ISSU client failed to send a session negotiation message to the peer device. If a problem occurs with the ISSU session negotiation, the standby device cannot be brought up properly.

Recommended Action LOG_STD_SH_CMD_ACTION(show logging and show checkpoint client)

```
%ARCHIVE_ISSU-2-SESSION_NEGO_FAIL_START : Failed to start Archive ISSU session nego-
tiation. Error: [dec] ([chars])
```

Explanation The Archive ISSU client failed to start session negotiation. If a problem occurs with the ISSU session start, the standby device cannot be brought up properly.

Recommended Action LOG_STD_SH_CMD_ACTION(show issu session <client_id>)

```
%ARCHIVE_ISSU-2-SESSION_REGISTRY : Archive ISSU client failed to register session
information. Error: [dec] ([chars])
```

Explanation The Archive ISSU client failed to register session information. If a problem occurs with the ISSU session registration, the standby device cannot be brought up properly.

Recommended Action LOG_STD_SH_CMD_ACTION(show issu capability entries <client_id> and show issu session <client_id> and show issu negotiated capability <session_id>)

```
%ARCHIVE_ISSU-3-INVALID_SESSION : Archive ISSU client does not have a valid regis-
tered session.
```

Explanation The Archive ISSU client does not have a valid registered session.

Recommended Action LOG_STD_SH_CMD_ACTION(show issu capability entries <client_id> and show issu session <client_id> and show issu negotiated capability <session_id>)

```
%ARCHIVE_ISSU-3-MSG_NOT_OK : Archive ISSU client 'Message Type [dec]' is not compat-
ible
```

A

Explanation The Archive ISSU client received an incompatible message from the peer device. The message cannot be processed.

Recommended Action LOG_STD_SH_CMD_ACTION(show issu message group <client_id> and show issu session <client_id> and show issu negotiated version <session_id>)

```
%ARCHIVE_ISSU-3-MSG_SIZE : Archive ISSU client failed to get the MTU for Message
Type [dec]. Error: [dec] ([chars])
```

Explanation The Archive ISSU client failed to calculate the MTU for the specified message. The Archive ISSU client is not able to send the message to the standby device.

Recommended Action LOG_STD_SH_CMD_ACTION(show issu message group <client_id> and show issu session <client_id> and show issu negotiated version <session_id>)

```
%ARCHIVE_ISSU-3-SESSION_UNREGISTRY : Archive ISSU client failed to unregister ses-
sion information. Error: [dec] ([chars])
```

Explanation The Archive ISSU client failed to unregister session information.

Recommended Action LOG_STD_SH_CMD_ACTION(show issu session <client_id> and show issu negotiated capability <session_id>)

```
%ARCHIVE_ISSU-3-TRANSFORM_FAIL : Archive ISSU client [chars] transform failed for
'Message Type [dec]'. Error: [dec] ([chars])
```

Explanation The Archive ISSU client could not transform the specified message type. If the transmit transformation failed, the checkpoint message was not sent to the standby device. If the receive transformation failed, the checkpoint message was not applied on the standby device. In both cases, the Archive state between the active device and the standby device is not identical.

Recommended Action LOG_STD_SH_CMD_ACTION(show issu session <client_id> and show issu negotiated version <session_id>)

ARP

```
%ARP-3-ARPHAMSGFMT : Malformed ARP HA checkpointing message (size = [int], entry
count = [int])
```

Explanation A malformed ARP HA checkpointing message has been received.

Recommended Action If this message recurs, copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%ARP-3-ARPINIT : Internal software error during ARP subsystem initialization
```

Explanation An internal software error has occurred during ARP subsystem initialization.

Recommended Action If this message recurs, copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/> . Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start> , or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%ARP-3-ARPIINT : ARP table accessed at interrupt level [dec]
```

Explanation ARP table is accessed at interrupt level which is forbidden.

Recommended Action If this message recurs, copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/> . Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start> , or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%ARP-3-ARPINVALIDEENTRY : ARP system internal error. Returns NULL arp entry on node [IPV6 address]
```

Explanation An internal software error has occurred in ARP subsystem, an NULL arp entry is got.

Recommended Action If this message recurs, copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/> . Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start> , or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%ARP-3-STCKYARPOVR : Attempt to overwrite Sticky ARP entry: [IP_address], hw: [enet] by hw: [enet]
```

Explanation Multiple stations configured with same IP in Private VLAN. Possible case of IP address stealing.

Recommended Action Change the IP address of one of the two systems.

```
%ARP-3-TABLEERR : Internal software error during ARP table operation for ARP entry
```

Explanation An internal software error has occurred during an ARP table operation.

Recommended Action If this message recurs, copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/> . Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start> , or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%ARP-4-ARPADJ : Received CEF Adjacency updation request on different interfaces: [IP_address] on [chars]
```

Explanation A request to update CEF adjacency came on two different interfaces.

Recommended Action If this message recurs, copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/> . Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start> , or contact your Cisco technical support representative and provide the representative with the gathered information.

`%ARP-4-ARPLEARNCROSS : [int] Learned ARP entries are installed in the ARP table and reached the max limit`

Explanation This message indicates that the number of dynamically learned ARP entries has reached a preconfigured max. limit in ARP Table.

Recommended Action First, inspect the ARP entries on the interface. If they are valid entries, either increase the configured max limit or reconfigure the network to reduce ARP peers.

`%ARP-4-ARPLEARNTHRES : Learned ARP entries have reached to threshold level [int]`

Explanation This message indicates that the number of learned ARP entries, which are not configured, has reached a preconfigured threshold, indicating a possible misconfiguration or DOS attack.

Recommended Action First, inspect the ARP entries on the interface.reconfigure the network to reduce ARP peers.

`%ARP-4-ENTRYTHRESHOLD : Cannot insert more than [int] dynamic ARP entries on [chars]`

Explanation This message indicates that the number of dynamically learned ARP entries, complete or incomplete, has exceeded a preconfigured limit, indicating a possible misconfiguration or DOS attack.

Recommended Action First, inspect the ARP entries on the affected interface. If they are valid entries, either increase the configured ARP entry limit or reconfigure the network to reduce ARP peers. If they are invalid entries, there is a possible DOS attack on the system.

`%ARP-4-NULL_SRC_MAC : NULL MAC address from [IP_address] on [chars]`

Explanation Application or peer tried to insert entry with NULL SRC MAC

Recommended Action If this message recurs, call your technical support representative for assistance.

`%ARP-4-TRAPENTRY : [int] dynamic ARP entries on [chars] installed in the ARP table`

Explanation This message indicates that the number of dynamically learned ARP entries, complete or incomplete, has exceeded a preconfigured threshold, indicating a possible misconfiguration or DOS attack.

Recommended Action First, inspect the ARP entries on the affected interface. If they are valid entries, either increase the configured log threshold or reconfigure the network to reduce ARP peers. If they are invalid entries, there is a possible DOS attack on the system.

`%ARP-6-ARPLEARNRESUME : Resuming Learn ARP entries to install in ARP table.`

A

Explanation This message indicates that the number of dynamically learned ARP entries is in range of permit threshold value. System is allowing new Learned ARP entries to install in ARP table.

Recommended Action No action is required.

ASPP

```
%ASPP-3-NOTTY : [chars]: Unable to set Rx/Tx tty async service hooks.
```

Explanation This message occurs only when ASP is configured. It indicates the serial interface using ASP is configured incorrectly or does not support asynchronous mode.

Recommended Action Verify the correct hardware interface type is being used.

AT

```
%AT-1-NOMEM : Could not allocate memory for [chars] at line [dec] in [chars]
```

Explanation An internal software error occurred.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start> , or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%AT-2-ASSERTFAILED : AppleTalk assertion failed: [chars]
```

Explanation The software detected an inconsistency. Although this error is serious, the router attempts to continue. AppleTalk processing might be impaired.

Recommended Action Copy the message exactly as it appears, note any AppleTalk problems you experience, and call your technical support representative.

```
%AT-3-CANTDEL : Cannot delete [chars] route [dec] by clearing; remove it by reconfiguring
```

Explanation You attempted to remove a route from the routing table by issuing the clear appletalk route command. The command failed because the route was on a directly connected interface, that is, it was created when you configured the router.

Recommended Action Remove the route by reconfiguring the directly connected interface with which it is associated.

```
%AT-3-DEFZONEERR : [chars]: AppleTalk interface warning; default zone differs from %a
```

Explanation During the verification startup process, there was a disagreement between the default zone (the first zone defined after the `appletalk cable-range` command) and the router that confirmed the configuration. When an AppleTalk end node is first connected to a network, it joins the default zone until it is overridden.

Recommended Action Use the `appletalk zone` command to correct the configuration so that all routers are advertising the same default zone. Note that several router implementations are known to mismanage the default zone.

```
%AT-3-DISCOFF : [chars]: AppleTalk node warning; discovery mode disabled
```

Explanation A hardware or software error occurred.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%AT-3-DOMLOOP : Loop detected on domain [dec] [[chars]]
```

Explanation The domain router detected a routing loop. Routing loops are not allowed. The domain router runs a background loop detection process. The domain router starts this process when it receives a new zone list from a domain that is identical to the list in the main routing table and whose network range length matches that in this list. The loop detection process sends several AppleTalk NBP loopback packets. When one of these packets is received on an interface that does not belong to the original domain, the domain router first shuts off all the domains involved in the loop, and then shuts off all the interfaces in these domains. The loop detection does not catch all types of loops. It is your responsibility to make sure that no loop exists.

Recommended Action Disable the cause of the routing loop. Then use the `clear appletalk` command to restart the interfaces involved.

```
%AT-3-DOMOVERFLOW : Remap range overflow for [chars] domain [dec]
```

Explanation The remap range overflowed. If a network (range) cannot fit inside the remapping range, the network or cable range being advertised by a neighboring router is not accepted. When an overflow occurs, all interfaces in the domain are disabled.

Recommended Action Use the `appletalk domain remap-range` command to increase the remapping range. Then restart the interfaces.

```
%AT-3-IFCONFLICT : [chars]: AppleTalk interface disabled; conflicts with interface [chars]
```

Explanation An attempt was made to configure an interface to have the same or a conflicting AppleTalk address or cable range as another interface on the same router.

Recommended Action Verify that you are not specifying an AppleTalk address or cable range used previously on this router, and reconfigure the interface.

```
%AT-3-INVNBPCMD : Invalid NBPtest command [chars]
```

A

Explanation An unrecognized command was specified in the Name Binding Protocol (NBP) test facility.

Recommended Action Enter a valid command.

```
%AT-3-MCMISMATCH : [chars]: AppleTalk interface warning; zone multicast [enet] differs from our multicast [enet]
```

Explanation A computed multicast address disagrees with that provided by another AppleTalk router. The other AppleTalk router might be misconfigured or faulty.

Recommended Action Correct the problem at the other router.

```
%AT-3-NETDISAGREES : [chars]: AppleTalk interface disabled; network incompatible with %#a
```

Explanation The interface was disabled because the configured AppleTalk address or cable range for the interface conflicts with that of another router on the attached network.

Recommended Action Reconfigure the affected routers so that there are no conflicting addresses or cable ranges on the attached network.

```
%AT-3-NOADDRSAVAIL : [chars]: AppleTalk node down; no addresses available
```

Explanation No free node could be found on the interface.

Recommended Action If your AppleTalk network has less than 250 nodes, issue the debug appletalk errors command and then call your technical support representative. If your AppleTalk network has more than 250 nodes, split it into smaller networks by creating new segments and moving some nodes into the new segments.

```
%AT-3-NOBESTPATH : Could not compute best path for network %#A
```

Explanation A path to the specified network could not be found.

Recommended Action Use the show appletalk route command to verify that a path to the specified network exists. If it does, copy the error message exactly as it appears, and report it along with the output of the show appletalk route command to your technical support representative.

```
%AT-3-NOROUTE : No route to destination %a
```

Explanation The router could not deliver a packet to a destination because it did not know where to send it.

Recommended Action Use the show appletalk route command to verify that a path to the destination exists. If it does, copy the error message exactly as it appears, and report it with the output of the show appletalk route command to your technical support representative.

```
%AT-3-NOSOCKET : [chars]: client tried to open socket, but failed
```

Explanation open socket failed;Possible out of memory situation

Recommended Action None

%AT-3-NOSRCADDR : [chars]: AppleTalk packet error; no source address available

Explanation The router could not generate an AppleTalk packet because no valid AppleTalk source address was available to identify this router in the packet.

Recommended Action Configure an interface to have an address or cable range. Use the show appletalk command to verify that the interface is operational.

%AT-3-NOSUCHNBR : No such neighbor, %#a

Explanation You specified a nonexistent neighbor address in a show appletalk neighbor or clear appletalk neighbor.

Recommended Action Specify a valid neighbor address, that is, one that appears in the output of the show appletalk neighbor command.

%AT-3-NOTRUNNING : AppleTalk not running

Explanation You tried to show or change the AppleTalk configuration when AppleTalk routing was not turned on.

Recommended Action Issue the appletalk routing command before issuing any other AppleTalk configuration or display command.

%AT-3-NOVIRTUAL : [chars]: client tried to connect, but no virtual network is declared

Explanation A hardware or software error occurred.

Recommended Action Copy the error message exactly as it appears, and report it to your technical support representative.

%AT-3-OUTOFSYNC : [chars]: AURP connection out of sync...terminating

Explanation AURP detected packets that were out of sequence. This might be caused by a lost connection.

Recommended Action Copy the error message exactly as it appears, and report it to your technical support representative.

%AT-3-SUBROUTINE_ERROR : AppleTalk error: [chars]

Explanation An internal error occurred. Specifically, a programming assertion in the AppleTalk networking code was violated.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

A

```
%AT-3-ZONEDISAGREES : [chars]: AppleTalk interface disabled; zone list incompatible with %#a
```

Explanation The zone list of the configured interface is inconsistent with the zone list of other routers.

Recommended Action Reconfigure the zone list on the router so that it does not conflict with that the zone lists on other routers.

```
%AT-4-MACIPBADCONF : [chars]: MacIP inoperable configuration, [IP_address]
```

Explanation If the appletalk event-logging command is configured, this message appears on the console when a MacIP server cannot begin or recover operations because of an invalid IP address configuration. This condition only occurs when the configured MacIP server's IP address is not valid on the same cable of any operable IP interface. The AppleTalk zone served by the MacIP server replaces the zone specified in the appletalk zone command. The IP address configured on the MacIP server replaces the IP address configured by the ip address command. When this error occurs, the MacIP configuration is considered invalid and is deleted.

Recommended Action No action is required.

```
%AT-4-MACIPNOCABLE : [chars]: MacIP inoperable IP interface, [IP_address]
```

Explanation If the appletalk event-logging command is configured, this message appears on the console when a MacIP server can no longer operate due to a change in the condition of the IP interface it serves. This condition can occur if IP routing is shut down on the interface, or the IP address of the interface is changed so that the MacIP server's IP address is no longer valid on the same cable. The AppleTalk zone served by the MacIP server replaces the zone specified in the appletalk zone command. The IP address configured on the MacIP server replaces the IP address configured by the ip address command.

Recommended Action No action is required.

```
%AT-4-NETINVALID : [chars]: AppleTalk node down; conflicts with active internet
```

Explanation The configuration specified for the interface conflicts with the active AppleTalk internetwork. For example, a cable range might be configured that overlaps an existing route but does not match the entry exactly.

Recommended Action Use the appletalk cable-range command to reconfigure the interface so that there are no conflicts with the existing AppleTalk network, or take any other actions necessary to resolve the conflict. AppleTalk will periodically attempt to restart the interface.

```
%AT-4-PATHREJECTED : AURP path %#A rejected; conflict detected
```

Explanation The router detected a conflicting cable range. A router is configured with a cable range that overlaps with an existing range but does not match the entry exactly.

Recommended Action Use the show appletalk command to identify the overlapped cable range, and then reconfigure the misconfigured router.

```
%AT-5-ADDRINUSE : [chars]: AppleTalk node warning; address %A already in use
```

Explanation The initial hint address was in use. A search will be made for a valid address.

Recommended Action No action is required.

`%AT-5-ADDRINVALID : [chars]: AppleTalk node warning; address %A is invalid`

Explanation The hint address specified for the interface was not valid for the current configuration.

Recommended Action The hint address is ignored and a random valid hint address is automatically computed.

`LOG_STD_NO_ACTION`

`%AT-5-BADNEIGHBOR : [chars]: AppleTalk neighbor ignored; %#a is misconfigured`

Explanation A neighboring router's AppleTalk configuration does not agree with this router's AppleTalk configuration. This condition can result from a mismatch between the neighbor's network range and this router's network range.

Recommended Action Modify either this router's or the neighboring router's configuration so that the network ranges agree.

`%AT-5-COMPATERR1 : [chars]: AppleTalk internet compatibility mode required by %#a`

Explanation A neighboring router supports only extended AppleTalk networks with a cable range of 1 and with one assigned zone, for example, 25-25.

Recommended Action Upgrade the routers that support only the original AppleTalk specification. In the meantime, observe the compatibility rules for AppleTalk Phase 1 and Phase 2 routers.

`%AT-5-COMPATERR2 : AppleTalk neighbor incompatibility; %#A has multiple zones`

Explanation Although this router has neighbors that require your internetwork to observe compatibility rules, AppleTalk has learned of a route with multiple zone names defined. This condition can cause node inconsistencies on your AppleTalk network.

Recommended Action Upgrade the routers that support only the original AppleTalk specification. In the meantime, observe the compatibility rules for AppleTalk Phase 1 and Phase 2 routers.

`%AT-5-COMPATERR3 : AppleTalk neighbor incompatibility; %#A has wide cable range`

Explanation Although this router has neighbors that require your internetwork to observe compatibility rules, AppleTalk has learned of a route that has a cable range greater than 1. This condition can cause node inconsistencies on your AppleTalk network.

Recommended Action Upgrade the routers that support only the original AppleTalk specification. In the meantime, observe the compatibility rules for AppleTalk Phase 1 and Phase 2 routers.

`%AT-5-DUPADDR : [chars]: AppleTalk interface restarting; node address taken by [enet]`

Explanation Another AppleTalk node on a common network interface claimed the same AppleTalk address that this router was using. This error indicates a serious, unexpected problem. If it recurs, a physical network problem in which the nodes cannot communicate with each other might exist.

A

Recommended Action The interface on this router restarts AppleTalk processing on the common network interface to resolve the address conflict. LOG_STD_NO_ACTION

`%AT-5-FDDICOMPAT : AppleTalk FDDI neighbor %a using obsolete FDDI addressing`

Explanation Another AppleTalk router on the FDDI ring is running a release of the router software earlier than 9.0(2). Routers running these early software releases use an encapsulation for AppleTalk on FDDI rings that is not compatible with the Apple FDDITalk implementation.

Recommended Action Upgrade the routers running the software releases that use the pre-FDDITalk encapsulation for AppleTalk on FDDI rings.

`%AT-5-INTCLEARED : [chars]: AppleTalk interface restarting; interface cleared`

Explanation A clear interface command was issued on an interface that is currently routing AppleTalk.

Recommended Action No action is required.

`%AT-5-INTDOWN : [chars]: AppleTalk node down; line protocol down`

Explanation An AppleTalk hardware interface was disabled because of a bad serial line, a configuration command, or a bad interface.

Recommended Action If the interface was not intentionally disabled, this message indicates a hardware problem. In this case, repair or replace the applicable hardware.

`%AT-5-INTRESTART : [chars]: AppleTalk interface restarting; protocol restarted`

Explanation The hardware interface was reset because of a configuration change. After the reset, AppleTalk automatically reinitialized the interface.

Recommended Action No action is required.

`%AT-5-LOSTNEIGHBOR : [chars]: AppleTalk neighbor down; lost contact with %a`

Explanation A peer router is unreachable.

Recommended Action No action is required.

`%AT-5-NOSUCHROUTE : No such route [dec]`

Explanation You specified a nonexistent route in a show appletalk route or clear appletalk route command.

Recommended Action Specify a valid route, that is, one that appears in the output of the show appletalk route command.

`%AT-5-NOTSUPPORTED : [chars]: AppleTalk node down; line protocol not supported`

Explanation An encapsulation method on the specified interface does not support AppleTalk.

Recommended Action No action is required.

%AT-5-OLDMCI : [chars]: AppleTalk route cache disabled; firmware is obsolete

Explanation The firmware on the MCI controller card does not support AppleTalk fast switching.

Recommended Action No corrective action is required. Normal AppleTalk operation continues, but the fast switching cache is disabled for the interface associated with the MCI card. If this message is unexpected, verify that the MCI firmware for the interface specified in the error message is at level 1.7 or higher.

%AT-5-PATHCHANGE : Route to %#A is now using path of type [chars] on [chars] via %#a

Explanation The path to a network changed because either the old path went down or the new path was better.

Recommended Action No action is required.

%AT-5-RTMPSTATE : [chars]: RTMP path to %#A via %#a now in [chars] state (metric [dec], [dec] hops)

Explanation The state of a path changed.

Recommended Action No action is required.

%AT-6-ACQUIREMODE : [chars]: AppleTalk interface initializing; acquiring [chars]

Explanation The interface is determining the correct configuration. This message is displayed when discovery mode is enabled and no other router is detected.

Recommended Action No action is required.

%AT-6-ADDRUSED : [chars]: AppleTalk node up; using address %A

Explanation No hint address or a bad hint address was specified. This message indicates which AppleTalk address will be used for the interface.

Recommended Action No action is required.

%AT-6-BADROUTE : Route to %#A has gone bad

Explanation The system did not detect a route within the required timeout period. Therefore, the route is marked as bad. A network might have become unreachable for some reason, perhaps because of a broken connection. This message does not necessarily indicate an error condition.

Recommended Action No action is required.

%AT-6-CONFIGOK : [chars]: AppleTalk interface enabled; verified by %#a

Explanation The AppleTalk configuration was verified by consulting the indicated router.

A

Recommended Action No action is required.

`%AT-6-DELRROUTE : AppleTalk network deleted; %#A removed from routing table`

Explanation A route on the AppleTalk network aged out.

Recommended Action No action is required.

`%AT-6-INTUP : [chars]: AppleTalk interface restarting; line protocol came up`

Explanation An AppleTalk interface that was previously shut down was restarted.

Recommended Action No action is required.

`%AT-6-MACIPDOWN : [chars]: MacIP server shutting down, [IP_address]`

Explanation If the appletalk event-logging command is configured, this message appears on the console when a MacIP server is no longer operational for any reason. MacIP servers shut down in response to MacIP configuration changes or errors, or a change in the condition or configuration of an AppleTalk or IP interface for which the MacIP server is providing service. The AppleTalk zone served by the MacIP server replaces the zone specified in the appletalk zone command. The IP address configured on the MacIP server replaces the IP address configured by the ip address command.

Recommended Action No action is required.

`%AT-6-MACIPUP : [chars]: MacIP server operational, [IP_address]`

Explanation If the appletalk event-logging command is configured, this message appears on the console when a MacIP server is fully initialized and is ready to accept client requests. The AppleTalk zone served by the MacIP server replaces the zone specified in the appletalk zone command. The IP address configured on the MacIP server replaces the IP address configured by the ip address command.

Recommended Action No action is required.

`%AT-6-NBRDELETED : Neighbor entry for %#a deleted`

Explanation The clear appletalk neighbor command displays this command when it completes successfully.

Recommended Action No action is required.

`%AT-6-NEIGHBORUP : [chars]: AppleTalk neighbor up; %#a has restarted`

Explanation A neighboring router to which this router previously lost connectivity reappeared on the network.

Recommended Action No action is required.

`%AT-6-NEWNEIGHBOR : [chars]: AppleTalk neighbor added; %#a is operational`

Explanation The router discovered a new AppleTalk router on the network.

A

Recommended Action No action is required.

```
%AT-6-NEWROUTE : [chars]: AppleTalk network added; %#A via %#a ([dec] hop [chars])
```

Explanation A new AppleTalk route was learned. The message indicates the source of the route and its distance in hops.

Recommended Action No action is required.

```
%AT-6-NEWZONE : AppleTalk zone added; zone %*s defined
```

Explanation A new AppleTalk zone was created.

Recommended Action No action is required.

```
%AT-6-NODEWRONG : [chars]: AppleTalk node %a misconfigured; reply has been broadcast
```

Explanation An AppleTalk node sent a GetNet Info request to this router specifying an invalid network number for the source of the GetNet Info request. This situation occurs when an AppleTalk end node is moved to another network and is therefore misconfigured for the current network.

Recommended Action No action is required.

```
%AT-6-NOPROXY : AppleTalk proxy deleted; zone [chars] freed network %#A
```

Explanation A previously configured Name Binding Protocol (NBP) proxy was deleted. The router can no longer convert NBP requests to a format understood by routers that support only the original AppleTalk specification.

Recommended Action No action is required.

```
%AT-6-ONLYROUTER : [chars]: AppleTalk interface enabled; no neighbors found
```

Explanation No other AppleTalk routers were found on the network attached to the interface.

Recommended Action No action is required.

```
%AT-6-PATHADD : [chars]: AppleTalk [chars] path to network %#A added; via %#a (metric [dec])
```

Explanation A new AppleTalk path has been learned. The message indicates the source of the path, its distance in hops, its metric, and the type of path.

Recommended Action No action is required.

```
%AT-6-PATHDEL : [chars]: AppleTalk [chars] path to %#A via %#a has been deleted
```

Explanation A path on the AppleTalk network aged out.

Recommended Action No action is required.

A

%AT-6-PATHNOTIFY : [chars]: AppleTalk [chars] path to %#A down; reported bad by %#a

Explanation A router went down somewhere on the AppleTalk network. The indicated peer notified this router of the change.

Recommended Action No action is required.

%AT-6-REGPENDING : NBP registration of [chars] at [[chars]] pending

Explanation A name registration call is being performed.

Recommended Action No action is required.

%AT-6-ROUTEDOWN : [chars]: AppleTalk network down; interface to %#A disabled

Explanation A connected route is being advertised as down (also known as notify neighbor) because the configured interface is no longer operational.

Recommended Action No action is required.

%AT-6-ROUTENOTIFY : [chars]: AppleTalk network down; %#A reported bad by %#a

Explanation A router went down somewhere on the AppleTalk network. The indicated peer notified this router of the change.

Recommended Action No action is required.

%AT-6-ROUTEOK : [chars]: AppleTalk network up; %#A via %#a ([dec] hop [chars])

Explanation A routing update was received for a previously suspect route.

Recommended Action No action is required.

%AT-6-ZONEGC : AppleTalk zone deleted; zone [chars] released

Explanation The router removed an unused zone from the zone table.

Recommended Action No action is required.

%AT-6-ZONEPROXY : AppleTalk proxy defined; zone [chars] using network %#A

Explanation This message reports the zone name and network number that are being advertised to support the appletalk nbp-proxy command.

Recommended Action When proxy service is initiated, this message is generated each time the appletalk nbp-proxy command is issued. LOG_STD_NO_ACTION

%AT-7-BUGREPORT : AppleTalk bug: [chars]

Explanation The software detected an unexpected condition. The router takes corrective action and continues.

A

Recommended Action Copy the message exactly as it appears, note any AppleTalk problems you experience, and call your technical support representative.

```
%AT-7-DEBUGMSG : AppleTalk debug: [chars]
```

Explanation This message is generated by a debug command and provides additional information about an AppleTalk condition.

Recommended Action Copy the message exactly as it appears, note any AppleTalk problems you experience, and call your technical support representative.

ATA

```
%ATA-3-ATA_STATUS_ERROR : Error occurred while querying the status of ATA device.  
Return: [dec], stat_reg: [hex]
```

Explanation An error occurred while querying the status of ATA device. Device not responding

Recommended Action Replace the new ATA device and retry the operation. If the problem persists, (1) Run 'show tech' command. (2) Enable file system operation logs using the following commands: (a) 'debug ifs file' (b) 'debug ifs fs' (c) 'debug ifs verbose' (3) Contact the TAC or engineering team with the output of the commands.

```
%ATA-6-ATA_STATUS_TIMEOUT : Timeout occurred while querying the status of ATA de-  
vice. Status returned :[hex], event: [dec]
```

Explanation A timeout occurred while querying the status of ATA device.

Recommended Action Replace the new ATA device and retry the operation. If the problem persists, (1) Run 'show tech' command. (2) Enable file system operation logs using the following commands: (a) 'debug ifs file' (b) 'debug ifs fs' (c) 'debug ifs verbose' (3) Contact the TAC or engineering team with the output of the commands.

ATMSIG

```
%ATMSIG-3-ATMSIG_CUG_DELETE_FAILED : ATMSIG([chars])
```

Explanation A software error occurred during removal of a member from a closed user group. Other error messages appearing immediately prior to this one may be related.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start> , or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%ATMSIG-3-ATMSIG_CUG_INSERT_FAILED : ATMSIG([chars])
```

Explanation A software error occurred during addition of a member to a closed user group. Other error messages appearing immediately prior to this one may be related.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start> , or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%ATMSIG-3-ATMSIG_LISTEN_FAILED_DUP : Duplicate LISTEN by [chars] for existing NSAP
[chars] owned by [chars]
```

Explanation An application attempted to either LISTEN on an NSAP owned by another application or to LISTEN for the same NSAP twice

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start> , or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%ATMSIG-3-ATMSIG_PRTY_DELETE_FAILED : ATMSIG([chars] [dec],[dec] -%04d/%02d) avl
prty del failed:svc [hex] party [hex]
```

Explanation A software error occurred during removal of a party from a point-to-multipoint call. Other error messages appearing immediately prior to this one may be related.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start> , or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%ATMSIG-3-ATMSIG_PRTY_INSERT_FAILED : ATMSIG([chars] [dec],[dec] -%04d/%02d) avl
prty ins failed:svc [hex] party [hex]
```

Explanation A software error occurred during addition of a party to a point-to-multipoint call. Other error messages appearing immediately prior to this one may be related.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start> , or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%ATMSIG-3-ATMSIG_SVC_DELETE_FAILED : ATMSIG([chars] [dec],[dec] -%04d/%02d) SVC wavl
del failed:svc [hex]
```

Explanation A software error occurred during closure of an SVC. Other error messages appearing immediately prior to this one may be related.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start> , or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%ATMSIG-3-ATMSIG_SVC_INSERT_FAILED : ATMSIG([chars] [dec],[dec] -%04d/%02d) SVC wavl
ins failed:svc [hex]
```

Explanation A software error occurred during creation of an SVC. Other error messages appearing immediately prior to this one may be related.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start> , or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%ATMSIG-3-DBINITFAIL : Signalling control block initialization failure, [chars]
```

Explanation An internal software or resource error occurred

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start> , or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%ATMSIG-3-ENQFAIL : process_enqueue failed, [chars]
```

Explanation An internal software error occurred while handling a user request.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start> , or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%ATMSIG-3-FAIL1STHALFLEG : 1st halfLeg failed, [chars]
```

Explanation An internal software error occurred.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start> , or contact your Cisco technical support representative and provide the representative with the gathered information.

%ATMSIG-3-FAIL2NDHALFLEG : 2nd halfLeg failed, [chars]

Explanation An internal software error occurred.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start> , or contact your Cisco technical support representative and provide the representative with the gathered information.

%ATMSIG-3-FAILASSERT : Assertion failed: [chars]

Explanation An internal software error occurred.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start> , or contact your Cisco technical support representative and provide the representative with the gathered information.

%ATMSIG-3-FAILHALFLEGREM : halfLeg removal failed, [chars]

Explanation An internal software error occurred. This message should only be displayed when verbose debugging is enabled for an SVC.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start> , or contact your Cisco technical support representative and provide the representative with the gathered information.

%ATMSIG-3-FAILXCONN : Xconnect failed, [chars]

Explanation An internal software error occurred during installation of an SVC cross-connect.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start> , or contact your Cisco technical support representative and provide

the representative with the gathered information.

%ATMSIG-3-INVPNNIMSG : Invalid msg from routing/pnni : [chars]

Explanation This message indicates an error in the PNNI routing subsystem. It could be caused by an internal software error or by bad control information received from peer equipment. The message will contain additional information that can help locate the cause. Any message with 'NULL' probably indicates a problem with this system, others probably point at the peer equipment.

Recommended Action Check this system and the peer equipment for any obvious errors. LOG_STD_RECUR_ACTION

%ATMSIG-3-NOCALLREF : Cannot find a Callref value to allocate: [chars]

Explanation This indicates an internal software error, probably including memory exhaustion.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start> , or contact your Cisco technical support representative and provide the representative with the gathered information.

%ATMSIG-3-NOSVC : no SVC, [chars]

Explanation An internal software error occurred.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start> , or contact your Cisco technical support representative and provide the representative with the gathered information.

%ATMSIG-3-PNNI_TRACE_INTERNAL : [chars]

Explanation An internal software error or unexpected condition occurred during PNNI (Connection/Path) Trace related processing

Recommended Action LOG_STD_SH_CMD_ACTION(show atm pnni trace information) Also gather information about where/how trace was initiated, and for what type of VC.

%ATMSIG-4-CONFIG_ERROR : Configuration Error: [chars] [chars]

Explanation This message indicates a configuration error in the ATM Signaling subsystem. The message will display more specific information about the problem location.

Recommended Action Change the configuration to correct the error.

A

ATMSPA

```
%ATMSPA-2-INITFAIL : [chars] -Init Failed return code: [int]
```

Explanation The SPA failed to complete hardware initialization. One of the devices in the SPA failed to initialize successfully. Information about the failed device is specified in the message text on the console or in the system log.

Recommended Action Please power down and reseal the indicated SPA card. If the condition persists, copy the error message exactly as it appears. Next research and attempt to resolve the issue using the SPA hardware troubleshooting documentation as well as the tools and utilities provided at <http://www.cisco.com/public/support/tac/tools.shtml>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start> or contact your Cisco technical support representative. Be sure to provide the the information you have gathered and a 'show tech-support' to your support representative, or attach it to your case in non-zipped, plain text format (.txt).

```
%ATMSPA-3-ATM_SPA_AUTOVC_FAIL : [chars]: atm autovc discovery configuration failed, reason: [chars]
```

Explanation A command to configure the atm autovc discovery on an atm interface has failed

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%ATMSPA-3-DATA_ERROR : [chars] Error [hex] [chars]
```

Explanation A datapath protocol violation or sequence error has been detected.

Recommended Action The message text on the console or in the system log provides more information on the specific nature of the error. LOG_STD_SH_TECH_ACTION

```
%ATMSPA-3-FATAL_ERROR : occurred on [chars]. Resetting SPA
```

Explanation The SPA has been reset due to a critical error in one of its devices. The error could either be a single occurrence of an event or multiple occurrences within a period of time. The message text on the console or in the system log provides more information on the specific nature of the error.

Recommended Action If the SPA is reset more than once, copy the error message exactly as it appears. Next research and attempt to resolve the issue using the SPA hardware troubleshooting documentation as well as the tools and utilities provided at <http://www.cisco.com/public/support/tac/tools.shtml>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start> or contact your Cisco technical support representative. Be sure to provide the the information you have gathered and a 'show tech-support' to your support representative, or attach it to your case in non-zipped, plain text format (.txt).

```
%ATMSPA-3-FPD_VER_DEPENDENCY_NOTE : Cannot perform the requested FPD update operation because [chars] in subslot [int]/[int] has incompatible HW version [int].[int] with FPD image version [dec].[dec] for FPD ID [dec]. Only image version greater than [int].[int] can be used in the update operation of [chars] with HW version greater than [int].[int].
```

Explanation The version of the FPD image from the FPD image bundle or package is not compatible with the HW version of the target card

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%ATMSPA-3-GEN_ERROR : [chars] Error [hex] [chars]
```

Explanation The specified error has been detected.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%ATMSPA-3-HW_ERROR : [chars] Error [hex] [chars]
```

Explanation The specified hardware error has been detected.

Recommended Action The message text on the console or in the system log provides more information on the specific nature of the error. LOG_STD_SH_TECH_ACTION

```
%ATMSPA-3-KEEPAALIVE_FAILURE : occurred on [chars]. Resetting SPA
```

Explanation One of the devices of the SPA failed to respond to keepalives due to which SPA has been reset. The message text on the console or in the system log provides more information on which device failed to respond.

Recommended Action If the SPA is reset more than once, copy the error message exactly as it appears. Next research and attempt to resolve the issue using the SPA hardware troubleshooting documentation as well as the tools and utilities provided at BUG_TOOLKIT. If you still require assistance, open a case with the Technical Assistance Center via the Internet at TAC_CASE_OPEN or contact your Cisco technical support representative. Be sure to provide the information you have gathered and show tech-support to your support representative, or attach it to your case

```
%ATMSPA-3-QOS_ALLOC_FAILED : [chars] [chars] [chars]: [dec]
```

Explanation Traffic shaping parameters could not be configured because the number of unique shaping parameters that are configured on the PVCs or PVPs in this specified ATM SPA is over the maximum limit. The maximum number of unique shaping parameters that can be configured on the PVCs or PVPs is 4096.

Recommended Action Ensure that the total number of unique shaping parameters that are configured on both PVCs and PVPs does not exceed the maximum limit of 4096.

```
%ATMSPA-3-SW_ERROR : [chars] Error [hex] [chars]
```

Explanation The specified software error has been detected.

A

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start> , or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%ATMSPA-3-VCQ_ERROR : [chars]: VC queue configuration failed due to un-initialized queue table (global identifier [dec])
```

Explanation Software configuration of a VC queue failed due to un-initialized queue table.

Recommended Action Attempt to perform a soft OIR operation by entering the command that is described in the shared port adapter software configuration guide. If the condition persists, copy the error message exactly as it appears, and report it to your technical support representative. Also supply a 'show tech-support' at that time.

```
%ATMSPA-4-SETUPVC : Interface [chars], VC ([dec]) setup failed, reason = [dec]
```

Explanation A command to setup a VC has failed on RP.

Recommended Action The SPA ATM driver has detected a problem creating the internal OAM VC. Reload the indicated SPA card to reconfigure the internal OAM VC. If the error messages persists, copy the error message exactly as it appears. Next research and attempt to resolve the issue using the SPA hardware troubleshooting documentation as well as the tools and utilities provided at <http://www.cisco.com/public/support/tac/tools.shtml>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start> or contact your Cisco technical support representative. Be sure to provide the the information you have gathered and a 'show tech-support' to your support representative, or attach it to your case in non-zipped, plain text format (.txt).

```
%ATMSPA-4-TEARDOWNVC : Interface [chars], VC ([dec]) teardown failed, reason = [dec]
```

Explanation A command to remove a VC config has failed on RP.

Recommended Action The SPA ATM driver has detected a problem tearing down the internal OAM VC. Reload the indicated SPA card to do a clean tear down of the internal OAM VC. If the error messages persists, copy the error message exactly as it appears. Next research and attempt to resolve the issue using the SPA hardware troubleshooting documentation as well as the tools and utilities provided at <http://www.cisco.com/public/support/tac/tools.shtml>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start> or contact your Cisco technical support representative. Be sure to provide the the information you have gathered and a 'show tech-support' to your support representative, or attach it to your case in non-zipped, plain text format (.txt).

```
%ATMSPA-4-VCSETUP : [chars]: VC setup command received on the LC for an existing VC (VCD [dec])
```

Explanation A command to set up a VC has been received for a VC that has already been set up. The VC has already been configured by a previous setup VC command from the RP. A duplicate setup command may indicate that the RP did not receive a response from the LC for the previous setup command.

Recommended Action No action is required.

A

%ATMSPA-4-VCTEARDOWN : [chars]: VC tear down command received on the LC for a non-existing VC (VCD [dec])

Explanation The VC does not exist on the LC. Most likely, it has been torn down by a previous teardown command from RP. A duplicate teardown command may indicate that the RP did not receive a response from the LC for the previous teardown command.

Recommended Action No action is required.

%ATMSPA-4-VPSETUP : [chars]: VP setup command received on the LC for an existing VP (VPI [dec])

Explanation A command to set up a VP has been received for a VP that has already been set up. The VP has already been configured by a previous setup VP command from the RP. A duplicate setup command may indicate that the RP did not receive a response from the LC for the previous setup command.

Recommended Action No action is required.

%ATMSPA-4-VPTEARDOWN : [chars]: VP tear down command received on the LC for a non-existing VP (VPI [dec])

Explanation The VP does not exist on the LC. Most likely, it has been torn down by a previous teardown command from RP. A duplicate teardown command may indicate that the RP did not receive a response from the LC for the previous teardown command.

Recommended Action No action is required.

ATMSSCOP

%ATMSSCOP-3-SSCOPERR : INIT SSCOP -Intf : [chars], Event : [chars], State : [chars].

Explanation A software error occurred in the ATM SSCOP subsystem.

Recommended Action LOG_STD_SH_CMD_ACTION

%ATMSSCOP-4-UNMATCHUNIVERSION : ([chars]): [chars]. Please verify peer UNI version

Explanation The ATM peer equipment appears to be running an old version of ATM UNI. Communication with it is not possible.

Recommended Action The ATM peer equipment may need attention. Please verify its UNI version is at least 3.1, and upgrade if necessary.

%ATMSSCOP-5-SSCOPINIT : -Intf : [chars], Event : [chars], State : [chars].

Explanation This message indicates a routine step of the ATM SSCOP initialization sequence.

Recommended Action LOG_STD_NO_ACTION

A

ATTN

`%ATTN-2-MBOX_REG_FAIL : return code [dec]`

Explanation Registration of handler function for mailbox event failed mailbox event failed.

Recommended Action LOG_STD_ACTION

`%ATTN-2-PROXY_INIT_FAIL_IPC_REG : return code [dec]`

Explanation Initialization of attention proxy failed due to error registering IPC handler function.

Recommended Action LOG_STD_ACTION

`%ATTN-3-PROXY_IPC_ALLOC_FAILED : [chars]`

Explanation Allocation of an IPC packet buffer by the attention proxy failed.

Recommended Action LOG_STD_ACTION

`%ATTN-3-PROXY_IPC_SEND_FAILED : [chars]`

Explanation Transmission of an IPC message by the attention proxy failed.

Recommended Action LOG_STD_ACTION

`%ATTN-3-PROXY_UNHANDLED_MSG : subtype [dec]`

Explanation Attention proxy received a message with an unknown subtype.

Recommended Action LOG_STD_ACTION

`%ATTN-3-SYNC_TIMEOUT : msec since last timeout [int], missing packets [dec]`

Explanation Attention sync command timed out.

Recommended Action LOG_STD_ACTION

AUTHMGR

`%AUTHMGR-0-CONFIG_CORRUPT : Checksummed interface configuration corruption detected.`

Explanation Interface configuration field was modified unexpectedly.

Recommended Action No action is required.

`%AUTHMGR-4-ILLEGAL_TRACE_REQ : Component ID [dec] not registered.`

Explanation Attempt to log a message with unregistered ID.

Recommended Action No action is required.

%AUTHMGR-4-UNAUTH_MOVE : [chars] MAC address ([enet]) from [chars] to [chars]

Explanation Move while not authenticated on old IDB

Recommended Action No action is required.

%AUTHMGR-5-FAIL : Authorization failed or unapplied for client ([enet]) on Interface [chars] AuditSessionID [chars]

Explanation Authorization was unsuccessful.

Recommended Action No action is required.

%AUTHMGR-5-MACMOVE : MAC address ([enet]) moved from Interface [chars] to Interface [chars] AuditSessionID [chars]

Explanation Client has moved to a new interface without logging off on the previous one.

Recommended Action No action is required.

%AUTHMGR-5-MACREPLACE : MAC address ([enet]) on Interface [chars] is replaced by MAC ([enet]) AuditSessionID [chars]

Explanation A new client has triggered a violation causing an existing client to be replaced

Recommended Action No action is required.

%AUTHMGR-5-SECURITY_VIOLATION : Security violation on the interface [chars], new MAC address ([enet]) is seen. AuditSessionID [chars]

Explanation A host on the specified interface is attempting to gain access into the network or is trying to authenticate in a host mode that does not support the number of hosts attached. This is treated as a security violation and the port has been error-disabled.

Recommended Action Ensure that the port is configured to support the number of hosts attached. Enter the **<cmd>shutdown</cmd>** command followed by **<cmd>no shutdown</cmd>** command to restart the port.

%AUTHMGR-5-START : Starting '[chars]' for client ([enet]) on Interface [chars] AuditSessionID [chars]

Explanation Starting an authentication method

Recommended Action No action is required.

%AUTHMGR-5-SUCCESS : Authorization succeeded for client ([enet]) on Interface [chars] AuditSessionID [chars]

A

Explanation Authorization was successful.

Recommended Action No action is required.

%AUTHMGR-5-VLANASSIGN : VLAN [dec] assigned to Interface [chars] AuditSessionID [chars]

Explanation VLAN assignment

Recommended Action No action is required.

%AUTHMGR-7-FAILOVER : Failing over from '[chars]' for client ([chars]) on Interface [chars] AuditSessionID [chars]

Explanation Failing over from the current authentication method

Recommended Action No action is required.

%AUTHMGR-7-NOMOREMETHODS : Exhausted all authentication methods for client ([chars]) on Interface [chars] AuditSessionID [chars]

Explanation All available authentication methods have been tried

Recommended Action No action is required.

%AUTHMGR-7-STOPPING : Stopping '[chars]' for client [enet] on Interface [chars] AuditSessionID [chars]

Explanation Stopping the current authentication method

Recommended Action No action is required.

AUTOSEC

%AUTOSEC-3-CONFSAVE_FAIL : Applying AutoSecure config to running-conf failed with error [dec]

Explanation Configuration of the AutoSecure session could not be applied to the running configuration

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

%AUTOSEC-5-ENABLED : AutoSecure is configured on the device

Explanation Security configuration of the device is done using AutoSecure.

A

Recommended Action Notification message only. No action required.

AUTO_UPGRADE

`%AUTO_UPGRADE-3-AUTO_ADVERTISE_SW_COM_BUNDLED : Switch [dec] running incompatible bundled software has been added to the stack. \Switch [dec] must be running compatible bundled software in order to join the stack.`

Explanation No explanation required.

Recommended Action Boot the member with compatible software.

`%AUTO_UPGRADE-3-AUTO_ADVERTISE_SW_FAILED_PLATFORM : Failed to determine platform hardware type of switch [dec]`

Explanation Somehow the platform type could not be determined.

Recommended Action Add an action

`%AUTO_UPGRADE-3-AUTO_ADVERTISE_SW_MODE_UNKNOWN : Switch [dec] has been added to the stack. Failed to initiate auto advertise \for switch [dec] because switch [dec] is not running installed or bundled software`

Explanation No explanation required.

Recommended Action Boot the member with compatible software.

`%AUTO_UPGRADE-3-AUTO_CONFIG_EXEC : Auto upgrade is enabled by config. Please disable auto upgrade configuration to execute auto upgrade manually using exec CLI.`

Explanation TODO: add an explanation.

Recommended Action TODO: add an action

`%AUTO_UPGRADE-3-AUTO_UPGRADE_FAILED_COPY : Failed to copy upgrade packages from switch [dec] to switch [dec].`

Explanation TODO: add an explanation.

Recommended Action TODO: add an action

`%AUTO_UPGRADE-3-AUTO_UPGRADE_FAILED_DISK : Switch [dec] doesn't have enough free disk space to perform auto upgrade. A minimum of [dec] KB of free disk space is required`

Explanation There might be older files because of which there is not enough memory.

A

Recommended Action Clean up disk space in the remote switch.

`%AUTO_UPGRADE-3-AUTO_UPGRADE_FAILED_EXPAND : Failed to install the running software on switch [dec]`

Explanation TODO: add an explanation.

Recommended Action No action required.

`%AUTO_UPGRADE-3-AUTO_UPGRADE_FAILED_MEM : Switch [dec] doesn't have enough free memory to perform auto upgrade. A minimum of [dec] KB of free memory is required`

Explanation There might be older files because of which there is not enough memory.

Recommended Action Clean up disk space in the remote switch.

`%AUTO_UPGRADE-3-AUTO_UPGRADE_FAILED_PLATFORM : Failed to determine platform hardware type of switch [dec]`

Explanation Somehow the platform type could not be determined.

Recommended Action Add an action

`%AUTO_UPGRADE-3-AUTO_UPGRADE_FAILED_STATE : A previous provisioning action is pending reboot. Please reboot the switch [dec].`

Explanation The user has run an operation that requires a reboot to take action.

Recommended Action Reload the switch

`%AUTO_UPGRADE-3-AUTO_UPGRADE_INTERNAL_ERROR : Stack manager did not publish local information`

Explanation Somehow the chassis number is missing.

Recommended Action Try to do it again.

`%AUTO_UPGRADE-3-AUTO_UPGRADE_MODE_UNKNOWN : Switch [dec] has been added to the stack. Failed to initiate auto upgrade for switch [dec] because switch [dec] is not running installed or bundled software`

Explanation No explanation required.

Recommended Action Boot the member with compatible software.

`%AUTO_UPGRADE-3-AUTO_UPGRADE_NOTHING_TO_UPGRADE : No incompatible switch is found, nothing to auto-upgrade.`

Explanation Exec autoupgrade scenario when there is no incompatible member in stack.

Recommended Action No action is required from the user

`%AUTO_UPGRADE-3-AUTO_UPGRADE_NOT_SUPPORTED` : The system is not running installed software. Auto upgrade for switch number [dec] cannot be initiated

Explanation A system with incompatible software has been detected in the stack. The auto upgrade functionality cannot be initiated because the stack is not running installed software. The user must manually upgrade the incompatible switch.

Recommended Action Expand the super package to /flash. Boot the package from the flash using 'boot flash:packages.conf'

`%AUTO_UPGRADE-3-AUTO_UPGRADE_PLATMISMATCH` : No software was found to upgrade switch [dec]

Explanation Happens because of incompatible switches. For example, ngwc and non-ngwc ones are incompatible

Recommended Action Plugin compatible switches for autoupgrade to run.

`%AUTO_UPGRADE-3-AUTO_UPGRADE_ROMMON` : Failed to set boot var on switch [dec]. Please use the 'reload' command to reload the switch and then manually set the BOOT rommon var to [chars].

Explanation TODO: add an explanation.

Recommended Action NO action is required.

`%AUTO_UPGRADE-3-SMU_SYNC_FAILED` : SMU upgrade failed on switch [dec]. Auto upgrade of image will pass with out syncing SMUs on this switch. SMUs will be synced at boot time of the switch [dec]

Explanation SMU sync failed because of some reason.

Recommended Action No action required, SMU sync will be tried in next reload.

`%AUTO_UPGRADE-3-SMU_UPGRADE_FAILED_DISK` : Switch [dec] doesn't have enough free disk space to sync SMU. A minimum of [dec] KB of free disk space is required. Auto upgrade will pass with out syncing SMUs on this switch

Explanation There might be older files because of which there is not enough memory.

Recommended Action Clean up disk space in the remote switch.

`%AUTO_UPGRADE-5-AUTO_ADVISE_SW_BUNDLED` : Switch [dec] running installed software has been added to the stack.\Switch [dec] must be running bundled software in order to join the stack.

Explanation No explanation required.

A

Recommended Action Boot the member with compatible software.

%AUTO_UPGRADE-5-AUTO_ADVICE_SW_CONV : Switch [dec] running bundled software has been added to the stack that is running installed software.\The 'request platform software package install autoupgrade' command can be used to convert switch [dec] to the installed running mode by \installing its running software.

Explanation No explanation required.

Recommended Action No specific action required.

%AUTO_UPGRADE-5-AUTO_ADVICE_SW_FOUND : Found donor switch [dec] to auto upgrade switch [dec].

Explanation Just an init message.

Recommended Action No action is required.

%AUTO_UPGRADE-5-AUTO_ADVICE_SW_INITIATED : Auto advise initiated for switch [dec].

Explanation A system with incompatible software has been detected in the stack. The stack will now determine whether or not \software is available to be copied to the incompatible system, and if so, advise the user how to copy it. \Otherwise, the system will merely let the user know that the software on the stack needs to be updated.

Recommended Action No action is required.

%AUTO_UPGRADE-5-AUTO_ADVICE_SW_MSG : Switch [dec] with incompatible software has been added to the stack. \all stack members were scanned and it has been determined that the\ 'request platform software package install autoupgrade' command can be used \to install compatible software on switch [dec].

Explanation TODO: add an explanation.

Recommended Action TODO: add an action

%AUTO_UPGRADE-5-AUTO_ADVICE_SW_SEARCH : Searching stack for software to upgrade switch [dec].

Explanation Just an init message.

Recommended Action No action is required.

%AUTO_UPGRADE-5-AUTO_ADVICE_SW_START : Upgrading switch [dec] with software from switch [dec].

Explanation Just an init message.

Recommended Action No action is required.

%AUTO_UPGRADE-5-AUTO_UPGRADE_CONV : Converting switch [dec] to installed mode by installing its running software.

Explanation This needs to be converted as part of the auto upgrade.

Recommended Action No action is required.

%AUTO_UPGRADE-5-AUTO_UPGRADE_FINISH : Finished installing software on switch [dec].

Explanation TODO: add an explanation.

Recommended Action TODO: add an action

%AUTO_UPGRADE-5-AUTO_UPGRADE_FOUND : Found donor switch [dec] to auto upgrade switch [dec].

Explanation Just an init message.

Recommended Action No action is required.

%AUTO_UPGRADE-5-AUTO_UPGRADE_INITIATED : Auto upgrade initiated for switch [dec].

Explanation A system with incompatible software has been detected in the stack. The stack will first attempt to download \software from a previously-configured location, and install it to make the system compatible. If this is not successful, the stack will then determine whether \running software on another stack member is available to be copied to the incompatible system, and \whether or not it is appropriate to copy the software automatically

Recommended Action No action is required.

%AUTO_UPGRADE-5-AUTO_UPGRADE_INSTALLED : Finished installing the running software on switch [dec].

Explanation TODO: add an explanation.

Recommended Action TODO: add an action

%AUTO_UPGRADE-5-AUTO_UPGRADE_RELOAD : Reloading switch [dec] to complete the auto upgrade.

Explanation Part of autoupgrade

Recommended Action Just wait until the reload completes.

%AUTO_UPGRADE-5-AUTO_UPGRADE_RELOAD_INSTALLED : Reloading switch [dec] to boot in installed mode.

Explanation TODO: add an explanation.

Recommended Action TODO: add an action

A

`%AUTO_UPGRADE-5-AUTO_UPGRADE_SEARCH : Searching stack for software to upgrade switch [dec].`

Explanation Just an init message.

Recommended Action No action is required.

`%AUTO_UPGRADE-5-AUTO_UPGRADE_START : Upgrading switch [dec] with software from switch [dec].`

Explanation Just an init message.

Recommended Action No action is required.

AUTO_UPGRADE_MODULAR

`%AUTO_UPGRADE_MODULAR-3-AUTO_ERR_SMU_SYNC_FAILED : Failed to sync SMUs to standby. Make sure that SMU files are present on active and there is space enough to copy SMUs on standby.`

Explanation SMU sync failed. Most probable cause are the smu files may have been removed from the active switch using IOS/linux commands. Another reason is there is no space enough to copy the files to the standby

Recommended Action If the files are removed from the active bring it back to same location. Make sure there is enough space to copy the files on the standby

`%AUTO_UPGRADE_MODULAR-3-AUTO_NOTICE_RUN_CORRECTION_FAILED : Failed to correct the SMU mismatch between the running version on active and standby. Pls abort the smu installation using 'install abort'`

Explanation The system tried to recover from the mismatch, but failed. Engineer intervention is required

Recommended Action Get the 'show install log' and the btrace logs from active and standby

`%AUTO_UPGRADE_MODULAR-5-AUTO_ADVISE_SW_MISMATCH : Active and standby are running different versions, SMUs will not be synced.`

Explanation No explanation required.

Recommended Action Boot the member with same software.

`%AUTO_UPGRADE_MODULAR-5-AUTO_NOTICE_RUN_MISMATCH_STBY_RELOAD : Mismatch between running version of SMUs. Trying to recover. Standby will reload`

Explanation There is a mismatch on the running version. This will happen when the standby reloads after activate/deactivate and before commit. The machine will try to correct it. One reload is required for correcting the changes.

Recommended Action No action required.

B

```
%AUTO_UPGRADE_MODULAR-5-AUTO_NOTICE_STBY_RELOAD : Installing SMUs on standby.
Standby will reload
```

Explanation No explanation required.

Recommended Action No action required.

B

BFD_HA

```
%BFD_HA-2-CF : [chars] [dec]
```

Explanation CF related error

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%BFD_HA-2-ET : [chars] [dec]
```

Explanation Enhanced-timer error

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%BFD_HA-2-RESOURCE : [chars]
```

Explanation System resource error occurred

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

BFD_ISSU

```
%BFD_ISSU-2-GET_BUFFER : BFD ISSU client failed to get buffer for message. Error:
[dec] ([chars])
```

B

Explanation The BFD ISSU client failed to get buffer space for building a negotiation message. A negotiation message cannot be sent to the standby device. If a problem occurs with the ISSU session negotiation, the standby device cannot be brought up properly.

Recommended Action LOG_STD_SH_CMD_ACTION(show logging and show checkpoint client)

```
%BFD_ISSU-2-INIT : BFD ISSU client initialization failed to [chars]. Error: [dec] ([chars])
```

Explanation The BFD ISSU client could not be initialized. This initialization failure must be addressed before in-service software upgrade or downgrade can be performed successfully. If you do not address this failure, there will be downtime during software upgrade or downgrade.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%BFD_ISSU-2-SEND_NEGO_FAILED : BFD ISSU client failed to send negotiation message. Error: [dec] ([chars])
```

Explanation The BFD ISSU client failed to send a session negotiation message to the peer device. If a problem occurs with the ISSU session negotiation, the standby device cannot be brought up properly.

Recommended Action LOG_STD_SH_CMD_ACTION(show logging and show checkpoint client)

```
%BFD_ISSU-2-SESSION_NEGO : BFD ISSU client encountered unexpected client nego_done. Error: [dec] ([chars])
```

Explanation An ISSU-compliant client transitions through a series of internal states. The BFD ISSU client encountered a 'client negotiation done' state that was unexpected. If a problem occurs with the ISSU session negotiation, the standby device cannot be brought up properly.

Recommended Action LOG_STD_SH_CMD_ACTION(show issu session <client_id> and show issu negotiated capability <session_id>)

```
%BFD_ISSU-2-SESSION_REGISTRY : BFD ISSU client failed to register session information. Error: [dec] ([chars])
```

Explanation The BFD ISSU client failed to register session information. If a problem occurs with the ISSU session registration, the standby device cannot be brought up properly.

Recommended Action LOG_STD_SH_CMD_ACTION(show issu capability entries <client_id> and show issu session <client_id> and show issu negotiated capability <session_id>)

```
%BFD_ISSU-3-INVALID_SESSION : BFD ISSU client does not have a valid registered session.
```

Explanation The BFD ISSU client does not have a valid registered session.

Recommended Action LOG_STD_SH_CMD_ACTION(show issu capability entries <client_id> and show issu session <client_id> and show issu negotiated capability <session_id>)

```
%BFD_ISSU-3-MSG_SIZE : BFD ISSU client failed to get the MTU for Message Type [dec].
Error: [dec] ([chars])
```

Explanation The BFD ISSU client failed to calculate the MTU for the specified message. The BFD ISSU client is not able to send the message to the standby device.

Recommended Action LOG_STD_SH_CMD_ACTION(show issu message group <client_id> and show issu session <client_id> and show issu negotiated version <session_id>)

```
%BFD_ISSU-3-SESSION_UNREGISTRY : BFD ISSU client failed to unregister session infor-
mation. Error: [dec] ([chars])
```

Explanation The BFD ISSU client failed to unregister session information.

Recommended Action LOG_STD_SH_CMD_ACTION(show issu session <client_id> and show issu negotiated capability <session_id>)

```
%BFD_ISSU-3-TRANSFORM_FAIL : bfd ISSU client [chars] transform failed for message
[dec]'. Error: [dec] ([chars])
```

Explanation The BFD ISSU client could not transform the specified message type. If the transmit transformation failed, the checkpoint message was not sent to the standby device. If the receive transformation failed, the checkpoint message was not applied on the standby device. In both cases, the BFD state between the active device and the standby device is not identical.

Recommended Action LOG_STD_SH_CMD_ACTION(show issu session <client_id> and show issu negotiated version <session_id>)

BFD_OFFLOAD

```
%BFD_OFFLOAD-3-ALLOC_FAILED : Allocation of [chars] memory failed for BFD Offload
feature in QFP
```

Explanation Allocation of memory by the QFP BFD Offload feature microcode failed. The name of the memory chunk is specified in the message. This indicates a software failure

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%BFD_OFFLOAD-3-HA_BULK_SYNC_FAIL : rg [dec], MSGDEF_LIMIT_MEDIUM
```

Explanation There was a failure such that BFD Offload domain bulk sync did not occur

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%BFD_OFFLOAD-3-HA_INVALID_STATE : state [dec], MSGDEF_LIMIT_MEDIUM
```

Explanation An invalid HA state was received from the HA infrastructure.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%BFD_OFFLOAD-3-INIT_FAILED : Initialization of the BFD Offload feature in QFP failed
```

Explanation Initialization of the BFD Offload feature in the QFP failed. This indicates a software failure.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%BFD_OFFLOAD-3-PKT_REPLICA_INIT_FAILED : Failed to register with generic packet replication for BFD Offload feature in QFP
```

Explanation BFD Offload initialization of packet replication registration failed.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

BFD_PROXY

```
%BFD_PROXY-2-PROXY_IPC_INIT_FAILED : QFP BFD Proxy IPC interface initialization failure (result: [dec]).
```

Explanation Cisco internal software error. QFP BFD Proxy initialization detected that the IPC interface initialization failed. QFP BFD proxy will not be functional while this condition exists.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and

provide the representative with the gathered information.

```
%BFD_PROXY-3-BFD_MEM_EXTEND_FAILED : BFD IPC subtype: [dec]
```

Explanation Extending memory failed.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%BFD_PROXY-3-BFD_MEM_REQ_FAILED : BFD IPC subtype: [dec]
```

Explanation Requesting more memory failed.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%BFD_PROXY-3-PROXY_BAD_MSG : QFP BFD Proxy received bad length message type [dec]
```

Explanation Cisco internal software error. QFP BFD Proxy received a corrupted message from control plane. This message will be ignored.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%BFD_PROXY-3-PROXY_IPC_ALLOC_FAILED : QFP BFD Proxy [chars] message lost due to mes-  
sage buffer allocation failure.
```

Explanation Cisco internal software error. QFP BFD Proxy message processing detected a message buffer allocation failure. The message is lost as the result of this condition.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%BFD_PROXY-3-PROXY_IPC_SEND_FAILED : QFP BFD Proxy [chars] message lost due to mes-  
sage sent failure (result: [dec]).
```

Explanation Cisco internal software error. QFP BFD Proxy message processing detected a message sent failure. The message is lost as the result of this condition.

B

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%BFD_PROXY-4-PROXY_INVALID_MSG : QFP BFD Proxy received invalid message type [dec]
```

Explanation Cisco internal software error. QFP BFD Proxy received an invalid message from control plane. This message will be ignored.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

```
%BFD_PROXY-4-PROXY_INVALID_MSG_LEN : QFP BFD Proxy IPC invalid length, [dec]:[dec]  
len [dec] flags [hex] source [dec]
```

Explanation Cisco internal software error. QFP BFD Proxy received invalid IPC message length from control plane. This message will be ignored.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Research and attempt to resolve the error using the tools at <https://cway.cisco.com/go/sa/>. Also perform a search using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

BINOS_LOGIN

```
%BINOS_LOGIN-3-AUTHERR : The authentication process failed, [chars]
```

Explanation This error occurs when there is an error in the system that prevents the user from being successfully authenticated

Recommended Action No action is required.

```
%BINOS_LOGIN-3-NOTROOT : login attempted to run without proper credentials.
```

Explanation login can not be run without proper credentials.

Recommended Action No action is required.

```
%BINOS_LOGIN-3-NOTTY : login attempted but stdin is not a tty
```

Explanation login can not be run without stdin set to tty

Recommended Action No action is required.

B

`%BINOS_LOGIN-3-PAMERR : PAM error [chars] encountered.`

Explanation The system encountered a PAM error.

Recommended Action No action is required.

`%BINOS_LOGIN-3-PWNOENT : No entry for user [chars] in passwd file`

Explanation The username/password authenticated correctly, but the user's environment could not be established because the user's environment data is missing.

Recommended Action No action is required.

`%BINOS_LOGIN-6-PAMAUTHDENY : User was not authenticated`

Explanation User was not authenticated

Recommended Action No action is required.

`%BINOS_LOGIN-6-PAMMAXTRIES : Maximum number of retries exceeded.`

Explanation The user tried and failed too many times to login.

Recommended Action No action is required.

BIPC

`%BIPC-3-BIPC_PERFORMANCE : buffer size request [int] failed`

Explanation An internal buffer allocation has failed.

Recommended Action No action is required. If the problem persists, or router performance is noticeably degraded, contact Cisco technical support. Copy the message exactly as it appears on the console or in the system log. Research and attempt to resolve the issue using the tools and utilities provided at <http://www.cisco.com/c/en/us/support/index.html>. With some messages, these tools and utilities will supply clarifying information. Search for resolved software issues using the Bug Search Tool: <https://bst.cloudapps.cisco.com/bugsearch/>. If you still require assistance, open a case with the Technical Assistance Center: <https://mycase.cloudapps.cisco.com/start>, or contact your Cisco technical support representative and provide the representative with the gathered information.

BIPCMGR

`%BIPCMGR-3-INVALID_TDL_ERROR_ON_MARSHAL : TDL epoch error on marshal [dec] unexpected: [chars]`

Explanation The bipc manager has attempt to marshal a message to be sent. The tdl library has generated an error on marshal that is unexpected. The message was not sent.