

EG25-G-GC Release Notes

LTE Standard Module Series

Rev. EG25-G-GC_Firmware_Release_Notes_V0702_30.203.30.203

Date: 2024-10-29



Our aim is to provide customers with timely and comprehensive service. For any assistance, please contact our company headquarters:

Quectel Wireless Solutions Co., Ltd.

Building 5, Shanghai Business Park Phase III (Area B), No.1016 Tianlin Road, Minhang District, Shanghai 200233, China

Tel: +86 21 5108 6236

Email: info@quectel.com

Or our local office. For more information, please visit:

<http://www.quectel.com/support/sales.htm>.

For technical support, or to report documentation errors, please visit:

<http://www.quectel.com/support/technical.htm>

Or email to support@quectel.com.

Disclaimer

While Quectel has made efforts to assure the accuracy of this document, unless otherwise provided by valid agreement, Quectel assumes no liability resulting from any inaccuracies or omissions in this document, or from use of the information obtained herein. Quectel reserves the right to make changes to any contents described herein and reserves the right to revise this document and to make changes from time to time in content hereof with no obligation to notify any person of revisions or changes. Before using any updated software, please read this statement carefully. By accessing or using the said software you irrevocably and unconditionally accept and confirm that you agree to be bound by this statement. In the event you disagree with any provision hereof and would not like to be bound by this statement you shall cease use of the said software immediately.

Duty of Confidentiality

The Receiving Party shall keep confidential all documentation and information provided by Quectel, except when the specific permission has been granted by Quectel. The Receiving Party shall not access or use Quectel's documentation and information for any purpose except as expressly provided herein. Furthermore, the Receiving Party shall not disclose any of the Quectel's documentation and information to any third party without the prior written consent by Quectel. For any noncompliance to the above requirements, unauthorized use, or other illegal or malicious use of the documentation and information, Quectel will reserve the right to take legal action.

Copyright

The information contained here is proprietary technical information of Quectel. Transmitting, reproducing, disseminating and editing this document as well as using the content without permission are forbidden. Offenders will be held liable for payment of damages. All rights are reserved in the event of a patent grant or registration of a utility model or design.

Copyright © Quectel Wireless Solutions Co., Ltd. 2024. All rights reserved.

1. Preamble

This document provides the Release Notes for EG25-G-GC firmware version **EG25GGCR07A02M1G** (Configuration version **30.203.30.203**). It describes major changes compared to EG25-G-GC firmware version **EG25GGCR07A02M1G** (Configuration version **30.202.30.202**).

2. Matters Needing Attention

SN	Brief Description
[1]	Multiple PDN is not supported by MBIM.
[2]	The new firmware version cannot be downgraded to versions released before EG25GGCR07A02M1G_30.200.30.200 , otherwise the module will not be able to work normally.
[3]	To extend the service life of flash, it is recommended that the total number of operations related to powering on/off the module, CFUN switching, SIM card hot swapping, dual-SIM switching, or repeated execution of NVM commands should not exceed 30 times per day.
[4]	It is not recommended to directly modify the pre-set APN profiles. Please create an APN profile after the existed CID number. Suppose you modify the APN profile of IMS, SOS, etc. with added specific attributes, these attributes are hidden after modification, causing the profile to still be unavailable.
[5]	AT+QGDCNT=1 and AT+QDPGDCNT=1 will write data to the flash. Therefore, please do not execute the AT commands frequently. AT+QAUGDCNT is used in conjunction with the above commands to automatically save the packet data counter. 1. If there are no mandatory needs, it is not recommended to use these AT commands; 2. The time interval set by the timer needs to be lengthened when you use these AT commands.
[6]	Cross-baseline software version update is not supported. For EG25GGCR07A02M1G , "R07" represents the baseline information. This Quectel module does not support updating to a firmware version other than R07. If you have any related requirements, please contact Quectel Technical Support.
[7]	During the FOTA upgrade process, it is necessary to ensure the stable power supply of the module. If the power is disconnected during the upgrade, there is a small probability that the flash will be damaged.
[8]	The current firmware version supports Secure Debugging. Secure Debugging is disabled by default, and you can enable it with AT commands as required.

3. New Features

Item/Category	Brief Description	Since
AUDIO	Added AT+QCFG="frhrcodec" to control the EFR/HR/FR voice coding method of GSM.	R07A02_30.2 03.30.203
DFOTA	Added AT+QFOTADL=<URL>,1 to support downloading the delta package through HTTPS without skipping certificate verification in FOTA.	R07A02_30.2 03.30.203
NETWORK	Added the new segment 46024 of China Mobile to match China Mobile correctly.	R07A02_30.2 03.30.203
Security	Added Secure Debugging.	R07A02_30.2 03.30.203
GENERAL	Added AT+QLEDFUNC to set or query the NET_STATUS and STATUS pins.	R07A02_30.2 03.30.203
GENERAL	Supported secure login base on RSA.	R07A02_30.2 03.30.203
GENERAL	Supported AT+QLWWANCID=<cid> to set the default dial APN in ECM or RNDIS modes.	R07A02_30.2 03.30.203
GENERAL	1. Added AT+QWWANINFO to query IP, gateway, subnet mask and DNS of dialing; 2. Added AT+QNETIFMAC to query the MAC of network card.	R07A02_30.2 03.30.203
GENERAL	Added AT+QVOLTEDTMFDET to control the in-band DTMF detection.	R07A02_30.2 03.30.203
GENERAL	Supported setting AT+QCFG= "hplmn/search_timer",0 to turn off the LPLMN search timer.	R07A02_30.2 03.30.203
GENERAL	Added AT+QNALSN to query or set network access license serial number of the module.	R07A02_30.2 03.30.203
HTTP	Added AT+QHTTPHEAD to get the head of data package.	R07A02_30.2 02.30.202
GENERAL	Supported AT+QAUDCFG= "alc5616e/dlgain" to adjust the downlink gain for 5616e codec.	R07A02_30.2 02.30.202
GENERAL	Added AT+QMTUINFO to get the MTU value issued by the network.	R07A02_30.2 02.30.202
GENERAL	Added AT+QSIMCFG="eid" to get the EID of M2M ESIM.	R07A02_30.2 02.30.202
GENERAL	Disabled eDRX in ATTACH and TAU message when RRC SIB did not support eDRX.	R07A02_30.2 02.30.202
MMS	Added AT+QMMSCFG="user_agent" and AT+QMMSCFG="x_wap_profile" to configure User-Agent and x-wap-profile respectively.	R07A02_30.2 01.30.201
GENERAL	Added AT+QLBSCFG="withaccuracy" to control whether to display accuracy information.	R07A02_30.2 01.30.201

GENERAL	Added AT+QLWWANURCCFG to enable WWAN URC reporting, and the configuration was still valid after rebooting.	R07A02_30.2 01.30.201
GENERAL	Added AT+QGPSCFG="estimation_error" to query the estimated error of GPS positioning.	R07A02_30.2 01.30.201
GENERAL	Added the DTLS resumption features: 1. Added AT+QSSLRESUMESAVE to configure the opening and closing of the session storage feature. 2. Added the feature of automatically saving the session when closed the session and automatically loading the session when started up.	R07A02_30.2 01.30.201
NETWORK	Relevant technical controls have been carried out to restrict normal network registration in regions such as RUS and IRN, thus ensuring that the module can be used only for civilian applications.	R07A02_30.2 00.30.200
GENERAL	Added AT+QCFG="call_profile" to set profiles used by ql_manager.	R07A02_30.2 00.30.200
GENERAL	Added AT+QMAP="LANIP" to query or set the default DHCP address pool for LAN interface.	R07A02_30.2 00.30.200
GENERAL	The new firmware version cannot be downgraded to previous versions, otherwise the module will not be able to work normally.	R07A02_30.2 00.30.200
DFOTA	Added AT command AT+QFOTATIMECFG to set DFOTA expiration time.	R07A02_30.0 02.30.002
DTMF	Added AT+QAUDCFG="voltedtmfcfg" to configure local playback time and interval time of VoLTE DTMF.	R07A02_30.0 02.30.002
FILE	Added AT+QFMov command to support moving a file.	R07A02_30.0 02.30.002
NETWORK	Added AT+QNwCFG="rej_cause_7_mapping" command to control whether to map the network rejection reason value #7.	R07A02_30.0 02.30.002
SIMCARD	Added AT command AT+QSIMCFG="disable_physim" to enable or disable SIM card.	R07A02_30.0 02.30.002
TCP SSL	Added AT+QSSLCFG="ignorecertitem" to solve the problem of SSL disconnection.	R07A02_30.0 02.30.002
GENERAL	Supported T-Mobile SIM card (311-882).	R07A02_30.0 02.30.002
GENERAL	Enabled xlat feature on T-Mobile MBN.	R07A02_30.0 02.30.002
GENERAL	Extended AT+QCFG="ledmode" command: When <mode>=3, the NET_STATUS light outputs a high level when SIM card is not inserted or registered, and the NET_STATUS light is expected to flash in the network state.	R07A02_30.0 02.30.002
GENERAL	Added AT+QUICKSHUTDOWN command to set the fast shutdown.	R07A02_30.0 02.30.002
GENERAL	Added AT+QCFG="gatewayset" and AT+QCFG="netmaskset" to set gateway address and subnet mask.	R07A02_30.0 02.30.002

DTMF	Added AT+QDTMFDETSET to configure the DTMF detection parameter of ACDB.	R07A02_30.0 02.30.002
GENERAL	Sent URC +QODM: "DME",0,APN PROFILE 3,apnname to notify the host of 3rd APNs changes of Verizon OMADM.	R07A02_30.0 02.30.002
GENERAL	Enable SMSoIP feature capability.	R07A02_30.0 02.30.002
GENERAL	Added AT+QCPUSN command to query CPU serial number.	R07A02_30.0 02.30.002
AUDIO	Extended the AT command AT+QCFG="tone/incoming" to support playing the specified ringtone when a call came in.	R07A02_30.0 01.30.001
AUDIO	Added AT+QDAI command to support digital audio interface configuration.	R07A02_30.0 01.30.001
DFOTA	Added AT command AT+QFOTADL=<url>,"down_to_ufs" to download the FTP file to local UFS directory.	R07A02_30.0 01.30.001
MMS	Added AT command AT+QCFG="mms_rec_control" to control whether to save the received MMS.	R07A02_30.0 01.30.001
MQTT	Added AT command AT+QMTCFG="protocol/check" to configure whether to check MQTT header information.	R07A02_30.0 01.30.001
NETWORK	Added AT command AT+QCFG="cops_control" to control AT+COPS to scan band, not affecting the band scan of AT+QCFG="nwscanmodeex" .	R07A02_30.0 01.30.001
TCP/UDP	Added the AT command AT+QCFG="TCP/SendMode" to configure TCP sending mode.	R07A02_30.0 01.30.001
Voice Call	Added DSCI report in emergency call.	R07A02_30.0 01.30.001
UAC	Supported 16K sampling rate by UAC.	R07A02_30.0 01.30.001
GENERAL	Supported outputting \$PQXMI NMEA sentences, and not outputting \$PQXMI sentences by default.	R07A02_30.0 01.30.001
GENERAL	Added AT+QCFG="usbauto" command to control USB network card to automatically adapt to Windows, Linux, macOS without a driver.	R07A02_30.0 01.30.001
GENERAL	Added AT command AT+QFORMATUSRDATA to format usrdata ubi.	R07A02_30.0 01.30.001
GENERAL	Added AT command AT+QCFG="secbootstat" to get whether the secboot is enabled.	R07A02_30.0 01.30.001
GENERAL	Supported Hong Kong Telecom SIM card, with ICCID 8985231 and PLMN 45431.	R07A02_30.0 01.30.001
GENERAL	1. Under Verizon, supported sending UPDATE message after the module powered down or AT+CFUN=1,1 was executed. 2. Added AT+QLWCFG="lwm2m_enable" to enable and disable LwWM2M for specific operators.	R07A02_30.0 01.30.001
GENERAL	Supported China Mobile, China Unicom, China Telecom, Reliance, TF_Spain_VoLTE/TF_Germany_VoLTE, Telstra, KDDI, DCM, SKT, KT and LGU MBNs.	R07A01_01.0 02.01.002

GENERAL	Supported to report all URC via command AT+QURCCFG="urcport","all" .	R07A01_01.0 02.01.002
GENERAL	Supported socket data forward and added related AT commands: AT+QFWDCLIENT , AT+QFWDSENDER , AT+QFWDRECV , AT+QFWDSEND and AT+QFWDRECV .	R07A01_01.0 02.01.002
DTMF	Added AT command AT+QVTS to send a DTMF tone.	R07A01_01.0 02.01.002
PPP	Solved the problem that setting PPP to IPV4V6 could dial but could not access the Internet under 3GPP network.	R07A01_01.0 02.01.002
NETWORK	Added AT command AT+QDISABLERETRY to cancel attaching request within 12 minutes when the value of attaching request is 19.	R07A01_01.0 02.01.002
DFOTA	Added HTTP DFOTA to parse URL with type of http://user:password@www.baidu.com.	R07A01_01.0 02.01.002
GENERAL	Added AT command AT+QCFG="fast/poweroff" to control whether to power off the module quickly.	R07A01_01.0 02.01.002
GENERAL	Added AT command AT+QCFG="goos" to optimize the power consumption of network search in sleep mode.	R07A01_01.0 02.01.002
SMS	Added AT+QCFG="sms_control" to control SMS sending and reception.	R07A01_01.0 02.01.002
Voice Call	Added AT+QCFG="call_control" command to control voice MO and MT functions.	R07A01_01.0 02.01.002
TCP SSL	Added AT command AT+QSSLRECV to read the remaining data.	R07A01_01.0 02.01.002
GENERAL	Supported to report URC to MCU when thermal mitigate level was up to 3.	R07A01_01.0 02.01.002
NETWORK	Added AT command AT+QEGPAPN to query the actual APN and the configured APN.	R07A01_01.0 02.01.002
GENERAL	Added AT+QFWDRCFG="urc_with_len" to control the reporting format and behavior of AT+QFWDRCFG="urc" .	R07A01_01.0 02.01.002
GENERAL	Added AT command AT+QLBSEX to enter the cell parameter for positioning.	R07A01_01.0 02.01.002
MBIM	Added MBIM function.	R07A01_01.0 02.01.002
NETWORK	Added the function of preferential registration to the network for the specified LTE band.	R07A01_01.0 02.01.002
Voice Call	Added AT command AT+QCFG="voice_busytone" to enable/disable busy tone playback for Verizon network.	R07A01_01.0 02.01.002
GENERAL	Added class 6 APN for Verizon.	R07A01_01.0 02.01.002
TCP SSL	Added AT command AT+QSSLCFG="alpn" to set SSL alpn.	R07A01_01.0 02.01.002
GENERAL	Added AT command AT+QCFG="wakepin/level" to set the wake-up pin level and whether to enable the wake-up function.	R07A01_01.0 02.01.002

TCP SSL	Added AT+QSSLCFG="session_cache" command to configure whether to enable session reuse for SSL.	R07A01_01.0 02.01.002
TCP SSL	Added AT command AT+QSSLCFG="renegotiation" to enable/disable renegotiation function.	R07A01_01.0 02.01.002
AUDIO	Supported recording and playing audio in AMR format.	R07A01_01.0 02.01.002
GENERAL	Added AT command AT+QOPS to scan full frequency and display a list of network information of all available operators in the current physical location.	R07A01_01.0 02.01.002
MMS	Added AT command AT+QMMSCFG="maxpktlen" to support setting MMS sending length.	R07A01_01.0 02.01.002
SIMCARD	Added AT command AT+QSIMCHK to send UIM_AUTHENTICATE_REQ (UIM authentication).	R07A01_01.0 02.01.002
SIMCARD	Added AT commands AT+QSIMWRFREQ to record the frequency of EF files written to SIM card and AT+QSIMVOL to configure SIM card supply voltage.	R07A01_01.0 02.01.002
NETWORK	Added AT commands AT+QOPSCFG="scancontrol" to configure bands to be scanned under 2G/3G/4G and AT+QOPSCFG="displayrssi" to enable/disable to display RSSI under LTE.	R07A01_01.0 02.01.002
FILE	Supported uploading and downloading files in SFS format.	R07A01_01.0 02.01.002
TCP/UDP	Added AT command AT+QICFG="tcp/keepalive" to configure whether to enable TCP keep-alive function.	R07A01_01.0 02.01.002
GENERAL	Supported using AT+CSCS command with no SIM card inserted.	R07A01_01.0 02.01.002
GENERAL	Supported RPM configuration for DT MBN.	R07A01_01.0 02.01.002
AUDIO	Optimized AT+QLTONE to play tone.	R07A01_01.0 02.01.002
GENERAL	Added AT+QGSN to get module GSN number and AT+QIMI to get IMEI number.	R07A01_01.0 02.01.002
DTMF	Added AT command AT+QWDTMF to play DTMF files or send it to Far-end.	R07A01_01.0 02.01.002
GENERAL	Optimized Telstra MBN related configuration.	R07A01_01.0 02.01.002
GENERAL	Added AT command AT+QLBSCFG="contextid" to configure the QLBS context ID.	R07A02_01.0 01.01.001

4. Improved Features

Item/Category	Brief Description	Since
AUDIO	Solved the problem of probabilistic noise occurring in specific scenarios after the module was configured with PCM slave mode.	R07A02_30.2 03.30.203
DFOTA	Solved the problem that the delta package was not deleted after FOTA upgrade failure, thereby freeing up flash space.	R07A02_30.2 03.30.203
FILE	Fixed the problem of file AT unauthorized access to other partitions on the AP side.	R07A02_30.2 03.30.203
NETWORK	Fixed the failure issue of IPv6 compliance certification #35 test case.	R07A02_30.2 03.30.203
NETWORK	Fixed the problem that the device with an AT&T card inserted could not register on the network when roaming in some small U.S. island areas.	R07A02_30.2 03.30.203
NETWORK	Fixed the problem that after the called party refused to answer, the caller could only hear the ringback tone, but could not hear the voice prompt sent by the network.	R07A02_30.2 03.30.203
NETWORK	Fixed the problem of network registration failure caused by the abnormal reading of EF_epsnsc file.	R07A02_30.2 03.30.203
NETWORK	Optimized AT+QOPS to solve the band scanning issue.	R07A02_30.2 03.30.203
NETWORK	Optimized IMS configuration that after the network sent the SIP 501 message, the URC could be reported.	R07A02_30.2 03.30.203
NETWORK	Removed PLMN 311882 from Sprint MBN.	R07A02_30.2 03.30.203
NETWORK	Fixed the problem that garbled characters were returned after executing AT+COPS? on the module with the China Broadnet SIM card inserted.	R07A02_30.2 03.30.203
NETWORK	Fixed the problem that the network registration status queried by AT+CREG? was incorrect when the module disconnected due to the network rejection.	R07A02_30.2 03.30.203
NETWORK	Fixed the problem that the returned value of <ACT> was 9 after AT+CREG? was executed.	R07A02_30.2 03.30.203
NETWORK	GEA1 and GEA2 were disabled, and GEA3 was enabled by default.	R07A02_30.2 03.30.203
SMS	Fixed the issue of SMS sending failure during the PDU assembly process by modifying the SMS destination address type from "91" to "81".	R07A02_30.2 03.30.203
UAC	Fixed the problem that there was no sound in special scenes in UAC.	R07A02_30.2 03.30.203
GENERAL	Fixed the problem that CAT busy error was reported after eSIM command was used to configure the profile.	R07A02_30.2 03.30.203
GENERAL	Fixed the problem of small probability abnormality of ATFWD process.	R07A02_30.2 03.30.203

GENERAL	Fixed the problem that AT+QLWWANCID configuration did not take effect after the module was powered down and rebooted.	R07A02_30.2 03.30.203
GENERAL	Removed support on commands related to AT+QLBS or AT+QIOT .	R07A02_30.2 03.30.203
GENERAL	Fixed the module exception problem caused by QMI dmc_activity_inf_ind_msg when the SIM card was inserted and the network was registered.	R07A02_30.2 03.30.203
GENERAL	Fixed the problem of low probability failure for AT\$QCRMCall to call.	R07A02_30.2 03.30.203
GENERAL	Fixed the PSI error obtained from SIM card, which caused the SMS sending failure.	R07A02_30.2 03.30.203
GENERAL	Fixed the problem of abnormal AT+QGPSGNMEA="GSA" execution when the output frequency of NMEA was 5 or 10 Hz.	R07A02_30.2 03.30.203
GENERAL	Fixed that problem that the IMS configuration was overwritten after power-on.	R07A02_30.2 03.30.203
FILE	Fixed the problem that SEC: was not displayed in the return value after AT+QFLST="SEC:* execution.	R07A02_30.2 02.30.202
LowPower	Fix the problem that the LED indicator of net_status did not turn off when the module entered low-power mode.	R07A02_30.2 02.30.202
NETWORK	Fixed the problem of incorrect retry time when Verizon initiated retry mechanism.	R07A02_30.2 02.30.202
QMI	Fixed the problem that the module did not report QMCTL_REVOKE_CLIENT_ID_IND, resulting in the RIL library not updating the dialing status.	R07A02_30.2 02.30.202
SMTP	Modified the format of the "To" and "CC" fields in the mail header to conform to the RFC 5322 standard.	R07A02_30.2 02.30.202
TCP SSL	Fixed the problem that data may be lost in case of retransmission when data was sent in SSL connection.	R07A02_30.2 02.30.202
GENERAL	Optimized the system by removing the useless function.	R07A02_30.2 02.30.202
GENERAL	Restored AT+QLWCFG="startup" to configure the startup mode of LwM2M client.	R07A02_30.2 02.30.202
GENERAL	Fixed the problem that the PF lock could be enabled without a password after AT+CLCK was executed.	R07A02_30.2 02.30.202
GENERAL	Fixed the problem that there was no value returned after AT+QFLOWCOUNT was executed frequently.	R07A02_30.2 02.30.202
GENERAL	1. Fixed the problem that GALILEO satellite could not be obtained in the United States. 2. Fixed the problem that QZSS could not be used for positioning after AT+QGPSCFG="gnssconfig" was executed.	R07A02_30.2 02.30.202
GENERAL	Fixed the problem of incorrect positioning information returned by AT+QGPSLOC=2 after the module woken up from sleep.	R07A02_30.2 01.30.201
GENERAL	Solved the problem that the configuration of AT+QCFG="call_control" was not saved after the module was rebooted.	R07A02_30.2 01.30.201

GENERAL	Optimized AT+QGPSPAI to support returning UTC time <UTC> and extending the <index> parameters.	R07A02_30.2 01.30.201
DFOTA	Fixed the CEFS backup mechanism and insufficient memory during DFOTA upgrade.	R07A02_30.2 00.30.200
MQTT	Fixed the problem that MQTT PINGREQ packet will still be sent after AT+QMTCFG="keepalive",0 was set.	R07A02_30.2 00.30.200
MQTT	Fixed the problem that URC +QMTRECV could not be reported.	R07A02_30.2 00.30.200
NETWORK	Fixed the problem that the network could not be attached to because AT+QICSGP repeatedly set the parameters for more than 32 times.	R07A02_30.2 00.30.200
SMTP	Solved the problem of slow sending 10 M files for SMTP.	R07A02_30.2 00.30.200
SMTP	Fixed the problem that an opened file descriptor attachment was not properly closed after the SMTP attachment was sent completely.	R07A02_30.2 00.30.200
GENERAL	Fixed the device report the wrong emm_status cause for ptcrcb tc44.2.5.2.	R07A02_30.2 00.30.200
GENERAL	Fixed the problem that no POWERED DOWN URC reported after AT+QPOWD=1 was executed to power off the module when AT+QCFG="urc/delay",1 was set.	R07A02_30.2 00.30.200
GENERAL	Fixed the supplementary service functions of DT operators under VoLTE and non-VoLTE.	R07A02_30.2 00.30.200
GENERAL	Solved the problem that AT+QTEMP may not respond sometimes.	R07A02_30.2 00.30.200
GENERAL	Modified the default Windows Size of TCP Client to 45 K bytes.	R07A02_30.2 00.30.200
GENERAL	Solved the problem of LGU VoLTE phone codec negotiation.	R07A02_30.2 00.30.200
GENERAL	Updated Korean operator requirements.	R07A02_30.2 00.30.200
GENERAL	Fixed the problem of 580-precondition failure when allocate bearer appeared immediately after SIP183 message during IMS call.	R07A02_30.2 00.30.200
DFOTA	Solved the problem of error code 701 returned in URC after DFOTA HTTPS download failure.	R07A02_30.0 02.30.002
DFOTA	Solved the problem that an error may be reported in low probability if the module powered down during DFOTA upgrade.	R07A02_30.0 02.30.002
FILE	Solved the problem that when uploading files by executing AT+QFUPL , the module would restart if the file name contained "\" and "/".	R07A02_30.0 02.30.002
HTTP	Solved the problem that error code 702 was returned at AT+QHTTPPOSTFILE to upload files.	R07A02_30.0 02.30.002
HTTP	Fixed the problem that the module was unstable after receiving RST during HTTPS handshake.	R07A02_30.0 02.30.002
HTTP	Optimized the problem that the error code 702 was reported in a small probability when HTTPS files were uploaded.	R07A02_30.0 02.30.002

MQTT	Solved the problem that when data transmitted through the MQTT protocol, one byte more or one byte less would occur with low probability in the received data	R07A02_30.0 02.30.002
NETWORK	Optimized China Telecom B5, and add frequency point 2452 to the historical frequency point (acq_db).	R07A02_30.0 02.30.002
NETWORK	Fixed the problem that the result returned by the AT+QCSQ command was an invalid value.	R07A02_30.0 02.30.002
SMTP	Optimized the recipients display of SMTP, and fixed the problem that more contacts cannot be viewed in the content of sent emails.	R07A02_30.0 02.30.002
TCP SSL	Solved the problem of no RI pin pulling when data reported in SSL client transparent transmission mode.	R07A02_30.0 02.30.002
TCP SSL	Solved the problem of SSL server connection failure due to incorrect SSL verification server certificate items.	R07A02_30.0 02.30.002
TCP/UDP	Optimized UDP IPv6 addresses display.	R07A02_30.0 02.30.002
Voice Call	Solved the problem that the previous call number returned by AT+CLIP may be abnormally sometimes.	R07A02_30.0 02.30.002
GENERAL	Solved the problem that the LwM2M program could not start normally after executing AT+CFUN=1,1 to reboot the module.	R07A02_30.0 02.30.002
GENERAL	Removed the configuration of default MTU 1430 in DCM MBN.	R07A02_30.0 02.30.002
GENERAL	Integrated Verizon SUPL Certificates in Verizon MBN.	R07A02_30.0 02.30.002
GENERAL	Optimized the dual serial port function to solve the problem of abnormal serial communication when AT commands is used for large data transmission.	R07A02_30.0 02.30.002
GENERAL	Set voice centric for Verizon MBN.	R07A02_30.0 02.30.002
GENERAL	Modified the attach APN to telstra.internet for Telstra operator.	R07A02_30.0 02.30.002
GENERAL	Set the ROW MBN profile1 to null and profile3 APN name to sos apn name.	R07A02_30.0 02.30.002
GENERAL	Solved the problem that AT+QGPSCFG="gpsnmeatype" returned an error after MBN was switched.	R07A02_30.0 02.30.002
GENERAL	Optimized Full Reg and Reg Update solutions for Verizon.	R07A02_30.0 02.30.002
GENERAL	Solved the problem that USB DM port may be abnormal sometimes.	R07A02_30.0 02.30.002
GENERAL	Modified IMS configuration parameters for Rogers MBN	R07A02_30.0 02.30.002
GENERAL	For STK authentication requirements, modified the MTU value to 1440.	R07A02_30.0 02.30.002
GENERAL	Solved the problem that there was an extra \r in the NMEA sentence after	R07A02_30.0

	AT+CFUN=1,1 was executed.	02.30.002
GENERAL	Solved the problem that AT performance port could not work normally after AT+COPS execution.	R07A02_30.0 02.30.002
GENERAL	Fixed the problem that cannot be queried and set normally through AT+ODIS and AT+QLWCFG="hostdevice".	R07A02_30.0 02.30.002
GENERAL	Fixed the problem that AT+CPOL? could not be used normally on the main serial port.	R07A02_30.0 02.30.002
GENERAL	Optimized the problem of frequent reading and writing of LWM2M EFS.	R07A02_30.0 02.30.002
GENERAL	Fixed the problem that the parameters <cellid> and <tac> would not be output by AT+CGREG with low probability.	R07A02_30.0 02.30.002
GENERAL	Optimized back-off algorithm of Rogers operator.	R07A02_30.0 02.30.002
GENERAL	Fixed the problem that ep could not send data when the USB phy is abnormal in low probability.	R07A02_30.0 02.30.002
GENERAL	Solved the problem that With a Non-VoLTE SIM card, the Call waiting could not adapt to the network or was determined by the UE.	R07A02_30.0 02.30.002
GENERAL	Optimize AT+CUSD command.	R07A02_30.0 02.30.002
GENERAL	Fixed the problem the enhanced sleep mode may fail to enter.	R07A02_30.0 02.30.002
AUDIO	Solved the problem that the following commands returned ERROR and CME ERROR at the same time: 1. AT+QAUDRD 2. AT+QAUDPLAY 3. AT+QPSND 4. AT+QWTTS 5. AT+QLDTMF	R07A02_30.0 01.30.001
AUDIO	Solved the problem that audio recording could not work normally after AT+QMIC set the gain of MIC.	R07A02_30.0 01.30.001
DFOTA	Supported using the fixed baud rate set before the upgrade during DFOTA upgrade.	R07A02_30.0 01.30.001
DFOTA	Solved the problem that the module could not report the DFOTA upgrade result to the Verizon server after the OMA-DM DFOTA upgrade ended.	R07A02_30.0 01.30.001
FTP	Solved the problem of timeout error (error code 609 returned) when executing AT+QFTPOPEN to log in to the FTP(S) server.	R07A02_30.0 01.30.001
HTTP	Solved the problem that the module automatically rebooted when AT+QHHTTPPOSTFILE sends a POST request to HTTP(S) server through a file larger than 1M.	R07A02_30.0 01.30.001
MBIM	Solved the problem that Host could not obtain the IP from MBIM if the network only allocated IP without DNS address.	R07A02_30.0 01.30.001
MQTT	Solved the problem that the MQTT disconnected when receiving the message with QoS level 2 subscribed successfully.	R07A02_30.0 01.30.001

MQTT	Solved the problem that when AT+QIDEACT was executed immediately after AT+QMTOPEN execution for the first time, +QMTSTAT: 0,2 was reported continuously after AT+QMTOPEN execution again.	R07A02_30.0 01.30.001
MQTT	Solved the problem of failure to connect to some servers caused by the inability to enable MQTT SNI.	R07A02_30.0 01.30.001
NETWORK	Change the range of SINR value returned by AT+QENG="SERVINGCELL" from (0~250) to (-20~30).	R07A02_30.0 01.30.001
PPP	Solved the problem that AT port may not work normally after executing AT+CGACT=1,1 to activate the first PDP context which has been activated by default again.	R07A02_30.0 01.30.001
SMS	Extended AT command AT+QCFG="ltesms/format" to send SMS in 3GPP2 format only and receive SMS in 3GPP2 and 3GPP format at the same time.	R07A02_30.0 01.30.001
Voice Call	Solved the problem that there may be no busy tone displayed when the call was hung up after enabling busy tone playing via AT+QCFG="voice_busytone" .	R07A02_30.0 01.30.001
GENERAL	Limited LTE band to B4&B13 for Verizon.	R07A02_30.0 01.30.001
GENERAL	Changed the configurations below: The first APN to au.au-net.ne.jp, user name to user@au.au-net.ne.jp, password to au, and authentication type to CHAP.	R07A02_30.0 01.30.001
GENERAL	For T-Mobile, modified the voipMinSessionExpires to 90.	R07A02_30.0 01.30.001
GENERAL	Solved the problem that the usrdta ubi may be mounted abnormally in a short time after the module was powered off by executing AT+QPOWD=0 .	R07A02_30.0 01.30.001
GENERAL	Updated SE13 TABLE date to 2020/12/21.	R07A02_30.0 01.30.001
GENERAL	Solved the problem that the module could not work normally when executing AT+QGPSGNMEA="GSV" after searching for multiple satellites.	R07A02_30.0 01.30.001
GENERAL	Solved the problem that AT+QCFG="PCMCLK",0 could not turn off PCM clock.	R07A02_30.0 01.30.001
GENERAL	Updated the AT&T MBN version to 202102031 to use the MTU size allocated by the network and change ue_usage_setting to DATA Centric.	R07A02_30.0 01.30.001
GENERAL	Modified the third and fourth APN profile for SKT and updated SKT MBN version to 202103121.	R07A02_30.0 01.30.001
GENERAL	Updated DCM MBN version to 202104121 to solve the problem of unable to connect to TCP for data transmission after a successful network search.	R07A02_30.0 01.30.001
GENERAL	When peer IP address length was more than 50 chars, silently truncated the string to 50 chars.	R07A02_30.0 01.30.001
GENERAL	Not triggered card power-down if EF-DIR read fails.	R07A02_30.0 01.30.001

GENERAL	Populated file attributes for EST file when card did not return FCP data.	R07A02_30.0 01.30.001
GENERAL	No sim E911 call for specific operators should not be blocked.	R07A02_30.0 01.30.001
GENERAL	Solved the problem that the Verizon OMA server could not be connected using IPv6.	R07A02_30.0 01.30.001
GENERAL	Set the first APN to IPV6 ONLY by default for T-Mobile.	R07A02_30.0 01.30.001
GENERAL	Solved the problem that the uploaded AT&T APN name of Object 11 instance 0 is null.	R07A02_30.0 01.30.001
GENERAL	Solved the problem URC broadcast could not work normally after enabling CMUX feature.	R07A02_30.0 01.30.001
GENERAL	Set the default MTU to 1430 for AT&T, and updated AT&T MBN version to 202105171.	R07A02_30.0 01.30.001
GENERAL	Updated Telstra MBN version to 202105192.	R07A02_30.0 01.30.001
GENERAL	Modified the configuration of the 2nd profile (IMS) for T-Mobile to change the OVRRIIDEHOPDP to IPV6.	R07A02_30.0 01.30.001
GENERAL	Extended AT command AT+QCFG="cmux/urcport" to support turning off CMUX port to report URC.	R07A02_30.0 01.30.001
GENERAL	Fixed the problem of incorrect RTC time synchronized from NITZ in some time zones.	R07A02_30.0 01.30.001
GENERAL	Optimized the operator's 3G Sunset solution to solve the problem of no network in some scenarios (such as roaming) at AT&T 3G Sunset.	R07A02_30.0 01.30.001
GENERAL	Modified 2nd, 3rd, and 4th APN for KT MBN, and updated the KT MBN version to 202106221.	R07A02_30.0 01.30.001
GENERAL	Disabled fast dormancy feature for T-Mobile.	R07A02_30.0 01.30.001
GENERAL	Solved the problem that AT+QCFG="qcautoconnect" could not enable the automatic connection in ECM or RNDIS mode.	R07A02_30.0 01.30.001
GENERAL	Solved the problem that after switching AT+CFUN=0 and AT+CFUN=1 , the APN type of "atm2mgloba1" was changed from IPV4V6 to IPV4 after AT&T was activated and the module registered to the network successfully.	R07A02_30.0 01.30.001
GENERAL	Updated LGU MBN version to 202103101.	R07A02_30.0 01.30.001
GENERAL	Fixed the problem that AT+QCFG="DIVCTL" did not take effect.	R07A01_01.0 02.01.002
GENERAL	Disabled FGI bit 27,28 and 29 for AT&T.	R07A01_01.0 02.01.002
GENERAL	Optimized RX performance under LTE.	R07A01_01.0 02.01.002
GENERAL	Disabled VICE feature for Verizon.	R07A01_01.0

		02.01.002
DFOTA	Supported to report DFOTA upgrade progress after powering down during DFOTA upgrade.	R07A01_01.0 02.01.002
AUDIO	Solved the problem that UAC had no sound.	R07A01_01.0 02.01.002
GENERAL	Optimized AT command AT+QDIAGPORT .	R07A01_01.0 02.01.002
GENERAL	Solved the problem CMAS message could not be received for AT&T test case of LTE-BTR-5-4121 &4125 & 4552 & 4127.	R07A01_01.0 02.01.002
GENERAL	Solved the problem that some special 7bit control characters (such as "@") could not be displayed normally in ASCII.	R07A01_01.0 02.01.002
GENERAL	Solved the problem that the base station positioning server could not be configured by AT+QLBSCFG="server" .	R07A01_01.0 02.01.002
GENERAL	Fixed CMAS bug for LTE-BTR-5-4118 AT&T bug for not display 7bit 0x00f1, increased extension ASCII.	R07A01_01.0 02.01.002
GENERAL	Updated GSMA TS.25 publication date.	R07A01_01.0 02.01.002
HTTP	Optimized the feature of HTTP after enabling automatically outputting HTTP(S) response header by AT+QHTTPCFG="rspout/auto",1 .	R07A01_01.0 02.01.002
NETWORK	Solved the problem that after CDMA is blocked and China Telecom LTE has been registered to,0 was returned unexpectedly by AT+CGATT? .	R07A01_01.0 02.01.002
GENERAL	Enabled ECBM function.	R07A01_01.0 02.01.002
GENERAL	Solved the problem occurred in test GPS use cases in PTCRB certification: SUPL-2.0-con-024-2 not displayed QGPSURC characters.	R07A01_01.0 02.01.002
GENERAL	Optimized AT+QWWAN command to solve the problem of incorrect file storage path.	R07A01_01.0 02.01.002
MQTT	Fixed the module rebooting caused by MQTT receiving many subscribed topics.	R07A01_01.0 02.01.002
GENERAL	Solved the problem that WCDMA Band4 and Band8 diversity were opened unexpectedly by AT+QCFG="diversity",1 .	R07A01_01.0 02.01.002
GENERAL	Optimized the history call record function.	R07A01_01.0 02.01.002
SIMCARD	Enabled invalid SIM card identification.	R07A01_01.0 02.01.002
MQTT	Solved the problem that after setting willmessage with a length of 256 bytes through AT+QMTCFG="WILLEX" , willtopic will also be returned after willmessage in URC.	R07A01_01.0 02.01.002
NETWORK	Disabled the eDRX function by default.	R07A01_01.0 02.01.002
SMS	Solved the problem that the current operator's SMS center number could not be displayed after enabling the SIM card hot-plugging function.	R07A01_01.0 02.01.002

GENERAL	Modified parameter format for AT commands related to base station positioning locator/LBS 2.0 as AT+QLBSCFG? , AT+QLBSCFG=? and AT+QLBSCFG="token" .	R07A01_01.0 02.01.002
GENERAL	Solved the problem that the incorrect error code returned by AT+QLBS .	R07A01_01.0 02.01.002
TCP SSL	Ignored the verification for multi-level certificate chains by default in the embedded SSL protocol.	R07A01_01.0 02.01.002
NETWORK	Optimized AT+QCFG="fast_dormancy" to support fast dormancy mode 3.	R07A01_01.0 02.01.002
NETWORK	Optimized AT command AT+QCFG="lte/preferfre" to solve the problem the module may be unstable due to incorrect bandwidth parameter of AT+QCFG="lte/preferfre" .	R07A01_01.0 02.01.002
MQTT	Optimized AT command AT+QMT PUBEX to improve the module's stability after the server automatically disconnected from the module and WM has been released under the data mode.	R07A01_01.0 02.01.002
Voice Call	Optimized the three-party call function.	R07A01_01.0 02.01.002
FTP	Supported multiple server response parsing in FTP mode.	R07A01_01.0 02.01.002
NETWORK	Optimized China Telecom LTE ONLY IoT card network registration.	R07A01_01.0 02.01.002
Voice Call	Reported DSCI when making an emergency call.	R07A01_01.0 02.01.002
GENERAL	Solved the problem of error code 707 (HTTP (S) network open failed) reported when using AT+QLBS for positioning under AUTO or fixed 4G mobile network.	R07A01_01.0 02.01.002
GENERAL	Update ROW MBN version to 201901141.	R07A01_01.0 02.01.002
GENERAL	Update the ID of Profile5 in Verizon MBN.	R07A01_01.0 02.01.002
NETWORK	Solved that problem of unable to relaunch Home PLMN search after 313-100 SIM card was registered on the 310-410 PLMN.	R07A01_01.0 02.01.002
GENERAL	Expanded AT+QFOTADL command to increase DFOTA upgrade path length.	R07A01_01.0 02.01.002
MMS	Supported using AT+QMMSCFG="proxy" to set MMS proxy address starting with 0.	R07A01_01.0 02.01.002
FTP	Solved the problem that the module could not work normally after executing AT+CFUN=0 on other AT ports during FTP upload or download.	R07A01_01.0 02.01.002
GENERAL	Updated Reliance MBN to not change the 2G band.	R07A01_01.0 02.01.002
TCP/UDP	Solved the problem that after activating PDP, the AT port may not work normally after executing AT+QIDEACT command immediately without	R07A01_01.0 02.01.002

	response.	
GENERAL	Solved the problem of error returned by AT+QNVFR to query the value of NV553 after activating AT&T MBN.	R07A01_01.0 02.01.002
GENERAL	Solved the problem that the default server port (80) could not be obtained by AT+QLBSCFG?	R07A01_01.0 02.01.002
GENERAL	Solved the problem that the SMS reporting port could not be set as the debug port by AT+QCFG="urcport/sms" .	R07A01_01.0 02.01.002
GENERAL	Updated AT command AT+CGSN to support querying IMEI number and SN number.	R07A01_01.0 02.01.002
GENERAL	Solved the problem of incorrect default value of ATX queried by AT&V .	R07A01_01.0 02.01.002
GENERAL	Solved the problem that the domain name address in IPV6 format resolved by AT+QIDNSGIP was incorrect.	R07A01_01.0 02.01.002
GENERAL	Update SBM MBN version to 202004041.	R07A01_01.0 02.01.002
FILE	Solved the problem that data may lost when uploading files by sending FILE related commands on UART or debug ports.	R07A01_01.0 02.01.002
GENERAL	Changed the range value returned by AT+QDAI=? from (1-4) to (1-6).	R07A01_01.0 02.01.002
GENERAL	Solved the problem of an error returned by AT+QSGMIICFG="config" to set SGMI.	R07A01_01.0 02.01.002
GENERAL	Updated Verizon MBN version to 202004091.	R07A01_01.0 02.01.002
MQTT	Fixed module RI changed but no URC reported when sending data via MQTT protocol.	R07A01_01.0 02.01.002
GENERAL	Changed the number of attachments returned by AT+QCFG="siminvalirecovery" from 208 to (0-1).	R07A01_01.0 02.01.002
GENERAL	Updated TF_Germany_VoLTE to support volte.	R07A01_01.0 02.01.002
HTTP	Solved the problem that the module worked improperly after asking an HTTP request with wrong URL.	R07A01_01.0 02.01.002
GENERAL	Solved the problem that after the band was set to a fixed value, it would resume to the default value obtained after the module rebooted twice or three times.	R07A01_01.0 02.01.002
LowPower	Solved the problem that the sleep light on the EVB board did not light up after the module entered the UART or USB slow clock mode.	R07A01_01.0 02.01.002
GENERAL	Update CMCC MBN to register the network via APN1.	R07A01_01.0 02.01.002
GENERAL	Optimized the AT+QCFG="airplanecontrol" command to support not exiting the airplane mode by setting QMI when pulling w_disable to low.	R07A01_01.0 02.01.002
GENERAL	Solved the problem that the local time queried by AT+CCLK was inconsistent with the local time synchronized by AT+CTZU=3 from the network.	R07A01_01.0 02.01.002

GENERAL	Solved the problem of disconnection after USB suspended and then resumed.	R07A01_01.0 02.01.002
DFOTA	Solved the problem of 502 and 520 error codes reported after rebooting the module due to powering down when DFOTA upgrade to 90%.	R07A01_01.0 02.01.002
GENERAL	Solved the problem of no sleep_ri jittered after receiving PPP data.	R07A01_01.0 02.01.002
NETWORK	Improved China Telecom B5 to search frequency 2452 in the historical frequency point (acq_db) in priority under LTE.	R07A01_01.0 02.01.002
GENERAL	Fixed the problem that the USB could not work normally when the module rebooted for the first time after DFOTA upgrade.	R07A01_01.0 02.01.002
GENERAL	For non-Chinese operators, turned on the AGPS function.	R07A01_01.0 02.01.002
GENERAL	Solved the problem that pcmclk could not be enabled by AT+QCFG="PCMCLK" .	R07A01_01.0 02.01.002
DTMF	Extended AT+QTONEDT=1 to support soft decode feature.	R07A01_01.0 02.01.002
TCP/UDP	Increased the length of domain name returned by AT+QSSLOPEN from 40 bytes to 256 bytes.	R07A01_01.0 02.01.002
GENERAL	Solved the problem that data sent and received by the module would lose after the module connected to the DTLS server.	R07A01_01.0 02.01.002
GENERAL	Updated CEFS version to "EG25_GC",00002,202007211.	R07A01_01.0 02.01.002
GENERAL	Solved the problem that the incorrect value (0, indicating that RNDIS is not automatically connected) returned by AT+QCFG="qcautoconnect" after RNDIS mode was set by AT+QCFG="usbnet",3 .	R07A01_01.0 02.01.002
TCP SSL	Solved the problem that memory leak occurred when unilateral and mutual authentication connection with SSL was performed.	R07A01_01.0 02.01.002
DFOTA	Solved the problem that DFOTA upgrade failed when special characters included in the HTTP URL.	R07A01_01.0 02.01.002
TCP/UDP	Extended AT+QICFG="window/scale" to configure TCP Window scale.	R07A01_01.0 02.01.002
GENERAL	Solved the problem that after PPP dialing was successful, USSD URC could not be received on the USB AT port after AT+CUSD=1,"**100#" was executed.	R07A01_01.0 02.01.002
GENERAL	Solved the problem that the default values of HSDPA returned by AT+QCFG="hsdpacat" and HSUPA returned by AT+QCFG="hsupacat" were incorrect.	R07A01_01.0 02.01.002
PHB	Fixed the problem that AT+CPBR could not read emergency call numbers from SIM card.	R07A01_01.0 02.01.002
SMS	Solved the problem that AT+QCFG="urcport/sms" could not set SMS reporting port to debug port.	R07A01_01.0 02.01.002
TCP/UDP	Solved the problem that the number of actually connected clients did not match the set clients when the module was used as a TCP server.	R07A01_01.0 02.01.002

SMS	Solved the problem that the AT port could not work normally due to the execution of the AT+QCFG="sms/listmsgmap" command.	R07A01_01.0 02.01.002
FTP	Solved the problem that error code 627 returned when data was downloaded discontinuously through FTP.	R07A02_01.0 01.01.001
MQTT	Corrected the response format of AT+QMTUNS=? from +QMTSUB to +QMTUNS.	R07A02_01.0 01.01.001
FTP	Solved the problem that error code 619 may be returned when PUT file via FTP.	R07A02_01.0 01.01.001
HTTP	Solved the problem that after connecting HTTP(S) server successfully with wrong URL and sending GET request through AT+QHTTPGET , executing AT+QHTTPSTOP to cancel HTTP(S) request before URC reported, AT port may not work normally.	R07A02_01.0 01.01.001
GENERAL	Solved the problem that AT&T could not be activated by FIRSTNET or NDO after activating ROW.	R07A02_01.0 01.01.001
GENERAL	Modified the 1st APN for DCM MBN to transfer data properly.	R07A02_01.0 01.01.001
HTTP	Solved the problem that an extra +QHTTPURC: "closed" reported when enabling HTTP(S) session closing reporting through AT+QHTTPCFG="closed/ind" .	R07A02_01.0 01.01.001
GENERAL	Modified the first T-Mobile profile to spmode.ne.jp to support T-Mobile data transmission.	R07A02_01.0 01.01.001
HTTP	Solved the problem that AT+QHTTPGET may not send the GET request to HTTP(S) server and there may be no timeout occurred.	R07A02_01.0 01.01.001
GENERAL	Fixed the problem that the system may not respond when loading/unloading Mac driver.	R07A02_01.0 01.01.001
TCP/UDP	Solved the problem that after connecting to TCP server through AT+QIOPEN for 60 seconds, the module did not send TCP disconnection wave after AT+QICLOSE was executed.	R07A02_01.0 01.01.001
GENERAL	Modified the value of voipMinSessionExpires to 90 for Commercial-TMO_VoLTE MBN.	R07A02_01.0 01.01.001
HTTP	Solved the problem of an error code 702 reported when there was no response from TCP server after HTTP PUT request was sent.	R07A02_01.0 01.01.001
TCP SSL	Solved the problem that there was one more empty line on the "cacertex" certificate path returned by AT+QSSLCFG="cacertex" .	R07A02_01.0 01.01.001

5. Known Issues

Item/Category	Brief Description
/	/

6. Functions

Basic Function

SMS	Voice Call	Data Call	USSD	PHB	CMUX	FILE ¹⁾	FAX	STK
Y	Y	N	N	Y	Y	Y	N	N

Protocol Function

QMI	TCP/UDP	PPP	FTP	NITZ	NTP	HTTP	PING	TCP SSL
Y	Y	Y	Y	Y	Y	Y	Y	Y
MQTT	MMS ²⁾	SMTP	SMTPTS	HTTPS				
Y	Y	Y	Y	Y				

Special Function

SIM Detection	DFOTA	DTMF ³⁾	Dual UART	MBIM	Security ⁴⁾	SD	UAC	LowPower
Y	Y	Y	Y	Y	Y	Y	Y	Y
RMNET	ECM	RNDIS						
Y	Y	Y						

NOTES

1. Y means the firmware supports this function.
2. N means the firmware does not support this function.
3. ¹⁾ Supports RAM FILE only.
4. ²⁾ Supports MMS sending only.
5. ³⁾ Supports DTMF decoding only.
6. ⁴⁾ Support Secure Debugging.
7. Verification Environment is shown below. For more details, please contact Quectel technical support.

For Windows,

USB Driver: Quectel_Windows_USB_Driver(Q)_NDIS_V2.7.1

Qflash Tool: QFlash_V7.0

For Linux,

QMI_WWAN Driver: Quectel_Linux&Android_QMI_WWAN_Driver_V1.2.2

GobiNet Driver: Quectel_Linux&Android_GobiNet_Driver_V1.6.3

QFirehose Tool: QFirehose_Linux_Android_V1.4.11
Quectel-CM Tool: Quectel_QConnectManager_Linux_V1.6.1
USB Driver: Quectel_Linux_USB_Serial_Option_Driver_V1.0
QLog Tool: QLog_Linux_Android_V1.5.16

Quectel
Confidential