1. Approving Civil Aviation Authority/Country:	2.	3. Form Tracking Number:
FAA/United States	**AUTHORIZED RELEASE CERTIFICATE** FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG	4312D
4. Organization Name and Address: FACC Solutions, Inc., 800 E 37th St North., Wichita, Kansas 67219 (FSOR210X)		5. Work Order/Contract/Invoice Number: R2099

6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
001	WINGLET	737-0010-37	1	C1976	MODIFIED

12. Remarks:

Customer Repair Order #: R57902 Delivery Note#: 5303

- Modified existing Winglet 737-0010-35 to 737-0010-37 in accordance with 737 AMM 57 Rev 80 Feb 2023, 737 SRM 51 & 57 Rev 79 July 2023, BAC 5615 Rev A Apr 2023 and Service Bulletin AP737-33-007 Rev 3 March 9, 2017.

Certifies that the work specified in Block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work, the Winglet is considered ready for release to service under EASA Part 145 approval no EASA.145.6792

13a. Certifies the items identified above were manufactured in conformity to:		14a. ☑ 14 CFR 43.9 Return to Service ☑ Other regulation specified in Block 12	
☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12.		Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.	
13b. Authorized Signature:	13c. Approval/Authorization No.:	14b. Authorized Signature: Nick Schumacher	14c. Approval/Certificate No.: FSOR210X
13d. Name (Typed or Printed):	13e. Date (dd/mmm/yyyy):	14d. Name (Typed or Printed): Nick Schumacher	14e. Date (dd/mmm/yyyy): 29/AUG/2023

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

FACC Solutions, Inc
800 East 37th Street North
Wichita, KS 67219

TEAR DOWN REPORT

R2099 **S/N: C1976** **RO: R57902**

001 Replace All Worn Bulb Seals
IAW AMM 57-21-21, Rev 80
FWD Bulb Seal (737-0805-1)
AFT LWR Bulb Seal (737-0010-9)
AFT UPR Bulb Seal (737-0010-5)
FWD UPR Bulb Seal (737-0010-3)
FWD LWR Bulb Seal (737-0010-7)

002 Replace Qty (2) Corroded Bond Jumper
per 737 SRM 51-40-02 Rev 79

003 FWD POS Assy has retainer scratches
FWD Position Light upgraded on NCMR R2099-009

004 ACL faded glare paint and retainer scratches, dirty lens
ACL Light upgraded on NCMR R2099-009

005 AFT POS light has missing glare paint, dirty lens and corroded jumper
AFT Position Light upgraded on NCMR R2099-009
Replace bond jumper per SRM 51-40-02, Rev 79

006 Unit has a worn finish
Refinish per APB AMM 57-21-21 Rev V

007 Polish INBD, MID & OUTBD Leading Edges per BAC 5615, Rev A

008 OUTBD Trailing Edge has an existing blend
Minimally blend OUTBD TE, NDI to verify crack free, touch up
IAW 737 SRM 57-30-01 Rev 79

009 Per RO, customer requests a Light Upgrade to -37
Install -37 Light Upgrade per Service Bulletin AP737-33-007
Forward Position Light Assembly (72303218-1)
Anti-Collision Light Assembly (72305039-3)
Stepdown Converter Cable Assembly (72605371-3)
Aft POS Light Assembly (72303219-3)