Field Service Report (FSR)											
Report No: FSR 2012-12_GMD Mec_SAGI					Mill1	Doc No: 3BHS306305_Rev.					
Dept/Loc: Prepared by: Approv ATBDFM3 H. Moser St. Bas			oved by: asler	Released by: R		Revision	Revision:		Oate: 2.12.2012		
Site I	nformation										
Custo					Country name: Indonesia				Customer Representative: xxxxxxxx		
Site:	«××				Unit: SAG Mill 1						
Plant: xxxxxxxx				Plant Type: Copper Mine					☐ E-House ☐ Motor		
Syste Ringm	m/Machine: otor		Type: WAZ 1380/88/72	2	Serial Num G0B059	ber:	Year o 2011	f delivery,	/Com:	Openi 11,20	ing hours:
Servi	ce Informati	ion									
☐ Ne\ ☐ Firs	Service Type: New Plant Upgrade / Modification Trouble shooting Others First Installation (Stator in op. Pos.) (Stator in Maint. Pos)										
Service Task: Installation (Assembly) Overhaul works Re-Commissioning Diagnostics Factory Insp. Inspection Motor Insp. Inside											
	Description of Services performed: 18 months inspection Stator - Inspection - Retorquing of all core pressing bolts Rotor Poles - Inspection Motor Auxiliaries - Inspection Additional works - Installation of new power supply for Gap Watch system - Replacement of UPS										
List o	of Distribution	on									
Loc	Dept. / Loc	:. 8	Surname, Name	Rema	arks:	Loc	Dept. / Lo	oc. Su	rname, N	lame	Remarks:
Dä	ATBDFM1		C. Vinclair								
Dä Dä	ATBDFM3 ATBDFM4		S. Basler H. Moser								
-	bution to cu										
				Det		Comme	nto from s	uoto mas m	Commi	nont- !	nto grote d
Send	by		Го	Date		Comme	nts from cu	istomer	Comr	nents I	ntegrated
Camfidantia	-1										

Report No: FSR 2012-12_GMD Mec_SAGMill1

Doc No: 3BHS306305_Rev.

Dept/Loc: ATBDFM3

Prepared by: H. Moser Approved by: St. Basler Released by: H.R. Fuchs Revision:

Date:

22.12.2012

13-25

Tab	Table of contents						
Des	Description						
1.	Summary of Inspection - Main difficulties - Recommendations - Points of General interest	2					
2.	Inspection data's - Technical information - Storage and spare parts - Tools	3-4					
3.	Inspection carried out on GMD motor						
	- Stator	5					
	- Rotor Poles	5					
	- Motor Auxiliaries	5/6					
4.	Enclosures						
	– Pictures report	7-12					

Summary of inspection

Work Performed during shutdown

- Checking and retightening of all core press bolts
- Checking of brush holders, brushes and slip rings
- Cleaning of insulation bolts at slip rings

- Measurement protocols

- Visual check of holding plates, key bars, stator core and lamination
- Visual check of the dust seal system
- Visual checks of sole plates and stator stop blocks
- Checking make up fan filters
- Checking cooling system and sealing
- Replacement of Gap Watch power supply
- Replacement of UPS

Main difficulties

- Customer people had low knowledge about GMD's
- No access on bottom of GMD because of re-lining (safety reason)

Recommendations (further action required)

- Next inspection after 6 months according maintenance manual including complete retorquing of core press bolts
- Two mech. supervisors have to be on site for two shifts
- Cleaning Stator core from abrasion powder (vibrations dust) and dust by vacuum cleaner
- The water at bottom of cooling boxes must be removed immediately.

For safety reason this was not possible during re-lining

- Slurry (sludge) around GMD should be cleaned up before shut down start, special at bottom side
- To have access to bottom of GMD, scaffoldings must be installed for protection of falling parts
- To increase customer knowledge for GMD's, same maintenance team should be at site for further services

Site storage conditions							
Store cleanliness/condition and localization	Checked	Date	Remarks				
- Tools and material stored well in containers	mech.	20.12.2012					



Report No: FSR 2012-12_GMD Mec_SAGMill1

Doc No: 3BHS306305_Rev.

Dept/Loc: ATBDFM3

Prepared by: H. Moser

Approved by: St. Basler Released by: H.R. Fuchs

Revision:

Date:

22.12.2012

Service information							
N°	Description	From	Until	Remarks:			
1	ABB at site - Briefing with customer	12:00	14:00				
2	Start of service and inspection works	14:00	15:00				
3	Finished shut down	15:00	16:00				

Personnel involved from ABB								
N°	Surname, Name	Cat	Function	Arrival date	Departure date	Dept. / Loc.		
1	C. Vinclair	5	Mech. Supervisor	6/6/2012	8/6/2012	ATBDFM3		
2	S. Basler	5	Mech. Supervisor	6/6/2012	8/6/2012	ATBDFM3		
3	H. Moser	5	Mech. Supervisor	6/6/2012	8/6/2012	ATBDFM3		

Perso	Personnel involved from client and/or consultant								
N°	N° Surname, Name Cat Function Arrival date Departure date Dept. / Loc.								
1	C. Vinclair	5	Mech. Supervisor	6/6/2012	8/6/2012	ATBDFM3			
2	S. Basler	5	Mech. Supervisor	6/6/2012	8/6/2012	ATBDFM3			
3	H. Moser	5	Mech. Supervisor	6/6/2012	8/6/2012	ATBDFM3			

Main	Main motor data							
N°	Description	Data	Remarks					
1	Туре	WAZ 1380/88/72						
2	Serial Number	G0B059						
3	Rated Apparent Power	15250 kVA						
4	Rated Active Power	14400 kW						
5	Rated Speed	9.77 rpm						
6	Max. Speed	10.29 rpm						
7	Rated Cos phi	0.97						
8	Rated Frequency	5.86 Hz						
9	Rated Voltage	3660 V +/- 5%						
10	Rated Current	2405.6 A						
11	Excit. Current at rated speed	505 A						
12	Excit. Voltage at rated speed	367 V						
13	Excit. Current at Start-up							
14	Excit. Voltage at Start-up							
15	Cooling type	Water / Air Heat Exchanger						
16	Altitude above sea level	170m						
17	Air gap (nominal)	16 mm						
18	Type of winding	VPI						

Report No: FSR 2012-12_GMD Mec_SAGMill1 Doc No: 3BHS306305_Rev.

Dept/Loc: Prepared by: Approved by: Released by: Revision: Date:

ATBDFM3 H. Moser St. Basler H.R. Fuchs 22.12.2012

Spec	Specific motor data							
N°	Description	Data	Data		Remarks			
1	Quantity of stator winding slots	540						
2	Quantity, size & torque of pressing bolts	Qty 268	Size M16	kN 76				
3	Quantity, size & torque of foundation bolts	Qty	Size	Nm				
4	Quantity & size of dowel pins	Qty	Size					
5	Quantity, size & torque of partition bolts	Qty	Size	Nm				
6	Quantity & Type of brushes	Qty 2x6 Type E486		Type E486				
7	Quantity & Type of earthing brushes	Qty 2		Type AG2				
8	Quantity, size & Type of dust seal	Qty	Size	Туре				
9	Quantity, size & Type of flat springs	Qty	Size	Туре				
10	Quantity, size & Type of pressure springs	Qty	Size	Туре				

Report No: FSR 2012-12_GMD Mec_SAGMill1

Doc No: 3BHS306305_Rev.

Dept/Loc: ATBDFM3

Prepared by: H. Moser Approved by: St. Basler Released by: H.R. Fuchs

Revision:

Date: 22.12.2012

Inspection of GMD: Stator

Stator foundation and stator frame

- The stator foundation and the stator frame was found in dirty condition regarding cleanliness and corrosion
- The air gap of the central sole plate has to be cleaned every 6 months
- No cracks have been observed at the stator foundations.
- Stator covers and their fixations were checked, where it was accessible and found in good condition.



Picture Number: 1 Pedestal sole plate

Must be proteced against corrosion



Picture Number: 2 Pedestal sole plate

Must be proteced against corrosion



Picture Number: 3 Stator fixation bolts

Must be proteced against corrosion



Picture Number: 4 Central sole plate

Air gap is free of slurry