

INCIDENT REPORT

Equipment Failure – Unplanned Downtime

Incident ID	INC-2024-119	Date	30-Sep-2024
Equipment	Compressor C-101	Location	Utility Block
Severity	High	Downtime	9 hours
Reported By	Rajesh Kumar (Senior Maintenance Engineer)	Time Reported	06:40

Description

Compressor C-101 shut down automatically on a low-pressure trip during early morning operation. On inspection, the valve plate was found cracked, causing loss of compression efficiency. Unplanned downtime of 9 hours was incurred while a replacement valve plate was sourced and fitted. Utility Block services dependent on C-101 were run on reduced capacity for the duration.

Immediate Action Taken

Compressor isolated per Permit to Work. Replacement valve plate fitted per WO-2025-0091. Compressor returned to service following pressure verification.

Root Cause

Valve plate fatigue beyond OEM-rated cycles, not flagged by the existing preventive maintenance schedule. The PM schedule for C-101 had not been updated to reflect the component's rated fatigue-cycle limit, meaning the plate remained in service well beyond its intended replacement point without triggering a scheduled inspection.

Corrective Action

Preventive maintenance schedule for C-101 to be revised to track valve plate fatigue cycles directly against the OEM rating, rather than a fixed calendar interval alone. Maintenance team to review whether comparable rotating equipment elsewhere in the plant carries the same latent risk.