

Suraksha Chemicals Pvt. Ltd.

Unit 4 – Specialty Chemicals & Intermediates, Ambarnath, Maharashtra

INCIDENT REPORT

Equipment Failure – Unplanned Downtime

Incident ID	INC-2025-041	Date	11-Feb-2025
Equipment	Centrifugal Pump P-204A	Location	Process Bay 2
Severity	High	Downtime	6.5 hours
Reported By	Ananya Deshmukh (Field Technician)	Time Reported	09:15

Description

At approximately 08:50, Pump P-204A tripped on high vibration during normal operation. On inspection, the bearing assembly was found to have failed, causing unplanned downtime of 6.5 hours while a replacement was sourced and fitted. Process Bay 2 transfer operations were suspended for the duration of the repair.

Immediate Action Taken

Pump isolated per Permit to Work. Standby transfer routing activated to maintain limited process continuity. Replacement bearing assembly fitted and pump returned to service following vibration verification.

Root Cause

Inadequate lubrication interval combined with delayed response to the vibration alarm trend. Investigation referenced the prior corrective work order on this equipment (WO-2024-1187, 14-Nov-2024), which had already flagged that the standard 90-day lubrication interval specified in SOP-PM-204 may be insufficient for current duty conditions on this pump. That recommendation had not been formally actioned at the time of this failure.

Corrective Action

Lubrication interval for P-204A to be reviewed and SOP-PM-204 updated accordingly. Recommendation from WO-2024-1187 to be formally tracked to closure rather than left as an informal note.

Filed under Unit 4 Incident Records, Process Bay 2 – Pump P-204A. Related record: WO-2024-1187.