

		FAILURE MODE AND EFFECTS ANALYSIS (PROCESS FMEA)											Format No : F/NPD/07						
		Project name:-		952NX		Component Part No.: 92187158		PFMEA no.:MPLUPFPPCHFFPFMEA/05050187158			Released on : 01/07/2022								
		Team Leader:		Mr. Satish Pandey		Component Description-DOOR, ASSY, LH, 952NX			Revision No. : 00										
		Team Members:		Mr. M.SSPRSBYDD/VNKA/AD/OM/SS/AJ		Component Revision No.:- C			PFMEA Last Review Date : 17-07-2025										
PROTOTYPE				PRE-LAUNCH				PRODUCTION											
No.	Process Function	Potential Failure Mode	Potential Effect(s) of Failure	Severity	CL	SS	Potential Cause(s) of Failure	Occurrence	Current Controls Prevention	Current Controls Detection	Detection	RPN	Recommended Action	Responsibility & Completion Date	Action Taken	Revised			
																Sev	Occ	Det	RPN
SUB-ASSY -92187146-1 -Door WA,LH,952NX, Rev-C																			
10	Child Part Collection	Wrong child part used	M/C: Part may be not fitted SO: Operation. Effected CU: Flimnet issue EU: Nil				Wrong part taken		Part no. wise child part storage	Failure Control		0							
20	Tack Welding	Visual Appearance	NO: Part visual appearance poor (4) SO: No Effect (1)				1. Weld feed rate high 2. Oil surface 3. Untrained Operator		1. Set up approval by attribute method	1. Operator Training for Welding		0							
		Weld Strength	NO: Part failure during testing, may be complete lot segregate (6) SO: No Effect (1) CE: Customer high dis-satisfied may be reject the				1. Process parameter variation 2. Oil surface 3. Less Weld Area 4. Fan Over Head		1. Set up approval by attribute method	1. SET UP INSPECTION OF PART 2. INPROCESS INSPECTION WITH BEND GAUGE		0							
30	Full Welding	Visual Appearance	NO: Part visual appearance poor (4) SO: No Effect (1)				1. Weld feed rate high 2. Oil surface 3. Untrained Operator		1. Set up approval by attribute method	1. Operator Training for Welding		0							
		Weld Strength	NO: Part failure during testing, may be complete lot segregate (6) SO: No Effect (1) CE: Customer high dis-satisfied may be reject the				1. Process parameter variation 2. Oil surface 3. Less Weld Area 4. Fan Over Head		1. Set up approval by attribute method	1. SET UP INSPECTION OF PART 2. INPROCESS INSPECTION WITH BEND GAUGE		0							
40	Finishing/Deburring	GRINDING MARKS ON THE SURFACE	M/C: Nil SO: PART MAY BE REJECTED CU: NIL EU: APPEARANCE NOT SMOOTH				1. LOW GRIT GRINDING WHEEL USED		1. USE HIGH GRIT GRINDING WHEEL	1. 100% VISUAL INSPECTION BY OPERATOR		0							
50	Move for Next Process																		
SUB-ASSY -92187146-2 -Door WA,LH,952NX, Rev-C																			
10	Child Part Collection	Wrong child part used	M/C: Part may be not fitted SO: Operation. Effected CU: Flimnet issue EU: Nil				Wrong part taken		Part no. wise child part storage	Failure Control		0							
20	Tack Welding	Visual Appearance	NO: Part visual appearance poor (4) SO: No Effect (1)				1. Weld feed rate high 2. Oil surface 3. Untrained Operator		1. Set up approval by attribute method	1. Operator Training for Welding		0							
		Weld Strength	NO: Part failure during testing, may be complete lot segregate (6) SO: No Effect (1) CE: Customer high dis-satisfied may be reject the				1. Process parameter variation 2. Oil surface 3. Less Weld Area 4. Fan Over Head		1. Set up approval by attribute method	1. SET UP INSPECTION OF PART 2. INPROCESS INSPECTION WITH BEND GAUGE		0							
30	Full Welding	Visual Appearance	NO: Part visual appearance poor (4) SO: No Effect (1)				1. Weld feed rate high 2. Oil surface 3. Untrained Operator		1. Set up approval by attribute method	1. Operator Training for Welding		0							
		Weld Strength	NO: Part failure during testing, may be complete lot segregate (6) SO: No Effect (1) CE: Customer high dis-satisfied may be reject the				1. Process parameter variation 2. Oil surface 3. Less Weld Area 4. Fan Over Head		1. Set up approval by attribute method	1. SET UP INSPECTION OF PART 2. INPROCESS INSPECTION WITH BEND GAUGE		0							
40	Finishing/Deburring	GRINDING MARKS ON THE SURFACE	M/C: Nil SO: PART MAY BE REJECTED CU: NIL EU: APPEARANCE NOT SMOOTH				1. LOW GRIT GRINDING WHEEL USED		1. USE HIGH GRIT GRINDING WHEEL	1. 100% VISUAL INSPECTION BY OPERATOR		0							
50	Move for Next Process																		
Full Welding -92187146-Door WA,LH,952NX, Rev-C																			
10	Child Part Collection	Wrong child part used	M/C: Part may be not fitted SO: Operation. Effected CU: Flimnet issue EU: Nil				Wrong part taken		Part no. wise child part storage	Failure Control		0							
20	Full Welding	Visual Appearance	NO: Part visual appearance poor (4) SO: No Effect (1)				1. Weld feed rate high 2. Oil surface 3. Untrained Operator		1. Set up approval by attribute method	1. Operator Training for Welding		0							
		Weld Strength	NO: Part failure during testing, may be complete lot segregate (6) SO: No Effect (1) CE: Customer high dis-satisfied may be reject the				1. Process parameter variation 2. Oil surface 3. Less Weld Area 4. Fan Over Head		1. Set up approval by attribute method	1. SET UP INSPECTION OF PART 2. INPROCESS INSPECTION WITH BEND GAUGE		0							
30	Finishing/Deburring	GRINDING MARKS ON THE SURFACE	M/C: Nil SO: PART MAY BE REJECTED CU: NIL EU: APPEARANCE NOT SMOOTH				1. LOW GRIT GRINDING WHEEL USED		1. USE HIGH GRIT GRINDING WHEEL	1. 100% VISUAL INSPECTION BY OPERATOR		0							
40	Move for Next Process																		
Painting (DOOR, ASSY, LH, 952NX-92244728) (Power Tan -Std-86628042)																			
10	Transportation to pretreatment	Material Spillage, wrong placement	Material Loss and Damage				Material Overflow		SDP	Area wise SS audit & CLR check sheet As per production plan, and PQ.		0							
20	Knock of Degrease	Total alkali less than 70 ml	Surface not cleaned properly				1. Wrong stacking 2. Un skilled Transport operator LR Crane		1. Stack Designed 2. 100% visual insp. by operator	Periodic insp. by inspector		0							
		Temperature less than 50°C	Surface not cleaned properly				Due to continuous production Bondrite AK-5055 is less		1. Inspection of the Titration once in every shift before start of the process	Inspection of the Titration once in every shift before start of the process		0							
30	Degrease	Pressure of water less than 0.8 kg/Cm2	Part cleaning not done properly				More Bondrite AK - 5055 is mixed by operator		1. Addition of the ARVN water. 2. Heater not working.	1. Visual inspection by the operator in pressure gauge before start of the process and 2 times visually in every shift		0							
		Oil content more than 40g/Ltr	Part surface should be oily				Filter bag choke due to dust		1. Oil separator off 2. Oil separator not working properly	1. Visual inspection by the operator in pressure gauge before start of the process and 2 times visually in every shift		0							
40	Water Rinse 1	Total alkali less than 90 ml	Surface not cleaned properly				1. Oil separator off 2. Oil separator not working properly		Using oil separator to remove oil from water	Inspection of the Titration once in every shift before start of the process		0							
		Temperature less than 50°C	Surface not cleaned properly				More Bondrite AK - 5055 is mixed by operator		1. Inspection of the Titration once in every shift before start of the process	Inspection of the Titration once in every shift before start of the process		0							
50	Water Rinse 2	Pressure of water less than 0.8 kg/Cm2	Part cleaning not done properly				1. Addition of the ARVN water. 2. Heater not working.		1. Visual inspection by the operator in pressure gauge before start of the process and 2 times visually in every shift	1. Visual inspection by the operator in pressure gauge before start of the process and 2 times visually in every shift		0							
		Oil content more than 40g/Ltr	Part surface should be oily				Filter bag choke due to dust		1. Oil separator off 2. Oil separator not working properly	1. Visual inspection by the operator in pressure gauge before start of the process and 2 times visually in every shift		0							
60	Surface Activation	Removal of alkali content	Customer dissatisfaction due to appearance not ok				Improper cleaning of material		1. Inspection of the Alkali once in every shift	1. Inspection of the Alkali once in every shift		0							
70	Phosphate	Uneven phosphate layer on job	Customer dissatisfaction due to appearance not ok				1) Improper cleaning of material 2) Improper parameters of the phosphate process		1. volumetric analysis, 2. pH	Check all the parameters of bath once in a shift		0							
80	Water Rinse 03	Traces of acid	Customer dissatisfaction due to appearance not ok				Improper cleaning of material		1. volumetric analysis	Check all the parameters of bath once in a shift		0							
90	Water Rinse 04	Traces of acid	Customer dissatisfaction due to appearance not ok				Improper cleaning of material		1. volumetric analysis	Check all the parameters of bath once in a shift		0							
100	PPICDM	Cleaning of component not ok	Customer dissatisfaction due to appearance not ok				1) Improper cleaning of material. 2) Chemical concentration Not in Range		Check all the parameters of bath once in a shift	Check all the parameters of bath once in a shift		0							
110	CEC Coating	Dust, rughn,craters, lump,grit/sand,uncover,scratches etc.	Customer dissatisfaction due to appearance not ok				Improper CED coating		1. Maintain level of the pH & conductivity of bath sample, VWA, voltage, current of bath as per requirement.	Check all the parameters of bath once in a day		0							
120	Ultra Filtration	Removal of Excess paint not done properly	Customer dissatisfaction due to appearance not ok				Improper Removal of Excess paint		1. Inspection and maintain pH of bath.	Check all the parameters of bath once in a day		0							
130	IDRCDM	Removal of Excess paint not done	Customer dissatisfaction due to appearance not ok				Removal of Excess paint		1. Maintain conductivity and pH of Bath	Check all the parameters of bath once in a day		0							
140	Unloading	Dust, rughn,craters, lump,grit/sand,uncover,scratches etc.	Customer dissatisfaction due to appearance not ok				Ununiform Coating of component		Defect free component	100 % visual inspection		0							
150	Baking	Temperature is less/more than required	1. Poor Adhesion of paint 2. bulble formation corrosion may occur. 3. Aesthetic issue part may reject 4. Aesthetic issue Corrosion will occur				1. Correct timing is not given for the process 2. Parameter of Certain process is not correctly followed 3. unwanted chemical reactions may occur further		Check control panel setting and conveyor speed	Auto cut off system and temp recording		0							

120	Move for Next Process																			
ABBREVIATION:		M/C- MACHINE	SO- SECOND OPERATION		CU- CUSTOMER USE		EU- EXTERNAL USE													
Prepared By : Mr.Amit Vishwakarma										Approved By- Mr.Prashant Raj Srivastava										
DATE		REV NO.		CHANGES										Prepared By		Approved By				
17-Jul-25		A		Initial for revision no. "C"										Mr.Amit Vishwakarma		Mr. Prashant Raj Srivastava				
Note		PFMEA UPDATE Frequency : During customer complaint / Any process change / Yearly review																		
		ACTION PLAN RULE : Action shall we taken if any RPN value crossed over 100 otherwise no need to take any action																		

