timer: PASS After Raising the Time Limit

PHASE	TEST	STATUS
Phase 2	timer	DIAGNOSTIC PASS



Figure 8. Backup copy of timer_tb.v with repeat (50) changed to repeat (200)

What this shows

- Final check printed: `countbits = 0xdcba0d07 (should be < 0xdcba9876)`, then `Monitor: Test Timer (RTL) Passed`.
- The run finished at 1,250,587,500 ps, which is 600 ns (24 clock cycles) after the original timeout.
- Only the time limit was changed. The original testbench was restored afterwards.

Conclusion. Root cause: the testbench limit was about 24 cycles too short. This is a testbench time-budget issue, not a design bug.