Inspection Summary – HiveRunner H3 Floor Markers after Floor Recoating

Phrom Daen Fulfilment Co., Ltd., Distribution Centre DC-2, Bang Phli, Samut Prakan · Ref. PDF-RB-2026-11 · Issued 24 September 2026

1. Background

The 46 HiveRunner H3 robots in Zone B (aisles B01–B28) find their position by reading square code markers glued to the floor every 1.2 metres. On the nights of 6 and 7 September 2026 the contractor recoated the Zone B floor with a new epoxy sealer. In the following week the robots logged 312 "marker not found" stops, compared with an average of 19 per week in August. This inspection, led by Robotics Maintenance Lead Thipwan Kesorn, checked every marker in Zone B on 15 and 16 September 2026.

2. Findings

- **Markers checked:** 4,860 in total.
- **Grade C (unreadable or lifting):** 214 markers, of which 171 lie in the charging lanes in aisles B25–B28, where the sealer was applied twice.
- **Grade B (readable but glossy):** 602 markers. Robots read them at the normal speed of 1.5 m/s, but not reliably at the old top speed of 2.0 m/s.
- **Grade A (as new):** all remaining markers.

No collision or injury was linked to the stops, but each stop blocked an aisle for about 4 minutes until a technician reset the robot.

3. Actions

All Grade C markers will be replaced by 3 October 2026, starting with the charging lanes. Grade B markers stay in place and will be checked again at the monthly inspection. The Zone B speed limit, temporarily lowered to 1.0 m/s on 9 September, returns to 1.5 m/s once the charging lanes are finished. Any future floor treatment in a robot zone must be approved in writing by the Site Safety Officer, Kittikorn Chaiyawong, at least 10 working days in advance.

4. Replacing a marker

1. Put the aisle in "maintenance" mode on the fleet console, so robots route around it.
2. Scrape off the old marker and clean the spot with the approved solvent; let it dry for 15 minutes.
3. Glue the new marker using the alignment template, with the arrow pointing to the aisle's even-numbered end.
4. Scan the marker with the handheld reader and enter its code in the console before releasing the aisle.

Note. Zone A was not recoated and is not affected. Its recoating, planned for November 2026, is on hold until a matte sealer is proposed.

Fictional document created for testing a question-answering system. All names, figures and organisations are invented.