

# FIELD TECHNICAL REPORT

Confidential - for internal use only

|                                |  |
|--------------------------------|--|
|                                |  |
| After - Countermeasure Failure |  |

## Subject

VJA300-LC300-AFTER CM PBD DOOR NOT WORKING DUE TO DEFEACTIVE TOUCH SENSOR

|                |                                    |            |  |
|----------------|------------------------------------|------------|--|
| Company        | MOHAMED NASER AL-SAYER & SONS EST. |            |  |
| FTR No.        | KUW/142/2026                       |            |  |
| Country,Region | Kuwait                             |            |  |
| Create by      | Abrarahmed Musthaq Shaikh          |            |  |
| Creation Date  | 29/Apr/2026                        | Issue Date |  |

|                  |                          |                 |               |          |        |         |
|------------------|--------------------------|-----------------|---------------|----------|--------|---------|
| VIN              | JTMABBBJ3R4132336        | or              | Model-FrameNo | VJA300   | -      | 4132336 |
| Model            | LAND CRUISER[TMC]-VJA300 |                 |               |          |        |         |
| Model Code       | VJA300L-GNUAZV           |                 |               |          |        |         |
| Engine Type      | V35AFTS                  | Engine No.      | 0224046       | T/M Type | AAJA0F |         |
| Model Year       | 2024                     | Production Date | 11/Jan/2024   |          |        |         |
| Production Plant | 11                       | TMC             |               |          |        |         |

|               |             |                                       |             |
|---------------|-------------|---------------------------------------|-------------|
| Delivery Date | 15/May/2024 | First Complaint Date                  | 23/Mar/2026 |
| Repair Date   | 23/Apr/2026 | <input type="checkbox"/> Not repaired |             |

|                    |        |                                   |   |         |        |                             |                               |
|--------------------|--------|-----------------------------------|---|---------|--------|-----------------------------|-------------------------------|
| Market Impact Rank | Medium | Technical Rank(Initial Judgement) | C | Mileage | 59,710 | <input type="checkbox"/> Km | <input type="checkbox"/> Mile |
|--------------------|--------|-----------------------------------|---|---------|--------|-----------------------------|-------------------------------|

## Reason of decision

AFTER CM FAILURE,

FTR DELAYED DUE TO LATE ARRIVAL OF PARTS

## Complaint situation

|                                                                                                                                                                            |               |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|
| <input type="checkbox"/> Buyback( <input type="checkbox"/> 1 case , <input type="checkbox"/> Over 1 case(       cases) , <input type="checkbox"/> Requested(       cases)) |               |
| <input type="checkbox"/> Complaints out of warranty                                                                                                                        |               |
| <input checked="" type="checkbox"/> After-countemeasure failure                                                                                                            | 2023YE-T/0085 |
| <input type="checkbox"/> From TRIGGER Alarm                                                                                                                                |               |

## Involvement of Third Party

- ☐ Government      ☐ Government official      ☐ Consumer protection      ☐ Police  
☐ Fire department      ☐ Court      ☐ Media  
☐ Others

## Type of Customer

- ☐ Private customer  
☐ Fleet  
☐ Others

## [Replaced Parts List]

|                       |             |                                  |
|-----------------------|-------------|----------------------------------|
| Original Failed Parts | 84280-60060 | SENSOR ASSY, POWER BACK DOOR, LH |
| Component Code        | J99         | J99: ELECTRICAL OTHERS           |

|                 |   |           |   |
|-----------------|---|-----------|---|
| Number of Cases | 1 | Acc.Total | 1 |
|-----------------|---|-----------|---|

## Recovered Parts

|                                                   |                      |                 |     |
|---------------------------------------------------|----------------------|-----------------|-----|
| <input type="checkbox"/> Shipped to               | <input type="text"/> | Courier Company | TBC |
| <input checked="" type="checkbox"/> To be shipped | 10/May/2026          |                 |     |
| <input type="checkbox"/> Not recovered            |                      | Tracking No.    | TBC |
| <input type="checkbox"/> No parts replaced        |                      |                 |     |

|            |         |
|------------|---------|
| Shipped to | TMC-WPC |
|------------|---------|

Attachment related to shipping details (AWB No., Shipping Documents, etc.)

## [Amend Information]

## Comments on Amendment

## [Follow-Up FTR Information]

| No | Regist Date | FTR No. | Subject | Created by |
|----|-------------|---------|---------|------------|
|----|-------------|---------|---------|------------|

## Customer's Voice (Request, Complaint, Order, etc.)

## 1. Phenomenon and Background of how this phenomenon was noticed

Customer noticed back door not operating properly

Customer first observed the symptom condition in mall parking where he tried to open the back door & it got stuck open & customer had to force close

Customer later reported to Toyota dealership

## 2. Detailed condition

2-1. Occurring condition (E.g.: Speed, Shift, E/G rpm, Warning lamps, Frequency of occurrence etc)

Speed: NA

SHIFT:NA

E/G RPM: NA

Warning Lamps: Nil

FOC: Always

2-2. External condition (E.g.: Time, Temperature, Weather, Road condition, Altitude etc)

Time: Irrelevant

Temp: min of 30 degrees to max of 40 degrees Celsius

Weather: Start of summer

Road condition: Well paved

2-3. Usage condition (E.g.: Purpose of use, operating hours, frequency of use etc)

Customer personal usage car

70-80kms/day

3. Risk factors (social media, involvement of authorities, etc.)

NA

## DLR/DIST Confirmation Results (Symptom/Phenomenon/Diagnosis Results)

[\*] Reproducible

[] Non-Reproducible

1. How to reproduce the phenomenon &amp; Result

Concern was duplicated in dealership reception office,  
 Concern can be reproduced easily since FOC is always while operating the  
 back door

2. Occurring condition when reproducing it (E.g.: Speed, Shift, E/G rpm etc)

Speed: NA

SHIFT:NA

E/G RPM: NA

3. Detailed diagnosis contents &amp; Result

4. Repair history / Maintenance record

## Attachment to support DLR/DIST confirmation

|                  |               |
|------------------|---------------|
| SYMPTOM.mp4      | After job.mp4 |
| TEST PART.mp4    | GTS DATA.zip  |
| FTR Details.pptx |               |

## Probable Cause estimated by DLR/DIST

We are not sure about the failure, But we suspect internal failure,

## Attachment to support DLR/DIST estimation

## Correction

- ☐ Difficult to repair  
☐ Problem reoccurred after repair  
☐ Repairable

## Repair Result

## Hyper Link

## Requests / Comments from Customer/DLR/DIST

- ☐ Potential high number of cases      1. Reason of decision on Market impact increasing (E.g.: Parts sales increasing etc)  
☐ Others

2. Request/Comment (Customer/DLR/DIST requirement)

## Attachment to support Requests/Comments

## Warranty / Problem Trend in your market

## Attachment to support Warranty/Problem Trend

## Other Affected Vehicles

| No | VIN               |               | Frame No.   |           |             | Model    |         |  |
|----|-------------------|---------------|-------------|-----------|-------------|----------|---------|--|
|    | Model Code        | Engine No.    | M/Y         | Prod.Date | Engine Type | T/M Type | Mileage |  |
|    | Recoverd Part No. | Part Name     |             |           |             |          |         |  |
|    | Status            | Delivery Date | Repair Date | DLR Code  | Remarks     |          |         |  |

## Replaced Parts List

| No | Part No.    | Part Name                        | Q'ty | OFP |
|----|-------------|----------------------------------|------|-----|
| 1  | 84280-60060 | SENSOR ASSY, POWER BACK DOOR, LH | 1    | [*] |

Information Public Area

Approver

|           |                  |
|-----------|------------------|
| APPROVER1 | Midhun Manmadhan |
| APPROVER2 |                  |
| APPROVER3 |                  |
| APPROVER4 |                  |