CN-TFE airframe logbook: entries from 1 January 2024 to 26 October 2026 (printed extract)

Date	Airframe hours	Work order	Entry	Signed
2024-02-25	12,035.7	WO-2024-0087	100-hour inspection per 14 CFR 91.409(b). Replaced right main tire. Replaced exhaust gasket at cylinder 3. Oil and filter changed.	A. Tazi, MA-B1-0457
2024-04-27	12,130.2	WO-2024-0184	100-hour inspection per 14 CFR 91.409(b). Replaced left brake linings. Replaced all eight spark plugs. Oil and filter changed.	R. El Fassi, MA-B1-0618
2024-05-28	12,177.5	WO-2024-0231	Found a loose pin in the KAP 140 roll servo connector. Repaired connector. Ground test of the autopilot satisfactory.	K. Bennani, MA-B1-0212
2024-06-29	12,226.2	WO-2024-0284	100-hour inspection per 14 CFR 91.409(b). Oil and filter changed.	R. El Fassi, MA-B1-0618
2024-08-28	12,317.7	WO-2024-0374	100-hour inspection per 14 CFR 91.409(b). Replaced left main tire. Serviced nose strut with hydraulic fluid and air. Oil and filter changed.	R. El Fassi, MA-B1-0618
2024-10-21	12,400.0	WO-2024-0457	Removed engine for overhaul. Engine sent to Souss Engine Overhaul, Agadir. Reinstalled the overhauled engine, same serial number. Engine time since overhaul reset to 0.0. Ground run and leak check satisfactory. Engine logbook updated.	K. Bennani, MA-B1-0212
2024-10-31	12,415.2	WO-2024-0475	100-hour inspection per 14 CFR 91.409(b). Removed corrosion, treated and painted battery box; neutralized battery area. Oil and filter changed.	K. Bennani, MA-B1-0212
2024-11-22	12,448.8	WO-2024-0509	Annual inspection per 14 CFR 91.409(a) and the scope and detail of 14 CFR Part 43 Appendix D. Replaced induction air filter. Oil and filter changed.	K. Bennani, MA-B1-0212
2024-12-03	12,465.6	WO-2024-0525	Static system test and altimeter test per 14 CFR 91.411 and Part 43 Appendix E. Transponder test per 14 CFR 91.413 and Part 43 Appendix F. All tests within limits. Next tests due within 24 calendar months.	R. El Fassi, MA-B1-0618
2025-01-21	12,540.3	WO-2025-0032	100-hour inspection per 14 CFR 91.409(b). Adjusted alternator belt tension per maintenance manual. Replaced exhaust gasket at cylinder 3. Oil and filter changed.	A. Tazi, MA-B1-0457
2025-03-22	12,631.8	WO-2025-0122	100-hour inspection per 14 CFR 91.409(b). Replaced left cabin door seal. Replaced all eight spark plugs. Oil and filter changed.	A. Tazi, MA-B1-0457
2025-05-21	12,723.3	WO-2025-0214	100-hour inspection per 14 CFR 91.409(b). Serviced nose strut with hydraulic fluid and air. Replaced left main tire. Cleaned, gapped, and rotated all eight spark plugs. Oil and filter changed.	A. Tazi, MA-B1-0457

Date	Airframe hours	Work order	Entry	Signed
2025-06-24	12,775.1	WO-2025-0264	Pitot heater element open circuit. Replaced pitot tube assembly. Pitot heat check satisfactory.	A. Tazi, MA-B1-0457
2025-07-20	12,814.8	WO-2025-0302	100-hour inspection per 14 CFR 91.409(b). Replaced right main tire. Adjusted alternator belt tension per maintenance manual. Oil and filter changed.	R. El Fassi, MA-B1-0618
2025-09-20	12,909.3	WO-2025-0396	100-hour inspection per 14 CFR 91.409(b). Replaced induction air filter. Removed corrosion, treated and painted battery box; neutralized battery area. Replaced trim tab actuator rod end bearings; free play within limits. Oil and filter changed.	A. Tazi, MA-B1-0457
2025-11-21	13,003.9	WO-2025-0489	Annual inspection per 14 CFR 91.409(a) and the scope and detail of 14 CFR Part 43 Appendix D. Replaced left cabin door seal. Oil and filter changed.	K. Bennani, MA-B1-0212
2026-01-20	13,095.4	WO-2026-0028	100-hour inspection per 14 CFR 91.409(b). Serviced nose strut with hydraulic fluid and air. Oil and filter changed.	R. El Fassi, MA-B1-0618
2026-01-20	13,095.4	WO-2026-0029	Adjusted and lubricated right door latch.	K. Bennani, MA-B1-0212
2026-03-23	13,189.9	WO-2026-0112	100-hour inspection per 14 CFR 91.409(b). Cleaned, gapped, and rotated all eight spark plugs. Replaced all eight spark plugs. Oil and filter changed.	A. Tazi, MA-B1-0457
2026-05-22	13,281.4	WO-2026-0195	100-hour inspection per 14 CFR 91.409(b). Replaced left brake linings. Replaced exhaust gasket at cylinder 3. Oil and filter changed.	A. Tazi, MA-B1-0457
2026-07-24	13,377.5	WO-2026-0281	100-hour inspection per 14 CFR 91.409(b). Replaced trim tab actuator rod end bearings; free play within limits. Oil and filter changed.	A. Tazi, MA-B1-0457
2026-09-26	13,475.1	WO-2026-0367	100-hour inspection per 14 CFR 91.409(b). Replaced left cabin door seal. Oil and filter changed.	A. Tazi, MA-B1-0457