Anfa Aero Services: work order WO-2026-0068

Field	Value
Date completed	18 February 2026
Registration	CN-TFF
Aircraft	Cessna 172S
Serial number	172S11845
Airframe total time at completion (h)	3,728.6
Station	Beni Mellal

Request

100-hour inspection.

Work performed

1. 100-hour inspection per 14 CFR 91.409(b), using the Cessna 172 inspection checklist.
2. Changed engine oil and filter. Compression check, cylinders 1 to 4: 75/80, 77/80, 78/80, 78/80.
3. Discrepancy: Left brake linings at minimum thickness. Corrective action: Replaced left brake linings.
4. Discrepancy: Spark plugs worn beyond limits. Corrective action: Replaced all eight spark plugs.
5. Discrepancy: Left cabin door seal torn. Corrective action: Replaced left cabin door seal.
6. Aircraft found airworthy after correction of the discrepancies listed.

Parts used

Part number	Description	Quantity	Serial number
CH48110-1	Oil filter	1	
REM37BY	Spark plug	8	

Certification: the work above was performed in accordance with 14 CFR Part 43 and the procedures manual. The aircraft is airworthy for the work performed.

Performed by: N. Berrada

Return to service: R. El Fassi, licence MA-B1-0618