ASIST

Concern Details

Your Reference Number is: KM0717652

Logged Date 12-Mar-2009

Base Model 165 Puma Tractor

Concern Description

Engine does not respond to throttle changes

Symptom

Engine does not respond to throttle changes

Resolution

Resolve a transmission configuration error

At machine start up, the Trans Config CAN message is sent from the FPS module for the RD controller to the Display of Gears (DOG). If the DOG does not receive the Trans Config message, CF appears in the DOG. CF indicates a configuration failure.

Troubleshoot the transmission configuration error.

1. Check all connections on the DOG and at the FPS module for the RD controller. Ensure all connections are tight and not damaged.
2. Check the main bulk head connectors under the floor plate. Ensure the connectors are good and the pins are not loose or damaged (for example, a pushed back pin at the XCM controller).
3. Check all of the grounds on the tractor.
    - Make sure all ground locations are clean (for example, free of tape, paint, and dirt) and that they are tight.
    - Check all fuses.
4. Ensure the instrument cluster has keyed power. With the ignition switch in the ON position, check for 12 volts at connector C079, pin 24.
5. Check for positive battery power at connector C079, pin 26. This power should be all the time. If no power is found, look for a loose connector in the battery compartment.
6. Check for stored errors codes and resolve as needed.
7. Connect to the Electronic Service Tool (EST) and ensure all controllers are online.
8. Ensure the CAN-BUS wiring and terminators are not faulty. With the ignition switch in the OFF position, check continuity at the diagnostic connector between pin C and pin D. The reading should be 55 to 60 ohms.
9. If the issue still occurs, check the visctronic fan harness for damage (for example, from shorts).

WARRANTY: Standard warranty terms apply.

12-Mar-2009