

Service Bulletin SB-PX200-04

Synthetic demonstration bulletin | Version 1.1 | Model PX-200
Not ABB equipment. Applies only under the conditions below.

Subject

Reduced cooling-filter inspection interval in dusty or fiber-rich environments.

Applicability

This bulletin applies to synthetic PX-200 controllers installed in woodworking, textile, aggregate-handling, or other locations where airborne dust or fibers can accumulate at the enclosure inlet.

Updated requirement

For affected installations, inspect the cooling filter every **250 operating hours or monthly, whichever occurs first**. This conditionally supersedes the 500-hour normal-condition interval in manual version 1.0 only for the environments listed above.

Record filter condition and heat-sink temperature in the maintenance log. If two consecutive inspections find a blocked filter, assess enclosure placement and consider an approved higher-capacity filtration kit.

E-17 clarification

An E-17 event does not by itself prove the cooling fan has failed. A blocked filter, obstructed exhaust, loose J4 connector, or high ambient temperature can produce the same event. Follow the complete E-17 procedure and diagnostic fan test before replacing the fan.

All electrical inspection remains subject to lockout/tagout and absence-of-voltage requirements in the base manual.