DGM Aircraft / Justice Air Maintenance

9100 Republic Airport Farmingdale, NY 11735 US +1 6312704144 diana@justiceair.com





INVOICE

 BILL TO
 INVOICE
 2174

 Avi
 DATE
 07/09/2024

 Aspire Aviation
 TERMS
 Net 10

 1100 New Highway
 DUE DATE
 07/19/2024

 Farmingdale, NY 11735

ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
Oil Change	N9863L - Oil change required. Drained oil, removed oil filter and checked for contaminants, none found. Installed new tempest oil filter. Serviced engine with 7 quarts Aeroshell 15W-50. Run up, leak checks and system checks good. All work performed I/A/W Piper and Lycoming service manuals. Approved for return to service.	1	150.00	150.00
Flight School Labor Rate	 N9863L Attitude indicator seems to be working fine during flight but not during taxiing. Performed run up and found vacuum pressure below limits at low RPM. Removed and replaced Vacuum pump with new I/A/W Cessna service manual. Run up, leak checks and system checks good. (3.0 hr labor) Radio #2 not working. Please troubleshoot. Re-racked radio, problem continues. Owner advised to go to Avionics shop for repair. (no additional labor charge) Carburetor temp indication inop. Troubleshot and found Carb temp instrument fault. Removed and replaced with new. Installed new Carb temp probe. Run up checks good. (1.5 Hr) Owner reports two Camloc fasteners missing on upper engine cowling. Found both cowling Camlock fastener receptacles damaged. Performed repair to cowling, removed damaged receptacles and replaced with new. Installed new Cam Loc fasteners as required. (1.0 Hr) 	3	95.00	285.00
Parts	Tempest oil filter	1	40.00	40.00
Parts	AeroShell 15W-50 oil	7	14.00	98.00
Parts	Lock washer	2	0.28	0.56
Parts	Vacuum pump (no charge at this time, awaiting assessment from Rapco's warranty)	1	0.00	0.00

Shipping and Freight Charges	Pump sent out for warranty		1	14.11	14.11
Shipping and Freight Charges	Attitude indicator Instrument back to vendor		1	29.81	29.81
WO#829 - Vacuum pump was se	nt for warranty repair.	BALANCE DUE			\$617.48