

Robert J. Franssen
Plant Manager

Susquehanna Nuclear, LLC
769 Salem Boulevard
Berwick, PA 18603
Tel. 570.542.3170 Fax 570.542.1504
robert.franssen@talenenergy.com



NOV 2 1 2016

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555-0001

10 CFR 50.73

SUSQUEHANNA STEAM ELECTRIC STATION
LICENSEE EVENT REPORT 50-387(388)/2016-023-00
UNIT 1 LICENSE NO. NPF-14
UNIT 2 LICENSE NO. NPF-22
PLA-7547

Docket No. 50-387
50-388

Attached is Licensee Event Report (LER) 50-387(388)/2016-023-00. The LER reports an event involving Secondary Containment being declared inoperable due to both doors of an airlock being open at the same time. This event was determined to be reportable in accordance with 10 CFR 50.73(a)(2)(v)(C) as a condition that could have prevented fulfillment of a safety function.

There were no actual consequences to the health and safety of the public as a result of this event.

This letter contains no new regulatory commitments.

A handwritten signature in black ink, appearing to read "R. J. Franssen".

R. J. Franssen

Attachment: LER 50-387(388)/2016-023-00

Copy: NRC Region I
Mr. J. E. Greives, NRC Sr. Resident Inspector
Ms. T. E. Hood, NRC Project Manager
Mr. M. Shields, PA DEP/BRP



LICENSEE EVENT REPORT (LER)

(See Page 2 for required number of digits/characters for each block)

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME

Susquehanna Steam Electric Station Unit 1

2. DOCKET NUMBER

05000387

3. PAGE

1 OF 3

4. TITLE

Secondary Containment Declared Inoperable Due to Airlock Doors Open Due to a Human Performance Error

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
09	26	2016	2016	- 023	- 00	11	21	2016	Susquehanna Steam Electric Station Unit 2	05000388
									FACILITY NAME	DOCKET NUMBER
										05000
9. OPERATING MODE			11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)							
1			☐ 20.2201(b)		☐ 20.2203(a)(3)(i)		☐ 50.73(a)(2)(ii)(A)		☐ 50.73(a)(2)(viii)(A)	
			☐ 20.2201(d)		☐ 20.2203(a)(3)(ii)		☐ 50.73(a)(2)(ii)(B)		☐ 50.73(a)(2)(viii)(B)	
			☐ 20.2203(a)(1)		☐ 20.2203(a)(4)		☐ 50.73(a)(2)(iii)		☐ 50.73(a)(2)(ix)(A)	
			☐ 20.2203(a)(2)(i)		☐ 50.36(c)(1)(i)(A)		☐ 50.73(a)(2)(iv)(A)		☐ 50.73(a)(2)(x)	
10. POWER LEVEL			☐ 20.2203(a)(2)(ii)		☐ 50.36(c)(1)(ii)(A)		☐ 50.73(a)(2)(v)(A)		☐ 73.71(a)(4)	
			☐ 20.2203(a)(2)(iii)		☐ 50.36(c)(2)		☐ 50.73(a)(2)(v)(B)		☐ 73.71(a)(5)	
			☐ 20.2203(a)(2)(iv)		☐ 50.46(a)(3)(ii)		☒ 50.73(a)(2)(v)(C)		☐ 73.77(a)(1)	
			☐ 20.2203(a)(2)(v)		☐ 50.73(a)(2)(i)(A)		☐ 50.73(a)(2)(v)(D)		☐ 73.77(a)(2)(i)	
			☐ 20.2203(a)(2)(vi)		☐ 50.73(a)(2)(i)(B)		☐ 50.73(a)(2)(vii)		☐ 73.77(a)(2)(ii)	
					☐ 50.73(a)(2)(i)(C)		☐ OTHER		Specify in Abstract below or in NRC Form 366A	

12. LICENSEE CONTACT FOR THIS LER

LICENSEE CONTACT

R. B. Genovese - Nuclear Regulatory Affairs

TELEPHONE NUMBER (Include Area Code)

(570) 542-2980

13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT

CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX

14. SUPPLEMENTAL REPORT EXPECTED

☐ YES (If yes, complete 15. EXPECTED SUBMISSION DATE)☒ NO

15. EXPECTED SUBMISSION DATE

MONTH

DAY

YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

On September 26, 2016 at approximately 11:55, the Control Room was informed of an airlock violation on the Refuel Floor. This violation resulted when an escorted individual who was part of a group opened the airlock exit door while the remainder of the group was still entering the airlock. This airlock serves as a secondary containment boundary; as such, having both doors open at the same time results in failure to meet Technical Specification 3.6.4.1 as a result of not satisfying Surveillance Requirement 3.6.4.1.3.

The condition requires a Licensee Event Report (LER) in accordance with 10 CFR 50.73(a)(2)(v)(C).

The cause of the event was less than adequate verification practices to ensure that Secondary Containment door requirements were utilized.

Corrective actions included coaching of the group of escorted individuals and the escorting individual. Additionally, direction for communication of airlock expectations will be added to plant escort expectations.

There were no actual consequences to the health and safety of the public as a result of this event.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-m/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME	2. DOCKET NUMBER	3. LER NUMBER		
		YEAR	SEQUENTIAL NUMBER	REV NO.
Susquehanna Steam Electric Station, Unit 1	05000387	2016	- 023	- 00

NARRATIVE**CONDITIONS PRIOR TO EVENT**

Unit 1 – Mode 1, approximately 100 percent Rated Thermal Power

Unit 2 – Mode 1, approximately 100 percent Rated Thermal Power

There were no structures, systems, or components that were inoperable at the start of the event that contributed to the event.

EVENT DESCRIPTION

On September 26, 2016 at approximately 11:55, a tour group entered an airlock [EIS Component Code: AL] while the escort held the entrance door [EIS Component Code: DR] open. One of the tour group members went in the airlock and immediately opened the exit door. As soon as the alarm [EIS Component Code: ALM] sounded, the escort directed the visitor to reclose the exit door. The exit door was opened about 6 inches and immediately reclosed. This airlock serves as a secondary containment [EIS System Code: VA] boundary; as such, having both doors open at the same time results in failure to meet Technical Specification 3.6.4.1 as a result of not satisfying Surveillance Requirement 3.6.4.1.3.

The individuals were coached again on the air lock door expectations and there were no further issues. The escort was also coached on escorting responsibilities relative to secondary containment doors.

The condition requires a Licensee Event Report (LER) in accordance with 10 CFR 50.73(a)(2)(v)(C).

CAUSE OF EVENT

The cause of this event was less than adequate verification practices to ensure that Secondary Containment door requirements were utilized.

ANALYSIS/SAFETY SIGNIFICANCE

Technical Specification 3.6.4.1 Surveillance Requirement 3.6.4.1.3 requires that one secondary containment access door in each access opening is closed. This event is being reported pursuant to 10 CFR 50.73(a)(2)(v)(C) as having both Secondary Containment airlock doors momentarily open simultaneously resulting in a condition that could have prevented fulfillment of a safety function to mitigate the consequences of an accident by controlling the release of radioactive material.

There was no actual safety consequence as a result of this event. Engineering analysis of this event has determined that secondary containment could have performed its safety function of isolating, as assumed in the accident analysis, and also of re-establishing 0.25 in w.g. vacuum (drawdown) within the assumed accident analysis time (10 minutes). Therefore, the subject event did not cause a loss of safety function.

This event will not be counted as a safety system functional failure (SSFF) for the NRC performance indicator based on the Engineering analysis supporting the system's ability to fulfill the safety function.

CORRECTIVE ACTIONS

Corrective actions completed include coaching of the group of escorted individuals and the escorting individual. Additionally, direction for communication of airlock expectations will be added to plant escort expectations.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME	2. DOCKET NUMBER	3. LER NUMBER		
		YEAR	SEQUENTIAL NUMBER	REV NO.
Susquehanna Steam Electric Station, Unit 1	05000387	2016	- 023	- 00

NARRATIVE**PREVIOUS SIMILAR EVENTS**

The following are recent LERs involving loss of secondary containment due to HuP Error:

LER 50-387(388)/2016-021-00, "Secondary Containment Declared Inoperable Due to Airlock Doors Open Due to a Human Performance Error," dated August 17, 2016 (PLA-7515).

LER 50-387(388)/2016-015-00, "Secondary Containment Declared Inoperable Due to Airlock Doors Open Due to a Human Performance Error," dated June 15, 2016 (PLA-7493).

LER 50-387(388)/2016-014-00, "Secondary Containment Declared Inoperable Due to Airlock Doors Open Due to a Human Performance Error," dated June 9, 2016 (PLA-7492).

LER 50-387(388)/2016-013-00, "Unit 1 Secondary Containment Airlock Doors on 676' opened at same time due to personnel error," dated June 9, 2016 (PLA-7492).

LER 50-387(388)/2016-005-00, "Secondary Containment Declared Inoperable Due to Airlock Doors Open Due to Human Performance Error," dated May 16, 2016 (PLA-7466).

LER 50-387(388)/2016-004-00, "Momentary Loss of Secondary Containment due to Both Airlock Doors on Elevation 779 of the Unit 2 Reactor Building being Opened at the Same Time," dated May 10, 2016 (PLA-7467).

LER 50-387(388)/2015-011-00, "Secondary Containment Declared Inoperable Due to an Airlock Door that Had Not Been Properly Latched," dated January 29, 2016 (PLA-7432).

LER 50-388(387)/2015-006-00, "Secondary Containment Declared Inoperable Due to Secondary Containment Boundary Door 104-R Breached," dated September 18, 2015 (PLA-7383).

LER 50-387/2015-004-00, "Secondary Containment Inoperable due Secondary Containment Boundary Door Found Ajar," dated June 25, 2015 (PLA-7353).

LER 50-388/2015-002-00, "Secondary Containment Inoperability Due Failure to Meet Technical Specification Surveillance Requirement 3.6.4.1.1," dated May 11, 2015 (PLA-7329).