

Brad Berryman
Site Vice President

Susquehanna Nuclear, LLC
769 Salem Boulevard
Berwick, PA 18603
Tel. 570.542.2904 Fax 570.542.1504
Brad.Berryman@TalenEnergy.com



MAR 08 2017

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555-0001

10 CFR 50.73

SUSQUEHANNA STEAM ELECTRIC STATION
LICENSEE EVENT REPORT 50-387(388)/2017-001-00
UNIT 1 LICENSE NO. NPF-14
UNIT 2 LICENSE NO. NPF-22
PLA-7576

Docket No. 50-387
50-388

Attached is Licensee Event Report (LER) 50-387(388)/2017-001-00. This LER reports a condition that could have prevented fulfillment of the Secondary Containment integrity safety function. In this event, both doors for one of the secondary containment access airlocks were briefly opened simultaneously due to a human performance error. This LER is being submitted pursuant to the requirements of 10 CFR 50.73(a)(2)(v)(C).

There were no actual consequences to the health and safety of the public as a result of this event.

This letter contains no new regulatory commitments.

A handwritten signature in black ink, appearing to read "B. Berryman", written over a horizontal line.

B. Berryman

Attachment: LER 50-387(388)/2017-001-00

Copy: NRC Region I
Ms. T. E. Hood, NRC Project Manager
Ms. L. H. Micewski, NRC Sr. Resident Inspector
Mr. M. Shields, PA DEP/BRP



LICENSEE EVENT REPORT (LER)

(See Page 2 for required number of digits/characters for each block)

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollections.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME
Susquehanna Steam Electric Station Unit 1**2. DOCKET NUMBER**
05000387**3. PAGE**
1 OF 3**4. TITLE** Secondary Containment Breach Due to Simultaneous Opening of Airlock Doors

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
01	17	2017	2017	001	00	03	08	2017	Susquehanna Steam Electric Station Unit 2	05000388
									FACILITY NAME	DOCKET NUMBER
										05000

9. OPERATING MODE	11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)			
1	☐ 20.2201(b)	☐ 20.2203(a)(3)(i)	☐ 50.73(a)(2)(ii)(A)	☐ 50.73(a)(2)(viii)(A)
	☐ 20.2201(d)	☐ 20.2203(a)(3)(ii)	☐ 50.73(a)(2)(ii)(B)	☐ 50.73(a)(2)(viii)(B)
	☐ 20.2203(a)(1)	☐ 20.2203(a)(4)	☐ 50.73(a)(2)(iii)	☐ 50.73(a)(2)(ix)(A)
	☐ 20.2203(a)(2)(i)	☐ 50.36(c)(1)(i)(A)	☐ 50.73(a)(2)(iv)(A)	☐ 50.73(a)(2)(x)
10. POWER LEVEL	☐ 20.2203(a)(2)(ii)	☐ 50.36(c)(1)(ii)(A)	☐ 50.73(a)(2)(v)(A)	☐ 73.71(a)(4)
	☐ 20.2203(a)(2)(iii)	☐ 50.36(c)(2)	☐ 50.73(a)(2)(v)(B)	☐ 73.71(a)(5)
	☐ 20.2203(a)(2)(iv)	☐ 50.46(a)(3)(ii)	☒ 50.73(a)(2)(v)(C)	☐ 73.77(a)(1)
	☐ 20.2203(a)(2)(v)	☐ 50.73(a)(2)(i)(A)	☐ 50.73(a)(2)(v)(D)	☐ 73.77(a)(2)(i)
	☐ 20.2203(a)(2)(vi)	☐ 50.73(a)(2)(i)(B)	☐ 50.73(a)(2)(vii)	☐ 73.77(a)(2)(ii)
		☐ 50.73(a)(2)(i)(C)	☐ OTHER	Specify in Abstract below or in NRC Form 366A

12. LICENSEE CONTACT FOR THIS LER

LICENSEE CONTACT

M. L. Krick, Senior Engineer - Nuclear Regulatory Affairs

TELEPHONE NUMBER (Include Area Code)

(570) 542-1818

13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT

CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX
					N/A	N/A	N/A	N/A	N/A

14. SUPPLEMENTAL REPORT EXPECTED☐ YES (If yes, complete 15. EXPECTED SUBMISSION DATE)☒ NO**15. EXPECTED SUBMISSION DATE**

MONTH DAY YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

On January 17, 2017 at approximately 11:45, three employees with a group of visitors were exiting the Unit 1 Reactor Building Airlock on Elevation 676'. While processing through the card reader, an individual in the group opened the Turbine Building airlock door prior to the Reactor Building airlock door being completely closed. This resulted in not meeting Technical Specification 3.6.4.1 Surveillance Requirement 3.6.4.1.3, which requires that one secondary containment access door in each access opening is closed.

The cause of this event was determined to be less than adequate use of Human Performance Tools, including Self-Checking/ Stop, Think, Act and Review (STAR).

This condition requires reporting in accordance with 10 CFR 50.73(a)(2)(v)(C) as having both Secondary Containment airlock doors momentarily open simultaneously results in a condition that could have prevented fulfillment of a safety function.

There were no actual consequences to the health and safety of the public as a result of this event.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME	2. DOCKET NUMBER	3. LER NUMBER		
		YEAR	SEQUENTIAL NUMBER	REV NO.
Susquehanna Steam Electric Station Unit 1	05000387	2017	- 001	- 00

NARRATIVE**CONDITIONS PRIOR TO EVENT**

Unit 1 – Mode 1, approximately 100 percent Rated Thermal Power

Unit 2 – Mode 1, approximately 100 percent Rated Thermal Power

There were no systems, structures or components that were inoperable at the start of the event and contributed to the event.

EVENT DESCRIPTION

On January 17, 2017 at approximately 11:45, three employees with a group of visitors were exiting the Unit 1 Reactor Building [EIS Component Identifier: AL] Airlock [EIS Component Identifier: DR] on Elevation 676'. While processing through the card reader, an individual in the group opened the Turbine Building [EIS Component Identifier: NM] airlock door prior to the Reactor Building airlock door being completely closed. Upon hearing the alarm, security, who was present to help process visitors through the card reader, notified Security Control and the Shift Manager. All personnel then provided statements with respect to the event.

CAUSE OF EVENT

The cause of the event was determined to be less than adequate use of Human Performance Tools including Self-Check (STAR).

ANALYSIS/SAFETY SIGNIFICANCE

Technical Specification 3.6.4.1 Surveillance Requirement 3.6.4.1.3 requires that one secondary containment access door in each access opening is closed. This event is being reported pursuant to 10 CFR 50.73(a)(2)(v)(C) as having both Secondary Containment airlock doors momentarily open simultaneously results in a condition that could have prevented fulfillment of a safety function to mitigate the consequences of an accident by controlling the release of radioactive material.

There was no actual safety consequence as a result of this event. Engineering analysis of this event has determined that secondary containment could have performed its safety function of isolating, as assumed in the accident analysis, and also of re-establishing 0.25 in w.g. vacuum (drawdown) within the assumed accident analysis time (10 minutes). Therefore, the subject event did not cause a loss of safety function.

This event will not be counted as a safety system functional failure (SSFF) for the NRC performance indicator based on the Engineering analysis supporting the system's ability to fulfill the safety function.

CORRECTIVE ACTIONS

Key corrective actions include the following:

1. Coaching was provided to the individuals involved with respect to the use of airlock doors (Complete).



LICENSEE EVENT REPORT (LER) CONTINUATION SHEET

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME	2. DOCKET NUMBER	3. LER NUMBER		
		YEAR	SEQUENTIAL NUMBER	REV NO.
Susquehanna Steam Electric Station Unit 1	05000387	2017	- 001	- 00

PREVIOUS SIMILAR EVENTS

The following recent LERs involved loss of Secondary Containment due to door issues:

LER 50-387(388)/ 2016-025-00 (PLA-7569), "Secondary Containment Breach due to Simultaneous Opening of Airlock Doors," dated January 26, 2017.

LER 50-387(388)/ 2016-023-00 (PLA-7547), "Secondary Containment Declared Inoperable Due to Airlock Doors Open Due to a Human Performance Error," dated November 21, 2016.

LER 50-387(388)/ 2016-022-00 (PLA-7544), "Secondary Containment Breach due to Simultaneous Opening of Airlock Doors," dated December 1, 2016.

LER 50-387(388)/ 2016-021-00 (PLA-7515), "Secondary Containment Declared Inoperable Due to Airlock Doors Open Due to a Human Performance Error," dated, August 17, 2016.

LER 50-387(388)/ 2016-017-00 (PLA-7564), "Secondary Containment Declared Inoperable Due to Airlock Doors Open Due to Human Performance Error During Security Response," dated December 21, 2016.

LER 50-387(388)/ 2016-015-00 (PLA-7493), "Secondary Containment Declared Inoperable Due to Airlock Doors Open Due to a Human Performance Error," dated June 15, 2016.

LER 50-387(388)/ 2016-014-00 (PLA-7489), "Secondary Containment Declared Inoperable Due to Airlock Doors Open Due to a Human Performance Error," dated June 9, 2016.

LER 50-387(388)/ 2016-013-00 (PLA-7492), "Secondary Containment Declared Inoperable Due to Simultaneous Opening of Double Airlock Doors," dated June 9, 2016.

LER 50-387(388)/ 2016-005-00 (PLA-7466), "Secondary Containment Declared Inoperable Due to Airlock Doors Open Due to a Human Performance Error," dated May 16, 2016.

LER 50-387(388)/ 2016-004-00 (PLA-7467), "Momentary Loss of Secondary Containment due to Both Airlock Doors on Elevation 779 of the Unit 2 Reactor Building being Opened at the Same Time," dated May 10, 2016.

LER 50-387(388)/2016-002-00 (PLA-7454), "Secondary Containment Declared Inoperable due to an Airlock Doors Open Due to Random Occurrence," dated April 18, 2016.

LER 50-387(388)/ 2016-001-00 (PLA-7453), "Secondary Containment Declared Inoperable Due to an Airlock Door Open Due to Random Occurrence," dated April 18, 2016.