

Brad Berryman
Site Vice President

Susquehanna Nuclear, LLC
769 Salem Boulevard
Berwick, PA 18603
Tel. 570.542.2904 Fax 570.542.1504
Brad.Berryman@TalenEnergy.com



APR 13 2017

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555-0001

10 CFR 50.73

**SUSQUEHANNA STEAM ELECTRIC STATION
LICENSEE EVENT REPORT 50-388(387)/2017-003-00
UNIT 1 LICENSE NO. NPF-14
UNIT 2 LICENSE NO. NPF-22
PLA-7587**

**Docket No. 50-387
50-388**

Attached is Licensee Event Report (LER) 50-388(387)/2017-003-00. This LER reports a condition that could have prevented fulfillment of the Secondary Containment integrity safety function. In this event, both doors for one of the secondary containment access airlocks were briefly opened simultaneously due to a human performance error. This LER is being submitted pursuant to the requirements of 10 CFR 50.73(a)(2)(v)(C).

There were no actual consequences to the health and safety of the public as a result of this event.

This letter contains no new regulatory commitments.

A handwritten signature in blue ink, appearing to be "B. Berryman", with a long horizontal stroke extending to the right.

B. Berryman

Attachment: LER 50-388(387)/2017-003-00

Copy: NRC Region I
Ms. T. E. Hood, NRC Project Manager
Ms. L. H. Micewski, NRC Sr. Resident Inspector
Mr. M. Shields, PA DEP/BRP

NRC FORM 366 (06-2016)		U.S. NUCLEAR REGULATORY COMMISSION			APPROVED BY OMB: NO. 3150-0104			EXPIRES: 10/31/2018			
 LICENSEE EVENT REPORT (LER) (See Page 2 for required number of digits/characters for each block)		Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.									
1. FACILITY NAME Susquehanna Steam Electric Station Unit 2					2. DOCKET NUMBER 05000388			3. PAGE 1 OF 3			
4. TITLE Secondary Containment Breach Due to Simultaneous Opening of Airlock Doors											
5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER	
03	02	2017	2017	003	00	04	13	2017	Susquehanna Steam Electric Station Unit 1	05000387	
									FACILITY NAME	DOCKET NUMBER	
										05000	
9. OPERATING MODE		11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)									
1		☐ 20.2201(b)			☐ 20.2203(a)(3)(i)			☐ 50.73(a)(2)(ii)(A)		☐ 50.73(a)(2)(viii)(A)	
		☐ 20.2201(d)			☐ 20.2203(a)(3)(ii)			☐ 50.73(a)(2)(ii)(B)		☐ 50.73(a)(2)(viii)(B)	
		☐ 20.2203(a)(1)			☐ 20.2203(a)(4)			☐ 50.73(a)(2)(iii)		☐ 50.73(a)(2)(ix)(A)	
		☐ 20.2203(a)(2)(i)			☐ 50.36(c)(1)(i)(A)			☐ 50.73(a)(2)(iv)(A)		☐ 50.73(a)(2)(x)	
10. POWER LEVEL 89%		☐ 20.2203(a)(2)(ii)			☐ 50.36(c)(1)(ii)(A)			☐ 50.73(a)(2)(v)(A)		☐ 73.71(a)(4)	
		☐ 20.2203(a)(2)(iii)			☐ 50.36(c)(2)			☐ 50.73(a)(2)(v)(B)		☐ 73.71(a)(5)	
		☐ 20.2203(a)(2)(iv)			☐ 50.46(a)(3)(ii)			☒ 50.73(a)(2)(v)(C)		☐ 73.77(a)(1)	
		☐ 20.2203(a)(2)(v)			☐ 50.73(a)(2)(i)(A)			☐ 50.73(a)(2)(v)(D)		☐ 73.77(a)(2)(i)	
		☐ 20.2203(a)(2)(vi)			☐ 50.73(a)(2)(i)(B)			☐ 50.73(a)(2)(vii)		☐ 73.77(a)(2)(ii)	
					☐ 50.73(a)(2)(i)(C)			☐ OTHER Specify in Abstract below or in NRC Form 366A			
12. LICENSEE CONTACT FOR THIS LER											
LICENSEE CONTACT R. B. Genovese - Nuclear Regulatory Affairs								TELEPHONE NUMBER (Include Area Code) (570) 542-2980			
13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT											
CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX		
					N/A	N/A	N/A	N/A	N/A		
14. SUPPLEMENTAL REPORT EXPECTED						15. EXPECTED SUBMISSION DATE		MONTH	DAY	YEAR	
☐ YES (If yes, complete 15. EXPECTED SUBMISSION DATE) ☒ NO											
ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)											
On March 2, 2017, at approximately 0930, two employees were transporting a cart of scaffold materials from Reactor Building Elevation 818' to Elevation 779'. While maneuvering the cart through an airlock on Elevation 779', personnel failed to ensure that the Reactor Building-side airlock door was fully closed prior to opening the Turbine Building-side airlock door. This resulted in not meeting Technical Specification 3.6.4.1 Surveillance Requirement 3.6.4.1.3, which requires that one secondary containment access door in each access opening is closed. The cause of this event was determined to be less than adequate use of Human Performance Tools, specifically Verification Practices. This condition requires reporting in accordance with 10 CFR 50.73(a)(2)(v)(C) as having both Secondary Containment airlock doors momentarily open simultaneously results in a condition that could have prevented fulfillment of a safety function. There were no actual consequences to the health and safety of the public as a result of this event.											

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME	2. DOCKET NUMBER	3. LER NUMBER		
		YEAR	SEQUENTIAL NUMBER	REV NO.
Susquehanna Steam Electric Station Unit 2	05000388	2017	- 003	- 00

NARRATIVE**CONDITIONS PRIOR TO EVENT**

Unit 1 – Mode 1, approximately 100 percent Rated Thermal Power

Unit 2 – Mode 1, approximately 89 percent Rated Thermal Power

There were no systems, structures or components that were inoperable at the start of the event and contributed to the event.

EVENT DESCRIPTION

On March 2, 2017, at approximately 0930, two contract employees were transporting a cart of scaffold materials from Reactor Building [EIS Component Identifier: NG] Elevation 818' to Elevation 779'. While maneuvering the cart through an airlock [EIS Component Identifier: AL] on Elevation 779', personnel failed to ensure that the Reactor Building-side airlock door [EIS Component Identifier: DR] was fully closed prior to opening the Turbine Building-side [EIS Component Identifier: NM] airlock door. This resulted in not meeting Technical Specification 3.6.4.1 Surveillance Requirement 3.6.4.1.3, which requires that one secondary containment access door in each access opening is closed.

CAUSE OF EVENT

The cause of this event was determined to be less than adequate use of Human Performance Tools, specifically Verification Practices.

ANALYSIS/SAFETY SIGNIFICANCE

Technical Specification 3.6.4.1 Surveillance Requirement 3.6.4.1.3 requires that one secondary containment access door in each access opening is closed. This event is being reported pursuant to 10 CFR 50.73(a)(2)(v)(C) as having both Secondary Containment airlock doors momentarily open simultaneously results in a condition that could have prevented fulfillment of a safety function to mitigate the consequences of an accident by controlling the release of radioactive material.

There was no actual safety consequence as a result of this event. Engineering analysis of this event has determined that secondary containment could have performed its safety function of isolating, as assumed in the accident analysis, and also of re-establishing 0.25 in w.g. vacuum (drawdown) within the assumed accident analysis time (10 minutes). Therefore, this event will not be counted as a safety system functional failure (SSFF) for the NRC performance indicator.

CORRECTIVE ACTIONS

Key corrective actions include the following:

1. Review Secondary Containment door verification practices communication with all employees of this contractor (Complete).



LICENSEE EVENT REPORT (LER) CONTINUATION SHEET

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME	2. DOCKET NUMBER	3. LER NUMBER		
		YEAR	SEQUENTIAL NUMBER	REV NO.
Susquehanna Steam Electric Station Unit 2	05000388	2017	- 003	- 00

PREVIOUS SIMILAR EVENTS

The following recent LERs involved loss of Secondary Containment due to simultaneous door opening:

LER 50-387(388)/ 2016-025-00 (PLA-7569), "Secondary Containment Breach due to Simultaneous Opening of Airlock Doors," dated January 26, 2017.

LER 50-387(388)/ 2016-023-00 (PLA-7547), "Secondary Containment Declared Inoperable Due to Airlock Doors Open Due to a Human Performance Error," dated November 21, 2016.

LER 50-387(388)/ 2016-022-00 (PLA-7544), "Secondary Containment Breach due to Simultaneous Opening of Airlock Doors," dated December 1, 2016.

LER 50-387(388)/ 2016-021-00 (PLA-7515), "Secondary Containment Declared Inoperable Due to Airlock Doors Open Due to a Human Performance Error," dated, August 17, 2016.

LER 50-387(388)/ 2016-017-00 (PLA-7564), "Secondary Containment Declared Inoperable Due to Airlock Doors Open Due to Human Performance Error During Security Response," dated December 21, 2016.

LER 50-387(388)/ 2016-015-00 (PLA-7493), "Secondary Containment Declared Inoperable Due to Airlock Doors Open Due to a Human Performance Error," dated June 15, 2016.

LER 50-387(388)/ 2016-014-00 (PLA-7489), "Secondary Containment Declared Inoperable Due to Airlock Doors Open Due to a Human Performance Error," dated June 9, 2016.

LER 50-387(388)/ 2016-013-00 (PLA-7492), "Secondary Containment Declared Inoperable Due to Simultaneous Opening of Double Airlock Doors," dated June 9, 2016.

LER 50-387(388)/ 2016-005-00 (PLA-7466), "Secondary Containment Declared Inoperable Due to Airlock Doors Open Due to a Human Performance Error," dated May 16, 2016.

LER 50-387(388)/ 2016-004-00 (PLA-7467), "Momentary Loss of Secondary Containment due to Both Airlock Doors on Elevation 779 of the Unit 2 Reactor Building being Opened at the Same Time," dated May 10, 2016.

LER 50-387(388)/2016-002-00 (PLA-7454), "Secondary Containment Declared Inoperable due to an Airlock Doors Open Due to Random Occurrence," dated April 18, 2016.

LER 50-387(388)/ 2016-001-00 (PLA-7453), "Secondary Containment Declared Inoperable Due to an Airlock Door Open Due to Random Occurrence," dated April 18, 2016.