

Brad Berryman
Site Vice President

Susquehanna Nuclear, LLC
769 Salem Boulevard
Berwick, PA 18603
Tel. 570.542.2904 Fax 570.542.1504
Brad.Berryman@TalenEnergy.com



APR 25 2017

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555-0001

10 CFR 50.73

SUSQUEHANNA STEAM ELECTRIC STATION
LICENSEE EVENT REPORT 50-388(387)/2017-004-00
UNIT 2 LICENSE NO. NPF-22
UNIT 1 LICENSE NO. NPF-14
PLA-7596

Docket No. 50-388
50-387

Attached is Licensee Event Report (LER) 50-388(387)/2017-004-00. This LER reports a condition that could have prevented fulfillment of the Secondary Containment integrity safety function. In this event, both doors for one of the secondary containment access airlocks were briefly opened simultaneously due to a human performance error. This LER is being submitted pursuant to the requirements of 10 CFR 50.73(a)(2)(v)(C).

There were no actual consequences to the health and safety of the public as a result of this event.

This letter contains no new regulatory commitments.

A handwritten signature in black ink, appearing to be "B. Berryman" with a stylized flourish at the end.

B. Berryman

Attachment: LER 50-388(387)/2017-004-00

Copy: NRC Region I
Ms. T. E. Hood, NRC Project Manager
Ms. L. H. Micewski, NRC Sr. Resident Inspector
Mr. M. Shields, PA DEP/BRP

NRC FORM 366 (04-2017)		U.S. NUCLEAR REGULATORY COMMISSION			APPROVED BY OMB: NO. 3150-0104			EXPIRES: 03/31/2020			
 LICENSEE EVENT REPORT (LER) (See Page 2 for required number of digits/characters for each block)										Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.	
1. FACILITY NAME Susquehanna Steam Electric Station Unit 2					2. DOCKET NUMBER 05000388			3. PAGE 1 OF 3			
4. TITLE Secondary Containment Breach Due to Simultaneous Opening of Airlock Doors											
5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER	
03	02	2017	2017	004	00	04	25	2017	Susquehanna Steam Electric Station Unit 1	05000387	
									FACILITY NAME	DOCKET NUMBER	
										05000	
9. OPERATING MODE		11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)									
1		☐ 20.2201(b)			☐ 20.2203(a)(3)(i)			☐ 50.73(a)(2)(ii)(A)		☐ 50.73(a)(2)(viii)(A)	
		☐ 20.2201(d)			☐ 20.2203(a)(3)(ii)			☐ 50.73(a)(2)(ii)(B)		☐ 50.73(a)(2)(viii)(B)	
		☐ 20.2203(a)(1)			☐ 20.2203(a)(4)			☐ 50.73(a)(2)(iii)		☐ 50.73(a)(2)(ix)(A)	
		☐ 20.2203(a)(2)(i)			☐ 50.36(c)(1)(i)(A)			☐ 50.73(a)(2)(iv)(A)		☐ 50.73(a)(2)(x)	
10. POWER LEVEL 088		☐ 20.2203(a)(2)(ii)			☐ 50.36(c)(1)(ii)(A)			☐ 50.73(a)(2)(v)(A)		☐ 73.71(a)(4)	
		☐ 20.2203(a)(2)(iii)			☐ 50.36(c)(2)			☐ 50.73(a)(2)(v)(B)		☐ 73.71(a)(5)	
		☐ 20.2203(a)(2)(iv)			☐ 50.46(a)(3)(ii)			☒ 50.73(a)(2)(v)(C)		☐ 73.77(a)(1)	
		☐ 20.2203(a)(2)(v)			☐ 50.73(a)(2)(i)(A)			☐ 50.73(a)(2)(v)(D)		☐ 73.77(a)(2)(i)	
		☐ 20.2203(a)(2)(vi)			☐ 50.73(a)(2)(i)(B)			☐ 50.73(a)(2)(vii)		☐ 73.77(a)(2)(ii)	
					☐ 50.73(a)(2)(i)(C)			☐ OTHER		Specify in Abstract below or in NRC Form 366A	
12. LICENSEE CONTACT FOR THIS LER											
LICENSEE CONTACT M. L. Krick, Senior Engineer - Nuclear Regulatory Affairs								TELEPHONE NUMBER (Include Area Code) (570) 542-1818			
13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT											
CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX		
					N/A	N/A	N/A	N/A	N/A		
14. SUPPLEMENTAL REPORT EXPECTED						15. EXPECTED SUBMISSION DATE		MONTH	DAY	YEAR	
☐ YES (If yes, complete 15. EXPECTED SUBMISSION DATE) ☒ NO											
ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) On March 2, 2017 at approximately 10:30, three employees were entering the Unit 2 Airlock on elevation 676' from the Reactor Building door. After entering the airlock, one employee opened the second airlock door prior to the first door being closed, resulting in an alarm. This resulted in not meeting Technical Specification 3.6.4.1 Surveillance Requirement 3.6.4.1.3, which requires that one secondary containment access door in each access opening is closed. The cause of this event was determined to be less than adequate Situational Awareness. This condition requires reporting in accordance with 10 CFR 50.73(a)(2)(v)(C) as having both Secondary Containment airlock doors momentarily open simultaneously results in a condition that could have prevented fulfillment of a safety function. There were no actual consequences to the health and safety of the public as a result of this event.											

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME	2. DOCKET NUMBER	3. LER NUMBER		
		YEAR	SEQUENTIAL NUMBER	REV NO.
Susquehanna Steam Electric Station Unit 2	05000-388	2017	- 004	- 00

NARRATIVE**CONDITIONS PRIOR TO EVENT**

Unit 1 – Mode 1, approximately 100 percent Rated Thermal Power

Unit 2 – Mode 1, approximately 88 percent Rated Thermal Power

EVENT DESCRIPTION

On March 2, 2017 at approximately 10:30, three employees were entering the Unit 2 Airlock [EIS Component Identifier: AL] on elevation 676' from the Reactor Building [EIS System Identifier: NG] door. The first employee observed the green light, swiped their badge and entered into the airlock. The two additional employees also swiped their badges and traversed into the airlock. As the first employee opened the second door within the airlock, the airlock door alarm sounded briefly as the first door was not completely closed and latched. Upon hearing the alarm, the employees promptly reported the incident to oversight and Operations. All personnel then provided statements with respect to the event.

CAUSE OF EVENT

The cause of the event was determined to be less than adequate use of Situational Awareness.

ANALYSIS/SAFETY SIGNIFICANCE

Technical Specification 3.6.4.1 Surveillance Requirement 3.6.4.1.3 requires that one secondary containment access door in each access opening is closed. This event is being reported pursuant to 10 CFR 50.73(a)(2)(v)(C) as having both Secondary Containment airlock doors momentarily open simultaneously results in a condition that could have prevented fulfillment of a safety function to mitigate the consequences of an accident by controlling the release of radioactive material.

There was no actual safety consequence as a result of this event. Engineering analysis of this event has determined that secondary containment could have performed its safety function of isolating, as assumed in the accident analysis, and also of re-establishing 0.25 in w.g. vacuum (drawdown) within the assumed accident analysis time (10 minutes). Therefore, the subject event did not cause a loss of safety function.

This event will not be counted as a safety system functional failure (SSFF) for the NRC performance indicator based on the Engineering analysis supporting the system's ability to fulfill the safety function.

CORRECTIVE ACTIONS

Key corrective actions include the following:

1. Coaching was provided to the individuals involved with respect to the use of airlock doors (Complete).

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME	2. DOCKET NUMBER	3. LER NUMBER		
		YEAR	SEQUENTIAL NUMBER	REV NO.
Susquehanna Steam Electric Station Unit 2	05000-388	2017	- 004	- 00

PREVIOUS SIMILAR EVENTS

The following recent LERs involving loss of Secondary Containment due to door issues:

LER 50-387 / 2017-001-00 (PLA-7576), "Secondary Containment Breach due to Simultaneous Opening of Airlock Doors," dated March 8, 2017.

LER 50-387(388)/ 2016-001-00 (PLA-7453), "Secondary Containment Declared Inoperable Due to an Airlock Door Open Due to Random Occurrence," dated April 18, 2016.

LER 50-387(388)/2016-002-00 (PLA-7454), "Secondary Containment Declared Inoperable due to an Airlock Doors Open Due to Random Occurrence," dated April 18, 2016.

LER 50-387/ 2015-011-00 (PLA-7432), "Secondary Containment Declared Inoperable Due to an Airlock Door that had not been Properly Latched," dated January 29, 2016.

LER 50-387(388) 2015-006-00 (PLA-7383), "Secondary Containment Declared Inoperable Due to Secondary Containment Boundary Door 104-R Breached," dated September 18, 2015.

LER 50-387/ 2015-004-00 (PLA-7353), "Secondary Containment Inoperable due Secondary Containment Boundary Door Found Ajar," dated June 25, 2015.

LER 50-387(388)/ 2015-002-00 (PLA-7329), "Secondary Containment Inoperability due Failure to Meet Technical Specification Surveillance Requirement 3.6.4.1.1," dated June 10, 2015.

LER 50-387(388)/2014-002-00 (PLA-7155), "Secondary Containment Door found Ajar," dated April 9, 2014.

LER 50-388(387)/ 2014-001-00 (PLA-7270), "Both Doors of a Secondary Containment Personnel Airlock Momentarily Open Due to a Personnel Error Resulting in Entry into Secondary Containment Technical Specification Limiting Condition for Operation," dated December 31, 2014.