



Entergy Operations, Inc.
P.O. Box 756
Port Gibson, MS 39150

Gregory G. Hawkins
Director Regulatory & Performance
Improvement
Grand Gulf Nuclear Station

GNRO-2017/00054

September 7, 2017

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
11555 Rockville Pike
Rockville, MD 20852

SUBJECT: Loss of Safety Function and Control Room Envelope Due to an Open Boundary
Door
Docket No. 50-416
License No. NPF-29

Dear Sir or Madam:

Attached is Licensee Event Report (LER) 2017-005-00, Loss of Safety Function and Control Room Envelope Due to an Open Boundary Door.

This letter contains no new commitments. Should you have any questions or require additional information, please contact Douglas Neve, Manager Regulatory Assurance at (601) 437-2103.

Sincerely,

A handwritten signature in black ink, appearing to read "Greg Hawkins", is written over the "Sincerely," text.

Gregory G. Hawkins
Director Regulatory and Performance Improvement
Grand Gulf Nuclear Station
GGH/ram

Attachment: Licensee Event Report (LER) 2017-005-00

cc: (See Next Page)

cc: with Attachment and Enclosures

Mr. John P. Boska, Project Manager
Plant Licensing Branch 1-1
Division of Operating Reactor Licensing
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Mail Stop 0-8-C2
Washington, DC 20555

Mr. Scott Morris
U.S. Nuclear Regulatory Commission
Acting Regional Administrator, Region IV
1600 East Lamar Boulevard
Arlington, TX 76011-4511

Mr. Siva Lingham
U.S. Nuclear Regulatory Commission
Mail Stop OWFN 8 B1
Rockville, MD 20852-2738

NRC Senior Resident Inspector
Grand Gulf Nuclear Station
Port Gibson, MS 39150

Attachment

Licensee Event Report (LER) 2017-005-00

NRC FORM 366 (04-2017)		U.S. NUCLEAR REGULATORY COMMISSION			APPROVED BY OMB: NO. 3150-0104 EXPIRES: 03/31/2020 Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.					
		LICENSEE EVENT REPORT (LER) (See Page 2 for required number of digits/characters for each block) (See NUREG-1022, R.3 for instruction and guidance for completing this form http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/)								
1. FACILITY NAME Grand Gulf Nuclear Station, Unit 1					2. DOCKET NUMBER 05000 416		3. PAGE 1 OF 3			
4. TITLE Loss of Safety Function and Control Room Envelope Due to an Open Boundary Door										
5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
7	9	2017	2017 - 005 - 00			9	7	2017	N/A	05000 N/A
11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: <i>(Check all that apply)</i>										
9. OPERATING MODE 1		☐ 20.2201(b)		☐ 20.2203(a)(3)(i)		☐ 50.73(a)(2)(ii)(A)		☐ 50.73(a)(2)(viii)(A)		
		☐ 20.2201(d)		☐ 20.2203(a)(3)(ii)		☐ 50.73(a)(2)(ii)(B)		☐ 50.73(a)(2)(viii)(B)		
		☐ 20.2203(a)(1)		☐ 20.2203(a)(4)		☐ 50.73(a)(2)(iii)		☐ 50.73(a)(2)(ix)(A)		
		☐ 20.2203(a)(2)(i)		☐ 50.36(c)(1)(i)(A)		☐ 50.73(a)(2)(iv)(A)		☐ 50.73(a)(2)(x)		
		☐ 20.2203(a)(2)(ii)		☐ 50.36(c)(1)(ii)(A)		☐ 50.73(a)(2)(v)(A)		☐ 73.71(a)(4)		
10. POWER LEVEL 100		☐ 20.2203(a)(2)(iii)		☐ 50.36(c)(2)		☐ 50.73(a)(2)(v)(B)		☐ 73.71(a)(5)		
		☐ 20.2203(a)(2)(iv)		☐ 50.46(a)(3)(ii)		☐ 50.73(a)(2)(v)(C)		☐ 73.77(a)(1)		
		☐ 20.2203(a)(2)(v)		☐ 50.73(a)(2)(i)(A)		☒ 50.73(a)(2)(v)(D)		☐ 73.77(a)(2)(i)		
		☐ 20.2203(a)(2)(vi)		☐ 50.73(a)(2)(i)(B)		☐ 50.73(a)(2)(vii)		☐ 73.77(a)(2)(ii)		
				☐ 50.73(a)(2)(i)(C)		☐ OTHER Specify in Abstract below or in NRC Form 366A				
12. LICENSEE CONTACT FOR THIS LER										
FACILITY NAME Douglas Neve / Manager, Regulatory Assurance								TELEPHONE NUMBER (Include Area Code) (601) 437-2103		
13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT										
CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX	
N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
14. SUPPLEMENTAL REPORT EXPECTED						15. EXPECTED SUBMISSION DATE				
☐ YES (If yes, complete 15. EXPECTED SUBMISSION DATE) ☒ NO						MONTH DAY YEAR N/A N/A N/A				
ABSTRACT <i>(Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)</i> On July 9, 2017, at approximately 2158 hours central daylight time a pressure boundary door to the Control Room Envelope was left unsecure. The Control Room Envelope was inoperable for approximately one minute, at which time the door was closed. Grand Gulf Nuclear Station personnel identified that a loss of Safety Function occurred due to a breach in the Control Room Envelope resulting in inoperability of both divisions of Standby Fresh Air. This event is being reported under 10CFR 50.72(a)(2)(v)(D), as any event or condition that, at the time of discovery, could have prevented the fulfillment of the safety function of structures or systems that are needed to mitigate the consequences of an accident. The cause was determined to be that the organization failed to understand the nuclear safety consequence associated with a degraded condition of door SZ100C516 and failed to implement a mitigating strategy. Corrective actions included restoration of the door to operable status and coaching of the responsible individual. Future corrective action will include implementation of a maintenance strategy for control room pressure boundary doors to ensure reliable operation. There were no nuclear safety consequences or radiological consequences as a result of this event.										

NRC FORM
(4-2017)

366A U.S. NUCLEAR REGULATORY COMMISSION

APPROVED BY OMB: NO. 3150-0104

EXPIRES: 3/31/2020



LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME	2. DOCKET	3. LER NUMBER		
		YEAR	SEQUENTIAL NUMBER	REV. NO.
Grand Gulf Nuclear Station, Unit 1	05000 416			
			2017 - 005 - 00	

NARRATIVE

DESCRIPTION

On July 9, 2017, at approximately 2158 hours central daylight time a pressure boundary door to the Control Room Envelope [NA] was left unsecured. The Control Room Envelope was inoperable for approximately one minute, at which time the door was closed. Grand Gulf Nuclear Station personnel identified that a loss of Safety Function occurred due to a breach in the Control Room Envelope resulting in inoperability of both divisions of Standby Fresh Air systems.

REPORTABILITY

This event is being reported under 10CFR50.73(a)(2)(v)(D), as any event or condition that, at the time of discovery, could have prevented the fulfillment of the safety function of structures or systems that are needed to mitigate the consequences of an accident.

CAUSE

The direct cause of the event was that the door was degraded, resulting in the door dragging on the floor such that the automatic door closer would not function properly. The organization failed to understand the nuclear safety consequence associated with the degraded condition and failed to implement a mitigating strategy.

CORRECTIVE ACTIONS

Immediate Corrective Actions:

Upon identification the door was immediately secured and the Control Room Supervisor was notified.

The event was entered into the Grand Gulf Nuclear Station corrective action program.

Grand Gulf Nuclear Station Security personnel provided immediate coaching to the employee who left the door open.

The support hinge bushing was replaced, restoring normal door closure.

Corrective Actions To Prevent Recurrence:

Implement a maintenance strategy for doors SZ100C715, Passageway Door; SZ100C708, Corridor Door; SZ100C612, Corridor No. 3 Door; SZ100C516, Corridor Door.

LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME	2. DOCKET	3. LER NUMBER		
		YEAR	SEQUENTIAL NUMBER	REV. NO.
Grand Gulf Nuclear Station, Unit 1	05000 416		2017 - 005 - 00	

NARRATIVE

SAFETY SIGNIFICANCE

There were no nuclear safety consequences or radiological consequences as a result of this event. No Technical Specification Safety Limits were violated.

PREVIOUS SIMILAR OCCURRENCES

LER 2015-002 Loss of Secondary Containment Differential Pressure during Drawdown Testing
LER 2015-003 Technical Specification Surveillance on Primary Containment Isolation Valves
LER 2016-003 Loss of Secondary Containment Safety Function During Routine Roof Inspection
LER 2016-009 Entry into Mode of Applicability with the OPRM Upscale Settings Incorrectly Set
LER 2017-002 Loss of Secondary Containment and Inoperability of the Standby Gas Treatment System

The identified licensee event reports were reviewed and it has been determined that the causes and corrective actions for the previously identified events were sufficiently different that they could not have predicted or prevented the occurrence of this event.