



Tennessee Valley Authority, Post Office Box 2000, Spring City, Tennessee 37381

November 3, 2017

10 CFR 50.73

ATTN: Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555-0001

Watts Bar Nuclear Plant, Units 1 and 2
Facility Operating License Nos. NPF-90 and NPF-96
NRC Docket No. 50-390 and 50-391

Subject: **Licensee Event Report 390/2017-007-01, Multiple Unreported Potential Loss of Safety Function Events Associated with Inoperable Single Train Systems Due to Misinterpretation of Reporting Guidance**

This submittal provides Licensee Event Report (LER) 390/2017-007-01. This LER supplement provides details concerning a failure by Watts Bar personnel to report potential Loss of Safety Function events associated with single train safety systems. This issue, and the related events are being reported in accordance with 10 CFR 50.73(a)(2)(v).

There are no regulatory commitments contained in this letter. Please direct any questions concerning this matter to Kim Hulvey, WBN Licensing Manager, at (423) 365-7720.

Respectfully,

A handwritten signature in black ink, appearing to read "Paul Simmons", written over a horizontal line.

Paul Simmons
Site Vice President
Watts Bar Nuclear Plant

Enclosure
cc: See Page 2

U.S. Nuclear Regulatory Commission
Page 2
November 3, 2017

cc (Enclosure):

NRC Regional Administrator - Region II
NRC Senior Resident Inspector - Watts Bar Nuclear Plant



LICENSEE EVENT REPORT (LER)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME

Watts Bar Nuclear Plant, Unit 1

2. DOCKET NUMBER

05000390

3. PAGE

1 OF 9

4. TITLE

Multiple Unreported Potential Loss of Safety Function Events Associated with Inoperable Single Train Systems Due to Misinterpretation of Reporting Guidance

5. EVENT DATE

MONTH	DAY	YEAR
06	09	2017

6. LER NUMBER

YEAR	SEQUENTIAL NUMBER	REV NO.
2017	007	01

7. REPORT DATE

MONTH	DAY	YEAR
11	03	2017

8. OTHER FACILITIES INVOLVED

FACILITY NAME	DOCKET NUMBER
Watts Bar Nuclear Plant, Unit 2	05000391
FACILITY NAME	DOCKET NUMBER

9. OPERATING MODE

11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)

1

☐ 20.2201(b)	☐ 20.2203(a)(3)(i)	☐ 50.73(a)(2)(ii)(A)	☐ 50.73(a)(2)(viii)(A)
☐ 20.2201(d)	☐ 20.2203(a)(3)(ii)	☐ 50.73(a)(2)(ii)(B)	☐ 50.73(a)(2)(viii)(B)
☐ 20.2203(a)(1)	☐ 20.2203(a)(4)	☐ 50.73(a)(2)(iii)	☐ 50.73(a)(2)(ix)(A)
☐ 20.2203(a)(2)(i)	☐ 50.36(c)(1)(i)(A)	☐ 50.73(a)(2)(iv)(A)	☐ 50.73(a)(2)(x)

10. POWER LEVEL

76

☐ 20.2203(a)(2)(ii)	☐ 50.36(c)(1)(ii)(A)	☐ 50.73(a)(2)(v)(A)	☐ 73.71(a)(4)
☐ 20.2203(a)(2)(iii)	☐ 50.36(c)(2)	☐ 50.73(a)(2)(v)(B)	☐ 73.71(a)(5)
☐ 20.2203(a)(2)(iv)	☐ 50.46(a)(3)(ii)	☒ 50.73(a)(2)(v)(C)	☐ 73.77(a)(1)
☐ 20.2203(a)(2)(v)	☐ 50.73(a)(2)(i)(A)	☒ 50.73(a)(2)(v)(D)	☐ 73.77(a)(2)(i)
☐ 20.2203(a)(2)(vi)	☐ 50.73(a)(2)(i)(B)	☐ 50.73(a)(2)(vii)	☐ 73.77(a)(2)(ii)
	☐ 50.73(a)(2)(i)(C)	☐ OTHER	Specify in Abstract below or in NRC Form 366A

12. LICENSEE CONTACT FOR THIS LER

LICENSEE CONTACT

Dean Baker, Licensing Engineer

TELEPHONE NUMBER (Include Area Code)

423-452-4589

13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT

CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX

14. SUPPLEMENTAL REPORT EXPECTED

☐ YES (If yes, complete 15. EXPECTED SUBMISSION DATE) ☒ NO

15. EXPECTED SUBMISSION DATE

MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

On June 9, 2017, Watts Bar Nuclear Plant (WBN) personnel determined that the reporting requirements of 10 CFR 50.72(b)(3)(v) and 10 CFR 50.73(a)(2)(v), as clarified by guidance in NUREG-1022, Revision 3, were being incorrectly applied for certain events associated with single train safety systems. When events occurred that resulted in these systems not meeting Technical Specification (TS) Limiting Conditions for Operation (LCO), the short duration of these events relative to their required action completion time, coupled with prompt return to allowable values, were not considered a loss of safety function by Operations and Licensing personnel. As a result, multiple potential loss of safety function events were not reported as required. These events were related to Refueling Water Storage Tank (RWST) level, Containment and Shield Building pressure, and Control Room Envelope integrity.

A review of these events indicate, when considering the actual system capability and the response of equipment and personnel, a loss of safety function capability impacting public health and safety did not occur for events associated with the RWST, Containment, Shield Building, or Control Room. Corrective actions include briefing personnel on the regulatory impact of these events, and the importance of the control room boundary.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME	2. DOCKET NUMBER	3. LER NUMBER		
		YEAR	SEQUENTIAL NUMBER	REV NO.
Watts Bar Nuclear Plant, Unit 1	05000390	2017	- 007	- 01

NARRATIVE**I. PLANT OPERATING CONDITIONS BEFORE THE EVENT**

Watts Bar Nuclear Plant (WBN) Unit 1 was at 76 percent rated thermal power (RTP). WBN Unit 2 was in Mode 5.

II. DESCRIPTION OF EVENT**A. Event Summary**

On June 9, 2017, Watts Bar Nuclear Plant (WBN) personnel determined that the reporting requirements of 10 CFR 50.72(b)(3)(v) and 10 CFR 50.73(a)(2)(v), as clarified by guidance in NUREG-1022, Revision 3, were being incorrectly applied for certain events associated with single train safety systems. When events occurred that resulted in these systems not meeting Technical Specification (TS) Limiting Conditions for Operation (LCO) for these systems, the short duration of these events relative to their required action completion time, coupled with prompt return to allowable values, were not considered a loss of safety function by Operations and Licensing personnel. As a result, multiple potential loss of safety function events were not reported as required.

This event is being reported to the Nuclear Regulatory Commission (NRC) under 10 CFR 50.73(a)(2)(v)(C) and (D) as an event or condition that could have prevented fulfillment of a safety function needed to control the release of radioactive material and to mitigate the consequences of an accident.

B. Inoperable Structures, Components, or Systems that Contributed to the Event

Various equipment issues and personnel errors did contribute to the events described in Section VIII of this report.

C. Dates and Approximate Times of Occurrences

Date	Time (EDT)	Event
3/13/17	N/A	Condition Report (CR)1273873 generated for Potential Failure to Report Loss of Safety Function
6/09/17	N/A	Extent of Condition for CR 1273873 completed for period of 3/17/14 to 3/17/17. This review incorrectly concludes no failure to report.
6/22/17	N/A	Condition Report 1310096 generated to address position on loss of safety function reporting. WBN licensing determines that multiple examples of failure to report have occurred and that the event/discovery date for reporting is 6/09/17.

D. Manufacturer and Model Number of Components that Failed During the Event

Not applicable.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME	2. DOCKET NUMBER	3. LER NUMBER		
		YEAR	SEQUENTIAL NUMBER	REV NO.
Watts Bar Nuclear Plant, Unit 1	05000390	2017	- 007	- 01

NARRATIVE**E. Other Systems or Secondary Functions Affected**

No other systems or secondary functions were affected.

F. Method of discovery of each Component or System Failure or Procedural Error

The failure to report these potential loss of safety function events was discovered during an on-going evaluation of this issue by WBN licensing personnel with assistance from other offsite licensing personnel who had been involved in the development of NUREG-1022 Revision 3.

G. Failure Mode and Effect of Each Failed Component

Individual failures for each event are summarized in Section VIII.

H. Operator Actions

No operator actions were required at the time, as there were no on-going events.

I. Automatically and Manually Initiated Safety System Responses

Not applicable.

III. CAUSE OF THE EVENT**A. The cause of each component or system failure or personnel error, if known.**

The cause of the failure to report was an incorrect understanding of the regulation associated with events or conditions that could have prevented fulfillment of a safety function.

B. The cause(s) and circumstances for each human performance related root cause.

The cause of the failure to report was an incorrect understanding of the regulation associated with events or conditions that could have prevented fulfillment of a safety function in addition to the individual human performance and equipment failures attributed to each event.

IV. ANALYSIS OF THE EVENT

When events occurred that resulted in single train systems not meeting TS LCO requirements; the short duration of these events relative to their required action completion time were not considered a loss of safety function by Operations and Licensing personnel. During evaluation of this issue, with input from offsite sources, WBN licensing personnel became aware of a letter transmitted by the Nuclear Regulatory Commission (NRC) staff to Exelon Corporation in January 2015 that provides an NRC position on loss of safety function related to single train type systems. This resulted in a reassessment of those events that should have been reported as a potential loss of safety function, considering the guidance of NUREG-1022 that a report is required when:

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME	2. DOCKET NUMBER	3. LER NUMBER		
		YEAR	SEQUENTIAL NUMBER	REV NO.
Watts Bar Nuclear Plant, Unit 1	05000390	2017	- 007	- 01

NARRATIVE

- "1) there is a determination that the SSC is inoperable in a required mode or other specified condition in the TS Applicability,
2) the inoperability is due to one or more personnel errors, including procedure violations; equipment failures; inadequate maintenance; or design, analysis, fabrication, equipment qualification, construction, or procedural deficiencies, and
3) no redundant equipment in the same system was operable."

Reassessment using these criteria identified a number of events related to single train systems. WBN had not reported events related to Refueling Water Storage Tank (RWST) {EIS:TK} level, shield building {EIS:NH} pressure being outside TS limits, containment pressure being outside TS limits, and the control room envelope {EIS:NA} being inoperable due to a boundary door {EIS:DR} inadvertently left open. Each event is described in Section VIII of this report. WBN's assessment of the safety impacts of these events is provided below.

1. With respect to RWST level, three events occurred where the RWST level went below the TS 3.5.4 allowed value. While the level was below that permitted by the TS, the level reduction was very small with respect to the tank volume. The safety function capability of the tank was determined to have been met for design basis events (DBEs).

2. The WBN containment design includes a free standing steel pressure vessel surrounded by a reinforced concrete shield building. The shield building is maintained at a negative pressure during normal operation by non-safety related ventilation systems required to be in operation in Modes 1 -4. In the event of an accident, safety related ventilation systems would filter the exhaust from the shield building, reducing the offsite dose to members of the public from postulated leakage of the containment pressure vessel. On multiple occasions, the pressure in the shield building went outside of TS 3.6.15 allowable limits as a result of equipment failures. While these events are reportable as a potential loss of safety function, evaluation of these events shows that the safety function capability of the shield building, the containment pressure vessel, and the associated ventilation systems would not have been lost. The Emergency Gas Treatment System (EGTS), which would function to filter the exhaust from the shield building, is capable of performing its safety function assuming the shield building is not at a negative pressure as documented in the dose analysis in the UFSAR. In addition, such testing or equipment malfunctions also has impacted containment pressure TS 3.6.4 which specifies the relative pressure limits between the containment and the annulus. The design of the containment pressure vessel bounds any minor pressure transient that may occur during ventilation system transients and its safety function capability would not be lost.

3. The control room envelope (CRE) is required to be operable in Modes 1 through 6. Operability requires integrity of the control room envelope such that it will have a low unfiltered inleakage during accident conditions to maintain the dose to operators within the requirements of 10 CFR 50, General Design Criterion 19. TS allows the CRE boundary to be opened intermittently under administrative control, normally to allow personnel ingress and egress from the control room. Administrative controls in the case of boundary doors are that an individual is in control of the door when it is opened. On multiple occasions, personnel entering and leaving the control room left one of the boundary doors open. This resulted in operations personnel entering TS LCO 3.7.10, Control Room Emergency Ventilation System (CREVS), Condition B for one or more CREVS trains inoperable due to an inoperable CRE boundary. Low positive pressure (less than 0.2 inches of water gauge (WG)) in the control room for 90 seconds results in a control room alarm. Upon receipt of the alarm, operations personnel promptly closed the CRE door. For these events, the time that the CRE boundary was open was approximately four minutes for each event, including the alarm delay time. The licensing basis at WBN for a loss of coolant accident (LOCA) assumes



LICENSEE EVENT REPORT (LER) CONTINUATION SHEET

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME	2. DOCKET NUMBER	3. LER NUMBER		
Watts Bar Nuclear Plant, Unit 1	05000390	YEAR	SEQUENTIAL NUMBER	REV NO.
		2017	- 007	- 01

NARRATIVE

instantaneous core damage and release, and therefore, a potential loss of safety function event for each case occurred. The physics of such an event are that core damage and a containment release would take some period of time much greater than a few minutes. The CRE door would be expected to be closed with high confidence well in advance of an actual radiological release. Most of the door events involved the door being ajar, and under these circumstances simplified, non-surveillance testing has shown that a positive control room pressure would be present.

V. ASSESSMENT OF SAFETY CONSEQUENCES

The failure to report potential loss of safety function events represents a significant concern from a regulatory standpoint. A review of these events indicate, when considering the actual system capability and the response of equipment and personnel, a loss of safety function capability impacting public health and safety did not occur with respect to the RWST, Shield Building, Containment or the Control Room.

- A. Availability of systems or components that could have performed the same function as the components and systems that failed during the event

Availability of systems to perform the required functions is described in Section IV.

- B. For events that occurred when the reactor was shut down, availability of systems or components needed to shutdown the reactor and maintain safe shutdown conditions, remove residual heat, control the release of radioactive material, or mitigate the consequences of an accident

Availability of systems to perform the required functions is described in Section IV.

- C. For failure that rendered a train of a safety system inoperable, an estimate of the elapsed time from the discovery of the failure until the train was returned to service

The time period that systems and equipment were outside of specified TS limits is described in Section VIII of this LER.

VI. CORRECTIVE ACTIONS

This event was entered into the Tennessee Valley Authority (TVA) Corrective Action Program and is being tracked under Condition Report (CR) 1310096.

- A. Immediate Corrective Actions

Upon determining that previous events were reportable, this LER was initiated and developed for submittal. Communication of this reporting issue has occurred within operations and licensing.

- B. Corrective Actions to Prevent Recurrence or to Reduce Probability of Similar Events Occurring in the Future

WBN will brief personnel, including supplementary staff, on the regulatory and nuclear safety impacts related to failure to close the control room boundary doors, and will post door watches as needed.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME	2. DOCKET NUMBER	3. LER NUMBER		
		YEAR	SEQUENTIAL NUMBER	REV NO.
Watts Bar Nuclear Plant, Unit 1	05000390	2017	- 007	- 01

NARRATIVE**VII. PREVIOUS SIMILAR EVENTS AT THE SAME SITE**

On November 11, 2015, WBN Unit 1 failed to enter TS 3.1.8 Condition A which was required when WBN Unit 1 experienced a rod drop event. This was subsequently reported to the NRC as a condition prohibited by TS in LER 390-2016-007 on June 20, 2016. This event is similar in that licensing personnel incorrectly interpreted requirements related to how to comply with TS 3.1.8.

VIII. POTENTIAL LOSS OF SAFETY FUNCTION EVENTS FOR PREVIOUS THREE YEARS

A summary of potential loss of safety function events over the last three years is provided below:

Events related to TS LCO 3.5.4 for the Refueling Water Storage Tank less than 370,000 gallons

Date	Time	Condition Report	Summary
3/24/14	0435	864251	Entry into TS LCO 3.5.4.B when level in the RWST went below TS minimum of 370,000 gallons with Unit 1 in Mode 4. Exited LCO when Unit 1 entered Mode 5 at 0620 on March 24, 2014. Due to other equipment issues, a decision was made to use the RWST to provide a Reactor Coolant System (RCS) makeup water source during cooldown.
7/7/14	1255	907544	Entry into TS LCO 3.5.4.B when level in the RWST went below TS minimum of 370,000 gallons. A leak from the suction side of the Refueling Water Purification Pumps was isolated and the Unit 1 RWST was refilled. The LCO condition was exited on July 7, 2014 at 1320.
6/5/16	1230	1317307	Entry into TS LCO 3.5.4 Condition B when level in the RWST went below TS minimum of 370,000 gallons due to a reactor trip with safety injection (SI) on WBN Unit 2. Exited TS LCO 3.5.4 Condition B on June 5, 2016 at 1622 when the RWST was above TS minimum level. The trip with SI was reported to the NRC in LER-391-2016-004 on August 4, 2016.

Events related to TS LCO 3.6.4 for Containment Pressure outside range of greater than or equal to -0.1 psid and less than or equal to +0.3 psid relative to the annulus

Date	Time	Condition Report	Summary
7/14/16	1307	1317307	Entry into TS LCO 3.6.4 condition A when the containment pressure was less than -0.1 psid relative to the annulus following the loss of power to the annulus vacuum fans. TS LCO 3.6.4 Condition A was exited on July 14, 2016 at 1354. This was subsequently determined to not be reportable because this occurred during a planned evolution performed using approved plant procedures.
3/13/17	1558	1273873	Entry into TS LCO 3.6.4 condition A when the containment pressure was less than -0.1 psid relative to the annulus during Auxiliary Building Gas Treatment System (ABGTS) Pressure Test of Train B. TS LCO 3.6.4 Condition A was exited On March 13, 2017 at 1613.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME	2. DOCKET NUMBER	3. LER NUMBER		
		YEAR	SEQUENTIAL NUMBER	REV NO.
Watts Bar Nuclear Plant, Unit 1	05000390	2017	- 007	- 01

NARRATIVE

Events related to TS LCO 3.6.15 Condition B for annulus pressure requirement not met for the Shield Building. SR 3.6.15.1 requires annulus to be greater than -5 inches WG with respect to atmosphere

Date	Time	Condition Report	Summary
3/12/15	1133	998890	Entry into TS 3.6.15 Condition B for annulus pressure not within limits (more negative than -5 inches WG) due to dropping below -5.5 inches WG because 1-FCO-65-49 Annulus Vacuum normal control damper not controlling properly. Annulus pressure restored at 1305.
9/13/15	1025	1317307	Entry into TS 3.6.15 Condition B for annulus pressure not within limits due to pressure transient from initiating an Auxiliary Building Isolation (ABI) for U2 testing. LCO 3.6.15 was exited at 1031. This was subsequently determined to not be reportable because this occurred during a planned evolution performed using approved plant procedures.
6/2/16	1512	1177619	Entry into TS 3.6.15 Condition B for annulus pressure not within limits due to failure of 2-FCO-65-45 to open during 2-SI-99-303-B. Exited LCO 3.6.15 at 1518.
6/5/16	1240	1317307	Shield building pressure less than -5 in WG due to U2 Reactor Trip with SI. Exited condition at 1242 on June 5, 2016. The trip with SI was reported to the NRC in LER-391-2016-004 on August 4, 2016.
7/14/16	1303	1317307	Shield building pressure less than -5 in WG due to Loss of Power Power Ascension Test (PAT). TS LCO 3.6.15 Condition B not entered into plant logs. Exited condition at 1438 on July 14, 2016 when annulus pressure was greater than -5 in WG. This was subsequently determined to not be reportable because this occurred during a planned evolution for power ascension performed using approved plant procedures.
3/1/17	1445	1317307	Entry into TS LCO 3.6.15 Condition A and B for annulus not more negative than -5 inches WG due to transient caused by storm front moving through area. Exited TS LCO 3.6.15 Condition A and B on March 1, 2017 at 1446.
3/13/17	1558	1272164/ 1272224	Shield building pressure less than -5 in WG due to ABGTS testing (No entry into LCO 3.6.15 Condition B logged). Exited condition at 1812 on March 13, 2017.

Events related to TS LCO 3.7.10 for the Control Room Emergency Ventilation System (CRE boundary breached)

Note: The control room pressure alarm comes in after a 90 second delay.

Date	Time (Alarm)	Condition Report	Summary
3/23/14	0424	862708	Boundary door closed by 0427
3/30/14	0951	866226	Boundary door closed by 0953
5/31/14	0157	894134	Boundary door closed by 0159
6/14/14	0915	899633	Boundary door closed by 0917
6/23/14	1135	903067	Boundary door closed by 1140
7/10/14	1255	909000	Boundary door closed by 1257
7/11/14	1014	910194	Boundary door closed by 1016

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME

Watts Bar Nuclear Plant, Unit 1

2. DOCKET NUMBER

05000390

3. LER NUMBER

YEAR

2017

SEQUENTIAL
NUMBER

- 007

REV
NO.

- 01

NARRATIVE

Date	Time (Alarm)	Condition Report	Summary
7/19/14	0822	912154	Boundary door closed by 0823
8/22/14	1740	1317307/1326447	Boundary door closed by 1743
8/23/14	2240	1317307/1326447	Boundary door closed by 2246
10/21/14	0708	948571	Boundary door closed by 0710
11/7/14	1722	1317307/1326447	Boundary door closed by 1725
12/15/14	1245	967964	Boundary door closed by 1247
1/18/15	0703	979264	Boundary door closed by 0705
2/3/15	1305	985860	Boundary door closed by 1306
2/8/15	0726	986637	Boundary door closed by 0727
2/11/15	0603	988464	Boundary door closed by 0605
3/15/15	1242	1000413	Boundary door closed by 1244
3/25/15	1924	1317307/1326447	Boundary door closed by 1925
6/15/15	1502	1040054	Boundary door closed by 1504
7/21/15	1918	1317307/1326447	Boundary door closed by 1922
7/22/15	2100	1061510	Boundary door closed by 2103
8/18/15	0427	1071973	Boundary door closed by 0429
10/13/15	0751	1092726	Boundary door closed by 0753
10/31/15	0240	1099526	Boundary door closed by 0242
10/31/15	1358	1099592	Boundary door closed by 1360
11/14/15	0728	1104089	Boundary door closed by 0731
12/5/15	2207	1112234	Boundary door closed by 2210
1/4/16	1053	1121123	Boundary door closed by 1055
1/22/16	0332	1127775	Boundary door closed by 0334
1/22/16	2247	1128181	Boundary door closed by 2250
1/26/16	0550	1129073	Boundary door closed by 0552
1/26/16	2005	1129477	Boundary door closed by 2007
2/15/16	1102	1137634	Boundary door closed by 1104
4/20/16	1827	1162773	Boundary door closed by 1830
4/27/16	2334	1317307/1326447	Boundary door closed by 2337
5/12/16	2134	1170567	Boundary door closed by 2141
6/29/16	1951	1187273	Boundary door closed by 1954
7/30/16	0404	1197627	Boundary door closed by 0406
10/21/16	1409	1225143	Boundary door closed by 1412
3/20/17	0120	1274363	Boundary door closed by 0122
3/21/17	0900	1275203	Boundary door closed by 0902. The Control room door was undergoing minor maintenance. Maintenance personnel were in control of the door during this activity.
4/6/17	1620	1281767	Boundary door closed by 1623
5/13/17	1408	1295376	Boundary door closed by 1410

IX. ADDITIONAL INFORMATION

None.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOF-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME

Watts Bar Nuclear Plant, Unit 1

2. DOCKET NUMBER

05000390

3. LER NUMBER

YEAR	SEQUENTIAL NUMBER	REV NO.
2017	- 007	- 01

NARRATIVE

X. COMMITMENTS

None.