



Entergy[®]

Entergy Operations, Inc.

River Bend Station
5485 U.S. Highway 61N
St. Francisville, LA 70775
Tel 225-381-4374

William F. Maguire
Site Vice President

RBG-47874

June 19, 2018

Attn: Document Control Desk
U.S. Nuclear Regulatory Commission
11555 Rockville Pike
Rockville, MD 20852-2738

Subject: Licensee Event Report 50-458 / 2018-003-00

River Bend Station, Unit 1
Docket No. 50-458
License No. NPF-47

Dear Sir or Madam:

In accordance with 10 CFR 50.73, enclosed is the subject Licensee Event Report. This document contains no commitments. If you have any questions, please contact Mr. Tim Schenk at 225-381-4177.

Sincerely,

WFM/twf

Enclosure

cc: (with Enclosure)

U.S. Nuclear Regulatory Commission
Attn: Ms. Lisa M. Regner, Project Manager
09-D-14
One White Flint North
11555 Rockville Pike
Rockville, MD 20852

U.S. Nuclear Regulatory Commission
Region IV
1600 East Lamar Blvd.
Arlington, TX 76011-4511

NRC Senior Resident Inspector
Attn: Mr. Jeff Sowa
5485 U.S. Highway 61, Suite 1
St. Francisville, LA 70775

Public Utility Commission of Texas
Attn: PUC Filing Clerk
1701 N. Congress Avenue
P. O. Box 13326
Austin, TX 78711-3326

INPO
(via ICES reporting)

RB1-18-0126

**LICENSEE EVENT REPORT (LER)**

(See Page 2 for required number of digits/characters for each block)

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NE08-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. Facility Name River Bend Station - Unit 1	2. Docket Number 05000 458	3. Page 1 OF 3
--	--------------------------------------	--------------------------

4. Title Condition Prohibited by Technical Specifications due to Untimely Recognition of Failed Laboratory Analysis of Ventilation Charcoal Sample
--

5. Event Date			6. LER Number			7. Report Date			8. Other Facilities Involved	
Month	Day	Year	Year	Sequential Number	Rev No.	Month	Day	Year	Facility Name	Docket Number
04	30	2018	2018	003	00	06	19	2018	NA	05000 NA

9. Operating Mode	11. This Report is Submitted Pursuant to the Requirements of 10 CFR §: (Check all that apply)			
1	☐ 20.2201(b)	☐ 20.2203(a)(3)(i)	☐ 50.73(a)(2)(ii)(A)	☐ 50.73(a)(2)(viii)(A)
	☐ 20.2201(d)	☐ 20.2203(a)(3)(ii)	☐ 50.73(a)(2)(ii)(B)	☐ 50.73(a)(2)(viii)(B)
	☐ 20.2203(a)(1)	☐ 20.2203(a)(4)	☐ 50.73(a)(2)(iii)	☐ 50.73(a)(2)(ix)(A)
	☐ 20.2203(a)(2)(i)	☐ 50.36(c)(1)(i)(A)	☐ 50.73(a)(2)(iv)(A)	☐ 50.73(a)(2)(x)
10. Power Level	☐ 20.2203(a)(2)(ii)	☐ 50.36(c)(1)(ii)(A)	☐ 50.73(a)(2)(v)(A)	☐ 73.71(a)(4)
100	☐ 20.2203(a)(2)(iii)	☐ 50.36(c)(2)	☐ 50.73(a)(2)(v)(B)	☐ 73.71(a)(5)
	☐ 20.2203(a)(2)(iv)	☐ 50.46(a)(3)(ii)	☐ 50.73(a)(2)(v)(C)	☐ 73.77(a)(1)
	☐ 20.2203(a)(2)(v)	☐ 50.73(a)(2)(i)(A)	☐ 50.73(a)(2)(v)(D)	☐ 73.77(a)(2)(i)
	☐ 20.2203(a)(2)(vi)	☒ 50.73(a)(2)(i)(B)	☐ 50.73(a)(2)(vii)	☐ 73.77(a)(2)(ii)
		☐ 50.73(a)(2)(i)(C)	☐ Other (Specify in Abstract below or in NRC Form 366A)	

12. Licensee Contact for this LER	
Licensee Contact Tim Schenk, Manager - Regulatory Assurance	Telephone Number (Include Area Code) 225-381-4177

13. Complete One Line for each Component Failure Described in this Report										
Cause	System	Component	Manufacturer	Reportable to ICES	Cause	System	Component	Manufacturer	Reportable to ICES	
NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	
14. Supplemental Report Expected					15. Expected Submission Date			Month	Day	Year
☐ Yes (If yes, complete 15. Expected Submission Date) ☒ No								NA	NA	NA

Abstract (Limit to 1400 spaces, i.e., approximately 14 single-spaced typewritten lines)

On April 30, 2018 with the Reactor operating in Mode 1 at 100% power, the results of a periodic surveillance test on Division II Control Room Fresh Air charcoal filter were received. The sample results indicated that the activated charcoal methyl iodide penetration test was above the allowable level. The test failure was determined to be due to the age of the charcoal. The condition was not immediately recognized because the sample results were received from the vendor thirteen days after the sample was obtained. This condition existed for a time longer than permitted by Technical Specifications. The activated charcoal was replaced and the filter has since been declared Operable. This event was of minimal significance to the health and safety of the public because the redundant Division I filter was Operable and available for use for the duration of the event.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollections.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME	2. DOCKET NUMBER	3. LER NUMBER		
River Bend Station - Unit 1	05000-	458	YEAR	SEQUENTIAL NUMBER
			2018	003
			REV NO.	00

NARRATIVE**BACKGROUND**

The Control Room Fresh Air system (CRFA) [VI] is designed to filter radioactive nuclides in accordance with General Design Criteria 19 and Regulatory Guide 1.52. The design consists of two 100% independent/redundant carbon filter trains that are divisionally separated. Control Room habitability includes maintaining Control Room operator dose within the limits of General Design Criteria 19, assuming an accident with onsite release. The dose calculations for Control Room habitability are based on the specified 1% penetration limit.

REPORTED CONDITION

On April 17, 2018 with the Reactor operating in Mode 1 at 100% power, a sample of activated charcoal from the Division II CRFA Filter (**FLT**) was obtained to be shipped to an offsite vendor for methyl iodide penetration analysis in accordance with a normally scheduled surveillance. On April 30, 2018 the sample results were received. The test result indicated 1.47% penetration with an acceptance criterion of 1.0% or less. A confirmatory sample was acquired and tested with a similar result. The charcoal was replaced and the Division II CRFA Filter was declared Operable on May 3, 2018.

Firm evidence indicates that this condition began on April 17, 2018 when the sample was obtained and was not rectified until May 3, 2018. This condition existed for a time longer than permitted by the Technical Specification (TS) for having one CRFA subsystem inoperable. This condition is being reported in accordance with 10CFR50.73(a)(2)(i)(B), Operation or Condition Prohibited by Technical Specifications.

CAUSAL ANALYSIS

The charcoal failed the methyl iodide penetration analysis due to age related degradation. The untimely identification of the condition was a result of procedural guidance that allowed 31 days from sample time to receive analytical results. Additionally, only one charcoal analysis was being tracked and trended. There were other available analysis and parameters that could have been trended to better predict the life expectancy of the charcoal.

CORRECTIVE ACTION TO PREVENT RECURRENCE

An extent of condition found that the Standby Gas [VF] and Fuel Building Ventilation [VG] Charcoal Filter Trains are susceptible to this event. The Division I and Division II Standby Gas trains were sampled on May 9, 2018 and May 8, 2018 respectively. Both trains were found to be well within specification. The Division I and Division II Fuel Building Filters were sampled on July 14, 2017 and December 12, 2016 respectively with both trains within specification. The Division I CRFA Filter was sampled on December 7, 2016 with satisfactory results. The following actions are planned and documented in the station's corrective action program.

Procedure changes that would require sample time coordination with the lab vendor in order to receive sample results within three days of receipt of the sample for all systems susceptible to this condition.

Additional charcoal analysis trending will be performed to improve life expectancy predictions.



LICENSEE EVENT REPORT (LER) CONTINUATION SHEET

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME	2. DOCKET NUMBER	3. LER NUMBER		
River Bend Station - Unit 1	05000- 458	YEAR 2018	SEQUENTIAL NUMBER 003	REV NO. 00

NARRATIVE

PREVIOUS OCCURRENCE EVALUATION

There have been no similar events reported by RBS in the last five years.

SAFETY SIGNIFICANCE

The Division II CRFA system was considered to be Inoperable from the time the charcoal sample was obtained to the time the charcoal was replaced. However, the Division I CRFA system was Operable for the duration of this event. Furthermore, the Division II CRFA system was returned to Operable status three days from the time of discovery. This event was of minimal significance to the health and safety of the public.

(NOTE: Energy Industry Identification System component function identifier and system name of each component or system referred to in the LER are annotated as (**XX**) and [XX], respectively.)