



10 CFR 50.73

NMP2L2687
July 9, 2018

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555-0001

Nine Mile Point Nuclear Station, Unit 2
Renewed Facility Operating License No. NPF-69
Docket No. 50-410

Subject: NMP2 Licensee Event Report 2018-001, Auto Start of Division II Emergency Diesel Generator Due to Loss of Line 6

In accordance with the reporting requirements contained in 10 CFR 50.73(a)(2)(iv)(A), please find enclosed NMP2 Licensee Event Report 2018-001, Auto Start of Division II Emergency Diesel Generator Due to Loss of Line 6.

There are no regulatory commitments contained in this letter.

Should you have any questions regarding the information in this submittal, please contact Dennis M. Moore, Site Regulatory Assurance Manager, at (315) 349-5219.

Respectfully,

A handwritten signature in cursive script, appearing to read "R. Kreider" followed by a flourish.

Robert E. Kreider Jr.
Plant Manager, Nine Mile Point Nuclear Station
Exelon Generation Company, LLC

REK/RSP

Enclosure: NMP2 Licensee Event Report 2018-001, Auto Start of Division II Emergency Diesel Generator Due to Loss of Line 6

cc: NRC Regional Administrator, Region I
NRC Resident Inspector
NRC Project Manager

IEZZ
NRR

**LICENSEE EVENT REPORT (LER)**

(See Page 2 for required number of digits/characters for each block)

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. Facility Name

Nine Mile Point Unit 2

2. Docket Number

05000410

3. Page

1 OF 4

4. Title

Auto Start of Division II Emergency Diesel Generator Due to Loss of Line 6

5. Event Date			6. LER Number			7. Report Date			8. Other Facilities Involved	
Month	Day	Year	Year	Sequential Number	Rev No.	Month	Day	Year	Facility Name	Docket Number
05	10	2018	2018	- 001	- 00	7	9	2018	NA	NA
9. Operating Mode			11. This Report is Submitted Pursuant to the Requirements of 10 CFR §: (Check all that apply)							
4			☐ 20.2201(b)		☐ 20.2203(a)(3)(i)		☐ 50.73(a)(2)(i)(A)		☐ 50.73(a)(2)(viii)(A)	
			☐ 20.2201(d)		☐ 20.2203(a)(3)(ii)		☐ 50.73(a)(2)(i)(B)		☐ 50.73(a)(2)(viii)(B)	
			☐ 20.2203(a)(1)		☐ 20.2203(a)(4)		☐ 50.73(a)(2)(iii)		☐ 50.73(a)(2)(ix)(A)	
			☐ 20.2203(a)(2)(i)		☐ 50.36(c)(1)(i)(A)		☒ 50.73(a)(2)(iv)(A)		☐ 50.73(a)(2)(x)	
10. Power Level			☐ 20.2203(a)(2)(ii)		☐ 50.36(c)(1)(ii)(A)		☐ 50.73(a)(2)(v)(A)		☐ 73.71(a)(4)	
000			☐ 20.2203(a)(2)(iii)		☐ 50.36(c)(2)		☐ 50.73(a)(2)(v)(B)		☐ 73.71(a)(5)	
			☐ 20.2203(a)(2)(iv)		☐ 50.46(a)(3)(ii)		☐ 50.73(a)(2)(v)(C)		☐ 73.77(a)(1)	
			☐ 20.2203(a)(2)(v)		☐ 50.73(a)(2)(i)(A)		☐ 50.73(a)(2)(v)(D)		☐ 73.77(a)(2)(i)	
			☐ 20.2203(a)(2)(vi)		☐ 50.73(a)(2)(i)(B)		☐ 50.73(a)(2)(vii)		☐ 73.77(a)(2)(ii)	
			☐ 50.73(a)(2)(i)(C)				☐ Other (Specify in Abstract below or in NRC Form 366A)			

12. Licensee Contact for this LER**Licensee Contact**

Dennis Moore, NMP Regulatory Assurance Manager

Telephone Number (Include Area Code)

315-349-5219

13. Complete One Line for each Component Failure Described in this Report

Cause	System	Component	Manufacturer	Reportable to ICES	Cause	System	Component	Manufacturer	Reportable to ICES
A	FK	RLY	GE	Y	NA	NA	NA	NA	NA

14. Supplemental Report Expected☐ Yes (If yes, complete 15. Expected Submission Date) ☒ No**15. Expected Submission Date**

Month	Day	Year

Abstract (Limit to 1400 spaces, i.e., approximately 14 single-spaced typewritten lines)

At approximately 0248 on May 10, 2018, while at 0% power and in Cold Shutdown (mode 4) in support of the Nine Mile Point Unit 2 (NMP2) refueling outage, NMP2 experienced a partial loss of off-site power (Line 6) during relay testing that resulted in an automatic start of the Division 2 Emergency Diesel Generator (EDG). All systems responded per design during the event. The station responded in accordance with appropriate Special Operating Procedures and restored impacted systems.

The condition was reported in Event Notification #53395 as an event or condition that results in a valid actuation of an emergency electrical power system, pursuant to 10 CFR.50.72(b)(3)(iv)(A). This event is being reported as an event or condition that results in a valid actuation of an emergency electrical power system, pursuant to 50.73(a)(2)(iv)(A).

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME	2. DOCKET NUMBER	3. LER NUMBER		
		YEAR	SEQUENTIAL NUMBER	REV NO.
Nine Mile Point Unit 2	05000410	2018	- 001	- 00

NARRATIVE**I. DESCRIPTION OF EVENT****A. PRE-EVENT PLANT CONDITIONS:**

Prior to the event NMP2 was at 0% power in cold shutdown, mode 4, in support of the refueling outage.

B. EVENT:

At approximately 0248 on May 10, 2018 with the plant in Cold Shutdown, Mode 4, in support of the refueling outage, Nine Mile Point Unit 2 experienced a partial loss of off-site power following the removal of the connection plug of Tripping Relay, 94BG-2/R925, during North American Electric Reliability Corporation (NERC) functional testing. This resulted in the loss of Line 6 and subsequently the automatic start of the Division 2 Emergency Diesel Generator. All systems responded as designed for the event. The station responded in accordance with appropriate Special Operating Procedures and restored impacted systems.

C. INOPERABLE STRUCTURES, COMPONENTS, OR SYSTEMS THAT CONTRIBUTED TO THE EVENT:

None

D. DATES AND APPROXIMATE TIMES OF MAJOR OCCURRENCES AND OPERATOR ACTIONS:

All Occurrences and Action took place on May 10, 2018:

0248: Control Room Alarm for Loss of 115KV from Scriba – Loss of line 6 received
0248: Division II EDG Energized and picked up the Division 2 Bus.
0248: Entered SOPs:
N2-SOP-3 Loss of AC.
N2-SOP-31 Loss of Shutdown Cooling, 2RHS*P1B Tripped.
N2-SOP-38 Loss of Spent Fuel Pool Cooling, 2SFC*P1B Tripped.
N2-SOP-97 RPS System Failures, Loss of 'B' RPM MG Set
0254: Shutdown Cooling re-established with 2RHS*P1B
0322: Spent Fuel Pool Cooling re-established with 2SFC*P1B in cooling only mode
0326: Exiting N2-SOP-38 Loss of Spent Fuel Pool Cooling
0332: Exiting N2-SOP-31 Loss of Shutdown Cooling
0344: Exited SOP-97 RPS Failures, RPS 'B' Half SCRAM Reset
1123: Line 6 restored per N2-OP-70
1130: Secured Division II EDG

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME	2. DOCKET NUMBER	3. LER NUMBER		
		YEAR	SEQUENTIAL NUMBER	REV NO.
Nine Mile Point Unit 2	05000410	2018	- 001	- 00

NARRATIVE**E. METHOD OF DISCOVERY:**

This event was self-revealing during the performance of the relay testing when the Control Room Alarm was received

F. SAFETY SYSTEM RESPONSES:

Following the loss of line 6 the Division 2 EDG actuated and operated per design.

II. CAUSE OF EVENT:

This event was directly caused by a protective relay that inadvertently actuated while technicians were pulling the relay connection plug. Pulling the relay connection plug is the risk elimination strategy for protective relaying to prevent actuation during testing. The relay actuated when the connection plug was removed. There is no industry operating experience associated with actuation of relays while pulling the connection plug. This is the industry accepted practice to prevent relay actuation.

III. ANALYSIS OF THE EVENT:

This event is reportable in accordance with 10 CFR 50.72(b)(3)(iv)(A), and 10 CFR 50.73(a)(2)(iv)(A). The event caused a valid actuation of the Division II EDG, a safety system named in 10 CFR 50.73(a)(2)(iv)(B). The actuation was not part of a preplanned sequence during testing or reactor operation. There were no nuclear safety consequences associated with this event and all safety systems and balance of plant equipment operated as expected.

IV. CORRECTIVE ACTIONS:**A. ACTION TAKEN TO RETURN AFFECTED SYSTEMS TO PRE-EVENT STATUS**

Operations responded in accordance with appropriate Special Operating Procedures and restored all impacted systems to pre-event status.

B. ACTION TAKEN TO PREVENT RECURRENCE

Corrective actions include planning and scheduling changes being implemented to create additional mitigating barriers in addition to the removal of the connecting plug.

V. ADDITIONAL INFORMATION

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME	2. DOCKET NUMBER	3. LER NUMBER		
		YEAR	SEQUENTIAL NUMBER	REV NO.
Nine Mile Point Unit 2	05000410	2018	- 001	- 00

NARRATIVE**A. FAILED COMPONENTS**

There were no failed components that contributed to this event

B. PREVIOUS LERS ON SIMILAR EVENT:

There are no previous LERs for similar events.

C. THE ENERGY INDUSTRY IDENTIFICATION SYSTEM (EIS) COMPONENT FUNCTION IDENTIFIER AND SYSTEM NAME OF EACH COMPONENT OR SYSTEM REFERRED TO IN THIS LER:

<u>Component</u>	<u>IEEE 803 Function Identifier</u>	<u>IEEE 805 System Identification</u>
Emergency Diesel Generator	DG	EK
Relay	RLY	FK

D. SPECIAL COMMENTS:

None