



Thomas A. Vehec
Vice President – Plant Hatch

Hatch Nuclear Plant
11028 Hatch Parkway North
Baxley, GA 31513
912 5375859 tel
912 366 2077 fax

MAY 16 2019

Docket Nos.: 50-366

NL-19-0576

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D. C. 20555-0001

Edwin I. Hatch Nuclear Plant Unit 2
Licensee Event Report 2019-002-00
High Pressure Coolant Injection System Inoperable Due to a Lack of Hydraulic Oil
Pressure by the Auxiliary Oil Pump

Ladies and Gentlemen:

In accordance with the requirements of 10 CFR 50.73(a)(2)(v)(D) Southern Nuclear Operating Company hereby submits the enclosed Licensee Event Report.

This letter contains no NRC commitments. If you have any questions, please contact the Hatch Licensing Manager, Jimmy Collins at 912.537.2342.

Respectfully submitted,

T. A. Vehec
Vice President – Hatch

TAV/URP/SCM

Enclosure: LER 2019-002-00

cc: Regional Administrator, Region II
NRR Project Manager – Hatch
Senior Resident Inspector – Hatch
RTYPE: CHA02.004

Edwin I. Hatch Nuclear Plant Unit 2

Licensee Event Report 2019-002-00

**High Pressure Coolant Injection System Inoperable Due to a Lack of
Hydraulic Oil Pressure by the Auxiliary Oil Pump**



LICENSEE EVENT REPORT (LER)

(See Page 2 for required number of digits/characters for each block)

(See NUREG-1022, R 3 for instruction and guidance for completing this form
http://www.nrc.gov/reading_rm/doc-collections/nuregs/staff/sr1022/r3/)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T 2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001 or by e-mail to infocollections.Resource@nrc.gov and to the Desk Officer, Office of Information and Regulatory Affairs, NE08 10202 (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to expose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. Facility Name	2. Docket Number	3. Page
Edwin I. Hatch Nuclear Plant Unit 2	05000 366	1 OF 2

4. Title
High Pressure Coolant Injection System Inoperable Due to a Lack of Hydraulic Oil Pressure by the Auxiliary Oil Pump

5. Event Date			6. LER Number			7. Report Date			8. Other Facilities Involved	
Month	Day	Year	Year	Sequential Number	Rev No.	Month	Day	Year	Facility Name	Docket Number
03	19	2019	2019	- 002	- 00	05	16	2019	Facility Name	Docket Number
										05000
										05000

9. Operating Mode	11. This Report is Submitted Pursuant to the Requirements of 10 CFR §: (Check all that apply)			
2	☐ 20.2201(b)	☐ 20.2203(a)(3)(i)	☐ 50.73(a)(2)(ii)(A)	☐ 50.73(a)(2)(viii)(A)
	☐ 20.2201(d)	☐ 20.2203(a)(3)(ii)	☐ 50.73(a)(2)(ii)(B)	☐ 50.73(a)(2)(viii)(B)
	☐ 20.2203(a)(1)	☐ 20.2203(a)(4)	☐ 50.73(a)(2)(iii)	☐ 50.73(a)(2)(ix)(A)
	☐ 20.2203(a)(2)(i)	☐ 50.36(c)(1)(i)(A)	☐ 50.73(a)(2)(iv)(A)	☐ 50.73(a)(2)(x)
10. Power Level	☐ 20.2203(a)(2)(ii)	☐ 50.36(c)(1)(ii)(A)	☐ 50.73(a)(2)(v)(A)	☐ 73.71(a)(4)
001	☐ 20.2203(a)(2)(iii)	☐ 50.36(c)(2)	☐ 50.73(a)(2)(v)(B)	☐ 73.71(a)(5)
	☐ 20.2203(a)(2)(iv)	☐ 50.46(a)(3)(ii)	☐ 50.73(a)(2)(v)(C)	☐ 73.77(a)(1)
	☐ 20.2203(a)(2)(v)	☐ 50.73(a)(2)(i)(A)	☒ 50.73(a)(2)(v)(D)	☐ 73.77(a)(2)(i)
	☐ 20.2203(a)(2)(vi)	☐ 50.73(a)(2)(ii)(B)	☐ 50.73(a)(2)(vii)	☐ 73.77(a)(2)(ii)
	☐ 50.73(a)(2)(i)(C)	☐ Other (Specify in Abstract below or in NRC Form 366A)		

12. Licensee Contact for this LER	
Licensee Contact Edwin I. Hatch / Jimmy Collins - Licensing Manager	Telephone Number (Include Area Code) 912-537-2342

13. Complete One Line for each Component Failure Described in this Report									
Cause	System	Component	Manufacturer	Reportable to ICES	Cause	System	Component	Manufacturer	Reportable to ICES
D	BJ	MCC	G080	Y					

14. Supplemental Report Expected	15. Expected Submission Date	Month	Day	Year
☐ Yes (If yes, complete 15. Expected Submission Date) ☒ No				

Abstract (Limit to 1400 spaces, i.e., approximately 14 single-spaced typewritten lines)

At 0140 EST on March 19, 2019, while Unit 2 was at approximately 1 percent power in Mode 2, Operations declared the High Pressure Coolant Injection (HPCI) inoperable following a failed Operability test. During the test, the HPCI auxiliary oil pump failed to start when the control switch was taken to start. Due to the lack of hydraulic oil pressure provided by the auxiliary oil pump, the HPCI main stop valve did not open followed by the illumination of the HPCI turbine trip annunciator, thus, preventing HPCI from starting and making it inoperable. An investigation was performed and found the secondary connection stabs on the Motor Control Center Pan Assembly feeding the auxiliary oil pump were not making adequate contact. The stab tension was adjusted and the oil pump was started followed by successful completion of the HPCI pump operability test. Because HPCI does not have a redundant system, the pump failure to start on demand represents a safety system functional failure as defined in NEI 99-02 and is reportable per 50.72(b)(3)(v)(D).

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-m/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOF-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME	2. DOCKET NUMBER	3. LER NUMBER		
Edwin I. Hatch Nuclear Plant Unit 2	05000-366	YEAR 2019	SEQUENTIAL NUMBER 002	REV NO. 00

NARRATIVE**EVENT DESCRIPTION:**

At 0140 EST on March 19, 2019, while Unit 2 was in MODE 2 (with Reactor Steam Dome Pressure > 150 PSIG) and at approximately 1 percent power, following a refueling outage, Operations declared the High Pressure Coolant Injection (HPCI) [EIS BJ] inoperable following a failed Operability test. During the test, the HPCI auxiliary oil pump failed to start when the control switch was taken to start. Due to the lack of hydraulic oil pressure provided by the auxiliary oil pump, the HPCI main stop valve did not open followed by the illumination of the HPCI turbine trip annunciator. The Unit entered into a required action statement (RAS) for technical specification 3.5.1 Condition C, for the auxiliary oil pump failure to start that resulted in HPCI being declared inoperable.

EVENT CAUSE ANALYSIS:

The subsequent investigation and analysis determined that the secondary connection stabs, on the Motor Control Center (MCC) [EIS MCC] Pan Assembly feeding the auxiliary oil pump, were not making adequate contact in the MCC causing the auxiliary oil pump not to start. The inspection procedure failed to include the inspections of the stabs and contacts.

REPORTABILITY AND SAFETY ASSESSMENT:

HPCI does not have a redundant system, therefore, this condition was reportable per 50.73(a)(2)(v)(D). A pump failure to start on demand represents a safety system functional failure as defined in NEI 99-02. The safety significance of this event is minimal due to the a short duration of less than 14 hours that HPCI was declared inoperable and the concurrent availability of the Reactor Core Isolation Cooling [EIS BN] system. This MCC Pan Assembly only feeds the HPCI auxiliary oil pump.

CORRECTIVE ACTIONS:

The stab tension was adjusted and the auxiliary oil pump started followed by the successful completion of the HPCI pump operability. The RAS was exited on March 19, 2019 at 1522 EST.

Corrective action will be taken to update the General Electric Low Voltage MCC Inspection procedure to include the visual inspection of the MCC subcomponents, such as the secondary connection stab tension. Work orders have been generated to inspect the MCC pan assembly connection stabs on both units by end of 2020 as part of the extent of condition.

PREVIOUS SIMILAR EVENTS:

None