



Kent Scott
Site Vice President
225-381-4374

RBG-48172

10 CFR 50.73

May 17, 2022

ATTN: Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

Subject: Licensee Event Report 50-458 / 2022-01-00, "Condition Prohibited by
Technical Specifications due to Residual Heat Removal B Pump Motor
Bearing Oil Leak"

River Bend Station – Unit 1
NRC Docket Nos. 50-458
Renewed Facility Operating License No. NPF-47

In accordance with 10 CFR 50.73, enclosed is the subject Licensee Event Report. This document contains no commitments.

Should you have any questions, please contact Mr. Tim Schenk, Regulatory Assurance Manager, at 225-381-4177.

Respectfully,

A handwritten signature in black ink, appearing to be 'K. Scott', written over a circular scribble.

KCS/dmw

Enclosure: Licensee Event Report 50-458 / 2022-01-00, "Condition Prohibited by
Technical Specifications due to Residual Heat Removal B Pump Motor Bearing
Oil Leak"

cc: NRC Region IV Regional Administrator - Region IV
NRC Senior Resident Inspector - River Bend Station
NRC Project Manager - River Bend Station

Enclosure

RBG-48172

Licensee Event Report 50-458 / 2022-01-00, "Condition Prohibited by Technical Specifications due to Residual Heat Removal B Pump Motor Bearing Oil Leak"

The oil leak was corrected by replacing the sight glass assembly and O-ring on March 30, 2022.

NRC FORM 366A (08-2020)	U.S. NUCLEAR REGULATORY COMMISSION LICENSEE EVENT REPORT (LER) CONTINUATION SHEET	APPROVED BY OMB: NO. 3150-0104 Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collection Branch (T-6 A10M), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov , and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503; e-mail: oir_submission@omb.eop.gov . The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.	EXPIRES: 08/31/2023						
(See NUREG-1022, R.3 for instruction and guidance for completing this form https://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/)									
1. FACILITY NAME River Bend Station, Unit 1	2. DOCKET NUMBER 05000- 458	3. LER NUMBER <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th style="width: 30%;">YEAR</th> <th style="width: 40%;">SEQUENTIAL NUMBER</th> <th style="width: 30%;">REV NO.</th> </tr> <tr> <td style="text-align: center;">2022</td> <td style="text-align: center;">- 001</td> <td style="text-align: center;">- 00</td> </tr> </table>		YEAR	SEQUENTIAL NUMBER	REV NO.	2022	- 001	- 00
YEAR	SEQUENTIAL NUMBER	REV NO.							
2022	- 001	- 00							
NARRATIVE EVENT DESCRIPTION On 03/29/2022, at 1900 Central Time (CT) with River Bend Station, Unit 1 operating at 100% power, Residual Heat Removal Pump B (RHR B) [BO] was declared inoperable when it was confirmed that the leakage rate from the motor lower bearing oil reservoir would prevent RHR B from meeting its mission time. The oil leak began following sight glass O-ring replacement performed on 03/14/2022. An oil leak was identified in condition reports on 03/18/2022 and 03/26/2022. In both cases, the oil level was low, but above the minimum required level and oil additions were made to bring the level up to the standstill mark. An analysis performed on 03/29/2022 determined that the identified leakage would not have supported the mission time of RHR B. On 03/30/2022, a new sight glass assembly and O-ring were installed. Engineering verified that the installation and post maintenance test were both satisfactory. RHR B was determined to be inoperable from the time of the original sight glass O-ring replacement on 03/14/2022 until the sight glass assembly and O-ring was replaced and re-tested satisfactorily on 03/30/2022. This resulted in inoperability for a time longer than allowed by Technical Specifications. There is no record of an oil leak prior to maintenance performed on 03/14/2022. This condition is being reported as an operation or condition prohibited by Technical Specifications in accordance with 10 CFR 50.73(a)(2)(i)(B).									
SAFETY ASSESSMENT The actual consequence of this event was the potential inability of RHR B to fulfill its mission time following a Design Basis Accident. Residual Heat Removal Pump A (RHR A) [BO] was Operable for the duration of this event; therefore, this event was of minimal significance to the health and safety of the public.									
EVENT CAUSE The direct cause of this event was improper installation of the sight glass O-ring during the performance of preventative maintenance.									
CORRECTIVE ACTIONS Complete: The condition was corrected by replacing the sight glass assembly and O-ring on 03/30/2022. Planned Actions tracked in the Corrective Action Program: • Update all affected ECCS model work orders for sight glass and O-ring replacement to include further guidance to prevent future occurrences. • Adjust the scope of the preventative maintenance work orders for sight glass and O-ring replacement to reflect the manufacturer recommendations. Timeliness of identification, evaluation, and resolution of this condition are being driven to resolution by individual condition reports within the Corrective Action Process.									
PREVIOUS SIMILAR EVENTS None									