

RA24-025

10 CFR 50.73

August 22, 2024

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555-0001

LaSalle County Station, Units 1 and 2
Renewed Facility Operating License Nos. NPF-11 and NPF-18
NRC Docket No. 50-373 and 50-374

Subject: Licensee Event Report 2024-004-01, Supplement to Emergency Diesel
Generator Auto-Start and Load due to Loss of System Auxiliary Transformer

Licensee Event Report 2023-002-01, Supplement to Air Circuit Breaker (ACB)
Mechanically Operated Contacts (MOC) switch failed to actuate

In accordance with 10 CFR 50.73(a)(2)(iv)(A), Constellation Energy Generation, LLC (CEG)
is submitting Licensee Event Report (LER) Number 2024-004-01 for LaSalle County
Station, Unit 1.

In accordance with 10 CFR 50.73(a)(2)(i)(B), CEG is submitting LER Number 2023-002-01
for LaSalle County Station, Units 1 and 2 due to administrative changes.

There are no regulatory commitments contained in this letter.

Should you have any questions concerning this report, please contact Ms. Laura Ekern,
Regulatory Assurance Manager, at (815) 415-2800.

Respectfully,



Deborah J McBreen
Acting Plant Manager
LaSalle County Station

Enclosure: Licensee Event Report 2024-004-01
Licensee Event Report 2023-002-01

cc: Regional Administrator – NRC Region III
NRC Senior Resident Inspector – LaSalle County Station



LICENSEE EVENT REPORT (LER)

(See Page 2 for required number of digits/characters for each block)
(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by email to Infocollections.Resource@nrc.gov, and the OMB reviewer at OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. Facility Name

LaSalle County Station, Unit 1

☒ 050
☐ 052

2. Docket Number

00373

3. Page

1 OF 5

4. Title

Emergency Diesel Generator Auto-Start and Load due to Loss of System Auxiliary Transformer

5. Event Date

Month	Day	Year
04	20	2024

6. LER Number

Year	Sequential Number	Revision No.
2024	- 004 -	01

7. Report Date

Month	Day	Year
08	22	2024

8. Other Facilities Involved

Facility Name	☐ 050	Docket Number
NA		NA
Facility Name	☐ 052	Docket Number
NA		NA

9. Operating Mode

1

10. Power Level

100 percent

11. This Report is Submitted Pursuant to the Requirements of 10 CFR §: (Check all that apply)

☒ 10 CFR Part 20	☐ 20.2203(a)(2)(vi)	☒ 10 CFR Part 50	☐ 50.73(a)(2)(ii)(A)	☐ 50.73(a)(2)(viii)(A)	☐ 73.1200(a)
☐ 20.2201(b)	☐ 20.2203(a)(3)(i)	☐ 50.36(c)(1)(i)(A)	☐ 50.73(a)(2)(ii)(B)	☐ 50.73(a)(2)(viii)(B)	☐ 73.1200(b)
☐ 20.2201(d)	☐ 20.2203(a)(3)(ii)	☐ 50.36(c)(1)(ii)(A)	☐ 50.73(a)(2)(iii)	☐ 50.73(a)(2)(ix)(A)	☐ 73.1200(c)
☐ 20.2203(a)(1)	☐ 20.2203(a)(4)	☐ 50.36(c)(2)	☒ 50.73(a)(2)(iv)(A)	☐ 50.73(a)(2)(x)	☐ 73.1200(d)
☐ 20.2203(a)(2)(i)	☒ 10 CFR Part 21	☐ 50.46(a)(3)(ii)	☐ 50.73(a)(2)(v)(A)	☒ 10 CFR Part 73	☐ 73.1200(e)
☐ 20.2203(a)(2)(ii)	☐ 21.2(c)	☐ 50.69(g)	☐ 50.73(a)(2)(v)(B)	☐ 73.77(a)(1)	☐ 73.1200(f)
☐ 20.2203(a)(2)(iii)		☐ 50.73(a)(2)(i)(A)	☐ 50.73(a)(2)(v)(C)	☐ 73.77(a)(2)(i)	☐ 73.1200(g)
☐ 20.2203(a)(2)(iv)		☐ 50.73(a)(2)(i)(B)	☐ 50.73(a)(2)(v)(D)	☐ 73.77(a)(2)(ii)	☐ 73.1200(h)
☐ 20.2203(a)(2)(v)		☐ 50.73(a)(2)(i)(C)	☐ 50.73(a)(2)(vii)		

☐ OTHER (Specify here, in abstract, or NRC 366A).

12. Licensee Contact for this LER

Licensee Contact

Joseph Reda, Operations Director

Phone Number (Include area code)

(815) 415-2200

13. Complete One Line for each Component Failure Described in this Report

Cause	System	Component	Manufacturer	Reportable to IRIS	Cause	System	Component	Manufacturer	Reportable to IRIS
X	FK	BKR	W120	Y	X	EB	BKR	I005	Y

14. Supplemental Report Expected

☒ No ☐ Yes (If yes, complete 15. Expected Submission Date)

15. Expected Submission Date

Month	Day	Year

16. Abstract (Limit to 1326 spaces, i.e., approximately 13 single-spaced typewritten lines)

On April 20, 2024, with LaSalle Unit 1 operating at 100 percent power and gas circuit breaker (GCB) 11-13 open to support transmission system operator testing of power line L0104 relays, oil circuit breaker (OCB) 1-13 tripped open on differential current resulting in the loss of the Unit 1 system auxiliary transformer (SAT). Bus 141Y (Division 1), normally supplied by the Unit 1 SAT, failed to fast transfer to the Unit 1 unit auxiliary transformer (UAT), resulting in the Division 1 emergency diesel generator (EDG) to automatically start and load onto the 141Y bus, causing a load shed of the 141Y bus and momentary loss of power to the 141Y bus. The loss of the Unit 1 SAT also caused the Division 3 EDG to automatically start and load, as designed, onto bus 143 (Division 3).

The load shed on bus 141Y caused power to be lost to the Unit 1 "A" (1A) reactor protection system (RPS) bus, resulting in a "A" RPS half-scam condition and closure of isolation valves in multiple systems. All actuations and isolations performed as designed. During the fast transfer of Division 2 from the Unit 1 SAT to UAT, the Unit 1 reactor building ventilation system (VR) 'B' supply isolation damper and "A" exhaust isolation damper went shut unexpectedly causing a loss of Unit 1 VR.

These events are reportable in accordance with 10 CFR 50.73(a)(2)(iv)(A).

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by email to Infocollections.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. FACILITY NAME LaSalle County Station, Unit 1	☒ 050	2. DOCKET NUMBER 00373	3. LER NUMBER		
	☐ 052		YEAR 2024	SEQUENTIAL NUMBER - 004	REV NO. - 01

NARRATIVE**Plant and System Identification**

LaSalle Country Station Unit 1 is a General Electric Boiling Water Reactor with 3546 Megawatts Thermal Rated Core Power. The affected system was the alternating current (AC) power system. The affected component is 345 kV oil circuit breaker (OCB) 1-13, the mechanism operated contacts (MOC) 15 and 16 of air circuit breaker (ACB) 1412, and the TSC switch contacts on ACB 1415.

Condition Prior to Event

Unit(s): 1	Date: April 20, 2024	Time: 07:04 CDT
Reactor Mode(s): 1	Mode(s) Name: Power Operation	Power Level: 100 percent

Description**Emergency Diesel Generator (EDG) Actuation and Load**

On April 20, 2024, with gas service breaker (GCB) 11-13 open to support transmission system operator (TSO) testing of power line L0104 relays, OCB 1-13 tripped open on differential current resulting in the loss of the Unit 1 system auxiliary transformer (SAT). Bus 141Y (engineered safety feature (ESF) Division 1), which is normally supplied by the Unit 1 SAT, failed to fast transfer to the Unit 1 unit auxiliary transformer (UAT), resulting in the Division 1 EDG to automatically start and load onto the 141Y bus, causing a load shed of the 141Y bus and a momentary loss of power to the 141Y bus. The loss of the Unit 1 SAT also caused the Division 3 EDG to automatically start and load, as designed, onto bus 143 (ESF Division 3), which is normally supplied by the Unit 1 SAT. Bus 142Y (ESF Division 2) fast transferred to the Unit 1 UAT, as expected, resulting in no requirement for the Division 2 EDG to automatically start. The automatic starting of the Division 1 and Division 3 EDGs is considered a valid actuation due to the loss of power to ESF buses.

During the fast transfer of ESF Division 2 from the Unit 1 SAT to UAT, the Unit 1 reactor building ventilation system (VR) 'B' supply isolation damper and 'A' exhaust isolation damper went shut unexpectedly causing a loss of Unit 1 VR. This resulted in a main steam tunnel high temperature condition which was bypassed per station procedure. The dampers were reopened, and Unit 1 VR was restored.

Reactor Protection System (RPS) Unit 1 "A" Half-Scram

As a result of the load shed on bus 141Y, power was lost to the Unit 1 "A" (1A) RPS bus, resulting in a "A" RPS half-scrum condition and closure of isolation valves in multiple systems. The condition was considered an invalid actuation because it was the result of losing power to the bus and not the result of a valid input signal to the RPS or intentional manual action. All actuations and isolations performed as designed.

The loss of the 1A RPS bus resulted in isolations of the reactor water cleanup system, main steam line drains, reactor coolant system sampling, instrument nitrogen system, reactor recirculation hydraulic power units, and containment monitoring system. The loss of the 1A RPS bus also resulted in the loss of power to portions of the average power range monitor, local power range monitor, oscillation power range monitor, and control rod block systems; as well as portions of the radiation monitoring for the main steam lines, reactor building vent, and fuel pool vent. Appropriate actuations and primary containment isolations occurred as designed.

After the loss of power to the 1A RPS bus, the applicable Technical Specification (TS) timeclocks and actions were entered. Power was restored to the 1A bus by transferring the bus to the alternate power supply in accordance with plant

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by email to Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. FACILITY NAME LaSalle County Station, Unit 1	☒ 050	2. DOCKET NUMBER 00373	3. LER NUMBER				
	☐ 052		<table border="1"><thead><tr><th>YEAR</th><th>SEQUENTIAL NUMBER</th><th>REV NO.</th></tr></thead><tbody><tr><td>2024</td><td>- 004</td><td>- 01</td></tr></tbody></table>	YEAR	SEQUENTIAL NUMBER	REV NO.	2024
YEAR	SEQUENTIAL NUMBER	REV NO.					
2024	- 004	- 01					

NARRATIVE

procedures. The half-scam and isolations were reset, and the equipment was returned to operable status. All applicable TS timeclocks and actions were exited.

Cause**EDG Actuation and Load**

The root cause of OCB 1-13 tripping open was an absence of procedural guidance requiring the switchyard owner to provide the details of their modification testing plan, including work instructions, and the required performance of a quality station review of testing plan / work instructions. Causal factors that were identified with the root cause are the following:

1. Placement of dispatched grounds by the switchyard owner with the presence of induced voltage on power line L0104.
2. Failure of LaSalle County Station personnel to recognize the possibility of induced voltage being present on the out-of-service 345 kV power line L0104 after switching, caused by the in-service 345 kV power line L0103 that runs parallel with power line L0104, flowing to ground via the bus 13-dispatched ground when GCB 11-13 was moved to the closed position.

Contributing causes to the event that were identified in the root cause are the following:

1. The TSC switch for ACB 1415 was not closed as expected.
2. Failure to follow the maintenance strategy template recommendation to verify contact resistance or cycle the MOC switch on a regular interval.

Troubleshooting determined the cause of the fast transfer failure of bus 141Y from the Unit 1 SAT to the Unit 1 UAT was increased resistance across MOC 15 and 16 of ACB 1412, and the TSC switch contacts were open on ACB 1415, Unit 1 UAT feed breaker to bus 141Y, even though they were verified to be closed the last time the breaker was racked in during refueling outage L1R20 earlier in 2024.

RPS Unit 1A Half-Scram

The cause of the RPS Unit 1A loss of power and half scram was the momentary loss of power from the 141Y bus due to the load shed caused by the fast transfer failure. The loss of power from the 141Y bus resulted in a loss of power to the 1A RPS motor-generator set that normally powers the 1A RPS.

Reportability and Safety Analysis**EDG Actuation and Load**

The loss of the Unit 1 SAT and actuation of the Division 1 and Division 3 emergency diesel generators was initially reported as an 8-hour notification (ENS 57083) in accordance with 10 CFR 50.72(b)(3)(iv)(A) for a valid actuation of the emergency AC electrical power systems. This event is also required to be reported in accordance with 10 CFR 50.73(a)(2)(iv)(A) as an event that results in the valid actuation of the emergency AC electrical power systems.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by email to Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. FACILITY NAME LaSalle County Station, Unit 1	☒ 050	2. DOCKET NUMBER 00373	3. LER NUMBER		
	☐ 052		YEAR 2024	SEQUENTIAL NUMBER - 004	REV NO. - 01

NARRATIVE**RPS Unit 1A Half-Scram**

The loss of the Unit 1A RPS bus and associated RPS actuation is considered an invalid actuation because it was not the result of a valid signal and not an intentional manual action. The loss of the RPS bus resulted in general containment isolation signals that actuated containment isolation valves in more than one system or multiple main steam isolation valves while the unit was critical. Therefore, the loss of the RPS bus is reportable in accordance with 10 CFR 50.73(a)(2)(iv)(A).

Safety System Functional Failure Review

The system equipment responses do not result in a safety system functional failure (SSFF) as defined in accordance with NEI 99-02, "Regulatory Assessment Performance Indicator Guideline." The EDG and RPS safety systems performed their as-designed safety functions.

Corrective Actions

Corrective actions taken in response to the conditions were:

- Entered the required TS timeclocks and actions and notified the TSO to secure all testing.
- Transferred the 1A RPS bus to the alternate power supply, reset the half-scram, and exited applicable TS timeclocks and actions.
- Closed OCB 1-13 and reenergized the Unit 1 SAT
- Transferred buses 141Y, 142Y, and 143 to the Unit 1 SAT; shutdown the Division 1 and Division 3 EDGs; and exited applicable TS timeclocks and actions.
- Transferred the 1A RPS bus back to the normal power supply.
- Racked out and then racked in ACB 1415 to close the TSC switch contacts.
- Cleaned MOC 15 and 16 on ACB 1412 to decrease the resistance back to acceptable levels.
- Develop electrical maintenance procedure to check all 4 kV and 6 kV switchgear breaker contacts to confirm alignment for fast transfer logic.
- Update the normal startup procedure to incorporate new electrical maintenance procedure during bus alignment.
- Revise the Switchyard Services Agreement procedure to add guidance for the station to perform a quality review for all modification testing instructions when modifications and testing are to be performed in the switchyard.
- Update 4 kV and 6 kV breaker inspection and operational test procedures to include preventative maintenance strategies for either verifying resistances or burnishing MOC switch contacts.
- Prioritize and expedite the engineering change for the removal of TSC switches.
- Remove and send the TSC switch on ACB 1415 for failure analysis.

Previous Occurrences

There have been no previous occurrences of an EDG actuation in the past 3 years.

There have been two occurrences of RPS half-scrams in the past 3 years that were attributed to a loss of power.

Unit 1 LER 373-2024-002-00

On March 25, 2024, LaSalle Unit 1 was operating at 100 percent power, when the 1B RPS MG set electric power monitoring assembly (EPMA) output breaker tripped due to an underfrequency condition, which resulted in the loss of the 1B RPS bus. The loss of power to this bus created a half-scram condition and initiated closure of isolation valves in



LICENSEE EVENT REPORT (LER) CONTINUATION SHEET

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by email to Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. FACILITY NAME LaSalle County Station, Unit 1	☒ 050	2. DOCKET NUMBER 00373	3. LER NUMBER		
	☐ 052		YEAR 2024	SEQUENTIAL NUMBER - 004	REV NO. - 01

NARRATIVE

multiple systems. The condition was an invalid actuation because it was not the result of actual plant conditions and not an intentional manual action. The cause of the MG set EPMA output breaker trip was the EPMA trip card for the output breaker being out of range high for the underfrequency setpoint which caused the trip on underfrequency. As a result, the EPMA trip card was replaced, and the system was restored back to its original configuration.

Unit 2 LER 374-2021-002-00

On May 31, 2021, LaSalle Unit 2 was operating at 100 percent power, when the 2A RPS motor generator (MG) set output breaker tripped due to an overload condition, which resulted in a loss of 2A RPS bus. Loss of power to this bus created a half-scrum and initiated closure of outboard isolation valves in multiple systems. The condition was an invalid actuation because it was not the result of actual plant conditions and not an intentional manual action. The cause of the issue was a degraded voltage adjustment potentiometer (device 1P) on the 2A RPS MG set, which was causing intermittent resistance readings. The intermittent resistance caused the output voltage of the RPS MG set to fluctuate. As a result, the degraded potentiometer and the voltage regulator were replaced as part of the trouble-shooting efforts, and the system was restored back to its original configuration.

Component Failure Data

Manufacturer: Westinghouse Electric Company
Device: Oil Circuit Breaker, 345 kV
Component ID: 0SYOCB1-13, 345 kV Oil Circuit Breaker 1-13

Manufacturer: ITE Circuit Breaker Limited
Device: Air Circuit Breaker, 4160 V
Component ID: ACB 1412 Bus Feed from SAT 1AP91E (TR 142)

Manufacturer: ITE Circuit Breaker Limited
Device: Air Circuit Breaker, 4160 V
Component ID: ACB 1415 1AP04E / 1AP03E (141Y / 141X) Bus Tie



LICENSEE EVENT REPORT (LER)

(See Page 2 for required number of digits/characters for each block)
(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by email to Infocollections.Resource@nrc.gov, and the OMB reviewer at OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. Facility Name

LaSalle County Station, Unit 2

☒ 050
☐ 052

2. Docket Number

00374

3. Page

1 OF 3

4. Title

Air Circuit Breaker (ACB) Mechanically Operated Contacts (MOC) switch failed to actuate

5. Event Date

Month	Day	Year
02	24	2023

6. LER Number

Year	Sequential Number	Revision No.
2023	002	01

7. Report Date

Month	Day	Year
08	22	2024

8. Other Facilities Involved

Facility Name	☒ 050	Docket Number
LaSalle County Station, Unit 1		00373
Facility Name NA	☐ 052	Docket Number NA

9. Operating Mode

5

10. Power Level

000 percent

11. This Report is Submitted Pursuant to the Requirements of 10 CFR §: (Check all that apply)

10 CFR Part 20	☐ 20.2203(a)(2)(vi)	10 CFR Part 50	☐ 50.73(a)(2)(ii)(A)	☐ 50.73(a)(2)(viii)(A)	☐ 73.1200(a)
☐ 20.2201(b)	☐ 20.2203(a)(3)(i)	☐ 50.36(c)(1)(i)(A)	☐ 50.73(a)(2)(ii)(B)	☐ 50.73(a)(2)(viii)(B)	☐ 73.1200(b)
☐ 20.2201(d)	☐ 20.2203(a)(3)(ii)	☐ 50.36(c)(1)(ii)(A)	☐ 50.73(a)(2)(iii)	☐ 50.73(a)(2)(ix)(A)	☐ 73.1200(c)
☐ 20.2203(a)(1)	☐ 20.2203(a)(4)	☐ 50.36(c)(2)	☐ 50.73(a)(2)(iv)(A)	☐ 50.73(a)(2)(x)	☐ 73.1200(d)
☐ 20.2203(a)(2)(i)	10 CFR Part 21	☐ 50.46(a)(3)(ii)	☐ 50.73(a)(2)(v)(A)	10 CFR Part 73	☐ 73.1200(e)
☐ 20.2203(a)(2)(ii)	☐ 21.2(c)	☐ 50.69(g)	☐ 50.73(a)(2)(v)(B)	☐ 73.77(a)(1)	☐ 73.1200(f)
☐ 20.2203(a)(2)(iii)		☐ 50.73(a)(2)(i)(A)	☐ 50.73(a)(2)(v)(C)	☐ 73.77(a)(2)(i)	☐ 73.1200(g)
☐ 20.2203(a)(2)(iv)		☒ 50.73(a)(2)(i)(B)	☐ 50.73(a)(2)(v)(D)	☐ 73.77(a)(2)(ii)	☐ 73.1200(h)
☐ 20.2203(a)(2)(v)		☐ 50.73(a)(2)(i)(C)	☐ 50.73(a)(2)(vii)		

☐ OTHER (Specify here, in abstract, or NRC 366A).

12. Licensee Contact for this LER

Licensee Contact

Joseph Reda, Operations Director

Phone Number (Include area code)

(815) 415-2200

13. Complete One Line for each Component Failure Described in this Report

Cause	System	Component	Manufacturer	Reportable to IRIS	Cause	System	Component	Manufacturer	Reportable to IRIS
X	EB	BKR	I005	Y					

14. Supplemental Report Expected

☒ No ☐ Yes (If yes, complete 15. Expected Submission Date)

15. Expected Submission Date

Month	Day	Year

16. Abstract (Limit to 1326 spaces, i.e., approximately 13 single-spaced typewritten lines)

During operability surveillance testing of the Unit 2, Division 2 Unit Cross Tie Air Circuit Breaker (ACB 2424), the Unit 1, Division 2 Cross Tie (ACB 1424) failed to close. It was found that the contact from the Mechanically Operated Contacts (MOC) switch of ACB 1422 was not made up as is required for closing in ACB 1424. Troubleshooting identified a misaligned linkage to the ACB 1422 MOC switch, resulting in contacts not closing as required. This established firm evidence that a past inoperability condition existed since the breaker was last racked out of service during the Unit 1 refueling outage in 2022.

Failure of ACB 1422 MOC switch contacts results in inoperability of one of the two offsite power sources for Unit 2 Division 2 required by LCO 3.8.1 (AC Sources – Operating) and degraded voltage protection required by LCO 3.3.8.1 (Loss of Power Instrumentation). At the failure time of discovery, Unit 2 was in Mode 5, and LCO 3.8.1 was not in the mode of applicability and the unit cross-tie power source was not required for LCO 3.8.2 (AC sources -Shutdown). There were no reportability thresholds applicable to this issue at the time of the event, and there was no loss of safety function. The condition is reportable in accordance with 10 CFR 50.73(a)(2)(i)(B) for operation or condition prohibited by Technical Specifications.

The MOC switch linkage was adjusted and ACB 1422 was restored to operable.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by email to Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. FACILITY NAME LaSalle County Station, Unit 2	☒ 050	2. DOCKET NUMBER 00374	3. LER NUMBER		
	☐ 052		YEAR 2023	SEQUENTIAL NUMBER - 002	REV NO. - 01

NARRATIVE**Plant and System Identification**

LaSalle County Station Unit 2 is a General Electric Boiling Water Reactor with 3546 Megawatts Thermal Rated Core Power. The affected system was the AC Power system. The affected component is ACB 1422, Unit 1 System Auxiliary Transformer Main Feed to Unit 1 Division 2 AC power, 142Y.

Condition Prior to Event

Unit(s): 1/2	Date: February 24, 2023	Time: 14:25 CST
Reactor Mode(s): 1/5	Mode(s) Name: Power Operation/Refuel	Power Level: 100 percent/0 percent

Description

On 2/24/2023, during performance of the operability surveillance testing of the Unit 2, Division 2 Air Circuit Breaker (ACB) 2424, the Unit 1, Division 2 Cross Tie ACB 1424 failed to close. It was identified that that contacts on the Unit 1 System Auxiliary Transformer (SAT) feed to Division 2, ACB 1422, MOC switch remained in the open position when they should have been closed. This resulted in the ACB 1422 closing permissive not being actuated and preventing closure of ACB 1424. Troubleshooting identified a misaligned linkage on the ACB 1422 MOC switch. This linkage misalignment occurred during the last time the breaker was racked out of service during the Unit 1 refueling outage in 2022. This established firm evidence that a past inoperability condition existed.

Cause

Troubleshooting identified a misaligned linkage for the ACB 1422 MOC switch which resulted in the MOC switch contacts remaining open when they should have been closed.

Reportability and Safety Analysis

ACB 1422 MOC switch linkage misalignment occurred during the last time the breaker was racked out of service during the Unit 1 refueling outage in 2022. This established firm evidence that a past inoperability condition existed. There were no reportability thresholds met for this issue at the time of the event, and there was no loss of safety function. The condition is reportable in accordance with 10 CFR 50.73(a)(2)(i)(B) for operation or condition prohibited by Technical Specifications.

Failure of ACB 1424 to close resulted in inoperability of one of the two offsite power sources for Unit 2 Division 2 required by LCO 3.8.1 (AC Sources – Operating). At the time of discovery Unit 2 was in Mode 5, and LCO 3.8.1 was not in the mode of applicability. Additionally, the unit cross-tie power source was not required for LCO 3.8.2 (AC sources - Shutdown). The required offsite power source for Unit 1 was not impacted by this failure. The contacts on ACB 1422 MOC switch also provide the permissive to enable degraded voltage protection for Unit 1 Division 2 emergency AC Power, 142Y. This function is required per LCO 3.3.8.1, (Loss of Power (LOP) Instrumentation).

LCO 3.8.1 requires two qualified circuits between the offsite transmission network and the onsite Class 1E AC Electric Power Distribution System in modes 1, 2 and 3. Condition A is entered when one required offsite circuit is inoperable. The 1422 MOC switch contact remaining open prevents the closure of ACB 1424, Unit 1 SAT feed to Unit 2 Division 2 Emergency AC bus 242Y. As such one of the qualified offsite sources for bus 242Y was inoperable. The applicable Required Actions (RA) are RA A.1 perform SR 3.8.1.1 for operable required offsite circuit and A.3 restore the required offsite circuit to operable status in 72 hours. If this action is not met Condition H is entered and requires the unit to be in Mode 3 in 12 hours.



LICENSEE EVENT REPORT (LER) CONTINUATION SHEET

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by email to Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. FACILITY NAME LaSalle County Station, Unit 2	☒ 050	2. DOCKET NUMBER 00374	3. LER NUMBER		
	☐ 052		YEAR 2023	SEQUENTIAL NUMBER - 002	REV NO. - 01

NARRATIVE

LCO 3.8.1 condition E is entered when one required offsite circuit AND one required Division 1, 2 or 3 Diesel Generator (DG) is inoperable. Required actions E.1 and E.2 include restore the required offsite circuit to operable OR restore the required DG to operable within 12 hours or in accordance with the Risk Informed Completion Time Program. If this action is not met condition H is entered and requires the unit to be in Mode 3 within 12 hours. Examples of concurrent inoperability were identified where the required actions were not taken.

LCO 3.3.8.1 requires the Division 1, 2 and opposite Unit Division 2 – 4.16 kV Emergency Bus Undervoltage function to be operable (Function 1.c). If this function is inoperable LCO 3.3.8.1 condition A is entered and RA A.1 requires the channel to be placed in trip within 1 hour or in accordance with the Risk Informed Completion Time Program. If this action is not met, condition B.1 is entered and requires the associated DG to be declared inoperable immediately. The ACB 1422 linkage misalignment resulted in the Unit 2 Division 2 degraded voltage function to be inoperable when the Emergency Bus 142Y is fed from the System Auxiliary Transformer (SAT) and non-Emergency bus, 142X, is fed from the Unit Auxiliary Transformer (UAT). This lineup was entered during the period of inoperability with required actions not taken.

Corrective Actions

The linkage was adjusted and surveillance testing was completed to restore operability.

Previous Occurrences

No previous occurrences identified.

Component Failure Data

Manufacturer: ITE

Device: Air Circuit Breaker, 4160V

Component ID: 1AP06E-1, Air Circuit Breaker, System Auxiliary Transformer Main Feed to bus 142Y