



Post Office Box 2000, Decatur, Alabama 35609-2000

April 24, 2025

10 CFR 50.73

ATTN: Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555-0001

Browns Ferry Nuclear Plant, Unit 3
Renewed Facility Operating License No. DPR-68
NRC Docket No. 50-296

Subject: Licensee Event Report 50-296/2024-004-01

Reference: Letter from TVA to NRC, "Licensee Event Report 50-296/2024-004-00,"
dated December 4, 2024 (ML24339B794)

The enclosed Licensee Event Report provides details of the Reactor Coolant System Pressure Boundary Leakage Identified from Recirculation System Small Bore Piping. The Tennessee Valley Authority is submitting this report in accordance with Title 10 of the Code of Federal Regulations (10 CFR) 50.73(a)(2)(i)(B), as any operation or condition which was prohibited by the plant's Technical Specifications. Revision 1 to this report includes information obtained during performance of the cause evaluation for the event that was not previously reported nor available.

There are no new regulatory commitments contained in this letter. Should you have any questions concerning this submittal, please contact David J. Renn, Site Compliance Manager, at (256) 729-2636.

Respectfully,

A handwritten signature in black ink, appearing to read "DLAK", is written over a horizontal line.

Daniel A. Komm
Site Vice President

Enclosure: Licensee Event Report 50-296/2024-004-01 – Reactor Coolant System
Pressure Boundary Leakage Identified from Recirculation System Small Bore
Piping

cc (w/ Enclosure):

NRC Regional Administrator - Region II
NRC Senior Resident Inspector - Browns Ferry Nuclear Plant
NRC Project Manager - Browns Ferry Nuclear Plant

ENCLOSURE

**Browns Ferry Nuclear Plant
Unit 3**

Licensee Event Report 50-296/2024-004-01

**Reactor Coolant System Pressure Boundary Leakage Identified from Recirculation System Small
Bore Piping**

See Enclosed

NRC FORM 366 (04-02-2024)		U.S. NUCLEAR REGULATORY COMMISSION		APPROVED BY OMB: NO. 3150-0104		EXPIRES: 04/30/2027				
		LICENSEE EVENT REPORT (LER) (See Page 2 for required number of digits/characters for each block) (See NUREG-1022, R.3 for instruction and guidance for completing this form http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/)				Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch T-6 A10M), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollections.Resource@nrc.gov , and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk ail: oir_submission@omb.eop.gov . The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.				
1. Facility Name Browns Ferry Nuclear Plant, Unit 3				☒ 050 ☐ 052		52. Docket Number 00296				
						3. Page 1 OF 7				
4. Title Reactor Coolant System Pressure Boundary Leakage Identified from Recirculation System Small Bore Piping										
5. Event Date			6. LER Number			7. Report Date			8. Other Facilities Involved	
Month	Day	Year	Year	Sequential Number	Revision No.	Month	Day	Year	Facility Name	Docket Number
10	05	2024	2024	- 004 -	01	04	24	2025	N/A	05000XXX
									Facility Name	Docket Number
									N/A	05000XXX
9. Operating Mode 4						10. Power Level 0				
11. This Report is Submitted Pursuant to the Requirements of 10 CFR §: (Check all that apply)										
10 CFR Part 20		☐ 20.2203(a)(2)(vi)		10 CFR Part 50		☐ 50.73(a)(2)(ii)(A)		☐ 50.73(a)(2)(viii)(A)		☐ 73.1200(a)
☐ 20.2201(b)		☐ 20.2203(a)(3)(i)		☐ 50.36(c)(1)(i)(A)		☐ 50.73(a)(2)(ii)(B)		☐ 50.73(a)(2)(viii)(B)		☐ 73.1200(b)
☐ 20.2201(d)		☐ 20.2203(a)(3)(ii)		☐ 50.36(c)(1)(ii)(A)		☐ 50.73(a)(2)(iii)		☐ 50.73(a)(2)(ix)(A)		☐ 73.1200(c)
☐ 20.2203(a)(1)		☐ 20.2203(a)(4)		☐ 50.36(c)(2)		☐ 50.73(a)(2)(iv)(A)		☐ 50.73(a)(2)(x)		☐ 73.1200(d)
☐ 20.2203(a)(2)(i)		10 CFR Part 21		☐ 50.46(a)(3)(ii)		☐ 50.73(a)(2)(v)(A)		10 CFR Part 73		☐ 73.1200(e)
☐ 20.2203(a)(2)(ii)		☐ 21.2(c)		☐ 50.69(g)		☐ 50.73(a)(2)(v)(B)		☐ 73.77(a)(1)		☐ 73.1200(f)
☐ 20.2203(a)(2)(iii)				☐ 50.73(a)(2)(i)(A)		☐ 50.73(a)(2)(v)(C)		☐ 73.77(a)(2)(i)		☐ 73.1200(g)
☐ 20.2203(a)(2)(iv)				☒ 50.73(a)(2)(i)(B)		☐ 50.73(a)(2)(v)(D)		☐ 73.77(a)(2)(ii)		☐ 73.1200(h)
☐ 20.2203(a)(2)(v)				☐ 50.73(a)(2)(i)(C)		☐ 50.73(a)(2)(vii)				
☐ OTHER (Specify here, in abstract, or NRC 366A).										
12. Licensee Contact for this LER										
Licensee Contact Justin Garner, Site Compliance Engineer								Phone Number (Include area code) 256-729-7955		
13. Complete One Line for each Component Failure Described in this Report										
Cause	System	Component	Manufacturer	Reportable to IRIS	Cause	System	Component	Manufacturer	Reportable to IRIS	
N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
4. Supplemental Report Expected)					15. Expected Submission Date			Month	Day	Year
☒ No ☐ Yes (If yes, complete 15. Expected Submission Date								N/A	N/A	N/A
16. Abstract (Limit to 1326 spaces, i.e., approximately 13 single-spaced typewritten lines)										
On June 3, 2024, an increase in Browns Ferry (BFN) Unit 3 Drywell Unidentified Leakage was identified. This condition was monitored and trended from June 3, 2024, to October 4, 2024. The unidentified leakage came from two different sources. Prior to shutdown, total drywell unidentified leakage was approximately 1.0 gallon per minute. On October 5, 2024, at 0456, during the initial drywell entry of BFN Unit 3 Planned Outage 13 for replacement of a suspected defective fuel bundle, the drone operator observed water leaking from the elbow near the 1-inch sensing line off the 3B recirculation pump. In addition to this, the drone operator also observed water leaking from near the 3A recirculation pump vent line on a 3/4-inch elbow. The direct cause of the code class boundary leakage were cracks in two socket welds. The corrective actions for the direct cause were to replace the small bore piping elbows. The apparent cause was high-cycle fatigue. The corrective actions to address this are to implement modifications on the 3A and 3B Recirculation Pump Vent and Seal Vent Line Piping and sensing lines.										

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503; e-mail: oira_submission@omb.eop.gov. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. FACILITY NAME Browns Ferry Nuclear Plant, Unit 3	☒ 050	2. DOCKET NUMBER 00296	3. LER NUMBER		
	☐ 052		YEAR 2024	SEQUENTIAL NUMBER - 004	REV NO. - 01

NARRATIVE**I. Plant Operating Conditions before the Event**

At the time of discovery, Browns Ferry Nuclear Plant (BFN) Unit 3 was in Mode 4 at 0 percent power.

II. Description of Event**A. Event Summary**

On June 3, 2024, an increase in BFN Unit 3 Drywell Unidentified Leakage was identified. This condition was monitored and trended from June 3, 2024, to October 4, 2024. The unidentified leakage came from two different sources. Prior to shutdown, total drywell unidentified leakage was approximately 1.0 gallons per minute (gpm).

On October 21, 2024, Tennessee Valley Authority (TVA) completed a Past Operability Evaluation (POE). Technical Requirements Manual (TRM) Limiting Condition of Operability (LCO) 3.4.3, Structural Integrity states that the structural integrity of American Society of Mechanical Engineers (ASME) Code Class 1, 2, and 3 equivalent components shall be maintained in accordance with Technical Specification Requirement (TSR) 3.4.3.1 and TSR 3.4.3.2 throughout the life of the plant. Technical Specification (TS) 3.4.4 LCO (a) states that Reactor Coolant System (RCS) operational leakage shall be limited to no pressure boundary leakage while in Modes 1, 2, and 3. The structural integrity of the Reactor Coolant Pressure Boundary (RCPB) was inoperable for both TRM LCO 3.4.3 and TS LCO 3.4.4 (a) due to the cracks in the 1-inch elbow on the high pressure side sensing line for 3-PDT-068-0082 (BFN-3-VTV-068-0255) and the 3/4-inch recirculation pump vent elbow weld, which are both ASME Code Class 2 pipes. The starting date of inoperability is June 3, 2024, when Unit 3 showed an increase in Drywell Unidentified Leakage, and the ending date is October 5, 2024, when Unit 3 shutdown for BFN Unit 3 Planned Outage 13 (F313) and the sources of the leaks were discovered.

The Tennessee Valley Authority is submitting this report in accordance with Title 10 of the Code of Federal Regulations (10 CFR) 50.73(a)(2)(i)(B), as any operation or condition which was prohibited by the plant's Technical Specifications.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503; e-mail: oira_submission@omb.eop.gov. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. FACILITY NAME Browns Ferry Nuclear Plant, Unit 3	☒ 050	2. DOCKET NUMBER 00296	3. LER NUMBER		
	☐ 052		YEAR 2024	SEQUENTIAL NUMBER - 004	REV NO. - 01

NARRATIVE**B. Status of structures, components, or systems that were inoperable at the start of the event and that contributed to the event**

There were no structures, systems, or components (SSCs) whose inoperability contributed to this event.

C. Dates and approximate times of occurrences

<u>DATE AND APPROXIMATE TIMES</u>	<u>OCCURRENCE</u>
June 3, 2024	An increase in BFN Unit 3 Drywell Unidentified Leakage was identified.
June 3, 2024 – October 4, 2024	Data was trended and monitored to evaluate the leakage
October 4, 2024, at 2300	Main Generator Breaker was opened to begin BFN Unit 3 F313 for replacement of a suspected defective fuel bundle.
October 5, 2024, at 0456	During the initial drywell entry of BFN Unit 3, the drone operator observed water leaking from the elbow near the 1-inch sensing line off the 3B recirculation pump and from the 3A recirculation pump vent line on a 3/4-inch elbow.
October 10, 2024	The leak sources were repaired by Work Orders (WOs) 124871621 and 124871622.

D. Manufacturer and model number of each component that failed during the event

There were no failed components related to this event.

E. Other systems or secondary functions affected

No other systems or secondary functions were affected.

F. Method of discovery of each component or system failure or procedural error

On June 3, 2024, an increase in BFN Unit 3 Drywell Unidentified Leakage was identified. This condition was monitored and trended from June 3, 2024, to October 4, 2024. The unidentified

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollcts.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503; e-mail: oira_submission@omb.eop.gov. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. FACILITY NAME

Browns Ferry Nuclear Plant, Unit 3



050



052

2. DOCKET NUMBER

00296

3. LER NUMBER**YEAR**

2024

**SEQUENTIAL
NUMBER**

-

004

**REV
NO.**

-

01

NARRATIVE

leakage came from two different sources. Prior to shutdown, the total drywell unidentified leakage was approximately 1.0 gpm.

On October 5, 2024, at 0456, during the initial drywell entry of the F313 outage for replacement of a suspected defective fuel bundle, the drone operator observed water leaking from the elbow near the 1-inch sensing line off the 3B recirculation pump. In addition to this, the drone operator also observed water leaking from the elbow near the 3A recirculation pump vent line on a 3/4-inch elbow.

G. The failure mode, mechanism, and effect of each failed component

The failure mode was determined to be reactor recirculation system small bore pump vent and sensing line piping developed through-wall leakage from cracking due to high-cycle fatigue failure.

H. Operator actions

There were no operator actions associated with this event.

I. Automatically and manually initiated safety system responses

There were no automatic or manual safety system responses associated with this event.

III. Cause of the event**A. Cause of each component or system failure or personnel error**

The direct cause of the code class boundary leakage from the 3/4-inch and 1-inch elbows were cracks in the socket weld, and the apparent cause was high-cycle fatigue. The primary stresses driving the fatigue cracking were likely operating stresses exacerbated by uprates in plant power and implementation of Maximum Extended Load Line Limit Analysis Plus (MELLLA+) which resulted in changes in recirculation pump speed. These operating changes increase vibrational loads and can cause pipes and systems to fall into resonant frequencies of the area.

B. Cause(s) and circumstances for each human performance related root cause

There were no human performance related causes.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503; e-mail: oir_submission@omb.eop.gov. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. FACILITY NAME Browns Ferry Nuclear Plant, Unit 3	☒ 050	2. DOCKET NUMBER 00296	3. LER NUMBER		
	☐ 052		YEAR 2024	SEQUENTIAL NUMBER - 004	REV NO. - 01

NARRATIVE**IV. Analysis of the event**

The Recirculation System [AD] is designed to provide forced coolant circulation through the reactor core. Adjustment of the core coolant flow rate changes reactor power output which provides a means of following plant load demand without adjusting control rods.

On October 5, 2024, the visual inspection of the weld interface between the elbow near the BFN-3-VTV-068-0255 and weld interface on the BFN-3-SHV-068-6603, (VTV-68-6601 Shut Off Valve) marked the time of discovery for this condition. The condition was first identified on June 3, 2024, when BFN Unit 3 showed an increase in unidentified leakage. The condition was monitored and trended from June 3, 2024, to October 4, 2024.

V. Assessment of Safety Consequences

The safety significance of this event is low. The cracks in both the 1-inch Elbow on the High Pressure Side Sensing Line for 3-PDT-068-0082 and the 3/4-inch Recirculation Pump Vent elbow weld are bounded by two calculations. Calculation MDQ0999950033 Rev. 3, Exclusion Criteria for In-Service Inspection (ISI) Scope, shows that the normal reactor coolant makeup systems, Reactor Core Isolating Cooling (RCIC)[BN], Control Rod Drive (CRD)[AA], and Feedwater (FW)[SJ] have adequate capacity to makeup reactor coolant in the worst-case scenario of a small break loss of coolant accident (LOCA). Calculation NDQ0074880118 Rev. 8, Evaluation of Low Pressure Coolant Injection (LPCI)[BO] Flow to Reactor Pressure Vessel (RPV) with Failed Open Min Flow Bypass Valve, shows that the LPCI mode of the Residual Heat Removal (RHR)[BO] system can still meet the required LPCI flow to the RPV in the worst-case scenario of a small break LOCA for the duration of its mission time.

Probabilistic Risk Analysis (PRA) personnel were notified of the condition and reported the following results of likelihood of core damage frequency event (CDF) to be very small at 5.33E-8/year or once every 533,000,000 years. Similarly, the likelihood for a large early release frequency (LERF) to be 6.88E-9/year or once every 6,880,000,000 years.

Based on the above, TVA has concluded that sufficient systems were available to provide the required safety functions needed to protect the health and safety of the public.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollections.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503; e-mail: oira_submission@omb.eop.gov. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. FACILITY NAME Browns Ferry Nuclear Plant, Unit 3	☒ 050	2. DOCKET NUMBER 00296	3. LER NUMBER		
	☐ 052		YEAR 2024	SEQUENTIAL NUMBER - 004	REV NO. - 01

NARRATIVE**A. Availability of systems or components that could have performed the same function as the components and systems that failed during the event**

The Reactor Recirculation System shall be designed so that failure of piping integrity does not compromise the ability of the reactor vessel internals to provide a re-floodable volume. The normal reactor coolant makeup systems, RCIC, CRD, and FW have an adequate capacity to makeup reactor coolant in the worst-case scenario of a small break LOCA.

During the time period from June 3, 2024, until BFN Unit 3 was depressurized below 150 psig on October 5, 2024, at 0207, the BFN Unit 3 RCIC System was unavailable for 0.6 hours on July 31, 2024. The unavailability time was during the performance of 3-SR-3.5.3.3, RCIC System Rated Flow at Normal Operating Pressure. This period of RCIC System unavailability was due to the closure of 3-FCV-071-0009, RCIC Turbine Stop Valve, and the valving out of service of 3-FT-071-0036, RCIC Flow Transmitter, in accordance with procedure 3-SR-3.5.3.3. The CRD system was available as a makeup source during the time RCIC was unavailable. Also, a complete failure of the 3/4-inch Recirculation Pump Line Vent Valve elbow weld or the 1-inch Elbow on the High Pressure Side Sensing Line for 3-PDT-068-0082 would result in a high drywell pressure SCRAM which would affect the capability of the FW system as a makeup water source.

B. For events that occurred when the reactor was shut down, availability of systems or components needed to shutdown the reactor and maintain safe shutdown conditions, remove residual heat, control the release of radioactive material, or mitigate the consequences of an accident

This event did not occur when the reactor was shut down.

C. For failure that rendered a train of a safety system inoperable, estimate of the elapsed time from discovery of the failure until the train was returned to service

The starting date of inoperability was June 3, 2024, when Unit 3 showed an increase in Drywell Unidentified Leakage, and the ending date was October 5, 2024, when Unit 3 shutdown for F313 and the leak was discovered.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503; e-mail: oira_submission@omb.eop.gov. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. FACILITY NAME Browns Ferry Nuclear Plant, Unit 3	☒ 050	2. DOCKET NUMBER 00296	3. LER NUMBER		
	☐ 052		YEAR 2024	SEQUENTIAL NUMBER - 004	REV NO. - 01

NARRATIVE**VI. Corrective Actions**

Corrective Actions are being managed by the TVA's Corrective Action Program (CAP) under Condition Reports (CRs) 1963793, 1963794, and 1965828.

A. Immediate Corrective Actions

The leak source documented by CR 1963793 was repaired by WO 124871621, and the other leak source documented by CR 1963794 was repaired by WO 124871622.

B. Corrective Actions to Prevent Recurrence or to reduce the probability of similar events occurring in the future

The following corrective actions have been completed or are planned:

1. Replace 3/4-inch small bore piping elbow located between the 3A Recirc Pump and the Pump Vent Shutoff Valve.
2. Replace 1-inch small bore piping elbow located on the 3B Recirc Pump sensing line (high pressure side) prior to the branch connection.
3. Implement a design change on 1A, 2A, 3A, 1B, 2B, and 3B Recirc Pump Vent and Seal Vent Line Piping and sensing lines.

VII. Previous Similar Events at the Same Site

A review of the BFN Licensee Event Reports (LERs) for Units 1, 2, and 3 over the last four years revealed three (3) previous, similar events. (LERs 259/2022-001-01, 260/2023-001-01, and 296/2022-003-01).

VIII. Additional Information

There is no additional information.

IX. Commitments

There are no new commitments.