



Matt Busch
Vice President – Plant Hatch

Hatch Nuclear Plant
11028 Hatch Parkway North
Baxley, GA 31513
912 537 5859 tel
912 366 2077 fax

July 29, 2025

Docket Nos.: 50-321

NL-25-0295

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D. C. 20555-0001

Edwin I. Hatch Nuclear Plant
Licensee Event Report 2025-001-00
Unit 1 High Pressure Coolant Injection System Inoperable

Ladies and Gentlemen:

In accordance with the requirements of 10 CFR 50.73(a)(2)(v)(D), Southern Nuclear Operating Company hereby submits the enclosed Licensee Event Report.

This letter contains no NRC commitments. If you have any questions, please contact the Hatch Licensing Manager, Jimmy Collins, at 912.453.2342.

Respectfully submitted,

A handwritten signature in black ink, appearing to read "Matt Busch", written in a cursive style.

Matt Busch
Vice President – Hatch

MSB/CJC

Enclosure: LER 2025-001-00

Cc: Regional Administrator, Region II
NRR Project Manager – Hatch
Senior Resident Inspector – Hatch
RTYPE: CHA02.004

Enclosure to NL-25-0295
LER 2025-001-00

**Edwin I. Hatch Nuclear Plant
Licensee Event Report 2025-001-00**

Unit 1 High Pressure Coolant Injection System Inoperable

Enclosure

LER 2025-001-00



LICENSEE EVENT REPORT (LER)

(See Page 2 for required number of digits/characters for each block)

(See NUREG-1022, R.3 for instruction and guidance for completing this form)

<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by email to Infocollections.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. Facility Name

Edwin I. Hatch Nuclear Plant Unit 1

☒ 050☐ 052

2. Docket Number

00321

3. Page

1 OF 2

4. Title

Unit 1 High Pressure Coolant Injection System Inoperable

5. Event Date

6. LER Number

7. Report Date

8. Other Facilities Involved

Month	Day	Year	Year	Sequential Number	Revision No.	Month	Day	Year	Facility Name	☐ 050	Docket Number
06	03	2025	2025	- 001	- 00	07	29	2025	Facility Name	☐ 052	Docket Number

9. Operating Mode

1

10. Power Level

098

11. This Report is Submitted Pursuant to the Requirements of 10 CFR §: (Check all that apply)

☒ 10 CFR Part 20	☐ 20.2203(a)(2)(vi)	☒ 10 CFR Part 50	☐ 50.73(a)(2)(ii)(A)	☐ 50.73(a)(2)(viii)(A)	☐ 73.1200(a)
☐ 20.2201(b)	☐ 20.2203(a)(3)(i)	☐ 50.36(c)(1)(i)(A)	☐ 50.73(a)(2)(ii)(B)	☐ 50.73(a)(2)(viii)(B)	☐ 73.1200(b)
☐ 20.2201(d)	☐ 20.2203(a)(3)(ii)	☐ 50.36(c)(1)(ii)(A)	☐ 50.73(a)(2)(iii)	☐ 50.73(a)(2)(ix)(A)	☐ 73.1200(c)
☐ 20.2203(a)(1)	☐ 20.2203(a)(4)	☐ 50.36(c)(2)	☐ 50.73(a)(2)(iv)(A)	☐ 50.73(a)(2)(x)	☐ 73.1200(d)
☐ 20.2203(a)(2)(i)	☒ 10 CFR Part 21	☐ 50.46(a)(3)(ii)	☐ 50.73(a)(2)(v)(A)	☒ 10 CFR Part 73	☐ 73.1200(e)
☐ 20.2203(a)(2)(ii)	☐ 21.2(c)	☐ 50.69(g)	☐ 50.73(a)(2)(v)(B)	☐ 73.77(a)(1)	☐ 73.1200(f)
☐ 20.2203(a)(2)(iii)		☐ 50.73(a)(2)(i)(A)	☐ 50.73(a)(2)(v)(C)	☐ 73.77(a)(2)(i)	☐ 73.1200(g)
☐ 20.2203(a)(2)(iv)		☐ 50.73(a)(2)(i)(B)	☒ 50.73(a)(2)(v)(D)	☐ 73.77(a)(2)(ii)	☐ 73.1200(h)
☐ 20.2203(a)(2)(v)		☐ 50.73(a)(2)(i)(C)	☐ 50.73(a)(2)(vii)		

☐ OTHER (Specify here, in abstract, or NRC 366A).

12. Licensee Contact for this LER

Licensee Contact

Jimmy Collins - Licensing Manager

Phone Number (Include area code)

912-453-2342

13. Complete One Line for each Component Failure Described in this Report

Cause	System	Component	Manufacturer	Reportable to IRIS	Cause	System	Component	Manufacturer	Reportable to IRIS
X	BJ	V	A372	Y					

14. Supplemental Report Expected

☒ No ☐ Yes (If yes, complete 15. Expected Submission Date)

15. Expected Submission Date

Month	Day	Year

16. Abstract (Limit to 1326 spaces, i.e., approximately 13 single-spaced typewritten lines)

At 2137 EDT on 06/03/2025, while Unit 1 was operating at 98% power in MODE 1, the High Pressure Coolant Injection (HPCI) turbine stop valve (TSV) failed to open as required during the testing of the auxiliary oil pump, resulting in the HPCI system being declared INOPERABLE. The cause of the TSV failing to open was a degraded reset spring located in the trip knob assembly of the valve.

The reset spring was replaced, the valve was tested satisfactorily, and the safety function was restored at 0115 EDT on 06/05/2025 when the HPCI system was declared OPERABLE. The Reactor Core Isolation Cooling (RCIC) and low pressure Emergency Core Cooling Systems (ECCS) were OPERABLE during the time HPCI was INOPERABLE. However, because HPCI does not have a redundant system, the failed TSV resulting in HPCI being INOPERABLE represents a condition that could have prevented the fulfillment of the HPCI safety function to mitigate the consequences of an accident and is reportable per 50.73(a)(2)(v)(D).

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by email to Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. FACILITY NAME Edwin I. Hatch Nuclear Plant Unit 1	☒ 050	2. DOCKET NUMBER 00321	3. LER NUMBER		
	☐ 052		YEAR 2025	SEQUENTIAL NUMBER 001	REV NO. 00

NARRATIVE**EVENT DESCRIPTION**

At 2137 EDT on 06/03/2025, while Unit 1 was operating at 98% power in MODE 1, the High Pressure Coolant Injection (HPCI) (EIS: BJ) turbine stop valve (TSV) failed to open as required during the testing of the auxiliary oil pump, resulting in the HPCI system being declared INOPERABLE. The safety function was restored at 0115 EDT on 06/05/2025 when HPCI was declared OPERABLE. The Reactor Core Isolation Cooling (RCIC) System (EIS: BN) and the low-pressure Emergency Core Cooling Systems (ECCS) remained operable during the time the HPCI was INOPERABLE.

FAILED COMPONENT INFORMATION:

Master Parts List Number: 1E41F3053

Manufacturer: AMETEK

Model Number: 69-XC-103

Type: Turbine Stop Valve (TSV)

EVENT CAUSE ANALYSIS

The cause of the TSV failing to open was a degraded reset spring located in the trip knob assembly of the valve. The degradation of the reset spring occurred because there was no preventive maintenance scheduled for replacing the spring. As a result, the degraded reset spring lacked the necessary spring force to assist in opening the valve.

SAFETY ASSESSMENT

Even though HPCI was declared INOPERABLE, the RCIC System and the low-pressure ECCS remained OPERABLE during the event. However, because HPCI does not have a redundant system, the failed TSV resulting in HPCI being INOPERABLE represents a condition that could have prevented the fulfillment of the HPCI safety function to mitigate the consequences of an accident and is reportable per 50.73(a)(2)(v)(D). There were no actual safety consequences as a result of this event, and the operating crew responded correctly. The event was within the analysis of UFSAR Chapter 15.

CORRECTIVE ACTIONS

The reset spring was replaced, the valve was tested satisfactorily, and the safety function was restored at 0115 EDT on 06/05/2025 when the HPCI system was declared OPERABLE. Additionally, the HPCI maintenance procedure and the HPCI twelve-year preventive maintenance overhaul are being revised to include the replacement of the reset spring. Also, the HPCI surveillance procedure is being updated with a more conservative spring force acceptance criteria.

PREVIOUS SIMILAR EVENTS

None.