

RBG-48374

10 CFR 50.73

September 16, 2025

ATTN: Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

Subject: Licensee Event Report 50-458 / 2025-004-00, Unsecured Pressure
Boundary Door Resulting in Condition That Could Have Prevented
Fulfillment of a Safety Function

River Bend Station – Unit 1
NRC Docket Nos. 50-458
Renewed Facility Operating License No. NPF-47

In accordance with 10 CFR 50.73, enclosed is the subject Licensee Event Report.

This document contains no commitments.

Should you have any questions, please contact Mr. Jack McCoy, Regulatory and Emergency
Planning Manager, at 225-381-3310.

Respectfully,

**Jack
McCoy**

Digitally signed by Jack McCoy
DN: cn=Jack McCoy, o=REP
Manager, ou=RBS,
email=jmccoy1@entergy.com
Date: 2025.09.16 12:38:48 -05'00'

JM/hpk

Enclosure: Licensee Event Report 50-458 / 2025-004-00

cc: NRC Region IV Regional Administrator - Region IV
NRC Senior Resident Inspector - River Bend Station
NRC Office of Nuclear Security and Incident Response

Enclosure

RBG-48374

Licensee Event Report
50-458/2025-004-00



LICENSEE EVENT REPORT (LER)

(See Page 2 for required number of digits/characters for each block)

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<https://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collection Branch (T-6 A10M), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollect.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. Facility Name

River Bend Station, Unit 1

☒ 050
☐ 052

2. Docket Number

00458

3. Page

1 of 2

4. Title

Unsecured Pressure Boundary Door Resulting in Condition That Could Have Prevented Fulfillment of a Safety Function

5. Event Date

6. LER Number

7. Report Date

8. Other Facilities Involved

Month	Day	Year	Year	Sequential Number	Rev No.	Month	Day	Year	Facility Name	☐ 050	Docket Number
7	21	2025	2025	004	00	09	16	2025	N/A	☐ 052	Docket Number

9. Operating Mode

1

10. Power Level

100

11. This Report is Submitted Pursuant to the Requirements of 10 CFR §: (Check all that apply)

☒ 10 CFR Part 20	☐ 20.2203(a)(2)(vi)	☒ 10 CFR Part 50	☐ 50.73(a)(2)(ii)(A)	☐ 50.73(a)(2)(viii)(A)	☐ 73.1200(a)
☐ 20.2201(b)	☐ 20.2203(a)(3)(i)	☐ 50.36(c)(1)(i)(A)	☐ 50.73(a)(2)(ii)(B)	☐ 50.73(a)(2)(viii)(B)	☐ 73.1200(b)
☐ 20.2201(d)	☐ 20.2203(a)(3)(ii)	☐ 50.36(c)(1)(ii)(A)	☐ 50.73(a)(2)(iii)	☐ 50.73(a)(2)(ix)(A)	☐ 73.1200(c)
☐ 20.2203(a)(1)	☐ 20.2203(a)(4)	☐ 50.36(c)(2)	☐ 50.73(a)(2)(iv)(A)	☐ 50.73(a)(2)(x)	☐ 73.1200(d)
☐ 20.2203(a)(2)(i)	☒ 10 CFR Part 21	☐ 50.46(a)(3)(ii)	☐ 50.73(a)(2)(v)(A)	☒ 10 CFR Part 73	☐ 73.1200(e)
☐ 20.2203(a)(2)(ii)	☐ 21.2(c)	☐ 50.69(g)	☐ 50.73(a)(2)(v)(B)	☐ 73.77(a)(1)(i)	☐ 73.1200(f)
☐ 20.2203(a)(2)(iii)		☐ 50.73(a)(2)(i)(A)	☒ 50.73(a)(2)(v)(C)	☐ 73.77(a)(2)(i)	☐ 73.1200(g)
☐ 20.2203(a)(2)(iv)		☐ 50.73(a)(2)(i)(B)	☐ 50.73(a)(2)(v)(D)	☐ 73.77(a)(2)(ii)	☐ 73.1200(h)
☐ 20.2203(a)(2)(v)		☐ 50.73(a)(2)(i)(C)	☐ 50.73(a)(2)(vii)		

☐ Other (Specify here, in abstract, or in NRC 366A).

12. Licensee Contact for this LER

Licensee Contact

Jack McCoy

Phone Number (Include Area Code)

(225) 381-3310

13. Complete One Line for each Component Failure Described in this Report

Cause	System	Component	Manufacturer	Reportable To IRIS	Cause	System	Component	Manufacturer	Reportable To IRIS
A	NF	DR	R275	Y					

14. Supplemental Report Expected

☒ No ☐ Yes (If yes, complete 15. Expected Submission Date)

15. Expected Submission Date

Month Day Year

16. Abstract (Limit to 1326 spaces, i.e., approximately 13 single-spaced typewritten lines)

On July 21, 2025, at 1548 CDT, River Bend Station, Unit 1 (RBS) was operating in Mode 1 at 100% reactor power when the Central Alarm Station (CAS) received a door alarm indicating that an auxiliary building pressure boundary door, PW 123-01 (T-Tunnel Access to 114' Aux West Access), was not fully secured. A security officer was dispatched and found the door closed with the dogs not engaged. PW 123-01 is a Secondary Containment door. With the dogs not engaged, Secondary Containment was declared inoperable.

At 1551 CDT, a security officer fully engaged the dogs, which restored Secondary Containment.

This event is reportable in accordance with 10 CFR 50.73(a)(2)(v)(C), as any event or condition that could have prevented the fulfillment of the safety function of structures or systems that are needed to control the release of radioactive material.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<https://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collection Branch (T-6 A10M), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. FACILITY NAME		2. DOCKET NUMBER	3. LER NUMBER		
River Bend Station, Unit 1	☒ 050	00458	YEAR	SEQUENTIAL NUMBER	REV NO.
	☐ 052		2025	004	00

NARRATIVE**Event Description**

On July 21, 2025, at 1548 CDT, River Bend Station, Unit 1 (RBS) was operating in Mode 1 at 100% reactor power when the Central Alarm Station (CAS) received a door alarm indicating that an auxiliary building [NF] pressure boundary door [DR], PW 123-01 (T-Tunnel Access to 114' Aux West Access), was not fully secured. A security officer was dispatched and found the door closed with the dogs not engaged. PW 123-01 is a Secondary Containment door. With the dogs not engaged, Secondary Containment was declared inoperable.

At 1548 CDT, Technical Specifications (TS) Limiting Condition for Operation (LCO) 3.6.4.1 Condition A, Secondary Containment inoperable was entered. When the security officer fully engaged the dogs at 1551 CDT, restoring Secondary Containment, LCO 3.6.4.1, Condition A, was exited.

The event was reported on July 21, 2025, at 2151 CDT in accordance with 10 CFR 50.72(b)(3)(v) for an event or condition that could have prevented fulfillment of a safety function due to the inoperability of Secondary Containment (EN 57820).

Event Cause

The direct cause of this event was a personnel error. PW123-01 was left unsecured because the individual passing through the door closed it but failed to fully engage the dogs.

Safety Assessment

The River Bend Updated Safety Analysis Report describes the sequence of events postulated to occur following a Loss of Coolant Accident (LOCA). Part of that analysis is a projection of the maximum radiation dose received by a person at the site boundary. The LOCA dose calculation assumes that the standby gas treatment system is initiated 20 minutes into the event, and that Secondary Containment is at the required negative pressure within 30 minutes, such that filtration may be credited. As such, the safety function of Secondary Containment is maintained as long as the boundary is secured (or capable of being secured) within 20 minutes of the time of the security alarm. Since the subject door was secured within approximately 3 minutes of the time of the alarm, the safety function of Secondary Containment was maintained. This event was of minimal significance with respect to the health and safety of the public. While the corresponding functions were declared inoperable from a TS perspective, functionality was maintained, therefore, this event is not considered a safety system functional failure.

Corrective Actions**Completed:**

- A Performance Analysis was utilized to evaluate if any training deficiencies exist that could have contributed to this event.
- Verified Engineering Pre-Job Briefs include door management and traversing to work locations.

In Progress:

- Performance management actions will be used to reinforce proper behaviors with the individual to prevent future errors.

Previous Occurrences

Two similar events were reported by RBS in LER 050/458-2013-002-00 and LER 050/458-2017-009-00. Both LERs document individual(s) failing to properly secure a door in the auxiliary building pressure boundary. The audible tamper alarms installed as a result of LER 2017-009-00, operated as designed. The tamper alarms are designed to be audible when the door is opened and extinguished upon closure. In the event described in this LER the door was closed but not properly latched.