



Entergy Operations, Inc.
P.O. Box 756
Port Gibson, Mississippi 39150

Jeffery A. Hardy
Manager Regulatory Assurance
Grand Gulf Nuclear Station
Tel: 802-380-5124

10 CFR 50.73

GNRO2025-01000

November 03, 2025

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555-0001

SUBJECT: Grand Gulf Nuclear Station, Unit 1 Licensee Event Report 2025-005-00,
Loss of Secondary Containment Due to Unsecured Roof Hatch

Grand Gulf Nuclear Station, Unit 1
Docket No. 50-416
Renewed License No. NPF-29

Attached is Licensee Event Report (LER) 2025-005-00, Loss of Secondary Containment Due to Unsecured Roof Hatch. This report is being made in accordance with 10 CFR 50.73(a)(2)(v)(C) as a condition which could have prevented the fulfillment of the safety function of structures or systems that are needed to control the release of radioactive material.

This letter contains no new Regulatory Commitments. Should you have any questions concerning the content of this letter, please contact me at 802-380-5124.

Sincerely,

A handwritten signature in blue ink, appearing to read 'JAH', with a stylized flourish at the end.

JAH/der

Attachments: Licensee Event Report 2025-005-00

cc: NRC Senior Resident Inspector
Grand Gulf Nuclear Station
Port Gibson, MS 39150

U.S Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555-0001

Attachment
Licensee Event Report 2025-005-00

NRC FORM 366 (04-02-2024)		U.S. NUCLEAR REGULATORY COMMISSION		APPROVED BY OMB: NO. 3150-0104		EXPIRES: 04/30/2027						
		LICENSEE EVENT REPORT (LER) (See Page 2 for required number of digits/characters for each block)		Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collection Branch (T-6 A10M), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov , and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.								
1. Facility Name Grand Gulf Nuclear Station, Unit 1		☒ 050 ☐ 052		2. Docket Number 00416		3. Page 1 of 2						
4. Title Loss of Secondary Containment Due to Unsecured Roof Hatch												
5. Event Date			6. LER Number			7. Report Date		8. Other Facilities Involved				
Month	Day	Year	Year	Sequential Number	Rev No.	Month	Day	Year	Facility Name N/A	☐ 050	Docket Number	
09	04	2025	2025	005	00	11	03	2025	Facility Name N/A	☐ 052	Docket Number	
9. Operating Mode 1						10. Power Level 100						
11. This Report is Submitted Pursuant to the Requirements of 10 CFR §: (Check all that apply)												
10 CFR Part 20		☐ 20.2203(a)(2)(vi)		10 CFR Part 50		☐ 50.73(a)(2)(ii)(A)		☐ 50.73(a)(2)(viii)(A)		☐ 73.1200(a)		
☐ 20.2201(b)		☐ 20.2203(a)(3)(i)		☐ 50.36(c)(1)(i)(A)		☐ 50.73(a)(2)(ii)(B)		☐ 50.73(a)(2)(viii)(B)		☐ 73.1200(b)		
☐ 20.2201(d)		☐ 20.2203(a)(3)(ii)		☐ 50.36(c)(1)(ii)(A)		☐ 50.73(a)(2)(iii)		☐ 50.73(a)(2)(ix)(A)		☐ 73.1200(c)		
☐ 20.2203(a)(1)		☐ 20.2203(a)(4)		☐ 50.36(c)(2)		☐ 50.73(a)(2)(iv)(A)		☐ 50.73(a)(2)(x)		☐ 73.1200(d)		
☐ 20.2203(a)(2)(i)		10 CFR Part 21		☐ 50.46(a)(3)(ii)		☐ 50.73(a)(2)(v)(A)		10 CFR Part 73		☐ 73.1200(e)		
☐ 20.2203(a)(2)(ii)		☐ 21.2(c)		☐ 50.69(g)		☐ 50.73(a)(2)(v)(B)		☐ 73.77(a)(1)(i)		☐ 73.1200(f)		
☐ 20.2203(a)(2)(iii)				☐ 50.73(a)(2)(i)(A)		☒ 50.73(a)(2)(v)(C)		☐ 73.77(a)(2)(i)		☐ 73.1200(g)		
☐ 20.2203(a)(2)(iv)				☐ 50.73(a)(2)(i)(B)		☐ 50.73(a)(2)(v)(D)		☐ 73.77(a)(2)(ii)		☐ 73.1200(h)		
☐ 20.2203(a)(2)(v)				☐ 50.73(a)(2)(i)(C)		☐ 50.73(a)(2)(vii)						
☐ Other (Specify here, in abstract, or in NRC 366A).												
12. Licensee Contact for this LER												
Licensee Contact Jeff Hardy, Regulatory Assurance Manager								Phone Number (Include Area Code) 802-380-5124				
13. Complete One Line for each Component Failure Described in this Report												
Cause	System	Component	Manufacturer	Reportable To IRIS	Cause	System	Component	Manufacturer	Reportable To IRIS			
A	NF	DR		Y								
14. Supplemental Report Expected								15. Expected Submission Date		Month	Day	Year
☒ No		☐ Yes (If yes, complete 15. Expected Submission Date)										
16. Abstract (Limit to 1326 spaces, i.e., approximately 13 single-spaced typewritten lines)												
On September 4, 2025, at 0855 CT while at 100 percent power Grand Gulf Nuclear Station (GGNS) Unit 1 staff discovered the Enclosure Building Roof Hatch was unsecured and slightly open which resulted in inoperability of secondary containment. The hatch had last been accessed at 0845 CT. After discovery, the hatch was secured, and secondary containment was restored. A lack of proper oversight and failure of the watch team to properly understand their duty resulted in the Enclosure Building Roof Hatch becoming unsecured. Supervisor and paired observations will be periodically performed to prevent recurrence of the issue and an engineering barrier will be added to indicate when the hatch is open. This report is being made in accordance with 10 CFR 50.73(a)(2)(v)(C) as a condition which could have prevented the fulfillment of the safety function of structures or systems that are needed to control the release of radioactive material.												

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<https://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collection Branch (T-6 A10M), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. FACILITY NAME		2. DOCKET NUMBER	3. LER NUMBER		
Grand Gulf Nuclear Station, Unit 1	☒ 050	00416	YEAR	SEQUENTIAL NUMBER	REV NO.
	☐ 052		2025	005	00

NARRATIVE**Plant Conditions:**

At the time of the event, Grand Gulf Nuclear Station (GGNS) Unit 1 was in MODE 1 at 100 percent power, and all safety systems were operable.

Description of Event:

On September 4, 2025, at 0855 CT, operators discovered the Enclosure Building Roof Hatch was unsecured and open by approximately one inch. This resulted in inoperability of secondary containment. Following the discovery, the hatch was immediately closed and latched, and secondary containment was restored to operability at 0940 CT. Based on available information the hatch had been last accessed at 0845 CT.

Reportability:

This report is being made in accordance with 10 CFR 50.73(a)(2)(v)(C) as a condition which could have prevented the fulfillment of the safety function of structures or systems that are needed to control the release of radioactive material.

Cause(s):

Failure of the hatch watch to properly understand their duty and inadequate oversight by supervisors resulted in the Enclosure Building Roof Hatch becoming unsecured.

Corrective Actions:

- The Enclosure Building Roof Hatch was closed and secured.
- Daily observations will be performed by supervisors to ensure that the hatch watch is properly fulfilling their functions.
- Additional paired observations of roof hatch usage will be performed.
- Engineering barrier will be developed to provide indication and alarm when the hatch is open.

Safety Significance:

There were no actual safety consequences associated with this condition.

Previous Similar Events:

LER 2016-003
LER 2018-006