



Matt Busch
Vice President – Plant Hatch

Hatch Nuclear Plant
11028 Hatch Parkway North
Baxley, GA 31513
912 453 5859 tel
912 366 2077 fax

November 11, 2025

Docket Nos.: 50-366

NL-25-0399

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D. C. 20555-0001

Edwin I. Hatch Nuclear Plant
Licensee Event Report 2025-003-00

Unit 2 Manual Reactor SCRAM Due to Trip of Both Reactor Recirculation Pumps

Ladies and Gentlemen:

In accordance with the requirements of 10 CFR 50.73(a)(2)(iv)(A), Southern Nuclear Operating Company hereby submits the enclosed Licensee Event Report.

This letter contains no NRC commitments. If you have any questions, please contact the Hatch Licensing Manager, Jimmy Collins, at 912.453.2342.

Respectfully submitted,

A handwritten signature in black ink, appearing to read "M Busch", written over a horizontal line.

Matt Busch
Vice President – Hatch

MSB/CJC

Enclosure: LER 2025-003-00

Cc: Regional Administrator, Region II
NRR Project Manager – Hatch
Senior Resident Inspector – Hatch
RTYPE: CHA02.004

**Edwin I. Hatch Nuclear Plant
Licensee Event Report 2025-003-00**

Unit 2 Manual Reactor SCRAM Due to Trip of Both Reactor Recirculation Pumps

Enclosure

LER 2025-003-00



LICENSEE EVENT REPORT (LER)

(See Page 2 for required number of digits/characters for each block)

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by email to Infocollections.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. Facility Name	☒ 050 ☐ 052	2. Docket Number	3. Page
Edwin I. Hatch Nuclear Plant Unit 2		00366	1 OF 2

4. Title
Unit 2 Manual Reactor SCRAM Due to Trip of Both Reactor Recirculation Pumps

5. Event Date			6. LER Number			7. Report Date			8. Other Facilities Involved	
Month	Day	Year	Year	Sequential Number	Revision No.	Month	Day	Year	Facility Name	Docket Number
09	13	2025	2025	- 003 -	00	11	11	2025	Facility Name	☐ 050 ☐ 052

9. Operating Mode	10. Power Level
1	070

11. This Report is Submitted Pursuant to the Requirements of 10 CFR §: (Check all that apply)

☒ 10 CFR Part 20	☐ 20.2203(a)(2)(vi)	☒ 10 CFR Part 50	☐ 50.73(a)(2)(ii)(A)	☐ 50.73(a)(2)(viii)(A)	☐ 73.1200(a)
☐ 20.2201(b)	☐ 20.2203(a)(3)(i)	☐ 50.36(c)(1)(i)(A)	☐ 50.73(a)(2)(ii)(B)	☐ 50.73(a)(2)(viii)(B)	☐ 73.1200(b)
☐ 20.2201(d)	☐ 20.2203(a)(3)(ii)	☐ 50.36(c)(1)(ii)(A)	☐ 50.73(a)(2)(iii)	☐ 50.73(a)(2)(ix)(A)	☐ 73.1200(c)
☐ 20.2203(a)(1)	☐ 20.2203(a)(4)	☐ 50.36(c)(2)	☒ 50.73(a)(2)(iv)(A)	☐ 50.73(a)(2)(x)	☐ 73.1200(d)
☐ 20.2203(a)(2)(i)	☒ 10 CFR Part 21	☐ 50.46(a)(3)(ii)	☐ 50.73(a)(2)(v)(A)	☒ 10 CFR Part 73	☐ 73.1200(e)
☐ 20.2203(a)(2)(ii)	☐ 21.2(c)	☐ 50.69(g)	☐ 50.73(a)(2)(v)(B)	☐ 73.77(a)(1)	☐ 73.1200(f)
☐ 20.2203(a)(2)(iii)		☐ 50.73(a)(2)(i)(A)	☐ 50.73(a)(2)(v)(C)	☐ 73.77(a)(2)(i)	☐ 73.1200(g)
☐ 20.2203(a)(2)(iv)		☐ 50.73(a)(2)(i)(B)	☐ 50.73(a)(2)(v)(D)	☐ 73.77(a)(2)(ii)	☐ 73.1200(h)
☐ 20.2203(a)(2)(v)		☐ 50.73(a)(2)(i)(C)	☐ 50.73(a)(2)(vii)		
☐ OTHER (Specify here, in abstract, or NRC 366A).					

12. Licensee Contact for this LER

Licensee Contact	Phone Number (Include area code)
Jimmv Collins. Licensina Manager	912-453-2342

13. Complete One Line for each Component Failure Described in this Report

Cause	System	Component	Manufacturer	Reportable to IRIS	Cause	System	Component	Manufacturer	Reportable to IRIS

14. Supplemental Report Expected

☒ No	☐ Yes (If yes, complete 15. Expected Submission Date)	15. Expected Submission Date	Month	Day	Year

16. Abstract (Limit to 1326 spaces, i.e., approximately 13 single-spaced typewritten lines)

At 1704 EDT on 09/13/2025, with Unit 2 in MODE 1 at 70-percent power, the reactor was manually tripped due to the loss of both reactor recirculation pumps during turbine control valve testing. Investigation determined that a procedure step to bypass the recirculation pump trip logic had not been performed, resulting in the recirculation pumps tripping during valve testing. The reactor trip was not complex, with all safety systems responding normally including the closure of containment isolation valves (CIVs) in multiple systems, as designed, due to reaching the actuation setpoint on reactor water level. The operating crew responded correctly to the event and stabilized the plant.

The event is reportable per 10 CFR 50.73(a)(2)(iv)(A) as any event or condition that resulted in the manual or automatic actuation of any of the systems listed in paragraph 10 CFR 50.73(a)(2)(iv)(B). Systems that actuated during this event that are listed in (a)(2)(iv)(B) include: the Reactor Protection System and CIVs in multiple systems.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by email to Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. FACILITY NAME

Edwin I. Hatch Nuclear Plant Unit 2



050



052

2. DOCKET NUMBER

00366

3. LER NUMBER

YEAR

2025

SEQUENTIAL

NUMBER

003

REV

NO.

00

NARRATIVE**EVENT DESCRIPTION**

At 1704 EDT on 09/13/2025, with Unit 2 in MODE 1 at 70-percent power, the reactor was manually tripped due to the loss of both reactor recirculation pumps (EIIS Code: P) during turbine control valve (EIIS Code: FCV) testing. The reactor trip was not complex, with all safety systems responding normally including the closure of containment isolation valves (CIVs) (EIIS Code: ISV) in multiple systems, as designed, due to reaching the actuation setpoint on reactor water level. The operating crew responded correctly to the event and stabilized the plant. There were no inoperable systems that contributed to this event.

EVENT CAUSE ANALYSIS

The event was caused by inadequate place-keeping by licensed operators, which led to a missed critical step to bypass the recirculation pump trip logic resulting in the pumps tripping during valve testing.

SAFETY ASSESSMENT AND REPORTABILITY

There were no safety consequences as a result of this event with all safety related systems functioning as designed. The operating crew responded correctly to the event. The applicable abnormal and emergency operating procedures were properly entered and the plant was stabilized. The event was within the analysis of the Updated Final Safety Analysis Report (UFSAR) Chapter 15.

The event is reportable per 10 CFR 50.73(a)(2)(iv)(A) as any event or condition that resulted in the manual or automatic actuation of any of the systems listed in paragraph 10 CFR 50.73(a)(2)(iv)(B). Systems that actuated during this event that are listed in (a)(2)(iv)(B) include: the Reactor Protection System (EIIS Code: JC) and CIVs in multiple systems.

CORRECTIVE ACTIONS

Corrective actions include highlighting all critical procedural steps, followed by the supervisor reviewing the critical steps during the pre-job brief, implementing supervisor hold points prior to the execution of each critical step, and place-keeping page numbers during performance of any continuous use procedure. Also, lessons learned from the event have been communicated to site personnel.

PREVIOUS SIMILAR EVENTS

None.