



Post Office Box 2000, Decatur, Alabama 35609-2000

February 17, 2026

10 CFR 50.73

ATTN: Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555-0001

Browns Ferry Nuclear Plant, Units 1 and 2
Subsequent Renewed Facility Operating License Nos. DPR-33 and DPR-52
NRC Docket Nos. 50-259 and 50-260

Subject: **Licensee Event Report 50-259/2025-002-00 – Unit 1/2 480V Load Shed Logic Division I/II Inoperable Longer Than Allowed by Technical Specifications**

The enclosed Licensee Event Report provides details of a condition discovered that rendered the Unit 1/2 480V Load Shed Logic Division I/II inoperable longer than allowed by Technical Specifications on Browns Ferry Nuclear Plant, Units 1 and 2. The Tennessee Valley Authority is submitting this report in accordance with Title 10 of the Code of Federal Regulations (10 CFR) 50.73(a)(2)(i)(B), as any operation or condition which was prohibited by Technical Specifications. A supplement to this Licensee Event Report is planned to allow additional time to complete the cause evaluation.

There are no new regulatory commitments contained in this letter. Should you have any questions concerning this submittal, please contact David J. Renn, Site Regulatory Compliance Manager, at (256) 729-2636.

Respectfully,

A handwritten signature in black ink, appearing to read "D. Komm", is written over a horizontal line.

Daniel A. Komm
Site Vice President

Enclosure: Licensee Event Report 50-259/2025-002-00 – Unit 1/2 480V Load Shed Logic Division I/II Inoperable Longer Than Allowed by Technical Specifications

cc (w/ Enclosure):

NRC Regional Administrator - Region II
NRC Senior Resident Inspector - Browns Ferry Nuclear Plant
NRC Project Manager - Browns Ferry Nuclear Plant

ENCLOSURE

**Browns Ferry Nuclear Plant
Units 1 and 2**

Licensee Event Report 50-259/2025-002-00

**Unit 1/2 480V Load Shed Logic Division I/II Inoperable
Longer Than Allowed by Technical Specifications**

See Enclosed

NRC FORM 366 (04-02-2024)		U.S. NUCLEAR REGULATORY COMMISSION		APPROVED BY OMB: NO. 3150-0104		EXPIRES: 04/30/2027					
		LICENSEE EVENT REPORT (LER) (See Page 2 for required number of digits/characters for each block) (See NUREG-1022, R.3 for instruction and guidance for completing this form http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/)		Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch T-6 A10M), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollections.Resource@nrc.gov , and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk ail: oir_submission@omb.eop.gov . The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.							
1. Facility Name Browns Ferry Nuclear Plant, Units 1 and 2				☒ 050 ☐ 052		52. Docket Number 00259		3. Page 1 OF 4			
4. Title Unit 1/2 480V Load Shed Logic Division I/II Inoperable Longer Than Allowed by Technical Specifications											
5. Event Date			6. LER Number			7. Report Date			8. Other Facilities Involved		
Month	Day	Year	Year	Sequential Number	Revision No.	Month	Day	Year	Facility Name	Docket Number	
12	17	2025	2025	- 002 -	00	02	17	2026	Browns Ferry Nuclear Plant, Unit 2	05000260	
									Facility Name	Docket Number	
									N/A	05000XXX	
9. Operating Mode 1						10. Power Level 100					
11. This Report is Submitted Pursuant to the Requirements of 10 CFR §: (Check all that apply)											
10 CFR Part 20		☐ 20.2203(a)(2)(vi)		10 CFR Part 50		☐ 50.73(a)(2)(ii)(A)		☐ 50.73(a)(2)(viii)(A)		☐ 73.1200(a)	
☐ 20.2201(b)		☐ 20.2203(a)(3)(i)		☐ 50.36(c)(1)(i)(A)		☐ 50.73(a)(2)(ii)(B)		☐ 50.73(a)(2)(viii)(B)		☐ 73.1200(b)	
☐ 20.2201(d)		☐ 20.2203(a)(3)(ii)		☐ 50.36(c)(1)(ii)(A)		☐ 50.73(a)(2)(iii)		☐ 50.73(a)(2)(ix)(A)		☐ 73.1200(c)	
☐ 20.2203(a)(1)		☐ 20.2203(a)(4)		☐ 50.36(c)(2)		☐ 50.73(a)(2)(iv)(A)		☐ 50.73(a)(2)(x)		☐ 73.1200(d)	
☐ 20.2203(a)(2)(i)		10 CFR Part 21		☐ 50.46(a)(3)(ii)		☐ 50.73(a)(2)(v)(A)		10 CFR Part 73		☐ 73.1200(e)	
☐ 20.2203(a)(2)(ii)		☐ 21.2(c)		☐ 50.69(g)		☐ 50.73(a)(2)(v)(B)		☐ 73.77(a)(1)		☐ 73.1200(f)	
☐ 20.2203(a)(2)(iii)				☐ 50.73(a)(2)(i)(A)		☐ 50.73(a)(2)(v)(C)		☐ 73.77(a)(2)(i)		☐ 73.1200(g)	
☐ 20.2203(a)(2)(iv)				☒ 50.73(a)(2)(i)(B)		☐ 50.73(a)(2)(v)(D)		☐ 73.77(a)(2)(ii)		☐ 73.1200(h)	
☐ 20.2203(a)(2)(v)				☐ 50.73(a)(2)(i)(C)		☐ 50.73(a)(2)(vii)					
☐ OTHER (Specify here, in abstract, or NRC 366A).											
12. Licensee Contact for this LER											
Licensee Contact Michael Oliver, Site Sr Nuclear Licensing Program Manager								Phone Number (Include area code) 256-729-7874			
13. Complete One Line for each Component Failure Described in this Report											
Cause	System	Component	Manufacturer	Reportable to IRIS	Cause	System	Component	Manufacturer	Reportable to IRIS		
N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
4. Supplemental Report Expected)					15. Expected Submission Date						
☐ No					☒ Yes (If yes, complete 15. Expected Submission Date						
					Month Day Year 4 16 2026						
16. Abstract (Limit to 1326 spaces, i.e., approximately 13 single-spaced typewritten lines)											
At Browns Ferry Nuclear Plant, Units 1 and 2, on November 5, 2025, at 1157 Central Daylight Time, the performance of 480V Load Shedding Logic System Functional Test (Division I) and subsequent troubleshooting discovered that the tripping circuit for the 480V Control Bay Vent Board (CBVB) A Normal Feeder Breakers position switch was not closed. From the past operability evaluation, it was concluded that, in the event of there were a Unit 1 and/or Unit 2 loss of offsite power and an accident signal, the loads on the 480V CBVB A would not have shed, and the potential to overload Diesel Generator (DG) A existed. Based on the results of the analysis and the overloading scenarios associated with this condition, it was concluded that DG A would not have been overloaded and was capable to perform its intended safety function for its mission time. Because of this condition, the 480V Load Shed logic did not meet Technical Specifications (TS) Limited Condition of Operation 3.8.1 multiple times in Modes 1, 2, and 3 from November 5, 2022, to November 5, 2025. Because it was determined that DG A was fully capable of performing its safety functions with the additional load from 480V CBVB A, there is no safety significance with this condition present.											

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollections.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503; e-mail: oira_submission@omb.eop.gov. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. FACILITY NAME

Browns Ferry Nuclear Plant, Units 1
and 2



050



052

2. DOCKET NUMBER

00259

3. LER NUMBER

YEAR	SEQUENTIAL NUMBER	REV NO.
2025	- 002	- 00

NARRATIVE**I. Plant Operating Conditions before the Event**

At the time of discovery, Browns Ferry Nuclear Plant (BFN), Units 1 and 2, were both in Mode 1 at approximately 100 percent power.

II. Description of Event**A. Event Summary**

On November 5, 2025, at 1157 Central Daylight Time, performance of Technical Specifications (TS) Surveillance Requirement (SR) procedure 0-SR-3.8.1.8(I), 480V Load Shedding Logic System Functional Test (Division I), and subsequent troubleshooting discovered that the tripping circuit for the 480V Control Bay Vent Board (CBVB) A Normal Feeder Breakers position switch [33] was not closed. From the past operability evaluation, completed December 17, 2025, it was concluded that, in the event of there were a Unit 1 and/or Unit 2 loss of offsite power and an accident signal (reactor low level or reactor low pressure and drywell high pressure), loads on the 480V CBVB A [EC] would not have shed, and the potential to overload Diesel Generator (DG) A [EK] existed.

Based on the results of an engineering analysis and the overloading scenarios associated with this condition, it was concluded that DG A would not have been overloaded and was capable to perform its intended safety function for the 0 to 3 minute period of operation with the maximum starting and running loads from Unit 1 or Unit 2 plus the loads on the 480V CBVB A through its 7-day mission time. Because of this condition, the 480V Load Shed logic [JE] did not meet TS Limited Condition of Operation (LCO) 3.8.1 multiple times in Modes 1, 2, and 3 from November 5, 2022, to November 5, 2025.

Because it was determined that DG A was fully capable of performing its safety functions with the additional load from 480V CBVB A, there is no safety significance with this condition present.

The Tennessee Valley Authority is submitting this report in accordance with Title 10 of the Code of Federal Regulations 50.73(a)(2)(i)(B), as any operation or condition which was prohibited by TS.

B. Status of structures, components, or systems that were inoperable at the start of the event and that contributed to the event

None.

C. Dates and approximate times of occurrences

DATE AND APPROXIMATE TIMES	OCCURRENCE
November 5-7, 2025	Unsatisfactory results during testing. Following position switch adjustment, the test was reperformed satisfactorily.
December 17, 2025	Completion of engineering analysis and past operability evaluation for CR 2048979.

D. Manufacturer and model number of each component that failed during the event

There was no component failure.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503; e-mail: oira_submission@omb.eop.gov. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. FACILITY NAME Browns Ferry Nuclear Plant, Units 1 and 2	☒ 050	2. DOCKET NUMBER 00259	3. LER NUMBER		
	☐ 052		YEAR 2025	SEQUENTIAL NUMBER - 002	REV NO. - 00

NARRATIVE**E. Other systems or secondary functions affected**

No other systems or secondary functions were affected.

F. Method of discovery of each component or system failure or procedural error

There was no component failure or failure to follow a procedure.

G. The failure mode, mechanism, and effect of each failed component

There was no failed component.

H. Operator actions

None. There were no operating impacts on BFN Units 1, 2, or 3.

I. Automatically and manually initiated safety system responses

None. There were no safety system expected or actual responses.

III. Cause of the event**A. Cause of each component or system failure or personnel error**

There was no component or system failure.

B. Cause(s) and circumstances for each human performance related root cause

The cause, suspected inadequate procedure/maladjustment of a position switch, from this event is not finalized, and a supplement to this LER will be provided.

IV. Analysis of the event

Due to a maladjustment of a position switch, an engineering evaluation concluded that, with the breakers tripping circuit open, 480V Load Shed Logic for Divisions I and II would not have shed loads on 480V CBVB A if an accident signal was received from Unit 1 and/or Unit 2. Tripping of nonessential loads is a required function for DG operability. It also determined that with the loads on the 480V CBVB A not shedding, DG A was capable to perform its specified safety functions in the event an accident signal and loss of offsite power occurred between 0 minutes through its 7-day mission time.

V. Assessment of Safety Consequences

From the engineering evaluation, it was concluded that DG A remained capable of performing its safety functions and carrying designated loads plus the additional load from the CBVB A from initial start through its 7-day mission time. Regarding Division I and II of 480V Load Shed Logic, because the position switch for the tripping circuit was open, the Normal Feeder Breaker for the CBVB A would not have tripped open to shed the load on an accident signal from Unit 1 and/or Unit 2, both divisions of 480V load Shed Logic were inoperable.

A. Availability of systems or components that could have performed the same function as the components and systems that failed during the event

There are no systems or components that could have performed the same function.

B. For events that occurred when the reactor was shut down, availability of systems or components needed to shutdown the reactor and maintain safe shutdown conditions, remove residual heat, control the release of radioactive material, or mitigate the consequences of an accident

This event did not occur when the Units 1 and 2 reactors were shut down.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503; e-mail: oira_submission@omb.eop.gov. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. FACILITY NAME Browns Ferry Nuclear Plant, Units 1 and 2	☒ 050	2. DOCKET NUMBER 00259	3. LER NUMBER		
	☐ 052		YEAR 2025	SEQUENTIAL NUMBER - 002	REV NO. - 00

NARRATIVE**C. For failure that rendered a train of a safety system inoperable, estimate of the elapsed time from discovery of the failure until the train was returned to service**

No train of a safety system was rendered inoperable.

VI. Corrective Actions

Corrective Actions are being managed by TVA's Corrective Action Program via CR 2048979.

A. Immediate Corrective Actions

An adjustment was made during troubleshooting of the breaker cradle, which then allowed the position switch to be in the correct state. The previously failed step of the SR was reperformed and completed satisfactorily. As a result, there are no potential adverse aggregate/cumulative effects for 480V Load Shed Logic Division I or Division II or DG A.

B. Corrective Actions to Prevent Recurrence or to reduce the probability of similar events occurring in the future

The cause of this event is not finalized, and a supplement to this LER will be provided.

VII. Previous Similar Events at the Same Site

There were no previous similar events at BFN within the last 5 years.

VIII. Additional Information

There is no additional information.

IX. Commitments

There are no new commitments.

Energy Industry Identification System (EIS) codes are identified in the text as [XX].