

RA26-002

10 CFR 50.73

February 24, 2026

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555-0001

LaSalle County Station, Unit 1
Renewed Facility Operating License No. NPF-11
NRC Docket No. 50-373

Subject: Licensee Event Report 2025-002-00, Manual Scram Due to Degrading
Containment Parameters

In accordance with 10 CFR 50.73(a)(2)(ii)(A) and 10 CFR 50.73(a)(2)(iv)(A), Constellation Energy Generation, LLC (CEG) is submitting Licensee Event Report (LER) Number 2025-002-00 for LaSalle County Station, Unit 1.

There are no regulatory commitments contained in this letter.

Should you have any questions concerning this report, please contact Ms. Laura Ekern, Regulatory Assurance Manager, at (815) 415-2800.

Respectfully,



Deborah McBreen
Plant Manager
LaSalle County Station

Enclosure: Licensee Event Report 2025-002-00

cc: Regional Administrator – NRC Region III
NRC Senior Resident Inspector – LaSalle County Station



LICENSEE EVENT REPORT (LER)

(See Page 2 for required number of digits/characters for each block)

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by email to Infocollections.Resource@nrc.gov, and the OMB reviewer at OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. Facility Name

LaSalle County Station, Unit 1

☒ 050
☐ 052

2. Docket Number

00373

3. Page

1 OF 3

4. Title

Manual Scram Due to Degrading Containment Parameters

5. Event Date

Month	Day	Year
12	28	2025

6. LER Number

Year	Sequential Number	Revision No.
2025	- 002 -	00

7. Report Date

Month	Day	Year
02	24	2026

8. Other Facilities Involved

Facility Name	☐ 050	Docket Number
NA		NA
Facility Name	☐ 052	Docket Number
NA		NA

9. Operating Mode

1

10. Power Level

93

11. This Report is Submitted Pursuant to the Requirements of 10 CFR §: (Check all that apply)

10 CFR Part 20	☐ 20.2203(a)(2)(vi)	10 CFR Part 50	☒ 50.73(a)(2)(ii)(A)	☐ 50.73(a)(2)(viii)(A)	☐ 73.1200(a)
☐ 20.2201(b)	☐ 20.2203(a)(3)(i)	☐ 50.36(c)(1)(i)(A)	☐ 50.73(a)(2)(ii)(B)	☐ 50.73(a)(2)(viii)(B)	☐ 73.1200(b)
☐ 20.2201(d)	☐ 20.2203(a)(3)(ii)	☐ 50.36(c)(1)(ii)(A)	☐ 50.73(a)(2)(iii)	☐ 50.73(a)(2)(ix)(A)	☐ 73.1200(c)
☐ 20.2203(a)(1)	☐ 20.2203(a)(4)	☐ 50.36(c)(2)	☒ 50.73(a)(2)(iv)(A)	☐ 50.73(a)(2)(x)	☐ 73.1200(d)
☐ 20.2203(a)(2)(i)	10 CFR Part 21	☐ 50.46(a)(3)(ii)	☐ 50.73(a)(2)(v)(A)	10 CFR Part 73	☐ 73.1200(e)
☐ 20.2203(a)(2)(ii)	☐ 21.2(c)	☐ 50.69(g)	☐ 50.73(a)(2)(v)(B)	☐ 73.77(a)(1)	☐ 73.1200(f)
☐ 20.2203(a)(2)(iii)		☐ 50.73(a)(2)(i)(A)	☐ 50.73(a)(2)(v)(C)	☐ 73.77(a)(2)(i)	☐ 73.1200(g)
☐ 20.2203(a)(2)(iv)		☐ 50.73(a)(2)(i)(B)	☐ 50.73(a)(2)(v)(D)	☐ 73.77(a)(2)(ii)	☐ 73.1200(h)
☐ 20.2203(a)(2)(v)		☐ 50.73(a)(2)(i)(C)	☐ 50.73(a)(2)(vii)		

☐ OTHER (Specify here, in abstract, or NRC 366A).

12. Licensee Contact for this LER

Licensee Contact

Matthew Tutich, Operations Director

Phone Number (Include area code)

(815) 415-2200

13. Complete One Line for each Component Failure Described in this Report

Cause	System	Component	Manufacturer	Reportable to IRIS	Cause	System	Component	Manufacturer	Reportable to IRIS
B	AD	VTV	A415	Y	NA	NA	NA	NA	NA

14. Supplemental Report Expected

☒ No ☐ Yes (If yes, complete 15. Expected Submission Date)

15. Expected Submission Date

Month	Day	Year

16. Abstract (Limit to 1326 spaces, i.e., approximately 13 single-spaced typewritten lines)

On December 28, 2025, at 1606 CST, LaSalle Station Unit 1 was manually scrambled due to degrading containment parameters associated with a leak from the 'B' reactor recirculation pump line. The scram was not complex. All control rods fully inserted as expected; no Emergency Core Cooling Systems actuated or injected into the core.

This event did not pose a threat to the health and safety of the public. This event was reported via Event Notification #58100 under 10 CFR 50.72(b)(2)(iv)(B) as an event that resulted in actuation of the Reactor Protection System when the Reactor was critical. Subsequent Event Notification #58102 under 10 CFR 50.72(b)(3)(ii)(A) reported a degraded reactor coolant system pressure boundary due to a through-wall leak identified on a reactor recirculation system three-quarter inch vent valve.

Failure analysis attributed the cause of the leakage to vibration induced cyclic fatigue. Corrective actions include replacement of the affected component and planned inspections/modifications to similar equipment configurations.



LICENSEE EVENT REPORT (LER) CONTINUATION SHEET

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by email to Infocollections.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. FACILITY NAME LaSalle County Station, Unit 1	☒ 050	2. DOCKET NUMBER 00373	3. LER NUMBER		
	☐ 052		YEAR 2025	SEQUENTIAL NUMBER - 002	REV NO. - 00

NARRATIVE

Plant and System Identification

LaSalle County Station Unit 1 is a General Electric Boiling Water Reactor with 3546 Megawatts Thermal Rated Core Power. The affected systems were the Reactor Protection System (RPS) and Reactor Recirculation (RR) System.

Condition Prior to Event

Unit(s): 1	Date: December 28, 2025	Time: 1606 CST
Reactor Mode(s): 1	Mode(s) Name: Power Operation	Power Level: 93 percent

No systems, structures, or components that were inoperable at the start of the event contributed to the event.

Description

On December 28, 2025 at 1606 CST, LaSalle County Station Unit 1 was manually scrammed due to degrading containment parameters caused by unidentified drywell leakage. Following the manual scram, personnel entered the Unit 1 drywell to investigate the source of the leakage. The investigation identified a degraded reactor coolant system pressure boundary due to a through wall leak from an RR system vent valve.

Cause

Through wall leakage was identified on the bonnet and body-to-bonnet seal weld of the upstream manually operated vent valve for a reactor recirculation pump discharge flow control valve. Failure analysis determined the leakage was caused by vibration induced fatigue cracking.

Reportability and Safety Analysis

The safety significance of this event was minimal. All control rods fully inserted and all systems responded as expected to the scram. Makeup capability was adequate to compensate for the leak. Emergency Core Cooling Systems were not needed, but operable and capable of fulfilling their intended safety functions. This event did not meet the NEI 99-02 definition of an unplanned scram with complications. The event did not constitute a safety system functional failure (SSFF) as defined in accordance with NEI 99-02, "Regulatory Assessment Performance Indicator Guideline."

RPS actuation is reportable under 10 CFR 50.72(b)(2)(iv)(B) as an event or condition that results in the actuation of the RPS when the reactor is critical. An ENS report was made to the NRC at 2026 EST on December 28, 2025 (EN #58100). Upon determination of the leakage source, ENS report #58102 under 10 CFR 50.72(b)(3)(ii)(A) addressed the degraded reactor coolant system pressure boundary.

Corrective Actions

Immediate corrective actions taken in response to the condition were:

- Removed the failed valve assembly and installed blind flange connection
- Initiated failure analysis and causal investigation

Planned corrective actions are:

- Installation of replacement vent valve assembly
- Inspection and/or replacement of similar piping and valve assemblies



**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by email to Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. FACILITY NAME LaSalle County Station, Unit 1	☒ 050	2. DOCKET NUMBER 00373	3. LER NUMBER		
	☐ 052		YEAR 2025	SEQUENTIAL NUMBER - 002	REV NO. - 00

NARRATIVE

Previous Occurrences

LER 373-2018-004-00

On March 22, 2018, while LaSalle Unit 1 was in Mode 1, leakage from the reactor coolant system pressure boundary required entry into technical specification actions for required shutdown. The source of the leakage was identified as a through-wall pipe leak on a reactor recirculation vent line. This was reported in accordance with 10 CFR 50.73(a)(2)(ii)(A) as a principal safety barrier being in a degraded condition, and 10 CFR 50.73(a)(2)(i)(A) for a required plant shutdown in accordance with technical specifications. Cause of the pipe leakage was determined to be fatigue cracking.

Component Failure Data

Manufacturer: Anderson Greenwood & Company (A415)
Part Number: M12A15S-6M3F-1LX