

RA26-004

10 CFR 50.73

March 27, 2026

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555-0001

LaSalle County Station, Unit 1
Renewed Facility Operating License No. NPF-11
NRC Docket No. 50-373


Subject: Licensee Event Report 2025-001-01, Automatic Scram on Turbine Control
Valves Fast Closure on Generator Lockout

In accordance with 10 CFR 50.73(a)(2)(iv)(A), Constellation Energy Generation, LLC (CEG) is submitting Licensee Event Report (LER) Number 2025-001-01 for LaSalle County Station, Unit 1.

There are no regulatory commitments contained in this letter.

Should you have any questions concerning this report, please contact Ms. Laura Ekern, Regulatory Assurance Manager, at (815) 415-2800.

Respectfully,


Deborah McBreen
Plant Manager
LaSalle County Station

Enclosure: Licensee Event Report 2025-001-01

cc: Regional Administrator – NRC Region III
NRC Senior Resident Inspector – LaSalle County Station



LICENSEE EVENT REPORT (LER)

(See Page 2 for required number of digits/characters for each block)

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by email to Infocollections.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. Facility Name LaSalle County Station, Unit 1	☒ 050	2. Docket Number 00373	3. Page 1 OF 3
	☐ 052		

4. Title Automatic Scram Due to Turbine Control Valves Fast Closure on Generator Lockout

5. Event Date			6. LER Number			7. Report Date			8. Other Facilities Involved		
Month	Day	Year	Year	Sequential Number	Revision No.	Month	Day	Year	Facility Name	☐ 050	Docket Number
11	02	2025	2025	- 001 -	01	03	27	2026	NA	☐ 052	NA

9. Operating Mode 1	10. Power Level 100
------------------------	------------------------

11. This Report is Submitted Pursuant to the Requirements of 10 CFR §: (Check all that apply)

☐ 10 CFR Part 20	☐ 20.2203(a)(2)(vi)	☐ 10 CFR Part 50	☐ 50.73(a)(2)(ii)(A)	☐ 50.73(a)(2)(viii)(A)	☐ 73.1200(a)
☐ 20.2201(b)	☐ 20.2203(a)(3)(i)	☐ 50.36(c)(1)(i)(A)	☐ 50.73(a)(2)(ii)(B)	☐ 50.73(a)(2)(viii)(B)	☐ 73.1200(b)
☐ 20.2201(d)	☐ 20.2203(a)(3)(ii)	☐ 50.36(c)(1)(ii)(A)	☐ 50.73(a)(2)(iii)	☐ 50.73(a)(2)(ix)(A)	☐ 73.1200(c)
☐ 20.2203(a)(1)	☐ 20.2203(a)(4)	☐ 50.36(c)(2)	☒ 50.73(a)(2)(iv)(A)	☐ 50.73(a)(2)(x)	☐ 73.1200(d)
☐ 20.2203(a)(2)(i)	☐ 10 CFR Part 21	☐ 50.46(a)(3)(ii)	☐ 50.73(a)(2)(v)(A)	☐ 10 CFR Part 73	☐ 73.1200(e)
☐ 20.2203(a)(2)(ii)	☐ 21.2(c)	☐ 50.69(g)	☐ 50.73(a)(2)(v)(B)	☐ 73.77(a)(1)	☐ 73.1200(f)
☐ 20.2203(a)(2)(iii)		☐ 50.73(a)(2)(i)(A)	☐ 50.73(a)(2)(v)(C)	☐ 73.77(a)(2)(i)	☐ 73.1200(g)
☐ 20.2203(a)(2)(iv)		☐ 50.73(a)(2)(i)(B)	☐ 50.73(a)(2)(v)(D)	☐ 73.77(a)(2)(ii)	☐ 73.1200(h)
☐ 20.2203(a)(2)(v)		☐ 50.73(a)(2)(i)(C)	☐ 50.73(a)(2)(vii)		

☐ OTHER (Specify here, in abstract, or NRC 366A).

12. Licensee Contact for this LER

Licensee Contact Matthew Tutich, Operations Director	Phone Number (Include area code) (815) 415-2200
---	--

13. Complete One Line for each Component Failure Described in this Report

Cause	System	Component	Manufacturer	Reportable to IRIS	Cause	System	Component	Manufacturer	Reportable to IRIS
X	EA	XFMR	W120	Y	NA	NA	NA	NA	NA

14. Supplemental Report Expected

☒ No	☐ Yes (If yes, complete 15. Expected Submission Date)	15. Expected Submission Date	Month	Day	Year

16. Abstract (Limit to 1326 spaces, i.e., approximately 13 single-spaced typewritten lines)

On November 2, 2025, at 1346 CST, LaSalle Station Unit 1 experienced a Unit Auxiliary Transformer (UAT) trip. A generator lockout, turbine control valves fast closure, and reactor scram was automatically initiated by the plant in response to the trip. All control rods fully inserted as expected; no Emergency Core Cooling Systems actuated or injected. Plant operators effectively maintained reactor pressure and level.

This event did not pose a threat to the health and safety of the public. This event was reported via Event Notification #58018 under 10 CFR 50.72(b)(2)(iv)(B) as an event that resulted in actuation of the Reactor Protection System when the Reactor was critical.

The cause of the transformer trip was corrosion and inadequate divisional separation of test switches which allowed potential unintended interaction between DC divisions within protective relay circuitry. Due to this underlying condition, ground troubleshooting activities caused an inadvertent actuation of the UAT sudden pressure relay trip circuit, resulting in the Unit 1 scram.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by email to Infocollections.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. FACILITY NAME LaSalle County Station, Unit 1	☒ 050	2. DOCKET NUMBER 00373	3. LER NUMBER		
	☐ 052		YEAR 2025	SEQUENTIAL NUMBER - 001	REV NO. - 01

NARRATIVE**Plant and System Identification**

LaSalle Country Station Unit 1 is a General Electric Boiling Water Reactor with 3546 Megawatts Thermal Rated Core Power. The affected system was the Reactor Protection System (RPS).

Condition Prior to Event

Unit(s): 1	Date: November 2, 2025	Time: 1346 CST
Reactor Mode(s): 1	Mode(s) Name: Power Operation	Power Level: 100 percent

No systems, structures, or components that were inoperable at the start of the event contributed to the event.

Description

On October 29, 2025, the Main Control Room received an unexpected 125 VDC ground detector alarm. Troubleshooting activities narrowed the ground location to the Unit 1 UAT trouble alarm circuitry. On November 2, 2025, test switches were opened to isolate the previously identified ground. Opening the switches resulted in a generator lockout, UAT deluge system actuation, turbine control valves fast closure, and automatic reactor scram initiated by RPS in response to the trip. All control rods fully inserted as expected and no Emergency Core Cooling Systems actuated or injected. Plant operators effectively maintained reactor pressure and level, and reset the deluge system following verification of no fire at the transformer.

Investigation following the scram identified the UAT sudden pressure relay circuit had energized, however circuit monitoring light indication and oil sample analysis concluded that sudden pressure conditions were not present to trigger a legitimate actuation. Inspection of the UAT local control cabinet identified corrosion at the test switch blocks.

Cause

The cause of the transformer trip was corrosion and inadequate divisional separation of test switches which allowed potential unintended interaction between DC divisions within protective relay circuitry. Due to this underlying condition, ground troubleshooting activities caused an inadvertent actuation of the UAT sudden pressure relay trip circuit, resulting in the Unit 1 scram.

Reportability and Safety Analysis

The safety significance of this event was minimal. All control rods fully inserted and all systems responded as expected to the scram. Emergency Core Cooling Systems were not challenged. This event did not meet the NEI 99-02 definition of an unplanned scram with complications. There were no safety system functional failures.

RPS actuation is reportable under 10 CFR 50.72(b)(2)(iv)(B) as an event or condition that results in the actuation of the RPS when the reactor is critical. An ENS report was made to the NRC at 1837 EST on November 2, 2025 (EN #58018).

Corrective Actions

Replaced test switch blocks that had exhibited corrosion
Relocated test switches to provide divisional separation
Disabled sudden pressure relay logic trips of the UAT



LICENSEE EVENT REPORT (LER) CONTINUATION SHEET

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by email to Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. FACILITY NAME LaSalle County Station, Unit 1	☒ 050	2. DOCKET NUMBER 00373	3. LER NUMBER		
	☐ 052		YEAR 2025	SEQUENTIAL NUMBER - 001	REV NO. - 01

NARRATIVE

Previous Occurrences

No previous occurrences identified.

Component Failure Data

Manufacturer: Westinghouse Electric Corporation
Device: 8684D88
Component ID: 1AP90E